

returned payment fee, the amount of the fee may be no more than \$25 pursuant to § 1026.52(b)(1)(ii)(A).

2. *Adjustments based on Consumer Price Index.* For purposes of § 1026.52(b)(1)(ii)(A) and (b)(1)(ii)(B), the Bureau shall calculate each year price level adjusted amounts using the Consumer Price Index in effect on June 1 of that year. When the cumulative change in the adjusted minimum value derived from applying the annual Consumer Price level to the current amounts in § 1026.52(b)(1)(ii)(A) and (b)(1)(ii)(B) has risen by a whole dollar, those amounts will be increased by \$1.00. Similarly, when the cumulative change in the adjusted minimum value derived from applying the annual Consumer Price level to the current amounts in § 1026.52(b)(1)(ii)(A) and (b)(1)(ii)(B) has decreased by a whole dollar, those amounts will be decreased by \$1.00. The Bureau will publish adjustments to the amounts in § 1026.52(b)(1)(ii)(A) and (b)(1)(ii)(B).

i. *Historical thresholds.*

A. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$25 under § 1026.52(b)(1)(ii)(A) and \$35 under § 1026.52(b)(1)(ii)(B), through December 31, 2013.

B. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$26 under § 1026.52(b)(1)(ii)(A) and \$37 under § 1026.52(b)(1)(ii)(B), through December 31, 2014.

C. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$27 under § 1026.52(b)(1)(ii)(A) and \$38 under § 1026.52(b)(1)(ii)(B), through December 31, 2015.

D. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$27 under § 1026.52(b)(1)(ii)(A), through December 31, 2016. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$37 under § 1026.52(b)(1)(ii)(B), through June 26, 2016, and \$38 under § 1026.52(b)(1)(ii)(B) from June 27, 2016 through December 31, 2016.

E. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$27 under § 1026.52(b)(1)(ii)(A) and \$38 under § 1026.52(b)(1)(ii)(B), through December 31, 2017.

F. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$27 under § 1026.52(b)(1)(ii)(A) and \$38 under § 1026.52(b)(1)(ii)(B), through December 31, 2018.

G. Card issuers were permitted to impose a fee for violating the terms of an agreement if the fee did not exceed \$28 under § 1026.52(b)(1)(ii)(A) and \$39 under § 1026.52(b)(1)(ii)(B), through December 31, 2019.

3. *Delinquent balance for charge card accounts.* Section 1026.52(b)(1)(ii)(C) provides that, when a charge card issuer that requires payment of outstanding balances in full at the end of each billing cycle has not received the required payment for two or more consecutive billing cycles, the card issuer may impose a late payment fee that does not exceed three percent of the delinquent balance. For purposes of § 1026.52(b)(1)(ii)(C), the delinquent balance is any previously billed amount that remains unpaid at the time the late payment fee is imposed pursuant to § 1026.52(b)(1)(ii)(C). Consistent with § 1026.52(b)(2)(ii), a charge card issuer that imposes a fee pursuant to § 1026.52(b)(1)(ii)(C) with respect to a late payment may not impose a fee pursuant to § 1026.52(b)(1)(ii)(B) with respect to the same late payment. The following examples illustrate the application of § 1026.52(b)(1)(ii)(C):

i. Assume that a charge card issuer requires payment of outstanding balances in full at the end of each billing cycle and that the billing cycles for the account begin on the first day of the month and end on the last day of the month. At the end of the June billing cycle, the account has a balance of \$1,000. On July 5, the card issuer provides a periodic statement disclosing the \$1,000 balance consistent with § 1026.7. During the July billing cycle, the account is used for \$300 in transactions, increasing the balance to \$1,300. At the end of the July billing cycle, no payment has been received and the card issuer imposes a \$25 late payment fee consistent with § 1026.52(b)(1)(ii)(A). On August 5, the card issuer provides a periodic statement disclosing the \$1,325 balance consistent with § 1026.7. During the August billing cycle, the account is used for \$200 in transactions, increasing the balance to \$1,525. At the end of the August billing cycle, no payment has been received. Consistent with § 1026.52(b)(1)(ii)(C), the card issuer may impose a late payment fee of \$40, which is 3% of the \$1,325 balance that was due at the end of the August billing cycle. Section 1026.52(b)(1)(ii)(C) does not permit the card issuer to include the \$200 in transactions that occurred during the August billing cycle.

ii. Same facts as above except that, on August 25, a \$100 payment is received. Consistent with § 1026.52(b)(1)(ii)(C), the card issuer may impose a late

payment fee of \$37, which is 3% of the unpaid portion of the \$1,325 balance that was due at the end of the August billing cycle (\$1,225).

iii. Same facts as in paragraph A above except that, on August 25, a \$200 payment is received. Consistent with § 1026.52(b)(1)(ii)(C), the card issuer may impose a late payment fee of \$34, which is 3% of the unpaid portion of the \$1,325 balance that was due at the end of the August billing cycle (\$1,125). In the alternative, the card issuer may impose a late payment fee of \$35 consistent with § 1026.52(b)(1)(ii)(B). However, § 1026.52(b)(2)(ii) prohibits the card issuer from imposing both fees.

* * * * *

Dated: July 24, 2019.

Thomas Pahl,

Policy Associate Director, Bureau of Consumer Financial Protection.

[FR Doc. 2019-16300 Filed 7-31-19; 8:45 am]

BILLING CODE 4810-AM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0567; Product Identifier 2019-NE-21-AD; Amendment 39-19698; AD 2019-15-05]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Rolls-Royce Deutschland Ltd & Co KG (RRD) Trent 1000-AE3, Trent 1000-CE3, Trent 1000-D3, Trent 1000-G3, Trent 1000-H3, Trent 1000-J3, Trent 1000-K3, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000-P3, Trent 1000-Q3 and Trent 1000-R3 engines. This AD requires removal of the affected high-pressure turbine (HPT) disk front cover plate before reaching its new life limit. This AD was prompted by a recent analysis that determined the HPT disk front cover plate may have a safe life below its declared life limit. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 16, 2019.

The FAA must receive comments on this AD by September 16, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, United Kingdom, DE24 8BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: corporate.care@rolls-royce.com; internet: <https://customers.rolls-royce.com/public/rollsroycecare>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0567.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0567; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Besian Luga, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7750; fax: 781-238-7199; email: Besian.luga@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the

European Community, has issued EASA AD 2018-0164R1, dated March 14, 2019 (corrected copy dated March 21, 2019) (referred to after this as “the MCAI”), to address an unsafe condition for the specified products. The MCAI states:

Following a recent analysis of the material condition used in manufacture of these parts, it was established that the HP turbine disc front cover plate may have a safe life below its declared safe cyclic life (DSCL).

This condition, if not corrected, could lead to premature failure of an affected part, possibly resulting in damage to the engine and reduced control of the aeroplane.

To address this potential unsafe condition, RR published the NMSB to provide the new DSCL and replacement instructions. Consequently, EASA issued AD 2018-0164 to require implementation of the reduced DSCL and removal from service of those affected parts that have exceeded the reduced DSCL.

Since that [EASA] AD was issued, further analysis has resulted in the approval of an extended life for the affected parts. RR has published the TLM Task for this extended limit and it is expected the NMSB will be cancelled accordingly.

You may obtain further information by examining the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0567.

Related Service Information

The FAA reviewed Rolls-Royce plc (RR) Alert Service Bulletin (ASB) TRENT1000 72-AK057, Initial Issue, dated April 10, 2018. The service information describes procedures for either removing the engine containing the affected HPT disk front cover plate or replacing the HPT disk front cover plate during a shop visit.

FAA's Determination

This product has been approved by EASA and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this AD because we evaluated all the relevant information provided by EASA and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires removal of the affected HPT disk front cover plate from service before reaching its new life limit and replacing it with a part eligible for installation.

Differences Between This AD and the MCAI or Service Information

This AD and EASA AD 2018-0164R1, dated March 14, 2019 (corrected copy dated March 21, 2019) require removal of the affected HPT disk front cover plate before accumulating 1,250 cycles since first installation on an engine. RR ASB Trent1000 72-AK057, Initial Issue, dated April 10, 2018, requires removal of the affected HPT disk front cover plate before accumulating 865 cycles since first installation. Since publication of the ASB, the manufacturer has revised its analysis, which has resulted in an extension of the life limit for this part to 1,250 cycles.

FAA's Justification and Determination of the Effective Date

No domestic operators use this product. Therefore, the FAA finds good cause that notice and opportunity for prior public comment are unnecessary. In addition, for the reason stated above, the FAA finds that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2019-0567 and Product Identifier 2019-NE-21-AD at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

The FAA will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact we receive about this final rule.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

| Action | Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
|--|--|------------|------------------|------------------------|
| Replace HPT disk front cover plate | 7 work-hours × \$85 per hour = \$595 | \$307,137 | \$307,732 | \$0 |

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–15–05 Rolls-Royce Deutschland Ltd & Co KG: Amendment 39–19698; Docket No. FAA–2019–0567; Product Identifier 2019–NE–21–AD.

(a) Effective Date

This AD is effective August 16, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Rolls-Royce Deutschland Ltd & Co KG (RRD) Trent 1000–AE3, Trent 1000–CE3, Trent 1000–D3, Trent 1000–G3, Trent 1000–H3, Trent 1000–J3, Trent 1000–K3, Trent 1000–L3, Trent 1000–M3, Trent 1000–N3, Trent 1000–P3, Trent 1000–Q3 and Trent 1000–R3 engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by recent analysis of the material condition used in the manufacture of these parts that determined the high-pressure turbine (HPT) disk front cover plate may have a safe life below its declared safe cyclic life. The FAA is issuing this AD to prevent failure of the HPT disk front cover plate. The unsafe condition, if not addressed, could result in uncontained release of the HPT turbine disk front cover plate, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Remove the HPT disk front cover plate, part number KH59279, from service prior to it reaching 1,250 engine cycles since first installation on an engine and replace with a part eligible for installation.

(h) Installation Prohibition

Do not install any HPT disk front cover plate, part number KH59279, into any engine, or any engine onto any airplane, if that part has exceeded 1,250 engine cycles since first installation on an engine.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Besian Luga, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7750; fax: 781–238–7199; email: Besian.Luga@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2018–0164R1, dated March 14, 2019 (corrected copy dated March 21, 2019), for more information. You may examine the EASA AD in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA–2019–0567.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on July 26, 2019.

Karen M. Grant,

Acting Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2019-16329 Filed 7-31-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 73

[Docket No. FDA-2018-C-4464]

Listing of Color Additives Exempt From Certification; Soy Leghemoglobin

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA or we) is amending the color additive regulations to provide for the safe use of soy leghemoglobin as a color additive in ground beef analogue products. We are taking this action in response to a color additive petition (CAP) submitted by Impossible Foods, Inc. (Impossible Foods or petitioner).

DATES: This rule is effective September 4, 2019. See section X for further information on the filing of objections. Submit either electronic or written objections and requests for a hearing on the final rule by September 3, 2019.

ADDRESSES: You may submit objections and requests for a hearing as follows. Please note that late, untimely filed objections will not be considered. Electronic objections must be submitted on or before September 3, 2019. The <https://www.regulations.gov> electronic filing system will accept comments until 11:59 p.m. Eastern Time at the end of September 3, 2019. Objections received by mail/hand delivery/courier (for written/paper submissions) will be considered timely if they are postmarked or the delivery service acceptance receipt is on or before that date.

Electronic Submissions

Submit electronic objections in the following way:

- **Federal eRulemaking Portal:** <https://www.regulations.gov>. Follow the instructions for submitting comments. Objections submitted electronically, including attachments, to <https://www.regulations.gov> will be posted to

the docket unchanged. Because your objection will be made public, you are solely responsible for ensuring that your objection does not include any confidential information that you or a third party may not wish to be posted, such as medical information, your or anyone else's Social Security number, or confidential business information, such as a manufacturing process. Please note that if you include your name, contact information, or other information that identifies you in the body of your objection, that information will be posted on <https://www.regulations.gov>.

- If you want to submit an objection with confidential information that you do not wish to be made available to the public, submit the objection as a written/paper submission and in the manner detailed (see "Written/Paper Submissions" and "Instructions").

Written/Paper Submissions

Submit written/paper submissions as follows:

- **Mail/Hand Delivery/Courier (for written/paper submissions):** Dockets Management Staff (HFA-305), Food and Drug Administration, 5630 Fishers Lane, Rm. 1061, Rockville, MD 20852.

- For written/paper objections submitted to the Dockets Management Staff, FDA will post your objection, as well as any attachments, except for information submitted, marked and identified, as confidential, if submitted as detailed in "Instructions."

Instructions: All submissions received must include the Docket No. FDA-2018-C-4464 for "Listing of Color Additives Exempt From Certification; Soy Leghemoglobin." Received objections, those filed in a timely manner (see **ADDRESSES**), will be placed in the docket and, except for those submitted as "Confidential Submissions," publicly viewable at <https://www.regulations.gov> or with the Dockets Management Staff between 9 a.m. and 4 p.m., Monday through Friday.

- **Confidential Submissions—**To submit an objection with confidential information that you do not wish to be made publicly available, submit your objections only as a written/paper submission. You should submit two copies total. One copy will include the information you claim to be confidential with a heading or cover note that states "THIS DOCUMENT CONTAINS CONFIDENTIAL INFORMATION." We will review this copy, including the claimed confidential information, in our consideration of comments. The second copy, which will have the claimed confidential information redacted/blacked out, will be available for public

viewing and posted on <https://www.regulations.gov>. Submit both copies to the Dockets Management Staff. If you do not wish your name and contact information to be made publicly available, you can provide this information on the cover sheet and not in the body of your comments and you must identify this information as "confidential." Any information marked as "confidential" will not be disclosed except in accordance with 21 CFR 10.20 and other applicable disclosure law. For more information about FDA's posting of comments to public dockets, see 80 FR 56469, September 18, 2015, or access the information at: <https://www.gpo.gov/fdsys/pkg/FR-2015-09-18/pdf/2015-23389.pdf>.

Docket: For access to the docket to read background documents or the electronic and written/paper comments received, go to <https://www.regulations.gov> and insert the docket number, found in brackets in the heading of this document, into the "Search" box and follow the prompts and/or go to the Dockets Management Staff, 5630 Fishers Lane, Rm. 1061, Rockville, MD 20852.

FOR FURTHER INFORMATION CONTACT: Ellen Anderson, Center for Food Safety and Applied Nutrition, Food and Drug Administration, 5001 Campus Dr., College Park, MD 20740-3835, 240-402-1309.

SUPPLEMENTARY INFORMATION:

I. Introduction

In a notice published in the **Federal Register** of December 13, 2018 (83 FR 64045), we announced that we filed a color additive petition (CAP 9C0314) submitted by Impossible Foods, Inc., c/o Exponent, Inc., 1150 Connecticut Avenue NW, Suite 1100, Washington, DC 20036. The petition proposed to amend the color additive regulations in part 73 (21 CFR part 73), "Listing of Color Additives Exempt from Certification" to provide for the safe use of soy leghemoglobin as a color additive in ground beef analogue products such that the amount of soy leghemoglobin protein does not exceed 0.8 percent by weight of the uncooked ground beef analogue product. For the purposes of this final rule, the term "ground beef analogue products" refers to plant-based or other non-animal derived ground beef-like food products. The petition describes soy leghemoglobin protein as the principal reddish brown coloring component of a stabilized mixture, referred to as soy leghemoglobin preparation. We are establishing soy leghemoglobin as the common or usual name for this color additive and note