

Rules and Regulations

Federal Register

Vol. 84, No. 177

Thursday, September 12, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF HOMELAND SECURITY

Office of the Secretary

6 CFR Part 37

RIN 1601-AA91

Minimum Standards for Driver's Licenses and Identification Cards Acceptable by Federal Agencies for Official Purposes; Implementation of the REAL ID Act Modification for Freely Associated States Act; Correction

AGENCY: Office of the Secretary, DHS.

ACTION: Final rule; correction.

SUMMARY: The Department of Homeland Security (DHS) is correcting a final rule that published in the **Federal Register** on September 4, 2019. On September 4, 2019, DHS published two documents in the **Federal Register** related to the implementation of the REAL ID Modification for Freely Associated States Act: A final rule implementing the REAL ID Modification for Freely Associated States Act, and a notice designating an unexpired foreign passport and valid Form I-94 (Arrival-Departure Record) as acceptable identity documentation for purposes of obtaining a REAL ID driver's license or identification card for eligible citizens of the Freely Associated States. The text of footnote 9, which was included in the final rule, was overtaken by the notice published on the same date. Through this correction, the text of footnote 9 is being revised.

DATES: Effective on September 12, 2019.

FOR FURTHER INFORMATION CONTACT: Steve Yonkers, Director, Biometrics and Credentialing/REAL ID Program, U.S. Department of Homeland Security Office of Policy, Strategy, and Plans, Washington, DC 20528, (202) 447-3274.

SUPPLEMENTARY INFORMATION: In FR Doc. 2019-19023 appearing on page 46423 in the **Federal Register** of Wednesday,

September 4, 2019, the following correction is made:

1. On page 46424, in the third column, in footnote 9, the text is revised to read as follows: "See 6 CFR 37.11."

Christina McDonald,

Associate General Counsel for Regulatory Affairs.

[FR Doc. 2019-19702 Filed 9-11-19; 8:45 am]

BILLING CODE 9110-9M-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0023; Product Identifier 2018-NM-145-AD; Amendment 39-19700; AD 2019-15-07]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to certain The Boeing Company Model 737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series airplanes. As published, a paragraph reference specified in the regulatory text is incorrect. This document corrects that error. In all other respects, the original document remains the same.

DATES: This correction is effective September 19, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 19, 2019 (84 FR 41614, August 15, 2019).

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA,

call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0023.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0023; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email: george.garrido@faa.gov.

SUPPLEMENTARY INFORMATION: AD 2019-15-07, Amendment 39-19700 (84 FR 41614, August 15, 2019) ("AD 2019-15-07"), requires repetitive inspections for cracking of the fuselage lower lobe frames, and applicable on-condition actions. That AD also provides an optional terminating action for certain repetitive inspections. That AD applies to certain The Boeing Company Model 737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series airplanes.

Need for the Correction

As published, paragraph (h) of the regulatory text of AD 2019-15-07 contains an error. Paragraph (h) of the AD incorrectly refers to paragraph (i) as the Exceptions to Service Information Specifications paragraph, and it should have referred to paragraph (j) of the AD.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Service Bulletin 737-53A1362, dated September 20, 2018. The service information describes procedures for repetitive inspections for cracking of the fuselage lower lobe frames, applicable on-condition actions, and an optional modification of the tooling holes and