

(h) *Appeal service report.* Immediately after appeal service has been performed for any products, a report shall be prepared and issued referring specifically to the original findings and stating the class, grade, other quality, or compliance of the products as shown by the appeal service.

■ 20. Revise § 54.20 to read as follows:

§ 54.20 Exemptions.

Any exemption to the regulations must be approved by the Director. Exemptions may include but are not limited to:

(a) Grading the meat of animals in other than carcass form if the class, grade, and other quality attributes may be determined under the applicable official standards.

(b) Grading in an establishment other than where the animal was slaughtered or initially chilled if the class, grade, and other quality attributes can be determined under the applicable official standards, and if the identity of the carcasses can be maintained.

(c) If the Branch is unable to provide grading service in a timely manner and the meat can be identified in conformance with the official standards.

(d) Grading in the establishment other than where the hide is removed, provided the meat can be identified in conformance with the official standards.

(e) Grading imported carcasses, provided:

(1) The imported carcass is marked so that the name of the country of origin is conspicuous to the USDA grader. The mark of foreign origin shall be imprinted by roller brand, handstamp, tag, or other approved method.

(2) The imprints of the mark of foreign origin have been submitted to the Chief for the determination of compliance with these regulations prior to use on meats offered for Federal grading.

(3) The applicant notifies the official grader performing the service whenever imported carcasses are offered for grading.

(f) For good cause and provided that the meat can be identified in conformance with the official standards and procedures.

§§ 54.21–54.26 [Removed and reserved]

■ 21. Remove and reserve §§ 54.21 through 54.26.

§ 54.30 [Removed and reserved]

■ 22. Remove and reserve § 54.30.

■ 23. Revise § 54.31 to read as follows:

§ 54.31 OMB control number.

The information collection and recordkeeping requirements of this part

have been approved by OMB under 44 U.S.C. Chapter 35 and have been assigned OMB Control Number 0581–0128.

Dated: September 6, 2019.

Bruce Summers,
Administrator.

[FR Doc. 2019–19707 Filed 9–13–19; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0324; Product Identifier 2019–NM–031–AD; Amendment 39–19726; AD 2019–17–06]

RIN 2120–AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. This AD was prompted by reports of cracks on certain nose landing gear (NLG) turning tubes resulting from incorrectly applied repairs. This AD requires removing the affected parts and replacing them with serviceable parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 21, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 21, 2019.

ADDRESSES: For Fokker service information identified in this final rule, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88–6280–350; fax +31 (0)88–6280–111; email technicalservices@fokker.com; internet <http://www.myfokkerfleet.com>. For Safran service information identified in this final rule, contact Safran Landing Systems, One Carbon Way, Walton, KY 41094; telephone (859) 525–8583; fax (859) 485–8827; internet <https://www.safran-landing-systems.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0324.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0324; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. The NPRM published in the **Federal Register** on May 14, 2019 (84 FR 21270). The NPRM was prompted by reports of cracks on certain NLG turning tubes resulting from incorrectly applied repairs. The NPRM proposed to require removing the affected parts and replacing them with serviceable parts.

The FAA is issuing this AD to address cracking of NLG turning tubes, which could lead to NLG turning tube failure, possibly resulting in damage to the airplane and injury to occupants.

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0037, dated February 19, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. The MCAI states:

Occurrences have been reported of finding cracks on certain NLG turning tubes. The subsequent investigation results revealed that the cracks initiated from an area that is sensitive to fatigue cracking, which had been subject to incorrectly applied repairs.

This condition, if not detected and corrected, could lead to NLG turning tube

failure, possibly resulting in damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Fokker Services published the SB [service bulletin] to provide replacement instructions, referring to SLS [Safran Landing Systems] SB F100-32-117 for in-shop inspection.

For the reasons described above, this [EASA] AD requires removal from service of the affected part and replacement with a serviceable part.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0324.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no

comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Fokker Services B.V. has issued Fokker Service Bulletin SBF100-32-

171, dated November 27, 2018. This service information describes procedures for removing and replacing affected NLG turning tubes.

Safran Landing Systems has issued Safran Service Bulletin F100-32-117, dated July 30, 2018. This service information describes procedures for a magnetic particle or eddy current inspection of NLG turning tubes.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 4 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
9 work-hours × \$85 per hour = \$765	\$1,282	\$2,047	\$8,188

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-17-06 Fokker Services B.V.: Amendment 39-19726; Docket No. FAA-2019-0324; Product Identifier 2019-NM-031-AD.

(a) Effective Date

This AD is effective October 21, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by reports of cracks on certain nose landing gear (NLG) turning tubes resulting from incorrectly applied repairs. The FAA is issuing this AD to address cracking of NLG turning tubes, which could lead to NLG turning tube failure, possibly resulting in damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

- (1) An affected part is an NLG turning tube assembly having part number (P/N) 201456200, 201071202, 201071240, or

201071241 installed on an NLG unit having a part number identified in Safran Service Bulletin F100-32-117, dated July 30, 2018.

(2) A serviceable part is an affected part that is new or that, before installation, has passed an inspection (no cracks found, having the correct radius), in accordance with the Accomplishment Instructions of Safran Service Bulletin F100-32-117, dated July 30, 2018.

(h) Replacement

Within 22,000 flight cycles after the effective date of this AD: Replace the affected parts, with serviceable parts, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-171, dated November 27, 2018.

(i) Parts Installation Limitation

As of the effective date of this AD, no person may install, on any airplane, an affected part, unless it is a serviceable part.

(j) No Reporting Requirement

Although Safran Service Bulletin F100-32-117, dated July 30, 2018, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0037, dated February 19, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0324.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des

Moines, WA 98198; telephone and fax 206-231-3226.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-32-171, dated November 27, 2018.

(ii) Safran Service Bulletin F100-32-117, dated July 30, 2018.

(3) For Fokker service information identified in this final rule, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; internet <http://www.myfokkerfleet.com>. For Safran service information identified in this final rule, contact Safran Landing Systems, One Carbon Way, Walton, KY, 41094; telephone (859) 525-8583; fax (859) 485-8827; internet <https://www.safran-landing-systems.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on August 22, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-19912 Filed 9-13-19; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 300

[EPA-HQ-SFUND-1983-0002; FRL-9999-31-Region 9]

National Oil and Hazardous Substances Pollution Contingency Plan; National Priorities List: Deletion of the MGM Brakes Superfund Site

AGENCY: Environmental Protection Agency (EPA).

ACTION: Final rule.

SUMMARY: The Environmental Protection Agency (EPA) Region 9 announces the deletion of the MGM Brakes Superfund Site (Site) located in Cloverdale, Sonoma County, California, from the National Priorities List (NPL). The NPL,

promulgated pursuant to section 105 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, as amended, is an appendix of the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). The EPA and the State of California, through the Department of Toxic Substances Control, have determined that all appropriate response actions under CERCLA have been completed. However, this deletion does not preclude future actions under Superfund.

DATES: This action is effective September 16, 2019.

ADDRESSES: *Docket:* EPA has established a docket for this action under Docket Identification No. EPA-HQ-SFUND-1983-0002. All documents in the docket are listed on the <http://www.regulations.gov> website. Although listed in the index, some information is not publicly available, *i.e.*, Confidential Business Information or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, is not placed on the internet and will be publicly available only in hard copy form. Publicly available docket materials are available either electronically through <http://www.regulations.gov> or in hard copy at the site information repositories. Locations, contacts, phone numbers and viewing hours are:

U.S. Environmental Protection Agency, Region 9, Regional Records Center, 75 Hawthorne Street, Room 3110, San Francisco, CA 94105, (415) 947-8717, Monday-Thursday: 9:00 a.m.-12:00 p.m., 1:00 p.m.-4:00 p.m., Or:

Sonoma County Library, Headquarters, 6135 State Farm Drive, Rohnert Park, California, (707) 545-0831, *Call for hours of operation*

FOR FURTHER INFORMATION CONTACT:

Olivia Trombadore, Remedial Project Manager, U.S. Environmental Protection Agency, Region 9, SFD-9-2, 75 Hawthorne St., San Francisco, CA 94105, (415) 972-3973, trombadore.olivia@epa.gov.

SUPPLEMENTARY INFORMATION: The site to be deleted from the NPL is: MGM Brakes Superfund Site, Cloverdale, Sonoma County, California. A Notice of Intent to Delete for this Site was published in the **Federal Register** (84 FR 28259) on June 18, 2019.

The closing date for comments on the Notice of Intent to Delete was July 18, 2019. No public comments were received, and EPA still believes that this deletion action is appropriate.