

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–23–13 Airbus SAS: Amendment 39–19807; Docket No. FAA–2019–0443; Product Identifier 2019–NM–056–AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A320–251N and A321–253N airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019–0068, dated March 27, 2019 (“EASA AD 2019–0068”).

(d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

(e) Reason

This AD was prompted by reports of cracks on the pylon block seals during the final assembly line. The FAA is issuing this AD to address cracks on pylon block seals, which could reduce the firewall integrity between the pylon and the nacelle.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0068.

(h) Exceptions to EASA AD 2019–0068

(1) Where EASA AD 2019–0068 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2019–0068 specifies credit for actions “accomplished before the effective date of this AD in accordance with the instructions of the applicable Airplane Maintenance Manual,” this AD provides credit for actions “accomplished before the

effective date of this AD in accordance with the instructions of an FAA-approved maintenance or inspection program.”

(3) The “Remarks” section of EASA AD 2019–0068 does not apply to this AD.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2019–0068 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3223.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019–0068, dated March 27, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019–0068, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: ADs@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the

FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0443.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 21, 2019.

Dorr Anderson,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–26703 Filed 12–11–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0973; Product Identifier 2019–NM–187–AD; Amendment 39–19811; AD 2019–23–17]

RIN 2120–AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 900EX and Model FALCON 2000EX airplanes. This AD was prompted by reports of iced angle-of-attack (AoA) probes after take-off, with associated misleading airspeed indication and/or misleading stall warning. This AD requires revising the existing airplane flight manual (AFM) to provide the flightcrew with updated procedures related to manually activating heating of the AoA probes during line up, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective December 27, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 27, 2019.

We must receive comments on this AD by January 27, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• *Federal eRulemaking Portal*: Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

• *Fax*: 202-493-2251.

• *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0973.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0973; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0273, dated November 4, 2019 (“EASA AD 2019-0273”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Model FALCON 900EX and FALCON 2000EX airplanes.

This AD was prompted by reports of iced AoA probes after take-off, with associated misleading airspeed indication and/or misleading stall warning. A slow or late positioning of thrust levers into the take-off position in certain conditions can lead to probes being heated too late during the take-off run, which increases the risk of icing on probes after take-off. The FAA is issuing this AD to address this condition, which could lead to blocked AoA probes, possibly resulting in reduced control of the airplane. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019-0273 describes procedures for revising the existing AFM to provide the flightcrew with updated normal procedures related to manually activating AoA probe heating during line up. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to a bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the agency evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2019-0273 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019-0273 will be incorporated by reference in the FAA final rule. This

AD, therefore, requires compliance with EASA AD 2019-0273 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2019-0273 that is required for compliance with EASA AD 2019-0273 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0973 after the FAA final rule is published.

FAA’s Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because these airplanes are subject to reduced efficiency of the AoA protections that may result in iced AoA probes after take-off, with associated misleading airspeed indication and/or misleading stall warning. A slow or late positioning of thrust levers into the take-off position in certain conditions can lead to probes being heated too late during the take-off run, which increases the risk of icing on probes after take-off. This condition could result in blocked AoA probes, which could possibly result in reduced control of the airplane. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reasons stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and the FAA did not precede it by notice and opportunity for public comment. The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0973; Product Identifier 2019-NM-187-AD” at the beginning of your comments. The FAA specifically invites comments on the overall

regulatory, economic, environmental, and energy aspects of this AD. The FAA will consider all comments received by the closing date and may amend this AD based on those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report

summarizing each substantive verbal contact received about this AD.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good

cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 146 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$12,410

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–23–17 Dassault Aviation:
Amendment 39–19811; Docket No. FAA–2019–0973; Product Identifier 2019–NM–187–AD.

(a) Effective Date

This AD becomes effective December 27, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 900EX and Model FALCON 2000EX airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019–0273, dated November 4, 2019 (“EASA AD 2019–0273”).

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of iced angle-of-attack (AoA) probes after take-off, with associated misleading airspeed indication and/or misleading stall warning. A slow or late positioning of thrust levers into the take-off position in certain conditions can lead to probes being heated too late during the take-off run, which increases the risk of icing on probes after take-off. The FAA is issuing this AD to address this condition, which could result in blocked AoA probes, possibly resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0273.

(h) Exceptions to EASA AD 2019–0273

- (1) Where EASA AD 2019–0273 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The “Remarks” section of EASA AD 2019–0273 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/ certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0273, dated November 4, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0273, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0973.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 21, 2019.

Dorr Anderson,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-26704 Filed 12-11-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-1024; Product Identifier 2017-NM-065-AD; Amendment 39-19746; AD 2019-19-10]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all The Boeing Company Model 737-300, -400, -500, -600, -700, -700C, -800, -900, and -900ER series airplanes; Model 757 series airplanes; Model 767 series airplanes; Model 777 series airplanes; and Model 787-8 and 787-9 airplanes. This AD was prompted by reports of fuel crossfeed valves failing to open when activated during flight. This AD requires, for certain airplanes, revising the existing airplane flight manual (AFM); and for certain other airplanes, revising the existing minimum equipment list (MEL) to do an operational check of the fuel crossfeed valve prior to each extended operations (ETOPS) flight if one fuel crossfeed valve (or the fuel balancing system on Model 787 airplanes) is inoperative. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 16, 2020.

ADDRESSES:

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1024; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Jon Regimbal, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3557; email: Jon.Regimbal@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 737-300, -400, -500, -600, -700, -700C, -800, -900, and -900ER series airplanes; Model 757 series airplanes; Model 767 series airplanes; Model 777 series airplanes; and Model 787-8 and 787-9 airplanes. The NPRM published in the **Federal Register** on December 5, 2017 (82 FR 57383). The NPRM was prompted by reports of fuel crossfeed valves failing to open when activated during flight. The NPRM proposed to require, for certain airplanes, revising the existing AFM; and for certain other airplanes, revising the existing MEL to do an operational check of the fuel crossfeed valve prior to each ETOPS flight if one fuel crossfeed valve (or the fuel balancing system on Model 787 airplanes) is inoperative.

The FAA is issuing this AD to prevent an airplane from being dispatched on an ETOPS flight with a single fuel crossfeed valve (due to design or due to MEL dispatch of a dual crossfeed valve equipped airplane with one crossfeed valve inoperative) that cannot be opened or a fuel balancing system that cannot properly operate when activated. This condition could cause the fuel in the main tank associated with a failed engine to be unavailable to the remaining operative engine, potentially resulting in a forced off-airport landing due to exhaustion of the remaining usable fuel and consequent loss of all engine thrust.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Withdraw the NPRM

United Airlines (UAL) and Delta Air Lines (DAL) asked that the NPRM be withdrawn until corrective action is proposed with an adequate level of safety.

UAL stated that the FAA processes leading to issuing the NPRM did not include certain expected elements (*e.g.*, risk analysis, adequate cost analysis [which the FAA addresses in the "Request to Increase Cost Estimate" comment], and consideration for airplanes equipped with aircraft health monitoring (AHM) [which the FAA addresses in the "Request to Exclude Airplanes with AHM" comment]). UAL added that it is not aware of an FAA risk