

Proposed Rules

Federal Register

Vol. 84, No. 240

Friday, December 13, 2019

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF ENERGY

10 CFR Part 430

[EERE-2017-BT-TP-0003]

RIN 1904-AD80

Energy Conservation Program: Energy Conservation Standards for Consumer Refrigerators, Refrigerator-Freezers, and Freezers

AGENCY: Office of Energy Efficiency and Renewable Energy, Department of Energy.

ACTION: Notice of extension of public comment period.

SUMMARY: On November 15, 2019, the U.S. Department of Energy (“DOE”) published a request for information (“RFI”) to solicit information from the public to help DOE determine whether amended standards for consumer refrigerators, refrigerator-freezers, and freezers would result in a significant amount of additional energy savings and whether those standards would be technologically feasible and economically justified. The November 15, 2019 RFI also stated that public comments will be accepted until December 30, 2019. On November 21, 2019, the DOE received a request from the Association of Home Appliance Manufacturers (AHAM) to extend the public comment period by 60 days. DOE has reviewed this request and will be granting a 45 day extension of the public comment period to allow public comments to be submitted until February 13, 2020.

DATES: The comment period for the RFI published on November 15, 2019 (84 FR 62470), is extended. DOE will accept comments, data, and information regarding this request for information received no later than February 13, 2020.

ADDRESSES: Interested persons are encouraged to submit comments using the Federal eRulemaking Portal at <http://www.regulations.gov>. Follow the instructions for submitting comments.

Alternatively, interested persons may submit comments, identified by docket number EERE-2017-BT-STD-0003, by any of the following methods:

1. *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

2. *Email:* ConsumerRefrigFreezer2017STD0003@ee.doe.gov. Include the docket number EERE-2017-BT-STD-0003 in the subject line of the message.

3. *Postal Mail:* Appliance and Equipment Standards Program, U.S. Department of Energy, Building Technologies Office, Mailstop EE-5B, 1000 Independence Avenue SW, Washington, DC 20585-0121. Telephone: (202) 287-1445. If possible, please submit all items on a compact disc (“CD”), in which case it is not necessary to include printed copies.

4. *Hand Delivery/Courier:* Appliance and Equipment Standards Program, U.S. Department of Energy, Building Technologies Office, 950 L’Enfant Plaza SW, 6th Floor, Washington, DC 20024. Telephone: (202) 287-1445. If possible, please submit all items on a CD, in which case it is not necessary to include printed copies.

No telefacsimilies (faxes) will be accepted. For detailed instructions on submitting comments and additional information on this process, see section III of this document.

Docket: The docket for this activity, which includes **Federal Register** notices, comments, and other supporting documents/materials, is available for review at <http://www.regulations.gov>. All documents in the docket are listed in the <http://www.regulations.gov> index. However, some documents listed in the index, such as those containing information that is exempt from public disclosure, may not be publicly available.

The docket web page can be found at <http://www.regulations.gov/#/docketDetail;D=EERE-2017-BT-TP-0003>. The docket web page contains instructions on how to access all documents, including public comments in the docket.

FOR FURTHER INFORMATION CONTACT:

Dr. Stephanie Johnson, U.S. Department of Energy, Office of Energy Efficiency and Renewable Energy, Building Technologies Office, EE-5B, 1000 Independence Avenue SW, Washington, DC 20585-0121. Telephone: (202) 287-1943. Email:

ApplianceStandardsQuestions@ee.doe.gov.

Mr. Pete Cochran, U.S. Department of Energy, Office of the General Counsel, GC-33, 1000 Independence Avenue SW, Washington, DC 20585-0121. Telephone: (202) 586-9496. Email: Peter.Cochran@hq.doe.gov.

For further information on how to submit a comment, review other public comments and the docket, contact the Appliance and Equipment Standards Program staff at (202) 287-1445 or by email: ApplianceStandardsQuestions@ee.doe.gov.

Signed in Washington, DC, on December 3, 2019.

Alexander N. Fitzsimmons,

Acting Deputy Assistant Secretary for Energy Efficiency, Energy Efficiency and Renewable Energy.

[FR Doc. 2019-26909 Filed 12-12-19; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0974; Product Identifier 2019-NM-155-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2017-15-01, which applies to certain The Boeing Company Model 777 airplanes. AD 2017-15-01 requires replacing the existing mode control panel (MCP) with a new MCP having a different part number. Since we issued AD 2017-15-01, the FAA has determined that the affected parts may be installed on airplanes outside of the original applicability of AD 2017-15-01. This proposed AD would retain the requirements of AD 2017-15-01, expand the applicability to include those other airplanes, and add a new requirement for certain airplanes to identify and replace the affected parts. The FAA is proposing this AD to

address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 27, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0974.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0974; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3539; email: frank.carreras@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or

arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0974; Product Identifier 2019-NM-155-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Discussion

The FAA issued AD 2017-15-01, Amendment 39-18961 (82 FR 33782, July 21, 2017) (“AD 2017-15-01”), for certain The Boeing Company Model 777 airplanes. AD 2017-15-01 requires replacing the existing MCP with a new MCP having a different part number. AD 2017-15-01 resulted from reports of uncommanded altitude display changes in the MCP altitude window. The FAA issued AD 2017-15-01 to address uncommanded changes to the MCP selected altitude; such uncommanded changes could result in incorrect spatial separation between airplanes, midair collision, or controlled flight into terrain.

Actions Since AD 2017-15-01 Was Issued

Since AD 2017-15-01 was issued, it has been determined that the affected parts may be installed as rotatable spares on airplanes outside of the applicability of AD 2017-15-01, thereby subjecting those airplanes to the unsafe condition. Therefore, the applicability in this proposed AD has been expanded to include all The Boeing Company Model 777 airplanes. In addition, the FAA has determined that the installation of later-approved parts is acceptable for the replacement that would be required by this proposed AD.

Related Service Information Under 1 CFR Part 51

This proposed AD would require Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016, which the Director of the Federal Register approved for incorporation by reference as of August 25, 2017 (82 FR 33782, July 21, 2017). This service information is reasonably available

because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

The FAA is proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would retain all of the requirements of AD 2017-15-01, and would expand the applicability to include all The Boeing Company Model 777 airplanes. This proposed AD would also require an inspection or records check to identify the part number of the affected parts, and for airplanes with affected parts, accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the Service Information.” For information on the procedures, see this service information at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0974.

Differences Between This Proposed AD and the Service Information

The effectivity of Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016, is limited to certain The Boeing Company Model 777 airplanes. However, the applicability of this proposed AD includes all The Boeing Company Model 777 airplanes. Because the affected parts are rotatable parts, the FAA has determined that these parts could later be installed on airplanes that were initially delivered with acceptable parts, thereby subjecting those airplanes to the unsafe condition. This difference has been coordinated with Boeing.

Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016, limits the replacement part to an MCP having part number S241W001-262. This proposed AD would allow the installation of later-approved parts for the replacement, provided those later-approved parts meet certain conditions.

Costs of Compliance

The FAA estimates that this proposed AD affects 231 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement (retained actions from AD 2017-15-01).	2 work-hours × \$85 per hour = \$170.	Up to \$5,800 *	Up to \$5,970 *	Up to \$1,379,070.*
Inspection/records check (new proposed action) (up to 28 airplanes).	1 work-hour × \$85 per hour = \$85.	\$0	\$85	Up to \$2,380.

* Since the FAA has received no definitive data regarding the cost of a new MCP, the FAA has provided costs for the upgrade (modified part) only.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA has determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2017–15–01, Amendment 39–18961 (82 FR 33782, July 21, 2017), and adding the following new AD:

The Boeing Company: Docket No. FAA–2019–0974; Product Identifier 2019–NM–155–AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by January 27, 2020.

(b) Affected ADs

This AD replaces AD 2017–15–01, Amendment 39–18961 (82 FR 33782, July 21, 2017) (“AD 2017–15–01”).

(c) Applicability

This AD applies to all The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Unsafe Condition

This AD was prompted by reports of uncommanded altitude display changes in the mode control panel (MCP) altitude window. The FAA is issuing this AD to address uncommanded changes to the MCP selected altitude; such uncommanded

changes could result in incorrect spatial separation between airplanes, midair collision, or controlled flight into terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) New Definitions

(1) For the purposes of this AD, an affected part is an MCP having part number S241W001–201, S241W001–202, S241W001–251, S241W001–252, or S241W001–261.

(2) For the purposes of this AD, later-approved parts are only those parts that are approved as a replacement for the applicable part identified in Boeing Special Attention Service Bulletin 777–22–0034, dated March 3, 2016; and are approved as part of the type design by the FAA or The Boeing Company Organization Designation Authorization (ODA) after March 3, 2016 (the publication date of Boeing Special Attention Service Bulletin 777–22–0034, dated March 3, 2016).

(h) Retained Replacement of MCP With Revised Compliance Language

This paragraph restates the requirements of AD 2017–15–01, with revised compliance language. For airplanes identified in Boeing Special Attention Service Bulletin 777–22–0034, dated March 3, 2016, within 60 months after August 25, 2017, (the effective date of AD 2017–15–01): Do the actions specified in paragraph (h)(1) or (2) of this AD.

(1) Replace the existing MCP part with an MCP having part number S241W001–262, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777–22–0034, dated March 3, 2016.

(2) Install a later-approved part as defined in paragraph (g)(2) of this AD.

(i) New MCP Identification and Replacement

For airplanes not identified in paragraph (h) of this AD with an original airworthiness certificate or original export certificate of airworthiness issued on or before the effective date of this AD, do the actions specified in paragraphs (i)(1) and (2) of this AD.

(1) Within 60 months after the effective date of this AD, perform a general visual inspection of the MCP to determine the MCP part number. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the MCP can be conclusively determined from that review.

(2) If the MCP is an affected part, within 60 months after the effective date of this AD:

Do the actions specified in paragraph (i)(2)(i) or (ii) of this AD.

(i) Replace the existing MCP with an MCP having part number S241W001-262, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016.

(ii) Install a later-approved part as defined in paragraph (g)(2) of this AD.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install an MCP having part number S241W001-201, S241W001-202, S241W001-251, S241W001-252, or S241W001-261, on any airplane.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company ODA that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2017-15-01 are approved as AMOCs for the corresponding provisions of this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(5)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA,

Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3539; email: frank.carreras@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on December 4, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-26643 Filed 12-12-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0979; Product Identifier 2019-NM-182-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A350-941 and -1041 airplanes. This proposed AD was prompted by a report of incorrectly engaged lock washer tabs of the main landing gear (MLG) forward pintle bearing (FPB) at the forward face of the trunnion block. This proposed AD would require detailed inspections of the left-hand (LH) and right-hand (RH) side MLG FPB nuts and lock washer tabs, and depending on findings, accomplishment of repetitive detailed inspections or corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 27, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 1000; email: ADS@easa.europa.eu; internet: www.easa.europa.eu. You may find this

IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0979.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0979; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3218.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0979; Product Identifier 2019-NM-182-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic,