

# Rules and Regulations

Federal Register

Vol. 85, No. 61

Monday, March 30, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0726; Product Identifier 2019-NM-102-AD; Amendment 39-19857; AD 2020-04-20]

RIN 2120-AA64

#### Airworthiness Directives; De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain De Havilland Aircraft of Canada Limited Model DHC-8-400 series airplanes. This AD was prompted by reports of wear on fuel couplings, bonding springs, and sleeves as well as fuel tube end ferrules and fuel component end ferrules. This AD requires repetitive inspections of certain parts for discrepancies that meet specified criteria, and replacement as necessary; repetitive inspections of certain parts for damage and wear, and rework of parts; and electrical bonding checks of certain couplings. This AD also requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. For certain airplanes, this AD allows a modification that would terminate the repetitive inspections. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 4, 2020.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of May 4, 2020.

**ADDRESSES:** For service information identified in this final rule, contact De

Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd@dehavilland.com](mailto:thd@dehavilland.com); internet <https://dehavilland.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0726.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0726; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7366; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2017-04R2, dated September 25, 2018 (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain De Havilland Aircraft of Canada Limited Model DHC-8-400 series airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0726.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR

part 39 by adding an AD that would apply to certain De Havilland Aircraft of Canada Limited Model DHC-8-400 series airplanes. The NPRM published in the **Federal Register** on October 30, 2019 (84 FR 58066). The NPRM was prompted by reports of wear on fuel couplings, bonding springs, and sleeves as well as fuel tube end ferrules and fuel component end ferrules. The NPRM proposed to require repetitive inspections of certain parts for discrepancies that meet specified criteria, and replacement as necessary; repetitive inspections of certain parts for damage and wear, and rework of parts; and electrical bonding checks of certain couplings. The NPRM also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. For certain airplanes, the NPRM proposed to allow a modification that would terminate the repetitive inspections. The FAA is issuing this AD to address wear on fuel couplings, bonding springs, and sleeves as well as fuel tube end ferrules and fuel component end ferrules, which could reduce the integrity of the electrical bonding paths through the fuel line and components, and ultimately lead to fuel tank ignition in the event of a lightning strike. See the MCAI for additional background information.

#### Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA’s response to the comment.

#### Request To Refer to Different Temporary Revisions (TRs)

Horizon Air requested that paragraph (k) of the proposed AD be revised to refer to TR ALI-0192 and TR ALI-0193. The commenter suggested that the proposed AD contains typographical errors in referring to TR ALI-00AS and TR ALI-00AT.

The FAA agrees to clarify. Paragraph (k) of the proposed AD requires incorporating “the information specified in Q400 Dash 8 (Bombardier) Temporary Revision ALI-00AS, dated April 24, 2018; and Q400 Dash 8 (Bombardier) Temporary Revision ALI-00AT, dated April 24, 2018.” TCCA notified the FAA that TR ALI-00AS and TR ALI-00AT are temporary

placeholder identifiers for TR ALI-0192 and TR ALI-0193. These temporary placeholder identifiers are used until the finalized TRs are provided new numerical identifiers. The FAA has confirmed that the information specified in these TRs is the same as the information specified in the TRs mentioned by the commenter. For these reasons, this AD has been revised to specify TR ALI-0192 and TR ALI-0193.

**Explanation of Change to Introductory Text to Paragraph (h) of This AD**

We have revised the introductory text to paragraph (h) of this AD to clarify that the actions apply to the same airplanes as those identified in the introductory text to paragraph (g) of this AD.

**Conclusion**

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and

- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

**Related Service Information Under 1 CFR Part 51**

Bombardier has issued Service Bulletin 84-28-20, Revision D, dated November 23, 2018. This service information describes procedures for repetitive detailed inspections of the clamshell coupling bonding wires, fuel couplings, and associated sleeves for discrepancies (wear and damage, including discoloration, worn coating, scuffing and grooves) that meet specified criteria, and replacement. This service information also describes procedures for repetitive detailed inspections for damage and wear of the fuel tube end ferrules, fuel component end ferrules, and ferrule O-ring flanges, and rework of parts.

Bombardier has also issued Service Bulletin 84-28-21, Revision C, dated July 13, 2018. This service information describes procedures for a detailed inspection for damage and wear of the fuel tube end ferrules, fuel component end ferrules, and ferrule O-ring flanges;

rework (repair, replacement, or blending, as applicable) of parts; and a retrofit (structural rework) of the fuel couplings, isolators, and structural provisions.

Bombardier has also issued Service Bulletin 84-28-26, Revision A, dated November 29, 2018. This service information describes procedures for electrical bonding checks of all threaded couplings on the inboard vent lines in the left and right wings.

Bombardier has also issued Q400 Dash 8 (Bombardier) Temporary Revision ALI-0192, dated April 24, 2018; and Q400 Dash 8 (Bombardier) Temporary Revision ALI-0193, dated April 24, 2018. This service information describes airworthiness limitations for fuel tank systems. These documents are distinct since they describe different airworthiness limitations.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

The FAA estimates that this AD affects 52 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS \***

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
268 work-hours × \$85 per hour = \$22,780 .....	\$0	\$22,780	\$1,184,560

\* Table does not include estimated costs for revising the maintenance or inspection program.

The FAA has determined that revising the maintenance or inspection program takes an average of 90 work-hours per operator, although this number may vary from operator to operator. In the past, the FAA has estimated that this

action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-

airplane estimate. Therefore, the FAA estimates the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

**ESTIMATED COSTS FOR OPTIONAL ACTIONS**

Labor cost	Parts cost	Cost per product
525 work-hours × \$85 per hour = \$44,625 .....	\$20,906	\$65,531

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required or optional actions. The FAA has no way of

determining the number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
174 work-hours × \$85 per hour = \$14,790 .....	\$16,767	\$31,557

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2020–04–20 De Havilland Aircraft of Canada Limited (Type Certificate previously held by Bombardier, Inc.):** Amendment 39–19857; Docket No. FAA–2019–0726; Product Identifier 2019–NM–102–AD.

#### (a) Effective Date

This AD is effective May 4, 2020.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to De Havilland Aircraft of Canada Limited Model DHC–8–400, –401, and –402 airplanes, certificated in any category, manufacturer serial numbers 4001, 4003, and subsequent.

#### (d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

#### (e) Reason

This AD was prompted by reports of wear on fuel couplings, bonding springs, and sleeves as well as fuel tube end ferrules and fuel component end ferrules. The FAA is issuing this AD to address such wear, which could reduce the integrity of the electrical bonding paths through the fuel line and components, and ultimately lead to fuel tank ignition in the event of a lightning strike.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Initial Inspection Compliance Times

For airplanes having serial numbers 4001 and 4003 through 4575 inclusive that, as of the effective date of this AD, have not done the actions specified in Bombardier Service Bulletin 84–28–21: At the applicable times specified in paragraph (g)(1) or (2) of this AD, do the actions specified in paragraphs (h)(1) and (2) of this AD.

(1) For all airplanes except those identified in paragraph (g)(2) of this AD: Within 6,000 flight hours or 36 months, whichever occurs first after the effective date of this AD.

(2) For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or after the effective date of this AD: Within 6,000 flight hours or 36 months, whichever occurs first after the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

#### (h) Repetitive Inspections and Corrective Actions

For airplanes having serial numbers 4001 and 4003 through 4575 inclusive that, as of the effective date of this AD, have not done the actions specified in Bombardier Service Bulletin 84–28–21: At the applicable times specified in paragraph (g)(1) or (2) of this AD, do the actions specified in paragraphs (h)(1) and (2) of this AD. Repeat the actions thereafter at intervals not to exceed 6,000 flight hours or 36 months, whichever occurs first.

(1) Do a detailed inspection of the clamshell coupling bonding wires, fuel

couplings, and associated sleeves for discrepancies that meet specified criteria, as identified in, and in accordance with paragraph 3.B., "Procedure," of the Accomplishment Instructions of Bombardier Service Bulletin 84–28–20, Revision D, dated November 23, 2018. If any conditions are found meeting the criteria specified in Bombardier Service Bulletin 84–28–20, Revision D, dated November 23, 2018, before further flight, replace affected parts with new couplings and sleeves of the same part number, in accordance with paragraph 3.B., "Procedure," of the Accomplishment Instructions of Bombardier Service Bulletin 84–28–20, Revision D, dated November 23, 2018.

(2) Do a detailed inspection of the fuel tube end ferrules, fuel component end ferrules, and ferrule O-ring flanges for damage and wear, and rework (repair, replace, or blend, as applicable) the parts, in accordance with paragraph 3.B., "Procedure," of the Accomplishment Instructions of Bombardier Service Bulletin 84–28–20, Revision D, dated November 23, 2018.

#### (i) Optional Terminating Action for Repetitive Inspections

For airplanes having serial numbers 4001 and 4003 through 4575 inclusive: Doing a detailed inspection of the fuel tube end ferrules, fuel component end ferrules, and ferrule O-ring flanges for damage and wear, and reworking (repair, replace, or blend, as applicable) the parts; and doing a retrofit (structural rework) of the fuel couplings, isolators, and structural provisions, in accordance with paragraph 3.B., "Procedure," of the Accomplishment Instructions of Bombardier Service Bulletin 84–28–21, Revision C, dated July 13, 2018, terminates the inspections specified in paragraphs (h)(1) and (2) of this AD.

#### (j) Electrical Bonding Checks/Detailed Inspection

For airplanes having serial numbers 4001, 4003 through 4489 inclusive, and 4491 through 4575 inclusive that, as of the effective date of this AD, have done the actions specified in Bombardier Service Bulletin 84–28–21, Revision A, dated September 29, 2017; and airplanes having serial numbers 4576 through 4581 inclusive: Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first, do the actions specified in paragraph (j)(1) or (2) of this AD.

(1) Accomplish electrical bonding checks of all threaded couplings on the inboard vent lines in the left and right wings, in accordance with paragraph 3.B., "Procedure," of the Accomplishment Instructions of Bombardier Service Bulletin 84–28–26, Revision A, dated November 29, 2018.

(2) Do a detailed inspection of the fuel tube end ferrules, fuel component end ferrules, and ferrule O-ring flanges for damage and wear, and rework (repair, replace, or blend, as applicable) the parts; and a retrofit (structural rework) of the fuel couplings, isolators, and structural provisions in accordance with paragraph 3.B., "Procedure," of the Accomplishment

Instructions of Bombardier Service Bulletin 84–28–21, Revision C, dated July 13, 2018.

**(k) Maintenance or Inspection Program Revision**

Within 30 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Q400 Dash 8 (Bombardier) Temporary Revision ALI–0192, dated April 24, 2018; and Q400 Dash 8 (Bombardier) Temporary Revision ALI–0193, dated April 24, 2018. Except as specified in paragraph (l) of this AD, the initial compliance time for doing the tasks in Q400 Dash 8 (Bombardier) Temporary Revision ALI–0192, dated April 24, 2018, is at the time specified in Q400 Dash 8 (Bombardier) Temporary Revision ALI–0192, dated April 24, 2018, or within 30 days after the effective date of this AD, whichever occurs later.

**(l) Initial Compliance Time for Task 284000–419**

The initial compliance time for task 284000–419 is at the time specified in paragraph (l)(1) or (2) of this AD, as applicable, or within 30 days after the effective date of this AD, whichever occurs later.

(1) For airplanes having serial numbers 4001 and 4003 through 4575, inclusive: Within 18,000 flight hours or 108 months, whichever occurs first, after the earliest date of embodiment of Bombardier Service Bulletin 84–28–21 on the airplane.

(2) For airplanes having serial numbers 4576 and subsequent: Within 18,000 flight hours or 108 months, whichever occurs first, from the date of issuance of the original airworthiness certificate or original export certificate of airworthiness.

**(m) No Alternative Actions, Intervals, or Critical Design Configuration Control Limitations (CDCCLs)**

After the existing maintenance or inspection program has been revised as required by paragraph (k) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (p)(1) of this AD.

**(n) No Reporting Requirement**

Although Bombardier Service Bulletin 84–28–20, Revision D, dated November 23, 2018, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(o) Credit for Previous Actions**

(1) This paragraph provides credit for the actions required by paragraphs (h)(1) and (2) of this AD, if those actions were performed before the effective date of this AD using the service information specified in paragraph (o)(1)(i), (ii), or (iii) of this AD.

(i) Bombardier Service Bulletin 84–28–20, Revision A, dated December 14, 2016.

(ii) Bombardier Service Bulletin 84–28–20, Revision B, dated February 13, 2017.

(iii) Bombardier Service Bulletin 84–28–20, Revision C, dated April 28, 2017.

(2) For the airplane having serial number 4164, this paragraph provides credit for the initial inspections required by paragraphs (h)(1) and (2) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84–28–20, dated September 30, 2016.

(3) This paragraph provides credit for the actions specified in paragraph (i) of this AD

if those actions were performed before the effective date of this AD using the service information specified in paragraph (o)(3)(i), (ii), or (iii) of this AD.

(i) Bombardier Service Bulletin 84–28–21, dated August 31, 2017.

(ii) Bombardier Service Bulletin 84–28–21, Revision A, dated September 29, 2017.

(iii) Bombardier Service Bulletin 84–28–21, Revision B, dated June 8, 2018.

(4) This paragraph provides credit for the actions required by paragraph (j)(1) of this AD if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84–28–26, dated August 14, 2018.

(5) This paragraph provides credit for the actions required by paragraph (j)(2) of this AD if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84–28–21, Revision B, dated June 8, 2018.

(6) For airplanes having serial numbers 4001, 4003 through 4489 inclusive, and 4491 through 4575 inclusive, and that are post Bombardier Service Bulletin 84–28–21, Revision A, dated September 29, 2017: This paragraph provides credit for the actions required by paragraph (j) of this AD if those actions were performed prior to the effective date of this AD using the service information specified in paragraph (o)(6)(i) or (ii) of this AD.

(i) Bombardier Modification Summary Package (ModSum) IS4Q2800032, dated February 1, 2018.

(ii) Any airworthiness limitation change request (ACR) specified in figure 1 to paragraph (o)(6)(ii) of this AD.

**BILLING CODE 4910–13–P**

Figure 1 to paragraph (o)(6)(ii) – ACRs

ACR Number	Dated
400-072	January 24, 2018
400-073	January 23, 2018
400-074	January 24, 2018
400-077	February 27, 2018
400-078	March 21, 2018
400-079	April 18, 2018
400-080	April 30, 2018
400-081	May 4, 2018
400-082	May 4, 2018
400-083	June 4, 2018
400-084	May 18, 2018

**BILLING CODE 4910-13-C****(p) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or De Havilland Aircraft of Canada Limited's TCCA Design Approval Organization (DAO). If approved by the DAO,

the approval must include the DAO-authorized signature.

**(q) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2017-04R2, dated September 25, 2018, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0726.

(2) For more information about this AD, contact Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7366; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (r)(3) and (4) of this AD.

**(r) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 84-28-20, Revision D, dated November 23, 2018.

(ii) Bombardier Service Bulletin 84-28-21, Revision C, dated July 13, 2018.

(iii) Bombardier Service Bulletin 84-28-26, Revision A, dated November 29, 2018.

(iv) Bombardier Q400 Dash 8 (Bombardier) Temporary Revision ALI-0192, dated April 24, 2018.

(v) Q400 Dash 8 (Bombardier) Temporary Revision ALI-0193, dated April 24, 2018.

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd@dehavilland.com](mailto:thd@dehavilland.com); internet <https://dehavilland.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 1, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.*

[FR Doc. 2020-06505 Filed 3-27-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0865; Product Identifier 2019-NM-158-AD; Amendment 39-19854; AD 2020-04-17]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A350-941 and -1041 airplanes. This AD was prompted by reports of passenger door girt bar fitting assembly safety hooks being stuck in the upward position. This AD requires repetitive detailed inspections of girt bar fitting assemblies, repetitive greasing of girt bar fitting assembly bushes, and, depending on findings, accomplishment of applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 4, 2020. The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 4, 2020.

**ADDRESSES:** For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0865.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0865; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218; email [kathleen.arrigotti@faa.gov](mailto:kathleen.arrigotti@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0207, dated August 22, 2019 (“EASA AD 2019-0207”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A350-941 and -1041 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A350-941 and -1041 airplanes. The NPRM published in the **Federal Register** on November 15, 2019 (84 FR 62485). The NPRM was prompted by reports of passenger door girt bar fitting assembly safety hooks being stuck in the upward position. The NPRM proposed to require repetitive detailed inspections of girt bar fitting assemblies, repetitive greasing of girt bar fitting assembly bushes, and, depending on findings, accomplishment of applicable corrective actions.

The FAA is issuing this AD to address passenger door girt bar fitting assembly safety hooks being stuck in the upward position, which could lead to girt bar disengagement from the girt bar fitting assembly and consequent failure of the passenger door slide deployment during an emergency, possibly preventing safe evacuation of the airplane. See the MCAI for additional background information.

##### Comments

The FAA gave the public the opportunity to participate in developing

this final rule. The following presents the comments received on the NPRM and the FAA’s response to each comment.

##### Support for the NPRM

The Air Line Pilots Association, International (ALPA) indicated its support for the NPRM.

##### Request To Remove or Revise Reporting Requirement

Delta Air Lines (Delta) requested that the proposed AD be revised to either not require reporting or to require reporting only in the case of discrepant findings. Delta noted that only 5 discrepant safety hooks were found during its inspection of 1,408 fittings. Delta added that the final fix will include a retrofit of the girt bar fittings, which should occur regardless of the number of reported failures.

The FAA disagrees with the commenter’s request. Reporting is necessary for the girt bar fitting assembly manufacturer to determine the extent of the discrepancies and to ascertain any necessary follow-on actions. The FAA has not changed this AD in this regard.

##### Request To Revise Reporting Compliance Time

Delta requested that paragraph (h)(3)(i) of the proposed AD be reworded to state that inspection report must be submitted within 90 days after the end of the maintenance visit/check during which the inspection was performed, rather than within 90 days after the inspection. Delta noted that maintenance personnel often do not report findings to engineering until closure of the maintenance visit/check, which usually happens several days or weeks after the inspection was actually performed. Delta suggested that the revised reporting time would remove restrictive time constraints while still meeting the intent of the proposed AD.

The FAA agrees with the commenter’s request for the reasons provided. The FAA has revised paragraph (h)(3)(i) of this AD to specify that a report of findings must be submitted within 90 days after the conclusion of the maintenance visit or check where the inspection was completed.

##### Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the change described previously and minor editorial changes. The FAA has determined that these minor changes: