

with its domestic and foreign affiliates, does not meet the 500-employee or other applicable PPP size standard is therefore ineligible for a PPP loan.

However, as an exercise of enforcement discretion due to reasonable borrower confusion based on SBA guidance (which was later resolved through a clarifying FAQ on May 5, 2020), SBA will not find any borrower that applied for a PPP loan prior to May 5, 2020 to be ineligible based on the borrower's exclusion of non-U.S. employees from the borrower's calculation of its employee headcount if the borrower (together with its affiliates)² had no more than 500 employees whose principal place of residence is in the United States. Such borrowers shall not be deemed to have made an inaccurate certification of eligibility solely on that basis. Under no circumstances may PPP funds be used to support non-U.S. workers or operations.

2. Additional Information

SBA may provide further guidance, if needed, through SBA notices that will be posted on SBA's website at www.sba.gov. Questions on the Paycheck Protection Program may be directed to the Lender Relations Specialist in the local SBA Field Office. The local SBA Field Office may be found at <https://www.sba.gov/tools/local-assistance/districtoffices>.

Compliance With Executive Orders 12866, 12988, 13132, 13563, and 13771, the Paperwork Reduction Act (44 U.S.C. Ch. 35), and the Regulatory Flexibility Act (5 U.S.C. 601–612)

Executive Orders 12866, 13563, and 13771

This interim final rule is economically significant for the purposes of Executive Orders 12866 and 13563, and is considered a major rule under the Congressional Review Act. SBA, however, is proceeding under the emergency provision at Executive Order 12866 Section 6(a)(3)(D) based on the need to move expeditiously to mitigate the current economic conditions arising

is disbursed, is assigned a North American Industry Classification System code beginning with 72; (2) any business concern operating as a franchise that is assigned a franchise identifier code by the Administration; and (3) any business concern that receives financial assistance from a company licensed under section 301 of the Small Business Investment Act of 1958 (15 U.S.C. 681). SBA also applies affiliation exceptions to certain categories of entities. 13 CFR 121.103(b).

²For purposes of this safe harbor, a borrower must include its affiliates to the extent required under the interim final rule on affiliates, 85 FR 20817 (April 15, 2020). SBA's affiliation exceptions in 13 CFR 121.103(b) apply to the PPP.

from the COVID-19 emergency. This rule's designation under Executive Order 13771 will be informed by public comment.

Executive Order 12988

SBA has drafted this rule, to the extent practicable, in accordance with the standards set forth in section 3(a) and 3(b)(2) of Executive Order 12988, to minimize litigation, eliminate ambiguity, and reduce burden. The rule has no preemptive or retroactive effect.

Executive Order 13132

SBA has determined that this rule will not have substantial direct effects on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various layers of government. Therefore, SBA has determined that this rule has no federalism implications warranting preparation of a federalism assessment.

Paperwork Reduction Act, 44 U.S.C. Chapter 35

SBA has determined that this rule will not impose new or modify existing recordkeeping or reporting requirements under the Paperwork Reduction Act.

Regulatory Flexibility Act (RFA)

The Regulatory Flexibility Act (RFA) generally requires that when an agency issues a proposed rule, or a final rule pursuant to section 553(b) of the APA or another law, the agency must prepare a regulatory flexibility analysis that meets the requirements of the RFA and publish such analysis in the **Federal Register**. 5 U.S.C. 603, 604. Specifically, the RFA normally requires agencies to describe the impact of a rulemaking on small entities by providing a regulatory impact analysis. Such analysis must address the consideration of regulatory options that would lessen the economic effect of the rule on small entities. The RFA defines a "small entity" as (1) a proprietary firm meeting the size standards of the Small Business Administration (SBA); (2) a nonprofit organization that is not dominant in its field; or (3) a small government jurisdiction with a population of less than 50,000. 5 U.S.C. 601(3)–(6). Except for such small government jurisdictions, neither State nor local governments are "small entities." Similarly, for purposes of the RFA, individual persons are not small entities. The requirement to conduct a regulatory impact analysis does not apply if the head of the agency "certifies that the rule will not, if promulgated, have a significant economic impact on a substantial number of small entities." 5 U.S.C.

605(b). The agency must, however, publish the certification in the **Federal Register** at the time of publication of the rule, "along with a statement providing the factual basis for such certification." If the agency head has not waived the requirements for a regulatory flexibility analysis in accordance with the RFA's waiver provision, and no other RFA exception applies, the agency must prepare the regulatory flexibility analysis and publish it in the **Federal Register** at the time of promulgation or, if the rule is promulgated in response to an emergency that makes timely compliance impracticable, within 180 days of publication of the final rule. 5 U.S.C. 604(a), 608(b). Rules that are exempt from notice and comment are also exempt from the RFA requirements, including conducting a regulatory flexibility analysis, when among other things the agency for good cause finds that notice and public procedure are impracticable, unnecessary, or contrary to the public interest. SBA Office of Advocacy Guide: How to Comply with the Regulatory Flexibility Act, Ch. 1, p. 9. Accordingly, SBA is not required to conduct a regulatory flexibility analysis.

Jovita Carranza,
Administrator.

[FR Doc. 2020-10967 Filed 5-19-20; 11:15 am]
BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0204; Project Identifier 2018-CE-042-AD; Amendment 39-21129; AD 2020-11-04]

RIN 2120-AA64

Airworthiness Directives; Learjet Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Learjet Inc. Model 60 airplanes. This AD was prompted by a report of a reverse thrust command accelerating the airplane instead of decelerating the airplane. The acceleration with reverse thrust commanded occurred when the thrust reverser doors were in the stowed position instead of the deployed position. This AD requires installing a thrust reverser (T/R) Voice Command Warning System (VCWS) to alert the crew of a T/R malfunction. The FAA is

issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 25, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 25, 2020.

ADDRESSES: For service information identified in this final rule, contact Learjet Inc., MS 53, P.O. Box 7707, Wichita, Kansas 67277-7707; telephone: (toll free) 1-866-538-1247; (514) 855-2999; internet: <https://my.businessaircraft.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0204.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0204; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

James Galstad, Aerospace Engineer, Wichita ACO Branch, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4135; fax: (316) 946-4107; email: james.galstad@faa.gov or Wichita-COS@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain serial-numbered Learjet Inc. Model 60 airplanes. The NPRM published in the **Federal Register** on May 13, 2019 (84 FR 20823). The NPRM was prompted by a report of a high-speed rejected takeoff involving a Learjet Model 60 airplane that occurred when all four main landing gear (MLG) tires blew out during the takeoff roll. The tires blew out due to internal heat damage consistent with under-inflation, overloading, or a combination of both.

Subsequently, damage from tires caused damage to various components, including the MLG squat switches, brake hydraulic tubes, wheel speed sensor wiring, and anti-skid components. In the event of squat switch wiring failures, thrust reverser operation can be adversely affected. During the subject accident, forward thrust occurred when the thrust reverser doors stowed due to the failure, and at the same time the crew was still commanding reverse thrust. Squat switch wiring can also be damaged by other external factors, such as bird strikes or deer strikes.

The FAA considers this AD to be the third of three related ADs that collectively address unsafe conditions that might result from damage to critical components on the landing gear or in the wheel well that affect the braking, spoiler, and thrust reverser systems. AD 2010-11-11, Amendment 39-16316 (75 FR 32255, June 8, 2010) was issued to prevent tire failure, and AD 2013-13-09, Amendment 39-17497 (78 FR 39574, July 2, 2013) was issued to prevent failure of the braking system or adverse operation of the spoiler and reverse thruster system due to external damage, particularly from tire failure, which could result in loss of control of the airplane.

The NPRM proposed to require installing a T/R VCWS to alert the crew of a T/R malfunction. The FAA is issuing this AD to mitigate failure of the engine thrust reverser system. The unsafe condition, if not addressed, could result in the airplane overrunning the runway or a runway excursion.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Support for the NPRM

The National Transportation Safety Board (NTSB) and Damian Palaich expressed support for the NPRM.

Request To Withdraw the NPRM

Charles Perrigoue requested that the NPRM be withdrawn. The commenter noted that modern aircraft designs have shifted away from a multitude of aural alarms and warnings and that most modern business jets and airline aircraft suppress alarms during critical phases of flight. The commenter stated there is no nexus between the proposed AD actions and the precipitating Learjet Model 60 accident, as the pilot correctly

recognized and reacted to the thrust reverser malfunction.

The FAA disagrees with the commenter's request. The design change required by paragraph (g) of this AD incorporates a direct aural voice command for a rapid effective response and design features to minimize faulty voice commands. The FAA's evaluation concludes that the installation of the T/R VCWS required by this AD will effectively mitigate the identified unsafe condition and prevent future scenarios similar to the September 19, 2008, accident involving a Learjet Model 60 airplane. The T/R VCWS is monitoring the thrust reversers and providing a voice command, when needed, which will enable a faster pilot response to decelerate the airplane. The FAA has not changed this AD in this regard.

Request To Incorporate a Solution That Is Not Reliant on Crew Action

An anonymous commenter stated the proposed AD does not eliminate the root cause of the unsafe condition. The commenter further suggested that relying on pilot response to address a catastrophic hazard is not always valid. The commenter stated that a design solution is available that would eliminate the uncontrollable high thrust condition. The commenter asserted that the FAA's proposed AD contradicts its guidance in draft advisory circular (AC) AC 25.901-2X. The acceptable design solution suggested by the commenter is a similar installation on another aircraft identified in the NTSB investigation report (NTSB/AAR-10/02) and addressed through AD 2016-13-13, Amendment 18577 (81 FR 44494, July 8, 2016) ("AD 2016-13-13"). The commenter noted that AD 2016-13-13 requires installation of a control system modification that, following a single failure cause, prevents uncontrolled high failure thrust from occurring and prevents the engine from accelerating above idle. The commenter further stated that Draft AC 25.901-2X identified that assuming a crew response to address a hazard is not proper.

The FAA infers that the commenter is requesting corrective action that does not rely on crew action, similar to the modification required by AD 2016-13-13. The FAA acknowledges that Draft AC 25.901-2X suggests that relying on pilot response to address a catastrophic hazard is not always feasible; however, Draft AC 25.901-2X is not current agency guidance because it has not yet been finalized and issued. In addition, the FAA has determined that in some cases, including this one, relying on pilot response to address a hazard is

appropriate. The installation of a T/R VCWS and performance of a functional test, as required by paragraph (g) of this AD, adequately addresses the unsafe condition on the affected airplanes. The T/R VCWS monitors the thrust reversers and provides voice command when needed, which will enable a faster pilot response to decelerate the airplane. However, if the FAA obtains and analyzes additional data that indicates the unsafe condition has not been adequately addressed by this AD, the FAA will consider further rulemaking. The FAA has not changed this AD in this regard.

Request To Shorten the Compliance Time

The NTSB requested that the FAA shorten the proposed compliance time of 1,200 hours time-in-service or 48 months, because of how much time has passed since the NTSB's July 17, 2009, safety recommendation regarding this issue.

The FAA disagrees with the commenter's request. Based on the FAA's risk assessment, the FAA has determined that the proposed compliance time in this AD is adequate to address the unsafe condition. In developing an appropriate compliance time for this action, the agency considered the urgency associated with the unsafe condition and the practical aspects of accomplishing the required modification within a period of time that corresponds to the normal scheduled maintenance for most affected owners/operators. The FAA has not changed this AD in this regard.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed except for minor editorial changes. The FAA has determined that these minor changes:

| ESTIMATED COSTS | | | | |
|--------------------------|---|------------|------------------|------------------------|
| Action | Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
| Install a T/R VCWS | 20 work-hours × \$85 per hour = \$1,700 | \$28,274 | \$29,974 | \$8,662,486 |

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all costs in this cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

- Are consistent with what was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any burden upon the public than was proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Bombardier Learjet 60 Service Bulletin SB 60-78-9, dated June 25, 2018. This service information contains procedures for installing a T/R VCWS to alert the pilot of a T/R malfunction. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSEES** section.

Costs of Compliance

The FAA estimates that this AD affects 289 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020-11-04 Learjet Inc.: Amendment 39-21129; Docket No. FAA-2019-0204; Project Identifier 2018-CE-042-AD.

(a) Effective Date

This AD is effective June 25, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Learjet Inc. Model 60 airplanes, serial numbers 60-001 through 60-430 inclusive, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 78, Engine Exhaust.

(e) Unsafe Condition

This AD was prompted by a report of a reverse thrust command accelerating the airplane instead of decelerating the airplane because the thrust reverser doors were stowed instead of deployed. The FAA is

issuing this AD to mitigate failure of the engine thrust reverser system. The unsafe condition, if not addressed, could result in the airplane overrunning the runway or a runway excursion.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Install a Thrust Reverser Voice Command Warning System

Within the next 1,200 hours time-in-service or within the next 48 months after June 25, 2020 (the effective date of this AD), whichever occurs first, install a Thrust Reverser Voice Command Warning System and perform a functional test in accordance with sections 3.A. through 3.C. of the Accomplishment Instructions in Bombardier Learjet 60 Service Bulletin SB 60-78-9, dated June 25, 2018.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact James Galstad, Aerospace Engineer, Wichita ACO Branch, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4135; fax: (316) 946-4107; email: james.galstad@faa.gov or Wichita-COS@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Learjet 60 Service Bulletin SB 60-78-9, dated June 25, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Learjet Inc., MS 53, P.O. Box 7707, Wichita, Kansas 67277-7707; telephone: (toll free) 1-866-538-1247; (514) 855-2999; internet: <https://my.businessaircraft.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 15, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10915 Filed 5-20-20; 8:45 am]

BILLING CODE 4910-13-P

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0026; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kristin Bradley, Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email kristin.bradley@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On February 12, 2020, at 85 FR 7894, the **Federal Register** published the FAA's notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS332C, AS332C1, AS332L, AS332L1, AS332L2, and EC225LP helicopters. This AD requires revising the Rotorcraft Flight Manual (RFM) for your helicopter and either installing placards or removing the hoist arm. This AD was prompted by a failure of a right-hand (RH) side lateral sliding plug door (sliding door) to jettison. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective June 25, 2020.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of June 25, 2020.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0026.

The NPRM was prompted by EASA AD No. 2018-0140-E, dated June 29, 2018 (EASA AD 2018-0140-E), issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale) Model AS 332 C, AS 332 C1, AS 332 L, AS 332 L1, AS 332 L2, and EC 225 LP helicopters. EASA