

and nuts of the tail rotor hub body with new bolts, washers, and nuts in accordance with the instructions of Airbus Helicopters

Emergency Alert Service Bulletin 05A020, Revision 1, dated November 8, 2019. Thereafter, repeat the replacement of the

bolts, washers, and nuts at intervals not to exceed 1,000 hours TIS.

**Figure 3 to paragraph (j) – Initial Replacement of Bolts, Washers and Nuts**

Accumulated Hours TIS on the bolts since first installation on a helicopter	Compliance Time
Less than 9,000 hours TIS	Within 1,000 hours TIS since the initial inspection required by paragraph (h) of this AD was done, without exceeding 9,000 hours TIS on the bolts since first installation on a helicopter
9,000 or more hours TIS, or hours TIS unknown	Within 15 hours TIS or 7 days, whichever occurs first after the effective date of this AD

**(k) Parts Installation Limitation**

As of the effective date of this AD, it is allowed to install on any helicopter an affected part, provided it is a serviceable part, as defined in paragraph (g) of this AD.

**(l) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraphs (h) through (j) of this AD, if those actions were performed before the effective date of this AD using Airbus Helicopters Emergency Alert Service Bulletin 05A020, Revision 0, dated October 29, 2019.

**(m) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, notify your principal inspector or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(n) Related Information**

The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2019-0272R1, dated November 18, 2019. This EASA AD may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0455.

**(o) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this

paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin 05A020, Revision 1, dated November 8, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 18, 2020.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-11082 Filed 5-21-20; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2020-0096; Product Identifier 2019-NM-211-AD; Amendment 39-19913; AD 2020-10-10]

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2016-07-28, which applied to all The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes, and Model MD-88 airplanes. AD 2016-07-28 required repetitive eddy current high frequency (ETHF) inspections for any cracking in the left and right side center wing lower skin, and repair if any crack was found. This AD continues to require repetitive ETHF inspections for any cracking in the left and right side center wing lower skin, and repair if any crack is found. This AD also requires expanding the inspection area to include adjacent stringers with similar stress levels and to perform repetitive inspections with increased sensitivity for crack detection. This AD was prompted by a report of a crack at a certain stringer not addressed by AD 2016-07-28, and cracks at certain other

stringers and associated end fittings, and skins in the center wing fuel tank where the stringers meet the end fittings addressed by AD 2016-07-28. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 26, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 26, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0096.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0096; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Mohit Garg, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: [mohit.garg@faa.gov](mailto:mohit.garg@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2016-07-28, Amendment 39-18473 (81 FR 21253, April 11, 2016) (“AD 2016-07-28”). AD 2016-07-28 applied to all The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes, and Model MD-88 airplanes. The NPRM

published in the **Federal Register** on February 13, 2020 (85 FR 8209). The NPRM was prompted by a report of a crack at stringer S-13 which was not addressed by AD 2016-07-28, and by reports of cracks at stringers S-15, S-16, or S-17 and associated end fittings, and skins in the center wing fuel tank where the stringers meet the end fittings, which were addressed by AD 2016-07-28. The NPRM proposed to continue to require repetitive ETHF inspections for any cracking in the left and right side center wing lower skin, and repair if any crack is found. The NPRM also proposed to require expanding the inspection type and area to include repetitive eddy current low frequency (ETLF) inspections of the left and right side fastener holes and the forward and aft skins at certain locations for any cracking. The FAA is issuing this AD to detect and correct cracking in the center wing lower skin. Such cracking could cause structural failure of the wings.

##### Comments

The FAA gave the public the opportunity to participate in developing this AD. The following represents the comment received on the NPRM and the FAA’s response to that comment.

##### Request To Clarify Actions Since AD 2016-07-28 Was Issued

Boeing requested a correction in the “Actions Since AD 2016-07-28 Was Issued” section of the NPRM. Boeing stated that the wording in the section suggests that there have been crack reports for other stringers not addressed in AD 2016-07-28 beyond the single crack report for stringer S-13, and that these additional reports are the reason for expanding the inspection area. Boeing reiterated that AD 2016-07-28 addresses stringers S-15, S-16, and S-17, and, with the exception of the single crack report for stringer S-13, the scope of stringers reported cracked since the issuance of AD 2016-07-28 has not increased.

Boeing contends that the reason for the new ruling is to expand the inspection area to include adjacent stringers with similar stress levels and to perform a new inspection with increased crack detection, as stated in the NPRM. Boeing stated that the first sentence in the “Actions Since AD 2016-07-28 Was Issued” section of the NPRM should read, “Since the FAA issued AD 2016-07-28, a single occurrence of cracking has been found in stringer S-13, which is the only area not addressed by AD 2016-07-28.”

The FAA agrees that the description in the NPRM is inaccurate. Since that

section of the preamble does not reappear in the final rule, the requested change to the final rule is not necessary. However, the FAA has changed the **SUMMARY** and Discussion section of the preamble, and paragraph (e) of this AD, to reflect that this AD was prompted by the single crack report at stringer S-13, and that stringer S-13 was not covered by AD 2016-07-28.

##### Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this AD with the changes described previously, and minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

##### Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019. This service information describes procedures for a general visual inspection (GVI) for existing repairs; repetitive ETLF inspections of the left and right side fastener holes common to stringers 11 through 22 and the forward and aft skins for any crack; repetitive ETHF inspections of the lower skin at stringers 18 through 20 for any crack; an ETHF inspection of the left side and right side center wing lower skin for any crack; and applicable on-condition actions. On-condition actions include repair and an internal GVI for any cracks in stringers 11 through 22 between Xcw=0.0 and Xcw=20.0. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

##### Costs of Compliance

The FAA estimates that this AD affects 288 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

## ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection (retained actions from AD 2016-07-28).	14 work-hours × \$85 per hour = \$1,190 per inspection cycle.	\$0	\$1,190 per inspection cycle ...	\$342,720 per inspection cycle.
Expanded inspection (new action).	Up to 48 work-hours × \$85 per hour = Up to \$4,080 per inspection cycle.	0	Up to \$4,080 per inspection cycle.	Up to \$1,175,040 per inspection cycle.

The FAA has received no definitive data that would enable the agency to provide cost estimates for the on-condition actions specified in this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–07–28, Amendment 39–18473 (81 FR 21253, April 11, 2016), and adding the following new AD:

**2020–10–10 The Boeing Company:**  
Amendment 39–19913; Docket No. FAA–2020–0096; Product Identifier 2019–NM–211–AD.

#### (a) Effective Date

This AD is effective June 26, 2020.

#### (b) Affected ADs

This AD replaces AD 2016–07–28, Amendment 39–18473 (81 FR 21253, April 11, 2016) ("AD 2016–07–28").

#### (c) Applicability

This AD applies to all The Boeing Company Model DC–9–81 (MD–81), DC–9–82 (MD–82), DC–9–83 (MD–83), and DC–9–87 (MD–87) airplanes, and Model MD–88 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

#### (e) Unsafe Condition

This AD was prompted by a report of a crack at a certain stringer not addressed by AD 2016–07–28, and cracks at certain other stringers and associated end fittings, and skins in the center wing fuel tank where the stringers meet the end fittings addressed by AD 2016–07–28. The FAA is issuing this AD to detect and correct cracking in the center wing lower skin. Such cracking could cause structural failure of the wings.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD80–57A244, Revision 1, dated October 1, 2019, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–57A244, Revision 1, dated October 1, 2019.

**Note 1 to paragraph (g) of this AD:** Boeing Alert Service Bulletin MD80–57A244, Revision 1, dated October 1, 2019, refers to Drawing SN09570007 for certain inspection sequences. If the pages of Drawing SN09570007 are illegible, guidance can be found in Boeing Multi Operator Message MOM–MOM–19–0549–01B, dated October 4, 2019.

#### (h) Exception to Service Information Specifications

Where Boeing Alert Service Bulletin MD80–57A244, Revision 1, dated October 1, 2019, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ANM-LAACO-AMOC-Requests@faa.gov](mailto:9-ANM-LAACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or

alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2016–07–28 are not approved as AMOCs for this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(5)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (j) Related Information

(1) For more information about this AD, contact Mohit Garg, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5264; fax: 562–627–5210; email: [mohit.garg@faa.gov](mailto:mohit.garg@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD80–57A244, Revision 1, dated October 1, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 14, 2020.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives,  
Compliance & Airworthiness Division,  
Aircraft Certification Service.*

[FR Doc. 2020–11034 Filed 5–21–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

**[Docket No. FAA–2020–0023; Airspace  
Docket No. 19–ANM–7]**

**RIN 2120–AA66**

#### **Establishment of Class E Airspace; Harlowton, MT**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace at Wheatland County at Harlowton Airport, Harlowton, MT. Two areas are established to contain arriving and departing IFR aircraft operating to/from the airport. The first area extends upward from 700 feet above the surface and the second area extends upward from 1,200 feet above the surface.

**DATES:** Effective 0901 UTC, July 16, 2020. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11D, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11D at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:** Matthew Van Der Wal, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231–3695.

**SUPPLEMENTARY INFORMATION:**

#### **Authority for This Rulemaking**

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace at Wheatland County at Harlowton Airport, Harlowton, MT, to ensure the safety and management of Instrument Flight Rules (IFR) operations at the airport.

#### **History**

The FAA published a notice of proposed rulemaking in the **Federal Register** (85 FR 10625; February 25, 2020) for Docket No. FAA–2020–0023 to establish Class E airspace at Wheatland County at Harlowton Airport, Harlowton, MT. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. One comment was received.

The comment was not germane to the proposed airspace action for the airport. Class E5 airspace designations are published in paragraph 6005 of FAA Order 7400.11D, dated August 8, 2019, and effective September 15, 2019, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

#### **Availability and Summary of Documents for Incorporation by Reference**

This document amends FAA Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019, and effective September 15, 2019. FAA Order 7400.11D is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11D lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### **The Rule**

This amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 establishes Class E airspace extending upward from 700 feet or more above the surface at Wheatland County at Harlowton Airport, Harlowton, MT. Two airspace areas are established to