

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters Deutschland GmbH:

Docket No. FAA-2020-1037; Project Identifier 2019-SW-077-AD.

(a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Deutschland GmbH Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 helicopters, certificated in any category, with a Titanium (Ti) bolt part number L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward tail rotor drive shaft.

Note 1 to paragraph (a): Helicopters with an EC135P3H designation are Model EC135P3 helicopters. Helicopters with an EC135T3H designation are Model EC135T3 helicopters.

(b) Unsafe Condition

This AD defines the unsafe condition as failure of an affected Ti-bolt installed in a critical location, possibly resulting in reduced control of the helicopter.

(c) Comments Due Date

The FAA must receive comments by January 14, 2021.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 50 hours time-in-service or 3 months, whichever occurs first, remove any Ti-bolt identified in paragraph (a) of this AD, located on the forward tail rotor drive shaft, from service.

(2) As of the effective date of this AD, do not install a Ti-bolt identified in paragraph

(a) of this AD on the forward tail rotor drive shaft of any helicopter.

(f) Alternative Methods of Compliance (AMOCs):

The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Manager, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(g) Additional Information

(1) Airbus Helicopters Alert Service Bulletin (ASB) No. EC135-00A-001 and ASB No. EC135H-00A-001, each Revision 1 and dated September 2, 2019, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) No. 2019-0199, dated August 16, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft System Component (JASC) Codes: 1430, Fasteners; and 6510, Tail Rotor Drive Shaft.

Issued on November 20, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-26253 Filed 11-27-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1038; Project Identifier MCAI-2020-00569-E]

RIN 2120-AA64

Airworthiness Directives; Safran Helicopter Engines, S.A. (Type Certificate Previously Held by Turbomeca, S.A.) Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A. (Safran) Arriel 2D and Arriel 2E model

turboshaft engines. This proposed AD was prompted by the manufacturer revising the maintenance and overhaul manuals to introduce new or more restrictive airworthiness limitations and maintenance tasks. This proposed AD would require the replacement of certain critical parts before reaching their published in-service life limits, performing scheduled maintenance tasks before reaching their published periodicity, and performing unscheduled maintenance tasks when the engine meets certain conditions. As a terminating action, this proposed AD would require operators to revise the airworthiness limitation section (ALS) of their existing approved aircraft maintenance program (AMP) by incorporating the revised airworthiness limitations and maintenance tasks. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 14, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12 140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Safran Helicopter Engines, S.A., 64511 Bordes—Cedex, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1038; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other

information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7134; fax: (781) 238-7199; email: wego.wang@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2020-1038; Project Identifier MCAI-2020-00569-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI

should be sent to Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2018-0273, dated December 13, 2018 (referred to after this as "the MCAI"), to address the unsafe condition on these products. The MCAI states:

The airworthiness limitations and maintenance tasks for the SAFRAN ARRIEL 2D, ARRIEL 2E and ARRIEL 2N engines, which are approved by EASA, are currently defined and published in the SAFRAN ARRIEL 2 Maintenance and Overhaul Manuals, as applicable. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

SAFRAN recently revised the applicable Maintenance and Overhaul Manuals (the applicable ALS), introducing new and/or more restrictive airworthiness limitations and maintenance tasks.

For the reason described above, this [EASA] AD requires accomplishment of the actions specified in the applicable ALS.

You may obtain further information by examining the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1038.

FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Chapter 05-10-00 of Safran Helicopter Engines ARRIEL 2D Maintenance Manual (MM) No. X292 R1 450 2, Update No. 20, dated June 15, 2020. Safran Helicopter Engines ARRIEL 2D MM X292 R1 450 2 identifies the terms used in tables for limits and mandatory maintenance tasks, usage counters of the engine log book, life limits for life-limited parts, and

mandatory inspection tasks to be carried out to reach the airworthiness objectives on Safran Arriel 2D model engines.

The FAA reviewed Chapter 05-10-00 of Safran Helicopter Engines ARRIEL 2E MM No. X292 R2 300 2, Update No. 16, dated June 15, 2020. Safran Helicopter Engines ARRIEL 2E MM X292 R2 300 2 identifies the terms used in tables for limits and mandatory maintenance tasks, usage counters of the engine log book, life limits for life-limited parts, and mandatory inspection tasks to be carried out to reach the airworthiness objectives on Safran Arriel 2E model engines.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would require the replacement of certain critical parts before reaching their published in-service life limits, performance of schedule maintenance tasks before reaching the published periodicity in the applicable Safran Arriel MM chapter, and performance of unscheduled maintenance tasks when the engine meets certain conditions specified in the applicable Safran Arriel MM chapter. As a terminating action, this proposed AD would require operators to revise the ALS of their existing approved AMP by incorporating the revised airworthiness limitations and maintenance tasks.

Differences Between This Proposed AD and the MCAI

The MCAI is applicable to Safran Arriel 2D, Arriel 2E, and Arriel 2N model turboshaft engines. This AD is only applicable to Safran Arriel 2D and 2E model turboshaft engines. Safran Arriel 2N model turboshaft engines are not type certificated in the U.S.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 426 engines installed on helicopters of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace critical parts	12 work-hours × \$85 per hour = \$1,020	\$1,152	\$2,172	\$925,272
Perform maintenance tasks	1 work-hour × \$85 per hour = \$85	1,152	1,237	526,962
Revise the ALS and AMP	1 work-hour × 85 per hour = 85	0	85	36,210

The FAA estimates the following costs to do any necessary corrective actions that would be required based on

the results of the proposed maintenance tasks. The agency has no way of

determining the number of aircraft that might need these actions.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Perform corrective action	1 work-hour × \$85 per hour = \$85	\$0	\$85

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Safran Helicopter Engines, S.A., (Type Certificate previously held by Turbomeca, S.A.); Docket No. FAA–2020–1038; Project Identifier MCAI–2020–00569–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 14, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Safran Helicopter Engines, S.A. (Safran) (Type Certificate previously held by Turbomeca, S.A.) Arriel 2D and Arriel 2E model turboshaft engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by the manufacturer revising the maintenance and overhaul manuals to introduce new or more restrictive airworthiness limitations and maintenance tasks. The FAA is issuing this AD to prevent failure of the engine. The unsafe condition, if not addressed, could result in uncontained release of a critical part, damage to the engine, and damage to the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Replace each critical part before reaching the in-service life limits specified in paragraph 1.C., “Table of authorized in-service life limits for the ARRIEL 2D,” or “Table of authorized in-service life limits for the ARRIEL 2E,” Chapter 05–10–00 of the

Safran ARRIEL Maintenance Manual (MM) for that engine.

(2) Before reaching the periodicity specified in paragraph 1., “Tables of Mandatory Maintenance Tasks,” table D., “Scheduled inspection,” Chapter 05–10–00 of the Safran ARRIEL MM for that engine, perform all maintenance tasks specified in table D.

(3) When the engine meets the conditions specified in paragraph 1., table E., “Unscheduled inspection,” Chapter 05–10–00 of the Safran ARRIEL MM for that engine, perform the maintenance tasks specified in table E.

(4) If, during performance of the maintenance tasks required by paragraph (g)(2) or (3) of this AD, a discrepancy is found, as defined in the applicable ALS, perform the corrective actions specified in paragraph 1., “Tables of Mandatory Maintenance Tasks,” table D., “Scheduled inspection,” or E. “Unscheduled inspection,” Chapter 05–10–00 of the Safran ARRIEL MM for the engine.

(5) If no compliance time is identified in Chapter 05–10–00 of the Safran ARRIEL MM, perform the corrective action before further flight.

(h) Exception to Paragraphs (g)(2) and (3)

Where the applicable Safran ARRIEL MM chapters provide instructions to send the Module 03 to a Safran Helicopter Engines-approved repair center, the operator may choose to send the Module 03 to any FAA-approved repair center capable of performing the required actions.

(i) Mandatory Terminating Action

As terminating action to the requirements in paragraph (g) of this AD, within 365 days after the effective date of this AD, revise the ALS of the existing approved aircraft maintenance program (AMP) by incorporating:

(i) Task 05–10–00–150–801–A01, “Airworthiness Limitations—General,” from the applicable Safran ARRIEL MM chapter.

(ii) Task 05–10–00–200–801–A01, “Airworthiness Limitations—Authorized In-Service Life Limits,” from the applicable Safran ARRIEL MM chapter.

(iii) Task 05–10–10–200–801–A01, “Airworthiness Limitations—Tables of Mandatory Maintenance Tasks,” from the applicable Safran ARRIEL MM chapter.

(j) Definitions

(1) For the purpose of this AD, a “critical part” is a part identified in paragraph 1.C., “Table of authorized in-service life limits for the ARRIEL 2D,” or “Table of authorized in-service life limits for the ARRIEL 2E,”

Chapter 05–10–00 of the Safran ARRIEL MM for that engine.

(2) For the purpose of this AD, the “Chapter 05–10–00 of the Safran ARRIEL MM” is:

(i) Chapter 05–10–00 of Safran Aircraft Engines ARRIEL 2D MM No. X292 R1 450 2, Update No. 20, dated June 15, 2020; or

(ii) Chapter 05–10–00 of Safran Aircraft Engines ARRIEL 2E MM No. X292 R2 300 2, Update No. 16, dated June 15, 2020.

(3) For the purpose of this AD, the “approved maintenance program” is defined as the basis for which the operator ensures the continuing airworthiness of each operated helicopter.

(k) Credit for Previous Actions

(1) For affected Safran Arriel 2D model turboshaft engines, you may take credit for revising the ALS of the existing approved AMP that is required by paragraph (i) of this AD if you incorporated the tasks before the effective date of this AD using Chapter 05–10–00 of Safran ARRIEL 2D MM No. X292 R1 450 2, Update No. 19, dated December 30, 2019.

(2) For affected Safran Arriel 2E model turboshaft engines, you may take credit for revising the ALS of the existing approved AMP that is required by paragraph (i) of this AD if you incorporated the tasks before the effective date of this AD using Chapter 05–10–00 of Safran ARRIEL 2E MM No. X292 R2 300 2, Update No. 15, dated December 30, 2019.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(m) Related Information

(1) For more information about this AD, contact Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7134; fax: (781) 238–7199; email: wego.wang@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2018–0273, dated December 13, 2018, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA–2020–1038.

(3) For service information identified in this AD, contact Safran Helicopter Engines, S.A., 64511 Bordes—Cedex, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this referenced service information at the FAA, Airworthiness

Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238–7759.

Issued on November 24, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–26337 Filed 11–27–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–1036; Project Identifier MCAI–2020–01430–R]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Helicopters Model SA–365N, SA–365N1, AS–365N2, AS 365 N3, EC 155B, and EC155B1 helicopters. This proposed AD was prompted by the FAA’s determination that to improve the process and performance in collecting metal particles in the main gear box (MGB) certain existing magnetic plugs (electrical and non-electrical) installed in the MGB pump intake must be replaced with improved non-electrical magnetic plugs. This proposed AD would require replacing the existing magnetic plug with an improved non-electrical magnetic plug, as specified in a European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 14, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room

W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet

www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1036.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1036; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mahmood Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5538; email mahmood.g.shah@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2020–1036; Project Identifier MCAI–2020–01430–R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other