

under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2020–24–09 Piper Aircraft, Inc.:

Amendment 39–21339; Docket No. FAA–2020–0712; Product Identifier 2019–CE–013–AD.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 5, 2021.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Piper Aircraft, Inc., Model PA–34–220T airplanes, serial numbers 3449459 and 3449467 through 3449508, certificated in any category.

#### (d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 27. Flight Controls.

#### (e) Unsafe Condition

This AD was prompted by a report of damage to the rudder flight control cables and the emergency power supply (EPS) system wiring due to inadequate clearance from the EPS wiring harness. The FAA is issuing this AD to detect, correct, and prevent damaged rudder flight control cables and EPS system wiring. The unsafe condition, if not addressed, could result in electrical arcing between the EPS and the rudder flight control cables with consequent failure of the rudder flight control system. This failure could cause loss of yaw control and lead to loss of control of the airplane during an engine out condition/operation.

#### (f) Compliance

Unless already done, comply with this AD within 50 hours time-in-service after the effective date of this AD or within 6 months after the effective date of this AD, whichever occurs first.

#### (g) Inspect, Replace, and Relocate

(1) Inspect the rudder flight control cables and the EPS wiring for chafing and damage

by following step 3 of the Instructions in Piper Service Bulletin No. 1337, dated February 15, 2019 (Piper SB No. 1337). If there is any chafing or damage, before further flight, replace the rudder flight control cable and EPS wiring.

(2) Relocate the EPS wiring harness by following steps 4 through 12 of the Instructions in Piper SB No. 1337.

#### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the following provisions apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (i) Related Information

For more information about this AD, contact Bryan Long, Aerospace Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474–5578; fax: (404) 474–5606; email: [bryan.long@faa.gov](mailto:bryan.long@faa.gov).

#### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piper Service Bulletin No. 1337, dated February 15, 2019.

(ii) [Reserved]

(3) For the service information identified in this AD, contact Piper Aircraft, Inc., 2916 Piper Drive, Vero Beach, Florida 32960; telephone: (772) 567–4361; email: [customer.service@piper.com](mailto:customer.service@piper.com); internet: <https://www.piper.com>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information

on the availability of this material at the FAA, call (816) 329–4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 17, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–26473 Filed 11–30–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–1027; Project Identifier MCAI–2020–01375–R; Amendment 39–21333; AD 2020–24–03]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, and AS355F2 helicopters. This AD requires testing the UP/DOWN switches of a certain part-numbered DUNLOP cyclic stick grip, installing a placard, and revising the existing Rotorcraft Flight Manual (RFM) for your helicopter, or removing the DUNLOP cyclic stick grip. This AD was prompted by an inadvertent activation of the rescue hoist cable cutter. The actions of this AD are intended to address an unsafe condition on these products.

**DATES:** This AD becomes effective December 16, 2020.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of December 16, 2020.

The FAA must receive comments on this AD by January 15, 2021.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.

- *Mail*: Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590-0001.

- *Hand Delivery*: Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1027; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Union Aviation Safety Agency (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1027.

**FOR FURTHER INFORMATION CONTACT:** Daniel E. Moore, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [daniel.e.moore@faa.gov](mailto:daniel.e.moore@faa.gov).

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include the docket number FAA-2020-1027 and Project Identifier MCAI-2020-01375-R at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Daniel E. Moore, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [daniel.e.moore@faa.gov](mailto:daniel.e.moore@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA Emergency AD No. 2020-0217-E, dated October 6, 2020, to correct an unsafe condition for Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale, Model AS 350 B, AS 350 BA, AS 350 B1, AS 350 B2, AS 350 D, AS 355 E, AS 355 F, AS 355 F1, and AS 355 F2 helicopters. EASA advises of a report of an unintended release of the rescue hoist hook on a Model AS 350 B2 helicopter during a ground check. The operator was using the UP/DOWN switches for rescue hoist control, installed on DUNLOP cyclic stick grip part number (P/N) AC66444, when the hoist's electrically-actuated cable cutter function activated. EASA states that this condition, if not corrected, could lead to further events of inadvertent activation of the rescue hoist cable cutter function and consequent detachment of an external load or person from the

helicopter hoist, possibly resulting in personal injury or injury to persons on the ground.

To address this potential unsafe condition, Airbus Helicopters published Emergency Alert Service Bulletin (EASB) Nos. 01.00.58 and 01.00.72, each Revision 0 and dated October 1, 2020, to introduce an operational limitation.

Accordingly, the EASA AD requires installing a dedicated placard in the cockpit and amending the applicable RFM to prohibit the in-flight use of the UP/DOWN switches for rescue hoist control installed on DUNLOP cyclic stick grip P/N AC66444. EASA states its AD is considered an interim action and further AD action may follow.

### FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA of the unsafe condition described in its AD. The FAA is issuing this AD after evaluating all information provided by EASA and determining the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

### Related Service Information Under 1 CFR Part 51

The FAA has reviewed Airbus Helicopters EASB No. 01.00.58 for Model AS355-series helicopters and Airbus Helicopters EASB No. 01.00.72 for Model AS350-series helicopters, each Revision 0 and dated October 1, 2020, which are co-published as one document. This service information specifies installing a placard and revising the Flight Manual to prohibit the use of the UP/DOWN switches of the DUNLOP cyclic stick grip manufacturer P/N (MP/N) AC66444.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### AD Requirements

This AD requires accomplishing a ground test of the UP/DOWN switches of DUNLOP cyclic stick grip MP/N AC66444 for proper function before each hoist operation. If there is any uncommanded hoist action, this AD requires removing the DUNLOP cyclic stick grip from service.

If DUNLOP cyclic stick grip MP/N AC66444 is installed, before the next hoist operation, this AD requires installing a placard and revising the existing RFM for your helicopter to prohibit the use of the UP/DOWN

switches of the DUNLOP cyclic stick grip. Alternatively, this AD allows removing DUNLOP cyclic stick grip MP/N AC66444, however before the DUNLOP cyclic stick grip is re-installed, this AD requires accomplishing the ground test of the UP/DOWN switches and installing the placard and revising the existing RFM for your helicopter. This AD also prohibits installing an affected DUNLOP cyclic stick grip unless the ground testing of the UP/DOWN switches has been accomplished, the placard has been installed, and the existing RFM for your helicopter has been revised.

#### Differences Between This AD and the EASA AD

The EASA AD applies to all Airbus Helicopters Model AS 350 B, AS 350 BA, AS 350 B1, AS 350 B2, AS 350 D, AS 355 E, AS 355 F, AS 355 F1, and AS 355 F2 helicopters, whereas this AD applies to Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, and AS355F2 helicopters with DUNLOP cyclic stick grip MP/N AC66444 with UP/DOWN switches for rescue hoist control installed instead. This AD requires accomplishing a ground test of the UP/DOWN switches for proper function before each hoist operation, whereas the EASA AD does not.

#### Interim Action

The FAA considers this AD to be an interim action. If final action is later identified, the FAA might consider further rulemaking then.

#### Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

#### Costs of Compliance

The FAA estimates that this AD affects 390 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates that operators may incur the following costs in order to comply with this AD.

Accomplishing a ground test of the UP/DOWN switches for proper function takes a minimal amount of time for a nominal cost. Installing a placard and revising the existing RFM for your helicopter takes about 0.5 work-hour for an estimated cost of \$43 per helicopter and \$16,770 for the U.S. fleet.

Alternatively, replacing the affected DUNLOP cyclic stick grip takes about 2.5 work-hours and parts cost about \$2,500 for an estimated cost of \$2,713.

#### FAA's Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (5 U.S.C.) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause" finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without seeking comment prior to the rulemaking.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because there are required corrective actions that must be completed before the next hoist operation. Therefore, notice and opportunity for prior public comment are impracticable and contrary to public interest pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the reasons stated above, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect

on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866, and
2. Will not affect intrastate aviation in Alaska.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2020–24–03 Airbus Helicopters:

Amendment 39–21333; Docket No. FAA–2020–1027; Project Identifier MCAI–2020–01375–R.

#### (a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, and AS355F2 helicopters, certificated in any category, with DUNLOP cyclic stick grip manufacturer part number AC66444 with UP/DOWN switches for rescue hoist control installed.

#### (b) Unsafe Condition

This AD defines the unsafe condition as inadvertent activation of the rescue hoist cable cutter and consequent detachment of an external load or person from the helicopter hoist. This condition could result in personal injury or injury to persons on the ground.

#### (c) Effective Date

This AD becomes effective December 16, 2020.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

- (1) Before each hoist operation, accomplish a ground test of the UP/DOWN switches for proper function. If there is any

uncommanded hoist action, before further flight, remove the DUNLOP cyclic stick grip from service.

(2) Before the next hoist operation:

(i) Install a placard in full view of the pilot by following the Accomplishment Instructions, paragraph 3.B., of Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 01.00.58 or 01.00.72, each Revision 0 and dated October 1, 2020 (EASB 01.00.58 or 01.00.72), as applicable to your helicopter.

(ii) Revise the existing Rotorcraft Flight Manual (RFM) for your helicopter by inserting the Limitations page applicable to your helicopter model and version from Appendix 4.C. through L, of EASB 01.00.58 or 01.00.72. Inserting a different document with information identical to that in Appendix 4.C. through L., of EASB 01.00.58 or 01.00.72, as applicable to your helicopter model and version, is acceptable for compliance with the requirement of this paragraph.

(3) After complying with paragraph (e)(2) of this AD, each time the DUNLOP cyclic stick grip that is identified in paragraph (a) of this AD is removed from the helicopter, you may remove the placard and RFM revision that are required by paragraphs (e)(2)(i) and (ii) of this AD. Before the DUNLOP cyclic stick grip is re-installed, you must re-install the placard and RFM revision that are required by paragraphs (e)(2)(i) and (ii) of this AD.

(4) As of the effective date of this AD, do not install a DUNLOP cyclic stick grip that is identified in paragraph (a) of this AD unless the requirements of paragraphs (e)(1) and (2) of this AD have been accomplished.

#### (f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Daniel E. Moore, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD No. 2020-0217-E, dated October 6, 2020. You may view the EASA AD on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2020-1027.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 6700, Rotorcraft Flight Control.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of

the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 01.00.58, Revision 0, dated October 1, 2020.

(ii) Airbus Helicopters EASB No. 01.00.72, Revision 0, dated October 1, 2020.

**Note 1 to paragraph (i)(2):** Airbus Helicopters EASB Nos. 01.00.58 and 01.00.72, each Revision 0 and dated October 1, 2020, are co-published as one document.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 12, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-26422 Filed 11-30-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2020-0701; Airspace Docket No. 20-ASO-19]

RIN 2120-AA66

#### Establishment of Class D and Class E Airspace and Amendment of Class E Airspace; Nashville, TN

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class D and Class E airspace designated as an extension to Class D or E surface area, and amends Class E airspace extending upward from 700 feet above the surface for John C. Tune Airport, Nashville, TN, as a new air traffic control tower shall service the airport. This action also updates the geographic coordinates of the airport, as well as Music City

Executive Airport, (formerly Sumner County Regional Airport), Lebanon Municipal Airport, and Murfreesboro Municipal Airport. In addition, this action establishes Class E airspace extending upward from 700 feet above the surface for Vanderbilt University Hospital Heliport, as instrument approach procedures have been designed for the heliport. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations in the area.

**DATES:** Effective 0901 UTC, June 17, 2021. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; Telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; Telephone (404) 305-6364.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rule regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace in Nashville, TN to support IFR operations in the area.