

Rules and Regulations

Federal Register

Vol. 85, No. 235

Monday, December 7, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0718; Project Identifier 2019-CE-045-AD; Amendment 39-21343; AD 2020-25-01]

RIN 2120-AA64

Airworthiness Directives; Textron Aviation, Inc. Airplanes (Type Certificate Previously Held by Beechcraft Corporation)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Textron Aviation Inc. (Textron) (type certificate previously held by Beechcraft Corporation) Models F90, 65-90, 65-A90, B90, C90, H90 (T-44A), E90, 65-A90-1 (JU-21A, U-21A, RU-21A, RU-21D, U-21G, RU-21H), 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), 65-A90-4 (RU-21E, RU-21H), 99, 99A, 99A (FACH), A99, A99A, B99, C99, 100, A100 (U-21F), and B100 airplanes. This AD was prompted by reports of fatigue cracks in the lower forward wing fitting. This AD requires a one-time inspection for the presence of washer part number (P/N) 90-380058-1 on the left-hand (LH) and right-hand (RH) lower forward wing bolt and, if applicable, removing washer P/N 90-380058-1, inspecting the wing fitting, bolt, and nut, replacing the wing fitting if it is cracked, and replacing the washer with washer P/N 90-380019-1. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 11, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 11, 2021.

ADDRESSES: For service information identified in this final rule, contact Textron Aviation Inc., P.O. Box 7706, Wichita, KS 67277; phone: 316-517-5800; internet: <https://txtav.com/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust St., Kansas City, MO 64106. For information on the availability of this material at the FAA, call 816-329-4148. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0718.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0718; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Brian C. Adamson, Aviation Safety Engineer, Wichita ACO Branch, AIR-7K3, FAA, 1801 Airport Rd, Wichita, KS 67209; phone: 316-946-4193; fax: 316-946-4107; email: brian.adamson@faa.gov or Wichita-COS@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Textron (type certificate previously held by Beechcraft Corporation) Models F90, 65-90, 65-A90, B90, C90, H90 (T-44A), E90, 65-A90-1 (JU-21A, U-21A, RU-21A, RU-21D, U-21G, RU-21H), 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), 65-A90-4 (RU-21E, RU-21H), 99, 99A, 99A (FACH), A99, A99A, B99, C99, 100, A100 (U-21F), and B100 airplanes. The NPRM published in the **Federal Register** on July 29, 2020 (85 FR 45545).

The NPRM was prompted by Textron receiving reports of fatigue cracks in the lower forward wing fitting on two airplanes. Investigation revealed that

installing washer P/N 90-380058-1 on the wing bolt will cause a premature torque indication. This washer may have been installed as part of kit 101-4024-3 on Models F90, 65-90, 65-A90, B90, C90, H90 (T-44A), E90, 65-A90-1 (JU-21A, U-21A, RU-21A, RU-21D, U-21G, RU-21H), 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), 65-A90-4 (RU-21E, RU-21H), 99, 99A, 99A (FACH), A99, A99A, B99, C99, 100, A100 (U-21F), and B100 airplanes, or as part of kit 90-4077-1 on Models 65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU-21A, RU-21D, U-21G, RU-21H), 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), 65-A90-4 (RU-21E, RU-21H), B90, C90, and E90 airplanes. Under-torque of the wing bolt causes a reduced clamping force that changes the load path reacted by the RH and LH lower forward wing fitting.

In the NPRM, the FAA proposed to require a one-time inspection for the presence of washer P/N 90-380058-1 on the LH and RH lower forward wing bolt and, if applicable, removing washer P/N 90-380058-1, inspecting the wing fitting, bolt, and nut, replacing the wing fitting if it is cracked, and replacing the washer with washer P/N 90-380019-1. This condition, if not addressed, could result in fatigue cracks that lead to failure of the forward lower wing fitting, wing separation, and loss of airplane control.

Comments

The FAA received one comment from an individual commenter. The following presents the comment received on the NPRM and the FAA's response to the comment.

Request Change to Applicability

An individual commenter requested that the AD identify the applicable airplanes by serial number. The commenter stated that on the Beech Model C90A serial number LJ-1450 airplane, the lower front wing connections are designed as shear fittings with shear bolts, and therefore the washers are not affected. The FAA disagrees. The AD, as proposed, clearly lists the applicable airplane models and serial numbers. The FAA responded to the commenter by email and advised that the AD, as proposed, would not apply to the Model C90A. A copy of the comment and the FAA's response is in the AD docket.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Beechcraft Mandatory Service Letter MTL-57-01, Revision 1, dated September 19, 2018. The service information contains procedures for a one-time inspection for the presence of washer P/N 90-380058-1 on the LH and RH lower forward wing bolt and, if applicable, removing washer

P/N 90-380058-1; inspecting the wing fitting, bolt, and nut; replacing the wing fitting if it is cracked; and replacing the washer with washer P/N 90-380019-1. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Differences Between This AD and the Service Information

The service information specifies inspecting within 200 flight hours or 12 months, whichever occurs earlier. This AD would require inspecting within the next 200 flight hours or 12 months, whichever occurs later.

The service information applies to Models A100A and A100C airplanes,

and to Model F90 with S/N LA-1. This AD would not apply to these airplanes because they do not have an FAA type certificate.

This AD would apply to military Models T-44A, JU-21A, RU-21A, RU-21B, RU-21C, RU-21D, RU-21E, RU-21H, U-21A, U-21F, U-21G, and FACH airplanes, because these models have a civil counterpart that is subject to the unsafe condition. The service information does not apply to all of these military models.

Costs of Compliance

The FAA estimates that this AD will affect 1,319 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection for washer P/N 90-380058-1 (LH Wing Fitting).	0.3 work-hour × \$85 per hour = \$25.50	Not applicable	\$25.50	\$33,634.50
Inspection for washer P/N 90-380058-1 (RH Wing Fitting).	0.3 work-hour × \$85 per hour = \$25.50	Not applicable	25.50	33,634.50

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the inspection. The FAA has no way of determining the number of

airplanes that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
RH Wing bolt, washer, and nut removal	8 work-hours × \$85 per hour = \$680	\$335	\$1,015
LH Wing bolt, washer, and nut removal	8 work-hours × \$85 per hour = 680	\$335	1,015
Inspection of RH Lower Forward Wing Fitting	2 work-hours × \$85 per hour = 170	Not applicable	170
Inspection of LH Lower Forward Wing Fitting	2 work-hours × \$85 per hour = 170	Not applicable	170
Removal and Replacement of P/N 50-120073-8 RH Lower Forward Wing Fitting.	150 work-hours × \$85 per hour = 12,750	\$7,297.85	20,047.85
Removal and Replacement of P/N 50-120073-7 LH Lower Forward Wing Fitting.	150 work-hours × \$85 per hour = 12,750	\$11,812.56	24,562.56

The FAA has included all known costs in this cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section

44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national

government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2020–25–01 Textron Aviation, Inc., (Type Certificate Previously Held by Beechcraft Corporation): Amendment 39–21343; Docket No. FAA–2020–0718; Project Identifier 2019–CE–045–AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 11, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Textron Aviation Inc., (Textron) (type certificate previously held by Beechcraft Corporation) airplanes, certificated in any category, identified in table 1 to paragraph (c) of this AD:

Models	Serial Numbers (S/Ns)
F90	LA-2 through LA-225
65-90, 65-A90, B90, C90	All S/Ns
H90 (T-44A)	LL-1 through LL-61
E90	LW-1 through LW-347
65-A90-1 (JU-21A, U-21A, RU-21A, RU-21D, U-21G, RU-21H)	LM-1 through LM-144
65-A90-2 (RU-21B)	LS-1, LS-2, LS-3
65-A90-3 (RU-21C)	LT-1 and LT-2
65-A90-4 (RU-21E, RU-21H)	LU-1 through LU-16
99, 99A, 99A (FACH), A99, A99A, B99, C99	U-1 through U-239
100, A100 (U-21F)	B-1 through B-247
B100	BE-1 through BE-137

Table 1 to paragraph (c)

(d) Subject

Joint Aircraft System Component (JASC): 5700, Wings.

(e) Unsafe Condition

This AD was prompted by information provided by Textron that a washer assembly may provide premature torque indication that could lead to cracking of the wing fitting. The FAA is issuing this AD to prevent such fatigue cracks. The unsafe condition, if not addressed, could result in failure of the forward lower wing fitting, which could lead to wing separation and loss of airplane control.

(f) Compliance

Comply with this AD within the compliance times specified below, unless already done.

(g) Action

(1) Within the next 200 flight hours after the effective date of this AD or within 12 months after the effective date of this AD, whichever occurs later, inspect each washer assembly attached to the left and right lower forward wing bolts and remove all part number 90–380058–1 washers in accordance with the Accomplishment Instructions, paragraphs 3 through 5, of Beechcraft Mandatory Service Letter MTL–57–01, Revision 1, dated September 19, 2018 (MTL–57–01, Revision 1). In all locations where a

washer part number 90–380058–1 was removed, do the following:

(i) Inspect the bolt, nut, and fitting in accordance with the Accomplishment Instructions, paragraph 6, of MTL–57–01, Revision 1. If there is a crack in the fitting, replace the fitting before further flight.

(ii) Install a part number 90–380019–1 washer in accordance with the Accomplishment Instructions, paragraph 7, of MTL–57–01, Revision 1.

(2) As of the effective date of this AD, do not install washer part number 90–380058–1 on any airplane listed in table 1 to paragraph (c) of this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Brian C. Adamson, Aviation Safety Engineer, Wichita ACO Branch, AIR–7K3, FAA, 1801 Airport Rd., Wichita, KS 67209; phone: 316–946–4193; fax: 316–946–4107; email: brian.adamson@faa.gov or Wichita-COS@faa.gov.

(2) Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(i) Related Information

For more information about this AD, contact Brian C. Adamson, Aviation Safety Engineer, Wichita ACO Branch, AIR–7K3, FAA, 1801 Airport Rd., Wichita, KS 67209; phone: 316–946–4193; fax: 316–946–4107; email: brian.adamson@faa.gov or Wichita-COS@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Beechcraft Mandatory Service Letter MTL–57–01, Revision 1, dated September 19, 2018.

(ii) [Reserved]

(3) For Beechcraft service information identified in this AD, contact Textron Aviation Inc., P.O. Box 7706, Wichita, KS 67277; phone: 316–517–5800; internet: <https://txtav.com/>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 23, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-26773 Filed 12-4-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1104; Project Identifier MCAI-2020-01421-P; Amendment 39-21347; AD 2020-25-05]

RIN 2120-AA64

Airworthiness Directives; Hoffmann GmbH & Co. KG Propellers

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Hoffmann GmbH & Co. KG (Hoffmann) model HO-V 72 propellers. This AD was prompted by reports of cracks at different positions on two affected propeller hubs. This AD requires amending the existing aircraft flight manual (AFM) with abnormal propeller vibration instructions. This AD requires visual inspection and non-destructive test (NDT) inspection of the propeller hub and, depending on the results of the inspections, replacement of the propeller hub with a part eligible for installation. This AD also requires replacement of the propeller hub before exceeding 30 years since the date of manufacture or within 30 days after the effective date of this AD, whichever occurs later. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 22, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 22, 2020.

The FAA must receive comments on this AD by January 21, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Hoffmann Propeller GmbH & Co. KG, Sales and Service, K pferlingstrasse 9, 83022, Rosenheim, Germany; phone: +49 (0) 8031 1878 0; fax: +49 (0) 8031 1878 78; email: info@hoffmann-prop.com; website: <https://hoffmann-prop.com/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1104.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1104; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for the Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Michael Schwetz, Aviation Safety Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7761; fax: (781) 238-7199; email: michael.schwetz@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2020-0226-E, dated October 16, 2020 (referred to after this as “the MCAI”), to address an unsafe condition for the specified products. The MCAI states:

Cracks have been reported at different positions on two affected parts, both installed on Slingsby T67 “Firefly” aeroplanes. One crack was found during scheduled inspection, the other crack during an unscheduled inspection after abnormal

vibrations occurred. Both cases are under investigation by Hoffmann Propeller.

This condition, if not detected and corrected, could lead to in-flight propeller detachment, possibly resulting in damage to the airplane and/or injury to persons on the ground.

To address this potential unsafe condition, Hoffmann issued the SB [service bulletin], providing applicable instructions.

For the reasons described above, this [EASA] AD requires inspections of affected parts and, depending on findings, replacement, and introduces a life limit for affected parts. This [EASA] AD also requires, for certain aeroplanes, amendment of the applicable Aircraft Flight Manual (AFM).

You may obtain further information by examining the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1104.

FAA’s Determination

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Hoffmann Propeller GmbH & Co. KG Service Bulletin SB E53, Rev. B, dated October 14, 2020. This service information specifies procedures for visual and NDT inspections of the propeller hub for cracks. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in

ADDRESSES.

AD Requirements

This AD requires amending the existing AFM with abnormal propeller vibration instructions. This AD also requires visual inspection and NDT inspection of the propeller hub and, depending on the results of the inspections, replacement of the propeller hub with a part eligible for installation. This AD also requires replacement of the propeller hub before exceeding 30 years since the date of manufacture or within 30 days after the effective date of this AD, whichever occurs later.

Differences Between the AD and the MCAI

EASA AD 2020-0226-E, dated October 16, 2020, applies to Hoffmann HO-V 72 propellers with propeller hub HO-V 72 () ()-()-() that have been used or are expected to be used for aerobatic maneuvers. This AD applies to all Hoffmann model HO-V 72 propellers regardless of their use.