

Rules and Regulations

Federal Register

Vol. 85, No. 248

Monday, December 28, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0796; Project Identifier MCAI-2020-00902-T; Amendment 39-21367; AD 2020-26-12]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Gulfstream Aerospace LP Model Gulfstream G280 airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a Civil Aviation Authority of Israel (CAAI) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 1, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, The Civil Aviation Authority of Israel (CAAI), P.O. Box 1101, Golan Street, Airport City, 70100, Israel; phone: 972-3-9774665; fax: 972-3-9774592; email: aip@mot.gov.il. You may find this IBR material on the CAAI website at <https://www.caa.gov.il>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des

Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0796.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0796; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226; email: tom.rodriguez@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The CAAI, which is the aviation authority for Israel, has issued CAAI AD ISR-I-04-2020-06-02, dated June 28, 2020 (CAAI AD ISR-I-04-2020-06-02) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Gulfstream Aerospace LP Model Gulfstream G280 airplanes. Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after September 15, 2019, must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Gulfstream Aerospace LP Model Gulfstream G280 airplanes. The NPRM published in the **Federal Register** on September 16, 2020 (85 FR57799). The NPRM was prompted by a determination that new or more

restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in CAAI AD ISR-I-04-2020-06-02.

The FAA is issuing this AD to address solder cracking of the flight control electronic control units (FCECUs), which, combined with latent failure of the horizontal stabilizer trim actuator (HSTA) “no-back” mechanism, could result in uncontrolled HSTA operation. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

CAAI AD ISR-I-04-2020-06-02 describes new or more restrictive airworthiness limitations for airplane structures and safe life limits. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 160 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. In the past, the agency has estimated that this action

takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2020–26–12 Gulfstream Aerospace LP:
Amendment 39–21367; Docket No. FAA–2020–0796; Project Identifier MCAI–2020–00902–T.

(a) Effective Date

This airworthiness directive (AD) is effective February 1, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Gulfstream Aerospace LP Model Gulfstream G280 airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before September 15, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address solder cracking of the flight control electronic control units (FCECUs), which, combined with latent failure of the horizontal stabilizer trim actuator (HSTA) "no-back" mechanism, could result in uncontrolled HSTA operation.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Civil Aviation Authority of Israel (CAAI) AD ISR–I–04–2020–06–02, dated June 28, 2020 (CAAI AD ISR–I–04–2020–06–02).

(h) Exceptions to CAAI AD ISR–I–04–2020–06–02

- (1) Where CAAI AD ISR–I–04–2020–06–02 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where CAAI AD ISR–I–04–2020–06–02 refers to the date of its issuance, this AD requires using the effective date of this AD.

(i) Provisions for Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs)

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no

alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of CAAI AD ISR–I–04–2020–06–02.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or CAAI; or CAAI's authorized Designee. If approved by the CAAI Designee, the approval must include the Designee's authorized signature.

(k) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3226; email: tom.rodriguez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) The Civil Aviation Authority of Israel (CAAI) AD ISR–I–04–2020–06–02, dated June 28, 2020.

(ii) [Reserved]

(3) For CAAI AD ISR–I–04–2020–06–02, contact the CAAI, P.O. Box 1101, Golan Street, Airport City, 70100, Israel; phone: 972–3–9774665; fax: 972–3–9774592; email: aip@mot.gov.il. You may find this IBR material on the CAAI website at <https://www.caa.gov.il>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0796.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 10, 2020.

Lance T. Gant,

*Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2020-28406 Filed 12-23-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0792; Project Identifier 2018-SW-049-AD; Amendment 39-21368; AD 2020-26-13]

RIN 2120-AA64

Airworthiness Directives; Sikorsky Aircraft Corporation Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Sikorsky Aircraft Corporation (Sikorsky) Model S-92A helicopters. This AD was prompted by seven incidents of fatigue cracks in the horizontal stabilizer root fitting FWD (forward root fitting). This AD requires establishing the life limit of certain part-numbered forward root fittings, establishing the life limit of certain part-numbered stabilizer strut fittings, repetitively inspecting certain parts, and depending on the inspection results, removing parts from service. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 1, 2021.

ADDRESSES: For service information identified in this final rule, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-946-4337 (1-800-Winged-S); email wcs_cust_service_eng.gr-sik@lmco.com. Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood

Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0792.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0792; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Dorie Resnik, Aerospace Engineer, Boston ACO Branch, 1200 District Avenue, Burlington, Massachusetts 01803; telephone 781-238-7693; email dorie.resnik@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Sikorsky Model S-92A helicopters with certain part-numbered horizontal stabilizer assemblies (stabilizer assembly), certain part-numbered forward root fittings, or certain part-numbered stabilizer strut fittings installed. The NPRM published in the **Federal Register** on September 17, 2020 (85 FR 58007). The NPRM was prompted by seven incidents of fatigue cracks in forward root fittings. Fatigue cracking in a forward root fitting degrades the load path and increases the load on other assembly parts, particularly at the aft horizontal stabilizer attachment points.

The NPRM proposed to require establishing the life limit of certain part-numbered forward root fittings and certain part-numbered stabilizer strut fittings. The NPRM also proposed to require repetitively inspecting each stabilizer assembly attachment bolt and barrel nut set, each forward root fitting, each attachment fitting including the bolt holes and fastener holes, condition of the fasteners, and each attachment fitting mating surface. Depending on the inspection results, the NPRM proposed to require removing parts from service. Finally, the NPRM proposed to prohibit

installing certain stabilizer assemblies on any helicopter. The FAA is issuing this AD to address the unsafe condition on these products.

Comments

The FAA gave the public the opportunity to participate in developing this final rule, but the FAA did not receive any comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed.

Related Service Information under 14 CFR Part 51

The FAA reviewed S-92 Maintenance Manual, SA S92A-AMM-000, Temporary Revision (TR) 55-33, dated March 24, 2020 (TR 55-33), which adds additional part numbers (P/Ns) to the Horizontal Stabilizer—Maintenance Practices and specifies procedures for inspecting each forward root fitting and aft root fitting bolt holes and fasteners, each forward and aft root fitting mating surface for wear of the abrasion-resistant Teflon coating, procedures for chemically stripping the abrasion-resistant Teflon coating from the entire mounting pad, applying alodine, and applying an abrasion-resistant Teflon coating. This service information also describes procedures for removing and installing a stabilizer (Tasks 55-11-01-900-001 and 55-11-01-900-002), checking the torque stabilization (Task 55-11-01-280-001), and inspecting the stabilizer and attaching hardware (Task 55-11-01-210-004). This service information also provides assembly diagrams and lists interchangeable stabilizer P/Ns and compatible strut P/Ns.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA also reviewed S-92 Maintenance Manual SA S92A-AWL-000, TR No. 4-58, dated October 2, 2017 (TR 4-58), and S-92 Maintenance Manual SA S92A-AWL-000, TR No. 4-66 dated November 20, 2019 (TR 4-66). This service information revises Task 4-00-00-200-000, Table 1 Replacement Schedule, dated November 30, 2015. Both TR 4-58 and 4-66 revise the Airworthiness Limitations Schedule by removing certain part-numbered components, introducing new part-