

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

■ a. Removing Airworthiness Directive (AD) 2016–07–14, Amendment 39–18459 (81 FR 21244, April 11, 2016), and

■ b. Adding the following new AD:

**2020–26–15 Airbus SAS:** Amendment 39–21370; Docket No. FAA–2020–0858; Project Identifier MCAI–2020–00949–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective February 2, 2021.

#### (b) Affected ADs

This AD replaces AD 2016–07–14, Amendment 39–18459 (81 FR 21244, April 11, 2016) (AD 2016–07–14).

#### (c) Applicability

This AD applies to Airbus SAS airplanes specified in paragraphs (c)(1) through (3) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020–0153, dated July 10, 2020 (EASA AD 2020–0153).

(1) Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes.

(2) Model A320–211, –212, –214, –216, –231, –232, and –233 airplanes.

(3) Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Reason

This AD was prompted by fatigue testing that determined that fatigue damage could appear on clips, shear webs, and angles at certain rear fuselage sections and certain frames. The FAA is issuing this AD to address fatigue damage on the clips, shear

webs, and angles, which could affect the structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020–0153.

#### (h) Exceptions to EASA AD 2020–0153

The “Remarks” section of EASA AD 2020–0153 does not apply to this AD.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email [Sanjay.Ralhan@faa.gov](mailto:Sanjay.Ralhan@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0153, dated July 10, 2020.

(ii) [Reserved]

(3) For EASA AD 2020–0153, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0858.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 11, 2020.

**Lance T. Gant, Director,**  
*Compliance & Airworthiness Division,*  
*Aircraft Certification Service.*

[FR Doc. 2020–28858 Filed 12–28–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–0781; Product Identifier 2018–CE–045–AD; Amendment 39–21369; AD 2020–26–14]

RIN 2120–AA64

#### Airworthiness Directives; Mitsubishi Heavy Industries, Ltd. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 75–16–20, which applied to all Mitsubishi Heavy Industries, Ltd., Model MU–2B, MU–2B–10, MU–2B–15, MU–2B–20, MU–2B–25, MU–2B–26, MU–2B–30, MU–2B–35, and MU–2B–36 airplanes. AD 75–16–20 required repetitive inspections of the propeller pitch control (PPC) lever for security and proper rigging. This AD requires

modification and repetitive inspections of the PPC lever linkage. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective February 2, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of February 2, 2021.

**ADDRESSES:** For Mitsubishi service information identified in this final rule, contact Mitsubishi Heavy Industries America, Inc., c/o Turbine Aircraft Services, Inc., 4550 Jimmy Doolittle Drive, Addison, Texas 75001; phone: (972) 248-3108, ext. 209; fax: (972) 248-3321; website: <https://mu-2aircraft.com>. For Honeywell service information identified in this final AD, contact Honeywell International Inc., 111 S 34th Street, Phoenix, Arizona 85034-2802; phone: 855-808-6500; email: [AeroTechSupport@honeywell.com](mailto:AeroTechSupport@honeywell.com); website: <https://aerospace.honeywell.com/en/services/maintenance-and-monitoring>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0781.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0781; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** John Turner, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Parkway, Fort Worth, Texas 76177; phone: (817) 222-4508; fax: (817) 222-5245; email: [johh.r.turner@faa.gov](mailto:johh.r.turner@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 75-16-20, Amendment 39-2294 (40 FR 31751, July 29, 1975) (AD 75-16-20). AD 75-16-20 applied to all Mitsubishi Heavy Industries, Ltd. (Mitsubishi) Models MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, MU-2B-26, MU-2B-30, MU-2B-35, and MU-2B-36 airplanes. The NPRM published in the **Federal Register** on August 25, 2020 (85 FR 52281). The NPRM was prompted by reports of the PPC lever linkages disconnecting at the engine and Mitsubishi developing a secondary retention feature to secure the PPC. The NPRM was also prompted by Mitsubishi type certificating additional airplanes that are subject to the unsafe condition. In the NPRM, the FAA proposed to require installation of the secondary retention feature, repetitive inspections of the PPC lever linkage, and reporting inspection results to the FAA.

**Comments**

The FAA received no comments on the NPRM or on the determination of the costs.

**Conclusion**

The FAA reviewed the relevant data and determined that air safety requires adoption of the AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these

products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

Mitsubishi has issued MU-2 Service Recommendation No. 049/76-002, dated June 29, 2018, and MU-2 Service Recommendation No. 080, dated June 29, 2018. This service information specifies procedures for installing a PPC lever secondary retention feature to secure the PPC lever. These documents are distinct since they apply to different airplane models and configurations.

Mitsubishi has also issued MU-2 Service Bulletin No. 106/76-004, dated February 24, 2016, and MU-2 Service Bulletin No. 244, dated December 25, 2015. This service information specifies procedures for replacing the PPC lever clamping bolt. These documents are distinct since they apply to different airplane models and configurations.

Honeywell International Inc. has issued Service Bulletin TPE331-72-2190, Revision 0, dated December 21, 2011. The procedures in this service information include instructions for incorporating a threaded hole in the splined end of the shouldered shaft of the PPC assembly and re-identifying the shouldered shaft part number. The threaded hole is used to accommodate a secondary retention method to secure the PPC lever.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

**Costs of Compliance**

The FAA estimates that this AD affects 260 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD. The average labor rate is \$85 per work hour.

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification .....	2 work-hours × \$85 per hour = \$170	\$2	\$172 .....	\$44,720.
Repetitive inspections .....	1 work-hour × \$85 per hour = \$85 per inspection cycle.	0	\$85 per inspection cycle ....	\$22,100 per inspection cycle.

The FAA estimates the following costs to do any necessary on-condition actions for the incorporation of the

threaded hole and reporting requirement. The FAA has no way of

determining the number of aircraft that might need these on-condition actions:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Incorporation of threaded hole .....	4 work-hours × \$85 per hour = \$340 .....	\$1,000	\$1,340

ON-CONDITION COSTS—Continued

Action	Labor cost	Parts cost	Cost per product
Reporting .....	1 work-hour × \$85 per hour = \$85 .....	0	85

If the PPC lever detaches, the necessary corrective actions could vary significantly from airplane to airplane. The FAA has received no definitive data that would enable estimating the cost to install the PPC lever on each airplane or the number of airplanes that may require this action.

**Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an

unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive 75-16-20, Amendment 39-2294 (40 FR 31751, July 29, 1975); and
  - b. Adding the following new airworthiness directive:

**2020-26-14 Mitsubishi Heavy Industries, Ltd.:** Amendment 39-21369; Docket No. FAA-2020-0781; Product Identifier 2018-CE-045-AD.

**(a) Effective Date**

This airworthiness directive (AD) is effective February 2, 2021.

**(b) Affected ADs**

This AD replaces AD 75-16-20, Amendment 39-2294 (40 FR 31751, July 29,

1975) (AD 75-16-20).

**(c) Applicability**

This AD applies to all Mitsubishi Heavy Industries, Ltd. (Mitsubishi) Models MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, MU-2B-26, MU-2B-26A, MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, MU-2B-40, and MU-2B-60 airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 61: Propellers.

**(e) Reason**

This AD was prompted by propeller pitch control (PPC) lever linkages disconnecting at the engine. The FAA is issuing this AD to address the PPC lever linkage from disconnecting at the engine, which could lead to the inability to control the propeller pitch with the power lever in the cockpit and consequent loss of control of the engine power settings.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Modification**

(1) For all airplanes except Model MU-2B and MU-2B-10 airplanes: Within 100 hours time-in-service (TIS) after the effective date of this AD or within 12 months after the effective date of this AD, whichever occurs first, modify the PPC lever linkage as specified in paragraphs (g)(1)(i) through (iii) of this AD, as applicable.

(i) Replace the PPC lever clamping bolt in accordance with the Accomplishment Instructions, section 2, of Mitsubishi MU-2 Service Bulletin No. 106/76-004, dated February 24, 2016, or Mitsubishi MU-2 Service Bulletin No. 244, dated December 25, 2015, as applicable to your model airplane.

(ii) For airplanes without a threaded hole in the splined end of the shouldered shaft of the PPC assembly, incorporate a threaded hole in accordance with the Accomplishment Instructions, paragraph 3.C.(3)(d)2, of Honeywell International Inc. Service Bulletin TPE331-72-2190, Revision 0, dated December 21, 2011.

(iii) Install a secondary retention feature in the threaded end of the PPC input shaft in accordance with the Accomplishment Instructions, section 2, of Mitsubishi MU-2 Service Recommendation No. 049/76-002, dated June 29, 2018, or Mitsubishi MU-2 Service Recommendation No. 080, dated June 29, 2018, as applicable to your model airplane.

(2) For Model MU-2B and MU-2B-10 airplanes: Within 100 hours TIS after the effective date of this AD or within 12 months after the effective date of this AD, whichever

occurs first, replace the PPC lever clamping bolt and install a secondary retention feature in the threaded end of the PPC input shaft using a method approved by the Manager of the Fort Worth ACO Branch, FAA. The Manager's approval letter must specifically refer to this AD.

#### (h) Repetitive Inspections and Reporting

Within 100 hours TIS after replacing the bolt and installing a secondary retention feature as required by paragraph (g) of this AD and thereafter at intervals not to exceed 100 hours TIS, inspect the security of the PPC lever by pulling the PPC lever upward by hand to ensure it does not detach from the PPC input shaft. If the PPC lever detaches, do the following.

(1) Before further flight, install the PPC lever using a method approved by the Manager of the Fort Worth ACO Branch, FAA. The Manager's approval letter must specifically refer to this AD.

(2) Within 30 days after the PPC lever detachment or within 30 days after the effective date of this AD, whichever occurs later, report the results of the inspection, including airplane model and serial number, to the FAA representative identified in paragraph (l)(2) of this AD.

#### (i) Special Flight Permit

(1) Special flight permits may be issued for the purpose of operating the airplane to a location where the requirements of paragraph (g) of this AD can be performed with the following limitations: Flights must not carry passengers, must operate in daytime visual meteorological conditions only, and must not operate in areas of known turbulence.

(2) Special flight permits may be issued for the purpose of operating the airplane to a location where the requirements of paragraph (h) of this AD may be performed without limitations.

#### (j) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD; the nature and extent of confidentiality to be provided, if any. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

#### (k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Fort Worth ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Fort Worth ACO Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Japan Civil Aviation Bureau (JCAB) AD No. TCD-8678-2016, dated February 5, 2016, for related information. This MCAI may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0781.

(2) For more information about this AD, contact John Turner, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Parkway, Fort Worth, Texas 76177; phone: (817) 222-4508; fax: (817) 222-5245; email: [johh.r.turner@faa.gov](mailto:johh.r.turner@faa.gov).

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Honeywell International Inc. Service Bulletin TPE331-72-2190, Revision 0, dated December 21, 2011.

(ii) Mitsubishi MU-2 Service Bulletin No. 244, dated December 25, 2015.

(iii) Mitsubishi MU-2 Service Bulletin No. 106/76-004, dated February 24, 2016.

(iv) Mitsubishi MU-2 Service Recommendation No. 049/76-002, dated June 29, 2018.

(v) Mitsubishi MU-2 Service Recommendation No. 080, dated June 29, 2018.

(3) For Mitsubishi service information identified in this AD, contact Mitsubishi Heavy Industries America, Inc., c/o Turbine Aircraft Services, Inc., 4550 Jimmy Doolittle Drive, Addison, Texas 75001; phone: (972) 248-3108, ext. 209; fax: (972) 248-3321; website: <https://mu-2aircraft.com>.

(4) For Honeywell service information identified in this AD, contact Honeywell International Inc., 111 S 34th Street, Phoenix, Arizona 85034-2802; phone: 855-808-6500; email: [AeroTechSupport@honeywell.com](mailto:AeroTechSupport@honeywell.com); website: <https://aerospace.honeywell.com/en/services/maintenance-and-monitoring>.

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 11, 2020.

**Lance T. Gant, Director,**  
Compliance & Airworthiness Division,  
Aircraft Certification Service.

[FR Doc. 2020-28855 Filed 12-28-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2020-0750; Airspace  
Docket No. 20-ACE-17]

RIN 2120-AA66

#### Amendment of the Class E Airspace; Trenton, MO

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends the Class E airspace extending upward from 700 feet above the surface at Trenton Municipal Airport, Trenton, MO. This action is the result of an airspace review caused by the decommissioning of the Trenton non-directional beacon (NDB) navigation information to the instrument procedures at this airport. The geographic coordinates of the airport are also being updated to coincide with the FAA's aeronautical database. Airspace redesign is necessary for the safety and management of instrument flight rules (IFR) operations at this airport.

**DATES:** Effective 0901 UTC, February 25, 2021. Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and