

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-02-15 The Boeing Company:
Amendment 39-21398; Docket No. FAA-2020-0211; Product Identifier 2020-NM-006-AD.

(a) Effective Date

This airworthiness directive (AD) is effective March 30, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of inboard foreflap departures from the airplane. The FAA is issuing this AD to address departures of the inboard foreflap assembly from the airplane, which could result in damage to the airplane and adversely affect the airplane's continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 747-57A2367, dated November 15, 2019, which is referred to in Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019.

(h) Exceptions to Service Information Specifications

Where Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019, uses the phrase "the original issue date of Requirements Bulletin 747-57A2367 RB," this AD requires using "the effective date of this AD."

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3523; email: eric.lin@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 747-57A2367 RB, dated November 15, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 14, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-03593 Filed 2-22-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-0691; Product Identifier 2020-NM-064-AD; Amendment 39-21377; AD 2021-01-01]

RIN 2120-AA64

Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This AD was prompted by evidence that a revised structural life limit of some components of the nose landing gear (NLG) and/or main landing gear (MLG) was not implemented during repair. This AD requires verifying that the affected components are installed on the airplane, revising the structural life limits in the existing structural deviation inspection requirements (SDIR) airplane document, and replacing affected components if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 30, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 30, 2021.

ADDRESSES: For service information identified in this final rule, contact MHI

RJ Aviation ULC, 12655 Henri-Fabre Blvd., Mirabel, Québec J7N 1E1, Canada; Widebody Customer Response Center North America toll-free telephone +1-844-272-2720 or direct-dial telephone +1-514-855-8500; fax +1-514-855-8501; email *thd.crj@mhjr.com*; internet *https://mhjr.com*. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at *https://www.regulations.gov* by searching for and locating Docket No. FAA-2020-0691.

Examining the AD Docket

You may examine the AD docket on the internet at *https://www.regulations.gov* by searching for and locating Docket No. FAA-2020-0691; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email *9-avs-nyaco-cos@faa.gov*.

SUPPLEMENTARY INFORMATION:

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2020-09, dated April 7, 2020 (also

referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. You may examine the MCAI in the AD docket on the internet at *https://www.regulations.gov* by searching for and locating Docket No. FAA-2020-0691.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The NPRM published in the **Federal Register** on October 5, 2020 (85 FR 62626). The NPRM was prompted by evidence that a revised structural life limit of some components of the NLG and/or MLG was not implemented during repair. The NPRM proposed to require verifying that the affected components are installed on the airplane, revising the structural life limits in the existing SDIR airplane document, and replacing affected components if necessary. The FAA is issuing this AD to address structural life limits that are lower than the life limit published in the Maintenance Requirements Manual (MRM), Part 2. This condition, if not corrected, could lead to the collapse of the affected NLG and/or MLG, possibly resulting in airplane damage and injury to the occupants. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. Air Line Pilots Association, International (ALPA) stated that it supports the NPRM.

Additional Change Made to This AD

This AD has been revised to provide the revised structural life limits in figure

1 to paragraph (h) of this AD instead of referencing the individual repair engineering orders (REOs) in paragraph (h) of this AD. The REOs did not meet the Office of the Federal Register’s criteria for incorporation by reference.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 601R-32-112, dated November 11, 2019. This service information describes procedures for verifying that affected components are installed on the airplane, revising the structural life limits in the existing SDIR airplane document, and replacing affected parts if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 456 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 143 work-hours × \$85 per hour = Up to \$12,155	Up to \$103,114	Up to \$115,269	Up to \$52,562,664.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a

substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–01–01 MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.): Amendment 39–21377; Docket No. FAA–2020–0691; Product Identifier 2020–NM–064–AD.

(a) Effective Date

This airworthiness directive (AD) is effective March 30, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to MHI RJ Aviation ULC (type certificate previously held by Bombardier, Inc.) Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 through 8999 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by evidence that a revised structural life limit of some components of the nose landing gear (NLG) and/or main landing gear (MLG) was not implemented during repair. The FAA is issuing this AD to address structural life limits that are lower than the life limits published in the Maintenance Requirements Manual (MRM), Part 2. This condition, if not

corrected, could lead to the collapse of the affected NLG and/or MLG, possibly resulting in airplane damage and injury to the occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Verification of Airplane or Technical Records

Within 6 months from the effective date of this AD: Verify the airplane or technical records to determine if an NLG or MLG component listed in Table 1 or Table 2 of Bombardier Service Bulletin 601R–32–112, dated November 11, 2019, is installed on the airplane. If this verification determines that an affected component listed in Table 1 or Table 2 of Bombardier Service Bulletin 601R–32–112, dated November 11, 2019, is installed on the airplane, perform the actions specified in paragraph (h) or (i) of this AD, as applicable.

(h) Incorporation of the Structural Deviation Inspection Requirements (SDIR) Life Limit Into the Existing SDIR Airplane Document

If the total flight cycles of the component is less than the revised SDIR life limit identified in figure 1 to paragraph (h) of this AD minus 2,000 flight cycles: Within 12 months after completing the actions specified in paragraph (g) of this AD, incorporate the applicable revised life limit of the affected component into the existing SDIR airplane document as specified in figure 1 to paragraph (h) of this AD.

BILLING CODE 4910–13–P

Figure 1 to paragraph (h) – Revised SDIR Life Limits

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-086, Revision A, dated October 29, 2015	MLG Axle (P/N 17050-1)	73,644	47,026 ^[1]	73,644	47,026 ^[1]	^[1] HAAO – Post Modsum TC601R15827 aircraft only
601R-32-11-089, Revision A, dated October 29, 2015	MLG Axle (P/N 17050-1)	73,644	47,026 ^[1]	73,644	47,026 ^[1]	^[1] HAAO – Post Modsum TC601R15827 aircraft only
601R-32-11-183, Revision B, dated January 15, 2013	MLG Pintle Pin (P/N 17040-1)	57,760	55,645 ^[1]	47,840	46,088 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0367, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	^[2]	^{[1][2]}	^[1] HAAO – Post-Modsum TC601R15827 aircraft only ^[2] Structure life limits for ATA NO. 32- 11-118 specified in Part 2 of maintenance requirements manual still apply for 53,000 lbs. MTOW
601R-32-11-0627, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	43,240	41,650 ^[1]	34,930	33,650 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-0630, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	57,760	55,645 ^[1]	47,840	46,088 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-634, Revision A, dated October 29, 2015	MLG Axle (P/N 17050-1)	73,644	47,026 ^[1]	73,644	47,026 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0712, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	^[2]	^{[1][2]}	^[1] HAAO – Post-Modsum TC601R15827 aircraft only ^[2] Structure life limits for ATA NO. 32- 11-118 specified in Part 2 of maintenance requirements manual still apply for 53,000 lbs. MTOW
601R-32-11-0783, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	57,760	55,645 ^[1]	47,840	46,088 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-786, Revision A, dated January 23, 2019	MLG Pintle Pin (P/N 17040-1)	43,240	41,650 ^[1]	34,930	33,650 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-835, Revision A, dated October 29, 2015	MLG Axle (P/N 17050-1)	73,644	47,026 ^[1]	73,644	47,026 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0913, Revision C, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	74,200 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-918, Revision B, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	48,190	46,425 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-921, Revision A, dated October 29, 2015	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	74,026	67,976 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0951, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0955, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-956, Revision A, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	43,240	41,240 ^[1]	34,930	33,650 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-0958, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1017, Revision B, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	^[2]	^[1] ^[2]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only ^[2] Structure life limits for ATA NO. 32- 11-118 specified in Part 2 of maintenance requirements manual still apply for 53,000 lbs. MTOW
601R-32-11-1041, Revision A, dated October 29, 2015	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	76,642 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-1084, Revision A, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	[2]	[1][2]	<p>^[1] HAAO – Post-Modsum TC601R15827 aircraft only</p> <p>^[2] Structure life limits for ATA NO. 32-11-118 specified in Part 2 of maintenance requirements manual still apply for 53,000 lbs. MTOW</p>
601R-32-11-1153, Revision A, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	80,000	80,000 ^[1]	[2]	[1][2]	<p>^[1] HAAO – Post-Modsum TC601R15827 aircraft only</p> <p>^[2] Structure life limits for ATA NO. 32-11-118 specified in Part 2 of maintenance requirements manual still apply for 53,000 lbs. MTOW</p>
601R-32-11-1154, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	76,642 ^[1]	<p>^[1] HAAO – Post-Modsum TC601R15827 aircraft only</p>

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-1187, Revision B, dated January 23, 2019	MLG Axle (P/N 17050-3)	80,000	71,640 ^[1]	80,000	71,640 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1206, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	74,200 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1219, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	74,200 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1220, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	74,200 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1224, Revision B, dated January 23, 2019	MLG Pivot Pin (P/N 17041-3)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1250, Revision A, dated January 15, 2014	MLG Pintle Pin (P/N 17040-1)	57,760	55,645 ^[1]	47,840	46,088 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1251, Revision B, dated January 23, 2019	MLG Pivot Pin (P/N 17041-3)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-11-1255, Revision B, dated January 23, 2019	MLG Pivot Pin (P/N 17041-3)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1286, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1302, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1650, Revision A, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-11-1673, Revision A, dated January 23, 2019	MLG Axle (P/N 17050-3)	73,644	47,026 ^[1]	73,644	47,026 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0225, Revision C, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-21-0227, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-414, Revision A, dated February 25, 2015	NLG Axle (P/N 16124- 101)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-489, Revision A, dated October 29, 2015	NLG Main Fitting (P/N 16114-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0526, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-535, Revision A, dated February 17, 2015	NLG Pin (P/N 16404-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0536, Revision B, dated January 23, 2019	NLG Axle (P/N 16124-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-21-0555, Revision B, dated January 23, 2019	NLG Axle (P/N 16124-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0557, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0562, Revision B, dated January 23, 2019	NLG Axle (P/N 16124-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-570, Revision A, dated February 25, 2015	NLG Axle (P/N 16124-1)	47,732	47,732 ^[1]	39,370	39,370 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0635, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0661, Revision B, dated January 23, 2019	NLG Main Fitting (P/N 16114-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-21-0663, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0685, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0689, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0691, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0692, Revision C, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-0693, Revision B, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

Bombardier Repair Engineering Order	Life Limited Component	DISCARD TIME/LIFE LIMIT (LANDINGS)				Notes
		51,000 lb. MTOW		53,000 lb. MTOW		
		TC/FAA Certification	TC/FAA Certification High Altitude Airfield Operation (HAAO)	TC/FAA Certification	TC/FAA Certification HAAO	
601R-32-21-1002, Revision A, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-21-1022, Revision A, dated January 23, 2019	NLG Axle (P/N 16122-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-32-0056, Revision C, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	80,000 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only
601R-32-32-0076, Revision B, dated January 23, 2019	MLG Side Stay Pin (P/N 17076-1)	80,000	80,000 ^[1]	80,000	74,200 ^[1]	^[1] HAAO – Post-Modsum TC601R15827 aircraft only

BILLING CODE 4910-13-C**(i) Replacement of Repaired NLG and/or MLG Component**

If the total flight cycles of the component is equal to or more than the applicable revised SDIR life limit specified in figure 1 to paragraph (h) of this AD minus 2,000 flight cycles: Within 12 months or 2,000 flight cycles, whichever occurs first, after completing the actions specified in paragraph (g) of this AD, replace the affected component with a serviceable component.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install any component listed in Table 1 or Table 2 of Bombardier Service Bulletin 601R-32-112, dated November 11,

2019, on any airplane without first incorporating the actions specified in paragraph (h) or (i) of this AD, as applicable.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational

Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or MHI RJ Aviation ULC's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2020-09, dated April 7, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0691.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-32-112, dated November 11, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact MHI RJ Aviation ULC, 12655 Henri-Fabre Blvd., Mirabel, Québec, J7N 1E1 Canada; Widebody Customer Response Center North America toll-free telephone +1-844-272-2720 or direct-dial telephone +1-514-855-8500; fax +1-514-855-8501; email thd.crj@mhjrj.com; internet <https://mhjrj.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 28, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-03565 Filed 2-22-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-0674; Product Identifier 2020-NM-070-AD; Amendment 39-21382; AD 2021-01-06]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A330-200 and A330-300 series airplanes, and all Model A340-200 and A340-300 series airplanes. This AD was prompted by reports of hydraulic system failure due to fatigue failure of the screws attaching the manual valve to the ground service manifold (GSM). This AD requires, for certain GSMs, repetitive replacement of the hydraulic system GSM manual valve attachment screws having certain part numbers; and, for certain other GSMs with certain screws installed, replacement of those screws, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 30, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 30, 2021.

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. For Airbus material incorporated by reference in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0674.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0674; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229; email vladimir.ulyanov@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0093, dated April 24, 2020 (EASA AD 2020-0093) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A330-200 and A330-300 series airplanes, and all Model A340-200 and A340-300 series airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A330-200 and A330-300 series airplanes, and all Model A340-200 and A340-300 series airplanes. The NPRM published in the **Federal Register** on July 31, 2020 (85 FR 46012). The NPRM was prompted by reports of hydraulic system failure due to fatigue failure of the screws attaching the manual valve to the GSM. The NPRM proposed to require, for certain GSMs, repetitive replacement of the hydraulic system GSM manual valve attachment screws having certain part numbers; and, for certain other GSMs with certain screws installed, replacement of those screws, as specified in an EASA AD.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM