

the requirements of section 801 when the agency for good cause finds that such procedure would be impracticable, unnecessary, or contrary to the public interest and the rule shall take effect at such time as the agency promulgating the rule determines. 5 U.S.C. 808(2). Pursuant to section 808(2), SBA for good cause finds that a 60-day delay to provide public notice is impracticable and contrary to the public interest. Likewise, for the same reasons, SBA for good cause finds that there are grounds to waive the 30-day effective date delay under the Administrative Procedure Act. 5 U.S.C. 553(d)(3).

The last day to apply for and receive a PPP loan is March 31, 2021. Given the short duration of this program, and the urgent need to issue loans quickly, SBA has determined that it is impractical and not in the public interest to provide a delayed effective date. An immediate effective date will give small businesses and nonprofit organizations affected by this interim final rule the maximum amount of time to apply for loans and lenders the maximum amount of time to process applications before the program ends.

Executive Order 12988

SBA has drafted this rule, to the extent practicable, in accordance with the standards set forth in section 3(a) and 3(b)(2) of Executive Order 12988, to minimize litigation, eliminate ambiguity, and reduce burden. The rule has no preemptive or retroactive effect.

Executive Order 13132

SBA has determined that this rule will not have substantial direct effects on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various layers of government. Therefore, SBA has determined that this rule has no federalism implications warranting preparation of a federalism assessment.

Paperwork Reduction Act, 44 U.S.C. Chapter 35

SBA has determined that this rule will require revisions to existing recordkeeping or reporting requirements of the Paycheck Protection Program (PPP) information collections (OMB Control Numbers 3245-0407 and 3245-0417). The revisions will affect SBA Form 2483, Borrower Application Form Revised March 3, 2021, SBA Form 2483-C, Borrower Application Form for Schedule C Filers Using Gross Income March 3, 2021, SBA Form 2483-SD, Second Draw Borrower Application Form Revised March 3, 2021, SBA Form 2483-SD-C, Second Draw Borrower

Application Form for Schedule C Filers Using Gross Income March 3, 2021, SBA Form 2484, Lender's Application—Paycheck Protection Program Loan Guaranty Revised March 3, 2021, SBA Form 2484-SD, Lender's Application—Second Draw Loan Guaranty Revised March 3, 2021, SBA Forms 2483, 2483-C, 2483-SD, and 2483-SD-C were amended to include the additional eligible entities (where applicable) and revise the Shuttered Venue Operator Grant Program certification due to the changes made by the American Rescue Plan Act. Other clarifying changes were also made to the forms. Additionally, conforming changes were made to SBA Forms 2484 and 2484-SD.

SBA has requested Office of Management and Budget (OMB) emergency approval of the revisions to the information collections to give small businesses and nonprofits affected by this interim final rule the maximum amount of time to apply for loans and lenders the maximum amount of time to process applications before the program ends.

Regulatory Flexibility Act (RFA)

The Regulatory Flexibility Act (RFA) generally requires that when an agency issues a proposed rule, or a final rule pursuant to section 553(b) of the Administrative Procedure Act or another law, the agency must prepare a regulatory flexibility analysis that meets the requirements of the RFA and publish such analysis in the **Federal Register**. 5 U.S.C. 603, 604.

Rules that are exempt from notice and comment are also exempt from the RFA requirements, including conducting a regulatory flexibility analysis, when among other things the agency for good cause finds that notice and public procedure are impracticable, unnecessary, or contrary to the public interest. SBA Office of Advocacy guide: How to Comply with the Regulatory Flexibility Act, Ch.1. p.9. Since this rule is exempt from notice and comment, SBA is not required to conduct a regulatory flexibility analysis.

Authority: 15 U.S.C. 636(a)(36); 15 U.S.C. 636(a)(37); 15 U.S.C. 636m; Coronavirus Aid, Relief, and Economic Security Act, Pub. L. 116-136, section 1114, Economic Aid to Hard-Hit Small Businesses, Nonprofits, and Venues Act (Pub. L. 116-260), section 303, and American Rescue Plan Act of 2021, sections 5001 and 5005.

James Rivera,

Acting Administrator, Small Business Administration.

[FR Doc. 2021-05930 Filed 3-18-21; 4:15 pm]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0971; Product Identifier 2020-NM-083-AD; Amendment 39-21453; AD 2021-05-10]

RIN 2120-AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. This AD was prompted by a report that threaded fuel couplings were incorrectly installed at final assembly and in service. This AD requires repetitive functional tests of the auxiliary power unit (APU) fuel feed line shroud, a general visual inspection of the APU fuel feed line shroud for any loose couplings; and tightening any loose couplings, which would terminate the repetitive functional tests. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 26, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 26, 2021.

ADDRESSES: For service information identified in this final rule, contact Airbus Canada Limited Partnership, 13100 Henri-Fabre Boulevard, Mirabel, Québec J7N 3C6, Canada; telephone 450-476-7676; email a220_crc@abc.airbus; internet <http://a220world.airbus.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0971.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-

0971; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2020-14, dated April 30, 2020 (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0971.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. The NPRM published in the **Federal Register** on October 28, 2020 (85 FR 68257). The NPRM was prompted by a report that threaded fuel couplings were incorrectly installed at final assembly and in service. The NPRM proposed to require repetitive functional tests of the APU fuel feed line shroud, a general visual inspection of the APU feed line shroud for any loose couplings; and tightening any loose couplings, which would terminate the repetitive functional tests. The FAA is issuing this AD to address loose fuel couplings, which could eventually disconnect and could lead to fuel starvation of the APU and pose a risk of fire. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. The Air Line Pilots Association, International (ALPA) stated that it supports the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this

final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Airbus Canada has issued Service Bulletin BD500-282009, Issue 003, dated August 14, 2020. This service information describes procedures for repetitive functional tests of the APU fuel feed line shroud, a general visual inspection of the APU fuel feed line shroud for any loose couplings, and tightening of any loose couplings if necessary. The inspection and tightening of the APU fuel feed line shroud couplings terminates the repetitive functional tests of the APU fuel feed line shroud.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 22 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 42 work-hours × \$85 per hour = Up to \$3,570	\$0	Up to \$3,570	Up to \$78,540.

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
8 work-hours × \$85 per hour = \$680	\$0	\$680

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on

the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-05-10 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39-21453; Docket No. FAA-2020-0971; Product Identifier 2020-NM-083-AD.

(a) Effective Date

This airworthiness directive (AD) is effective April 26, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (type certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) airplanes, certificated in any category, as identified in paragraphs (c)(1) and (2) of this AD.

(1) Model BD-500-1A10 airplanes, serial numbers 50010 through 50018 inclusive, and 50020 through 50041 inclusive.

(2) Model BD-500-1A11 airplanes, serial numbers 55003 through 55016 inclusive, 55018 through 55054 inclusive, and 55056.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a report that threaded fuel couplings were incorrectly installed at final assembly and in service. The FAA is issuing this AD to address loose fuel couplings, which could eventually disconnect and could lead to fuel starvation of the auxiliary power unit (APU) and pose a risk of fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Functional Test of the APU Fuel Feed Line Shroud

Within 4,000 flight hours after the effective date of this AD, do an initial functional test of the APU fuel feed line shroud, in accordance with Part A of the Accomplishment Instructions of Airbus Canada Service Bulletin BD500-282009, Issue 003, dated August 14, 2020. Thereafter, repeat the functional test at intervals not to exceed 4,000 flight hours. If any functional test reveals a leak, before further flight, do the applicable actions specified in paragraph (h) of this AD.

(h) Inspection and Torque of APU Fuel Feed Line Shroud Couplings

(1) Except as required by paragraph (g) of this AD: Within 9,350 flight hours or 56 months, whichever occurs first after the effective date of this AD: Do a general visual inspection of the APU fuel feed line shroud for any loose couplings, and tighten any loose couplings as applicable, in accordance with Part B of the Accomplishment Instructions of Airbus Canada Service Bulletin BD500-282009, Issue 003, dated August 14, 2020.

(2) For airplanes on which the inspection and tightening of the APU fuel feed line shroud couplings was done before the effective date of this AD, using Part B of the Accomplishment Instructions of Airbus Canada Service Bulletin BD500-282009, Issue 001, dated December 13, 2019: Within 9,350 flight hours or 56 months, whichever occurs first after the effective date of this AD, do a general visual inspection of the APU fuel feed line shroud for any loose couplings between frame (FR) 63 and FR 80, and tighten any loose couplings as applicable, in accordance with Part C of the Accomplishment Instructions of Airbus Canada Service Bulletin BD500-282009, Issue 003, dated August 14, 2020.

(i) Terminating Action for the Functional Tests

The inspection and tightening of the APU fuel feed line shroud couplings as specified in paragraph (h) of this AD terminate the initial and repetitive functional tests of the APU fuel feed line shroud specified in paragraph (g) of this AD.

(j) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Airbus Canada Service Bulletin BD500-282009, Issue 001,

dated December 13, 2019, or Airbus Canada Service Bulletin BD500-282009, Issue 002, dated March 18, 2020, provided the functional test is repeated at intervals not to exceed 4,000 flight hours from the completion of those actions specified in paragraph (g) of this AD.

(2) This paragraph provides credit for actions required by paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD using Airbus Canada Service Bulletin BD500-282009, Issue 001, dated December 13, 2019.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Airbus Canada Limited Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF-2020-14, dated April 30, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0971.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyacos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Canada Service Bulletin BD500–282009, Issue 003, dated August 14, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Canada Limited Partnership, 13100 Henri-Fabre Boulevard, Mirabel, Québec J7N 3C6, Canada; telephone 450–476–7676; email a220_crc@abc.airbus.com; internet <http://a220world.airbus.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 21, 2021.

Ross Landes,

Deputy Director for Regulatory Operations,
Compliance & Airworthiness Division,
Aircraft Certification Service.

[FR Doc. 2021–05583 Filed 3–19–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–1115; Product Identifier MCAI–2020–01230–T; Amendment 39–21455; AD 2021–05–12]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A330–200 Freighter series airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 26, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 26, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1115.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1115; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229; email vladimir.ulyanov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020–0190, dated August 27, 2020 (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI) (EASA AD 2020–0190), to correct an unsafe condition for all Airbus SAS Model A330–200 Freighter series airplanes, and Model A340–213 and –313 airplanes. EASA AD 2020–0190 refers to Airbus A330 Airworthiness Limitations Section (ALS) Part 1, Variation 10.2, dated June 29, 2020. Airplanes with an original airworthiness certificate or original export certificate of airworthiness

issued after June 29, 2020 must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A330–200 Freighter series airplanes. The NPRM published in the **Federal Register** on December 10, 2020 (85 FR 79440). The NPRM was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2020–0190.

The FAA is issuing this AD to address fatigue cracking, accidental damage, or corrosion in principal structural elements, and possible failure of certain life limited parts, which could result in reduced structural integrity of the airplane. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

EASA AD 2020–0190 describes new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 6 airplanes of U.S. registry. The