

appointed as conservator or receiver under 12 U.S.C. 4617.

(b) *No private right of action.* Nothing in this part creates or is intended to create a private right of action based on a resolution plan prepared or submitted under this part or based on any action taken by FHFA with respect to any resolution plan submitted under this part.

Mark A. Calabria,

Director, Federal Housing Finance Agency.

[FR Doc. 2021-09287 Filed 5-3-21; 8:45 am]

BILLING CODE 8070-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1169; Project Identifier MCAI-2020-01373-T; Amendment 39-21526; AD 2021-09-12]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2020-07-16, which applied to certain Dassault Aviation Model FALCON 7X airplanes. AD 2020-07-16 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations; as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 8, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 8, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of May 18, 2020 (85 FR 20405, April 13, 2020).

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact

EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1169.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1169; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226; email tom.rodriguez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0214, dated October 6, 2020 (EASA AD 2020-0214) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Dassault Aviation Model FALCON 7X airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2020-07-16 Amendment 39-19895 (85 FR 20405, April 13, 2020) (AD 2020-07-16). AD 2020-07-16 applied to certain Dassault Aviation Model FALCON 7X airplanes. The NPRM published in the **Federal Register** on January 15, 2021 (86 FR 3879). The NPRM was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing

maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2020-0214.

The FAA is issuing this AD to address reduced structural integrity and reduced control of airplanes due to the failure of system components. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. One commenter indicated support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related IBR Material Under 14 CFR Part 39

EASA AD 2020-0214 describes new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This AD also requires EASA AD 2019-0257, dated October 17, 2019, which the Director of the Federal Register approved for incorporation by reference as of May 18, 2020 (85 FR 20405, April 13, 2020).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 122 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA estimates the total cost per operator for the retained actions from AD 2020-07-16 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate

is more accurate than a per-airplane estimate. The FAA estimates the total cost per operator for the new actions to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing airworthiness directive 2020–07–16, Amendment 39–19895 (85 FR 20405, April 13, 2020); and
 - b. Adding the following new airworthiness directive:

2021–09–12 Dassault Aviation:

Amendment 39–21526; Docket No. FAA–2020–1169; Project Identifier MCAI–2020–01373–T.

(a) Effective Date

This airworthiness directive (AD) is effective June 8, 2021.

(b) Affected ADs

- (1) This AD replaces AD 2020–07–16, Amendment 39–19895 (85 FR 20405, April 13, 2020) (AD 2020–07–16).
- (2) This AD affects AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014) (AD 2014–16–23).

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 1, 2020.

Note 1 to paragraph (c): Model FALCON 7X airplanes with modification M1000 incorporated are commonly referred to as "Model FALCON 8X" airplanes as a marketing designation.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity and reduced control of airplanes due to the failure of system components.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Maintenance or Inspection Program Revision, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2020–07–16, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 1, 2019, except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0257, dated October 17, 2019 (EASA AD 2019–0257).

(h) Retained Exceptions to EASA AD 2019–0257, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2020–07–16 with no

changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 1, 2019:

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2019–0257 do not apply to this AD.

(2) Where paragraph (3) of EASA AD 2019–0257 specifies a compliance time of "Within 12 months" after its effective date to "revise the approved AMP [Aircraft Maintenance Program]," this AD requires "revising the existing maintenance or inspection program, as applicable" to incorporate the "limitations, tasks and associated thresholds and intervals" specified in paragraph (3) of EASA AD 2019–0257 within 90 days after May 18, 2020 (the effective date of AD 2020–07–16).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2019–0257 is at the applicable "associated thresholds" specified in paragraph (3) of EASA AD 2019–0257, or within 90 days after May 18, 2020 (the effective date of AD 2020–07–16), whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2019–0257 do not apply to this AD.

(5) The "Remarks" section of EASA AD 2019–0257 does not apply to this AD.

(i) Retained Provisions for Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs) With a New Exception

This paragraph restates the requirements of paragraph (k) of AD 2020–07–16, with a new exception. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 1, 2019, except as required by paragraph (j) of this AD, after the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2019–0257.

(j) New Maintenance or Inspection Program Revision

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020–0214, dated October 6, 2020 (EASA AD 2020–0214). Accomplishing the maintenance or inspection program revision required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2020–0214

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2020–0214 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2020–0214 specifies revising "the approved AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the "limitations, tasks and associated thresholds and intervals" specified in paragraph (3) of EASA

AD 2020–0214 within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2020–0214 is at the applicable “associated thresholds” specified in paragraph (3) of EASA AD 2020–0214, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2019–0257 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2020–0214 does not apply to this AD.

(l) New Provisions for Alternative Actions, Intervals, and CDCCLs

After the maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs are allowed except as specified in the provisions of the “Ref. Publications” section of EASA AD 2020–0214.

(m) Terminating Action for Certain Requirements in AD 2014–16–23

Accomplishing the actions required by paragraphs (g) or (j) of this AD terminates the requirements of paragraph (q) of AD 2014–16–23.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (o) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226; email tom.rodriguez@faa.gov.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference

(IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 8, 2021.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0214, dated October 6, 2020.

(ii) [Reserved]

(4) The following service information was approved for IBR on May 18, 2020 (85 FR 20405, April 13, 2020).

(i) European Union Aviation Safety Agency (EASA) AD 2019–0257, dated October 17, 2019.

(ii) [Reserved]

(5) For EASA AD 2020–0214, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1169.

(7) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 21, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–08852 Filed 5–3–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0789; Project Identifier AD–2020–00849–T; Amendment 39–21519; AD 2021–09–06]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2019–22–10, which applied to all The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series

airplanes. AD 2019–22–10 required repetitive inspections for cracking of the left- and right-hand side outboard chords of frame fittings and failsafe straps at a certain station around eight fasteners, and repair if any cracking is found. For certain airplanes, this AD reduces the compliance time for the initial inspection, and for all airplanes this AD reduces the repetitive interval. This AD was prompted by a determination that the initial inspection threshold and repetitive inspection interval are inadequate to address the cracking in a timely manner. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 8, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 8, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of November 13, 2019 (84 FR 61533, November 13, 2019).

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of October 3, 2019 (84 FR 52754, October 3, 2019).

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0789.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0789; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.