

cycles per hour TIS, the IFWU assembly is an REL IFWU assembly.

(i) If any calculation specified in paragraph (h)(2) of this AD results in 6 or less lift cycles per hour TIS, the IFWU assembly is a Non-REL IFWU assembly.

Note 1 to paragraph (h)(2): Sikorsky Aircraft Corporation All Operators Letter (AOL) CCS-61-AOL-04-0005, dated May 18, 2004, provides an example and additional information about tracking cycles and the moving average procedure.

Note 2 to paragraph (h)(2): The following is a sample calculation for subsequent 50 hour TIS intervals. Assume the total number of lift cycles for the first 50 hour TIS interval used in the previous moving average calculation = 450 lift cycles and the total number of lift cycles for the previous 300 hours TIS = 2,700 lift cycles. The subsequent moving average of lift cycles per hour TIS = $(2,700 - 450) / 250 = 9$ lift cycles per hour TIS.

(3) Once an IFWU assembly is determined to be an REL IFWU assembly, it remains an REL IFWU assembly for the rest of its service life and is subject to the inspection for REL IFWU assemblies required by paragraph (i) of this AD.

(4) Once an IFWU assembly is determined to be an REL IFWU assembly, you no longer need to perform the 250-hour TIS moving average calculation required by paragraph (h)(2) of this AD, but you must continue to count and record the lift cycles as required by paragraph (g)(2) of this AD.

(i) Repetitive Inspections of REL IFWU Assemblies and Replacement

For each REL IFWU assembly, as determined by paragraph (h)(1) or (2) of this AD:

(1) Within 500 hours TIS or 7,500 lift cycles, whichever occurs first since the assembly was determined to be a REL IFWU assembly, and thereafter at intervals not to exceed 500 hours TIS or 7,500 lift cycles, whichever occurs first, inspect for wear, surface distress, and endplay by following paragraphs B.(1) through B.(6) of the Accomplishment Instructions of Sikorsky Aircraft Corporation Alert Service Bulletin 61B35-67B, Revision B, dated August 11, 2003. Record all the information specified in Figures 1 through 3 of the Sikorsky Aircraft Corporation Alert Service Bulletin 61B35-67B, Revision B, dated August 11, 2003. You may record this information on any suitable maintenance record, or you may use the Sikorsky evaluation forms provided in Sikorsky Aircraft Corporation Alert Service Bulletin 61B35-67B, Revision B, dated August 11, 2003. This AD does not require you to contact Sikorsky or provide information to Sikorsky.

(2) If during any inspection required by paragraph (i)(1) of this AD, any IFWU assembly part is found whose average wear, wear marks, surface distress, or endplay exceeds the limits specified in paragraphs B.(1) through B.(6) of the Accomplishment Instructions of Sikorsky Aircraft Corporation Alert Service Bulletin 61B35-67B, Revision B, dated August 11, 2003, before further flight, replace the affected part with an airworthy IFWU assembly part.

Note 3 to paragraph (i)(2): Sikorsky Aircraft S-61L/N Overhaul Manual, SA4045-83, Revision 20, dated August 15, 2003, as revised by Temporary Revisions 65-193, -194, -195, and -196, contains the overhaul procedures for the IFWU assembly.

(j) Part Marking

For each REL IFWU assembly, as determined by paragraph (h)(1) or (2) of this AD: Before further flight after the assembly was determined to be an REL IFWU assembly, permanently mark IFWU camshafts, P/N 61350-24052, 61350-24072, S6135-20611, S6135-20614 and S6137-23075, and IFWU gear housings, P/N 61350-24051, 61350-24068, S6135-20695, and S6137-23057, with the letters "REL". Mark the camshafts by applying etching ink on the surface of the part that is 0.5-inch square with the depth of the letters not to exceed 0.001 inch. Before further flight and after etching, neutralize the etched surface and oil to prevent corrosion.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Isabel Saltzman, Aviation Safety Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; telephone 781-238-7649; email Isabel.L.Saltzman@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Sikorsky Aircraft Corporation Alert Service Bulletin 61B35-67B, Revision B, dated August 11, 2003.

(ii) [Reserved]

(3) For service information identified in this AD, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT

06611; telephone 1-800-Winged-S; email wcs_cust_service_eng.gr-sik@lmco.com. Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 4, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-11081 Filed 5-26-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1171; Product Identifier 2017-SW-124-AD; Amendment 39-21548; AD 2021-10-15]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Deutschland GmbH Model MBB-BK 117 C-2 and Model MBB-BK 117 D-2 helicopters. This AD was prompted by a determination that a life limit for the adapter forward (FWD) of the outboard load system, repetitive inspections of other components of that system, and for certain helicopters, a modification of the outboard load system, are necessary to address the unsafe condition. This AD requires a modification of the outboard load system for certain helicopters, repetitive inspections of the outboard load system and its components for any defect (including cracking, damage, corrosion, and incorrect installation) and applicable corrective actions, and implementation of a new life limit for the FWD adapter, as specified in a European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, which is

incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 1, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1171.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1171; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Kathleen Arrigotti, Program Manager, Large Aircraft Section, International Validation Branch, Compliance & Airworthiness Division, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218; email kathleen.arrigotti@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0177, dated September 14, 2017 (EASA AD 2017-0177) (also referred to

as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus Helicopters Deutschland GmbH Model MBB-BK 117 C-2 helicopters, except the Model C-2e variant, and all Model MBB-BK 117 D-2 helicopters.

EASA's Model MBB-BK 117 C-2e variant helicopters are not a unique model on the U.S. type certificate but are considered a configuration of the Model MBB-BK117 C-2. The U.S. type certificate data sheet explains that the FAA determined that the type design changes involved did not rise to the level that required an FAA amended type certificate. However, the FAA does recognize that helicopters with these type design changes exist, therefore the designation Model MBB-BK117 C-2(e) is used, starting from Serial Number 9601. The Model MBB-BK117 C-2(e) is a visual flight rules only configuration of the Model MBB-BK117 C-2 utilizing a Garmin 500H flight display system.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Deutschland GmbH Model MBB-BK 117 C-2 and Model MBB-BK 117 D-2 helicopters, except the Model MBB-BK117 C-2(e) configuration. The NPRM published in the **Federal Register** on March 11, 2021 (86 FR 13830). The NPRM was prompted by a determination that a life limit for the adapter FWD of the outboard load system, repetitive inspections of other components of that system, and for certain helicopters, a modification of the outboard load system, are necessary to address the unsafe condition. The NPRM proposed to require a modification of the outboard load system for certain helicopters, repetitive inspections of the outboard load system and its components for any defect (including cracking, damage, corrosion, and incorrect installation) and applicable corrective actions, and implementation of a new life limit for the FWD adapter, as specified in an EASA AD.

The FAA is issuing this AD to address detachment of an external load or person from the helicopter hoist, resulting in personal injury, or injury to persons on the ground. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Costs of Compliance Update

The NPRM had specified no definitive data was available for the costs of the modification and certain parts. The FAA has received data on the costs of the modification and parts and has updated the costs of compliance accordingly.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes and a change to paragraph (i)(1) of this AD. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2017-0177 describes procedures for modification of the outboard load system for certain Model MBB-BK 117 C-2 helicopters, repetitive inspections of the outboard load system and its components for any defect (including cracking, damage, corrosion, and incorrect installation) and corrective actions, and implementation of a new life limit for the FWD adapter (*i.e.*, repetitive replacements). The corrective actions include replacement of any defective component with a serviceable part.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 175 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
4 work-hours × \$85 per hour = \$340	\$2,276	\$2,616	\$457,800

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of helicopters that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTION

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170	Up to \$970	Up to \$1,140.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–10–15 Airbus Helicopters

Deutschland GmbH: Amendment 39–21548; Docket No. FAA–2020–1171; Product Identifier 2017–SW–124–AD.

(a) Effective Date

This airworthiness directive (AD) is effective July 1, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH Model MBB–BK 117 C–2 and Model MBB–BK 117 D–2 helicopters, certificated in any category, all manufacturer serial numbers, except the Model MBB–BK117 C–2(e) configuration.

Note 1 to paragraph (c): Model MBB–BK117 C–2 helicopters utilizing a Garmin 500H flight display system are designated by EASA as Model MBB–BK117 C–2e variants of the Model BK 117 C–2 helicopters, and by the FAA as a Model MBB–BK117 C–2(e) configuration.

(d) Subject

Joint Aircraft System Component (JASC) Code 2500, Cabin Equipment/Furnishings.

(e) Reason

This AD was prompted by a determination that a life limit for the adapter forward of the outboard load system, repetitive inspections of other components of that system, and for certain helicopters, a modification of the outboard load system, are necessary to

address the unsafe condition. The FAA is issuing this AD to address detachment of an external load or person from the helicopter hoist, which could result in personal injury, or injury to persons on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2017–0177, dated September 14, 2017 (EASA AD 2017–0177).

(h) Exceptions to EASA AD 2017–0177

(1) Where EASA AD 2017–0177 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2017–0177 does not apply to this AD.

(3) Where the service information referenced in EASA AD 2017–0177 specifies contacting the applicable manufacturer of the dedicated equipment for a definition of a cycle and recalculation to hoist cycles, this AD does not require contacting the manufacturer for a definition of a cycle and recalculation to hoist cycles.

(4) Where paragraph (3) of EASA AD 2017–0177 specifies to do "applicable corrective actions," for this AD, if there are any defective components, replace all defective components with serviceable components in accordance with FAA-approved procedures. For the purposes of this AD, a defect may be indicated by cracking, damage, corrosion, or incorrect installation.

(5) Although the service information referenced in EASA AD 2017–0177 specifies to discard certain parts, this AD requires removing those parts from service instead.

(6) Where the service information referenced in EASA AD 2017–0177 refers to flight hours (FH), this AD requires using hours time-in-service.

(7) Paragraph (9) of EASA AD 2017–0177 does not apply to this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly

to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Program Manager, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3218; email: kathleen.arrigotti@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2017-0177, dated September 14, 2017.

(ii) [Reserved]

(3) For EASA AD 2017-0177, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1171.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-11080 Filed 5-26-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0018; Project Identifier MCAI-2020-01214-T; Amendment 39-21546; AD 2021-10-13]

RIN 2120-AA64

Airworthiness Directives; De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2015-17-08, which applied to certain Bombardier, Inc. Model DHC-8-400 series airplanes. AD 2015-17-08 required installing new cable assemblies with a pull-down resistor. This AD requires modifications to the nose wheel steering (NWS) system. This AD was prompted by a report indicating that several failure modes of the NWS system may cause the loss of feedback from both rotary variable differential transformers to the steering control unit. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 1, 2021.

ADDRESSES: For service information identified in this final rule, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd@dehavilland.com; internet <https://dehavilland.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0018.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0018; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday

through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7362; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2020-28, dated August 14, 2020 (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain De Havilland Aircraft of Canada Limited Model DHC-8-401 and -402 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0018.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2015-17-08, Amendment 39-18241 (80 FR 51459, August 25, 2015) (AD 2015-17-08). AD 2015-17-08 applied to certain Bombardier, Inc. Model DHC-8-400 series airplanes. The NPRM published in the **Federal Register** on February 24, 2021 (86 FR 11175). The NPRM was prompted by a report indicating that several failure modes of the NWS system may cause the loss of feedback from both rotary variable differential transformers to the steering control unit. The NPRM proposed to require modifications to the NWS system. The FAA is issuing this AD to address failure modes of the NWS system, which could lead to NWS runaway, loss of directional control of the airplane, and possible consequent runway excursion. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. The Air Line Pilots Association, International (ALPA) indicated its support for the NPRM.