

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by a report that showed a non-compliance exists on some in-service galley attendant seat fitting installations, and a determination that additional airplanes are subject to the unsafe condition. The FAA is issuing this AD to address non-compliant flight attendant seats, which could fail in a high-G crash and result in potential injury to flight attendants and consequent inability of the flight attendants to assist with passenger evacuation in a timely manner.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020.

(h) Exception to Service Information Specifications

Where Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020, uses the phrase "the Revision 2 date of this service bulletin," this AD requires using "the effective date of this AD."

(i) No Reporting Requirement

Although the service information referenced in Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 777-25-0649, Revision 1, dated October 6, 2017 (which is incorporated by reference in AD 2019-01-08).

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with

14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2019-01-08 are approved as AMOCs for the corresponding provisions of Boeing Special Attention Service Bulletin 777-25-0649, Revision 2, dated October 8, 2020, that are required by paragraph (g) of this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(5)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: brandon.lucero@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on May 28, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-13407 Filed 6-24-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-0502; Project Identifier 2018-CE-043-AD]

RIN 2120-AA64

Airworthiness Directives; B-N Group Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain B-N Group Ltd. Models BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, and BN-2T-4R airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as failure of the rudder final drive rod because of cracks in the region of the taper pins. This proposed AD would require repetitively inspecting the rudder final drive rod assembly and replacing the rudder final drive assembly, if necessary. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 9, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Britten-Norman Aircraft Limited, Commodore House, Mountbatten Business Centre, Millbrook Road East, Southampton SO15 1HY, United Kingdom; phone: +44 20 3371 4000; fax: +44 20 3371 4001; email: info@bnaircraft.com; website: <https://britten-norman.com/approvals-technical-publications/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0502; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249; phone: (303) 342-1094; email: penelope.trease@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0502; Project Identifier 2018-CE-043-AD" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner.

Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0153, dated July 19, 2018 (referred to after this as "the MCAI"), to correct an unsafe condition for B-N Group Ltd. (Britten-Norman Aircraft Ltd., or "BNA") Models BN-2, BN-2A, BN-2B, BN-2T, BN-2T-2, BN-2T-2R, and BN-2T-4R airplanes. The MCAI states:

Occurrences have been reported of failures of the rudder final drive rod, [part number] P/N NB-45-0991. Cracks were found in the region of the taper pins. There is evidence that replacing the taper pins could be a significant factor contributing to the failure of this rod.

This condition, if not detected and corrected, could lead to failure of the affected part, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, BNA issued the applicable SB [service bulletin], providing inspection instructions. Prompted by operator comments, BNA revised the applicable SB (issue 3) to introduce repetitive inspections.

For the reason described above, this [EASA] AD requires repetitive inspections of the affected part and, depending on findings, replacement. This AD also prohibits replacement of taper pins on an affected part. BNA will amend the applicable Maintenance Manuals accordingly.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0502.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Britten-Norman Aircraft Limited Service Bulletin Number SB 363, Issue 3, dated May 23, 2018, and Service Bulletin Number SB 364, Issue 3, dated May 23, 2018. For the applicable airplane models identified on each document, this service information contains procedures for repetitively inspecting the rudder final drive rod assembly and replacing the rudder final drive assembly, if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This AD requires accomplishing the actions specified in the service information already described.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 76 airplanes of U.S. registry. The FAA also estimates that inspecting the rudder final drive assembly would take about 1 work-hour at the average labor rate of \$85 per work-hour.

Based on these figures, the FAA estimates the cost of this proposed AD on U.S. operators to be \$6,460, or \$85 per product, each inspection cycle.

In addition, the FAA estimates that any necessary follow-on actions to replace the rudder final drive assembly would take about 5 work-hours and require parts costing \$1,200, for a cost of \$1,625 per product. The FAA has no way of determining the number of airplanes that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

B-N Group Ltd.: Docket No. FAA-2021-0502; Project Identifier 2018-CE-043-AD.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 9, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to B-N Group Ltd. Models BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, and BN-2T-4R airplanes, all serial numbers, certificated in any category, with a rudder final drive rod part number (P/N) NB-45-0991 installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 2720, Rudder Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of the rudder final drive rod because of cracks in the region of the taper pins. The FAA is issuing this AD to detect and correct defects on the rudder final drive rod assembly to prevent failure of the assembly. The unsafe condition, if not addressed, could result in loss of rudder control and reduced airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Action

(1) Inspect the rudder final drive rod assembly for loose taper pins, loose end connections, bending, and cracks within the applicable compliance times for your airplane specified in paragraph (g)(1)(i) or (ii) of this AD.

(i) For Models BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, and BN-2B-27 airplanes, within 100 hours time-in-service (TIS) after the effective date of this AD and thereafter at intervals not to exceed 1,000 hours TIS.

(ii) For Models BN-2T and BN-2T-4R airplanes, within 200 hours TIS after the effective date of this AD and thereafter at intervals not to exceed 1,000 hours TIS.

(2) If a loose taper pin, a loose end connection, any bending, or a crack is found during any inspection required by paragraph (g)(1) of this AD, before further flight, replace the rudder final drive rod assembly by following section 7, Removal and Installation Instructions for Unserviceable Units, of Britten-Norman Service Bulletin Number SB 363, Issue 3, dated May 23, 2018 (SB 363, Issue 3) or Britten-Norman Service Bulletin Number SB 364, Issue 3, dated May 23, 2018 (SB 364, Issue 3), as applicable to your model airplane.

(3) If no loose taper pins, no loose end connections, no bending, and no cracks are found during the initial inspection required by paragraph (g)(1) of this AD, review the airplane maintenance records to determine whether any taper pins have been replaced or reworked on the rudder final drive rod assembly.

(4) If a taper pin has ever been replaced or reworked, without exceeding the initial compliance time in paragraph (g)(1)(i) or (ii) of this AD, replace the rudder final drive rod assembly by following section 7, Removal and Installation Instructions for Unserviceable Units, of SB 363, Issue 3 or SB 364, Issue 3, as applicable to your model airplane.

(5) As of the effective date of this AD, do not install a rudder final drive rod assembly P/N NB-45-0991 on any airplane unless:

(i) The rudder final drive rod assembly is unused (zero hours TIS); or

(ii) The taper pins in the rudder final drive rod assembly have never been replaced.

(6) As of the effective date of this AD, do not replace any taper pin on a rudder final drive rod assembly P/N NB-45-0991 installed on any airplane.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249; phone: (303) 342-1094; email: penelope.trease@faa.gov.

(2) Refer to European Aviation Safety Agency (EASA) AD 2018-0153, dated July 19, 2018, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2021-0502.

(3) For service information identified in this AD, contact Britten-Norman Aircraft Limited, Commodore House, Mountbatten Business Centre, Millbrook Road East, Southampton SO15 1HY, United Kingdom; phone: +44 20 3371 4000; fax: +44 20 3371 4001; email: info@bnaircraft.com; website: <https://britten-norman.com/approvals-technical-publications/>. You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO

64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued on June 11, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-13463 Filed 6-24-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0511; Project Identifier AD-2020-01229-E]

RIN 2120-AA64

Airworthiness Directives; Williams International Co., L.L.C. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Williams International Co., L.L.C. (Williams) FJ44-2A, FJ44-2C, FJ44-3A, and FJ44-3A-24 model turbofan engines. This proposed AD was prompted by a report of cracks in high-pressure turbine (HPT) disk posts and failure of an HPT disk post. This proposed AD would require the removal and replacement of the affected HPT disk before reaching its new life limit. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 9, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Williams International Co., L.L.C., Product Support, 2000 Centerpoint Pkwy., Pontiac, MI 48341; phone: (800) 859-3544; website: <http://www.williams->

[int.com/product-support](http://www.williams-int.com/product-support). You may view this service information at the Chicago ACO Branch, 2300 East Devon Avenue, Des Plaines, IL 60018. For information on the availability of this material at the FAA, call (781) 238-7759.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0511; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Kyle Bush, Aviation Safety Engineer, Chicago ACO Branch, FAA, 2300 East Devon Avenue, Des Plaines, IL 60018; phone: (847) 294-7870; fax: (847) 294-7834; email: kyle.bush@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0511; Project Identifier AD-2020-01229-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each

page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kyle Bush, Aviation Safety Engineer, Chicago ACO Branch, FAA, 2300 East Devon Avenue, Des Plaines, IL 60018. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received a report that Williams discovered cracks in one HPT disk post during a scheduled inspection of an FJ44-2A model turbofan engine. An operator also discovered that one HPT disk post failed, while the engine was in service, resulting in the release of an HPT blade.

Williams initiated an investigation to understand the root cause of the cracks and to determine the necessary corrective action. Williams found that, between August 2018 and July 2019, nine FJ44-2A HPT disks were rejected during inspection after discovery of cracks in the HPT disk post. As part of its investigation, Williams conducted several tests and analysis to determine the failure mechanism. Engine tests confirmed that FJ44-2A and FJ44-2C model turbofan engines operate at a higher temperature than most recently certified engines. Metallurgical evaluation showed cracking is intergranular with oxidation attack near and around the crack, with no fatigue striations. Metallurgical evaluation and comparison of HPT disk, part number (P/N) 67093, installed on both FJ44-2A and FJ44-3A model turbofan engines, showed cracking of the HPT disk.

As a result of this investigation, Williams determined the root cause of this cracking was due to higher temperatures and a difference in manufacturing processes (electrical discharge machining vs. broaching). Williams determined that these cracks have only occurred on HPT disks with P/N 67093. Williams subsequently issued service information to instruct operators to remove the HPT disk, P/N 67093. This condition, if not addressed, could result in failure of the engine, in-flight shutdown of the engine, and loss of control of the aircraft.

FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.