

Act, 12 U.S.C. 1790d, as added by section 301 of the Credit Union Membership Access Act, Public Law 105-219, 112 Stat. 913 (1998).

(b) *Purpose.* This subpart provides for the phase in of the adverse effects on the regulatory capital of federally insured credit unions that may result from the adoption of the current expected credit losses (CECL) accounting methodology.

(c) *Scope.* (1) The transition provisions of this subpart apply to Federally insured credit unions, whether Federally or State-chartered, including credit unions defined as “new” pursuant to section 1790d(b)(2) that make charges for loan losses in accordance with:

(i) Generally accepted accounting principles (GAAP) under § 702.402(d)(1)(i); or

(ii) In the case of Federally-insured, State-chartered credit unions, any other applicable standard under State law or regulation under § 702.402(d)(1)(ii)(B).

(2) The transition provisions of this subpart do not apply to Federally-insured credit unions, whether Federally or State-chartered, including credit unions defined as “new” pursuant to section 1790d(b)(2), that make charges for loan losses using a reasonable reserve methodology under § 702.402(d)(1)(ii)(A).

§ 702.702 Definitions.

In addition to the definitions set forth in § 702.2, the following definitions apply to this subpart:

Current Expected Credit Losses (CECL) means the current expected credit losses methodology under GAAP.

CECL transitional amount means the decrease of a credit union’s retained earnings resulting from its adoption of CECL, as determined pursuant to § 702.703(b).

Transition period means the 12-quarter reporting period beginning the first day of the fiscal year in which the credit union adopts CECL.

§ 702.703 CECL transition provisions.

(a) *Eligibility*—The NCUA shall use the transition provisions of this subpart in determining a credit union’s net worth category under this part, as applicable, if:

(1) The credit union has not adopted CECL before its first fiscal year beginning after December 15, 2022; and

(2) The credit union records a reduction in retained earnings due to the adoption of CECL.

(b) *Determination of CECL transition amount.* (1) For purposes of calculating the first three quarters of the transition period, as described in paragraph (c)(1) of this section, the CECL transitional

amount is equal to the difference between the credit union’s retained earnings as of the beginning of the fiscal year in which the credit union adopts CECL and the credit union’s retained earnings as of the closing of the fiscal year immediately prior to the credit union’s adoption of CECL.

(2) For purposes of calculating the fourth through twelfth quarters of the transition period, as described in paragraphs (c)(2) and (c)(3) of this section, the CECL transitional amount is equal to the difference between the credit union’s retained earnings as of the end of the fiscal year in which the credit union adopts CECL and the credit union’s retained earnings as of the beginning of its next fiscal year.

(c) *Calculation of CECL transition provision.* In determining the net worth category of a credit union as provided in paragraph (a) of this section, the NCUA shall:

(1) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by 100 percent of its CECL transitional amount during the first three quarters of the transition period (first three reporting quarters of the fiscal year in which the credit union adopts CECL);

(2) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by sixty-seven percent of its CECL transitional amount during the second four quarters of the transition period (fourth reporting quarter of the fiscal year in which the credit union adopts CECL and first three reporting quarters of the next fiscal year); and

(3) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by thirty-three percent of its CECL transitional amount during the final four quarters of the transition period.

[FR Doc. 2021-13907 Filed 6-30-21; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0540; Project Identifier MCAI-2021-00694-T; Amendment 39-21635; AD 2021-14-08]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A319-151N, A319-153N, A319-171N, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N and A321-272NX airplanes. This AD was prompted by reports of an increasing number of operational disruptions due to airspeed discrepancies. This AD requires revising the existing airplane flight manual (AFM) to include a procedure to reinforce the airspeed check during the take-off phase and provide instructions to abort take-off in certain cases, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective July 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 1, 2021.

The FAA must receive comments on this AD by August 16, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for

and locating Docket No. FAA–2021–0540.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0540; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021–0150, dated June 21, 2021; corrected June 25, 2021 (EASA AD 2021–0150) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus SAS Model A319–151N, A319–153N, A319–171N, A320–251N, A320–252N, A320–253N, A320–271N, A320–272N, A320–273N, A321–251N, A321–251NX, A321–252N, A321–252NX, A321–253N, A321–253NX, A321–271N, A321–271NX, A321–272N and A321–272NX airplanes.

EASA and Airbus issued various communication documents (respectively EASA Safety Information Bulletin (SIB) 2020–14, Airbus Operators Information Transmission (OIT) 999.0048/20, Airbus Operational Training Transmission (OTT) 999.0025/21, and Airbus Flight Operations Transmission (FOT) 999.0020/21) to remind operators to apply appropriate procedures for returning airplanes to service from short term or long term storage/parking, including procedures to inspect the pitot static system. However, an increasing number of operational disruptions have been reported, due to contaminated air data system, caused by lack of application of appropriate maintenance procedures for returning airplanes to service.

This AD was prompted by reports of an increasing number of operational disruptions due to airspeed discrepancies after airplanes have been parked or stored (a large number of airplanes have been parked or stored due to the COVID–19 pandemic).

Consistent erroneous airspeed indications (which stands for 2 or 3 pitot probes delivering erroneous speed information within the same speed range) may adversely affect airplane response, in particular during the rotation phase. The FAA is issuing this AD to address airspeed discrepancies, which could lead to an unstable flight path after take-off, possibly resulting in reduced control of the airplane. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021–0150 describes procedures for, among other actions, revising the AFM to include a procedure to reinforce the airspeed check during the take-off phase and provide instructions to abort take-off in certain cases (e.g., an unreliable airspeed situation or certain airspeed differences).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the FAA evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2021–0150 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under “Differences Between this AD and the MCAI.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2021–0150

is incorporated by reference in this AD. This AD requires compliance with EASA AD 2021–0150 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021–0150 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021–0150. Service information required by EASA AD 2021–0150 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0540 after this AD is published.

Differences Between This AD and the MCAI

Paragraph (3) of EASA AD 2021–0150 requires revising the minimum equipment list (MEL) to incorporate an EASA master minimum equipment list (MMEL) change to mandate that the integrated standby instrument system (ISIS) airspeed indication must be operative. However, the FAA MMEL does not provide relief for an inoperative ISIS airspeed indication function. Therefore, paragraph (3) of EASA AD 2021–0150 is unnecessary for this AD.

EASA AD 2021–0150 requires operators to “inform all flight crews” of revisions to the AFM and thereafter to “operate the aeroplane accordingly.” However, this AD does not specifically require those actions as those actions are already required by FAA regulations.

FAA regulations require operators furnish to pilots any changes to the AFM (ex: 14 CFR 121.137), and to ensure the pilots are familiar with the AFM (ex: 14 CFR 91.505). As with any other training requirement, training on the updated AFM content is tracked by the operators and recorded in each pilot’s training record, which is available for the FAA to review. FAA regulations also require pilots to follow the procedures in the existing AFM including all updates. 14 CFR 91.9 requires that no person may operate a civil aircraft without complying with the operating limitations specified in the AFM.

Therefore, including a requirement in this AD to operate the airplane according to the revised AFM would be redundant and unnecessary. Further, compliance with such requirements in

an AD would be impracticable to demonstrate or track on an ongoing basis; therefore, a requirement to operate the airplane in such a manner would be unenforceable.

FAA’s Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because consistent erroneous airspeed indications may adversely affect airplane response, in particular during the rotation phase. This unsafe condition is particularly prevalent in the large number of airplanes that are returning to service after airplanes have been parked or stored due to the COVID-19 pandemic. Without reinforcing the airspeed check and providing instructions to abort take-off in certain cases, airspeed discrepancies could lead to an unstable flight path after take-off, possibly resulting in reduced control of the airplane. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2021-0540; Project Identifier MCAI-2021-00694-T” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA

will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Explanation of Special Flight Permit Limitation

Once the compliance time specified in this AD has passed, special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed. As a result of the COVID-19 pandemic, a large numbers of airplanes have been put in storage. For those airplanes removed from storage after the compliance time specified in this AD has passed, operators must incorporate the AFM revision required by this AD before further flight.

Interim Action

The FAA considers this AD interim action and further AD action might follow.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 204 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$17,340

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–14–08 Airbus SAS: Amendment 39–21635; Docket No. FAA–2021–0540; Project Identifier MCAI–2021–00694–T.

(a) Effective Date

This airworthiness directive (AD) becomes effective July 1, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A319–151N, A319–153N, A319–171N, A320–251N, A320–252N, A320–253N, A320–271N, A320–272N, A320–273N, A321–251N, A321–251NX, A321–252N, A321–252NX, A321–253N, A321–253NX, A321–271N, A321–271NX, A321–272N and A321–272NX airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by reports of an increasing number of operational disruptions due to airspeed discrepancies that have occurred due to the large number of airplanes returning to service after airplanes have been parked or stored (a large number of airplanes

have been parked or stored due to the COVID–19 pandemic). The FAA is issuing this AD to address airspeed discrepancies, which could lead to an unstable flight path after take-off, possibly resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0150, dated June 21, 2021; corrected June 25, 2021 (EASA AD 2021–0150).

(h) Exceptions to EASA AD 2021–0150

(1) Where EASA AD 2021–0150 refers to its effective date, this AD requires using the effective date of this AD.

(2) Paragraph (1) of EASA AD 2021–0150 specifies amending “the applicable AFM [airplane flight manual],” but this AD requires amending “the existing applicable AFM and applicable corresponding operational procedures.”

(3) Paragraph (3) of EASA AD 2021–0150 does not apply to this AD.

(4) The “Remarks” section of EASA AD 2021–0150 does not apply to this AD.

(5) Where paragraph (1) of EASA AD 2021–0150 specifies to “inform all flight crews, and, thereafter, operate the aeroplane accordingly,” this AD does not require those actions as those actions are already required by existing FAA operating regulations.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed after 7 days after the effective date of this AD unless the AFM revision required by paragraph (g) of this AD is accomplished.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or

EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0150, dated June 21, 2021; corrected June 25, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0150, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0540.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 28, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–14158 Filed 6–29–21; 11:15 am]

BILLING CODE 4910–13–P