

Executive Order 12988 and Executive Order 13132—Federalism

According to Executive Orders 12988 and 13132, agencies must state in clear language the preemptive effect, if any, of new regulations. The amendments to the agency's Sunshine Act implementing regulations affect only how the Board conducts nonpublic meetings, and therefore, have no effect on preemption of State, tribal, or local government laws or otherwise have federalism implications.

Congressional Review Act

This rule will not result in and is not likely to result in (A) an annual effect on the economy of \$100,000,000 or more; (B) a major increase in costs or prices for consumers, individual industries, Federal, State, or local government agencies, or geographic regions; or (C) significant adverse effects on competition, employment, investment, productivity, innovation, or on the ability of United States-based enterprises to compete with foreign-based enterprises in domestic and export markets. As such, the Office of Management and Budget has not found it to be a major rule as defined in the Congressional Review Act. To comply with the Congressional Review Act, the Board will submit the required information each House of the Congress and the Comptroller General.

Finding of No Significant Environmental Impact

The proposed regulations amend the Board procedures for holding meetings pursuant to the Government in the Sunshine Act. The procedural changes to the Sunshine Act implementing regulations will not result in significant impacts affecting the quality of the human environment, unavoidable adverse environmental effects, rejection of reasonable alternatives to the proposed action, or irreversible or irretrievable commitments of environmental resources. The agency has not consulted with any other agencies in making this determination.

IV. Rulemaking Procedure

In light of the amendments made to the AEA at 42 U.S.C. 2286b(k), this rulemaking makes limited conforming changes to the Board's rules implementing the Sunshine Act (10 CFR part 1704). The Board is using the "direct final rule" procedure because this rulemaking represents a limited, routine change to implement the new provisions of the AEA. This amendment will become effective on November 29, 2021. However, if the Board receives a significant adverse comment by

September 29, 2021, then the Board will publish a notice in the **Federal Register** withdrawing this rule and publishing the changes as a notice of proposed rulemaking. The Board will respond to the significant adverse comment(s) in that notice of proposed rulemaking and take an additional 30 days of comments before publishing any final rule. If no significant adverse comment is received, the Board will publish a notice that confirms the effective date of this direct final rule.

A significant adverse comment is a comment where the commenter explains why the rule would be inappropriate, including challenges to the rule's underlying premise or approach, or would be ineffective or unacceptable without a change. A comment is adverse and significant if:

- (1) The comment opposes the rule and provides a reason sufficient to require a substantive response in a notice-and-comment process. For example, a substantive response is required when:
 - (a) The comment causes the Board staff to reevaluate (or reconsider) its position or conduct additional analysis;
 - (b) The comment raises an issue serious enough to warrant a substantive response to clarify or complete the record; or
 - (c) The comment raises a relevant issue that was not previously addressed or considered by the Board.
- (2) The comment proposes a change or an addition to the rule, and it is apparent that the rule would be ineffective or unacceptable without incorporation of the change or addition; or
- (3) The comment causes the Board to make a change (other than editorial) to the rule.

List of Subjects in 10 CFR Part 1704

Sunshine Act.

For the reasons stated in the preamble, the Defense Nuclear Facilities Safety Board amends 10 CFR part 1704 as follows:

PART 1704—RULES IMPLEMENTING THE GOVERNMENT IN THE SUNSHINE ACT

- 1. The authority citation for part 1704 is revised to read as follows:

Authority: 5 U.S.C. 552b; 42 U.S.C. 2286, 2286b(c), (k).

- 2. Add § 1704.11 to read as follows:

§ 1704.11 Nonpublic collaborative discussions.

(a) *In general.* Notwithstanding the other requirements of this part, a quorum of Members may hold a meeting that is not open to public observation to

discuss official business of the Board if—

- (1) No formal or informal vote or other official action is taken at the meeting;
- (2) Each individual present at the meeting is a Member or an employee of the Board;
- (3) At least one Member from each political party is present at the meeting, unless all Members are of the same political party at the time of the meeting; and
- (4) The general counsel of the Board, or a designee of the general counsel, is present at the meeting.

(b) *Disclosure of nonpublic collaborative discussions.* (1) Except as provided by paragraph (b)(2) of this section, not later than two business days after the conclusion of a meeting described in subsection (a), the Board shall make available to the public, in a place easily accessible to the public—

- (i) A list of the individuals present at the meeting; and
 - (ii) A summary of the matters, including key issues, discussed at the meeting, except for any matter the Board properly determines may be withheld from the public under § 1704.4.
- (2) Information about matters withheld from the public. If the Board properly determines under paragraph (b)(1)(ii) of this section that a matter may be withheld from the public under § 1704.4, the Board shall include in the summary required by paragraph (b)(1)(ii) as much general information as possible with respect to the matter.

Dated: August 24, 2021.

Joyce Connery,

Chair.

[FR Doc. 2021–18549 Filed 8–27–21; 8:45 am]

BILLING CODE 3670–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0719; Project Identifier MCAI–2021–00858–T; Amendment 39–21709; AD 2021–18–08]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A319–171N; Model A320–271N, –272N, and –273N

airplanes; and Model A321–271N, –272N, –271NX, and –272NX airplanes. This AD was prompted by a report indicating that during inspection of the engines, two original rods installed to maintain an interface plate between the pylon and nacelle were found damaged at both rod-eye ends. This AD requires repetitive inspections of the pylon/engine interface rods for damage, and applicable corrective actions, and limits the installation of affected parts under certain conditions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective September 14, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 14, 2021.

The FAA must receive comments on this AD by October 14, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0719.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0719; or in person at Docket Operations between 9 a.m. and 5 p.m.,

Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2021–0719; Project Identifier MCAI–2021–00858–T” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des

Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021–0177, dated July 23, 2021 (EASA AD 2021–0177) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Airbus SAS Model A319–171N; Model A320–271N, –272N, and –273N airplanes; and Model A321–271N, –272N, –271NX, and –272NX airplanes.

This AD was prompted by a report indicating that during inspection of the engines, two original rods installed to maintain an interface plate between the pylon and nacelle were found damaged at both rod-eye ends. Investigation revealed that the rod damage was caused by the high amplitude of vibrations during take-off and climb flight phases, generated by engine-driven pump hydraulic pulsation and potential resonance effects. The FAA is issuing this AD to address damage that could lead to rupture of the rod-eye ends, which could result in fuel and hydraulic pipe chafing, consequent fuel or hydraulic leakage, and possible fire. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021–0177 specifies procedures for repetitive detailed inspections for damage (e.g., hole damage, a crack, or an abnormal deformation) of the left- and right-hand pylon/engine interface rod ends of the rod attachment fittings, and the interface plate and upper support brackets, a measurement of the play/gap of the pylon/engine interface upper and lower rod ends, and applicable corrective actions including rod replacement. EASA AD 2021–0177 also limits the installation of affected parts if/unless inspected within the compliance time specified. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the

FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2021–0177 described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2021–0177 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2021–0177 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021–0177 does not mean that operators need comply only with that

section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021–0177. Service information required by EASA AD 2021–0177 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0719 after this AD is published.

Interim Action

The FAA considers this AD interim action. If final action is later identified, the FAA might consider further rulemaking then.

FAA’s Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because rupture of the rod-eye ends could result in fuel and hydraulic pipe chafing, consequent fuel or hydraulic leakage, and possible fire. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forego notice and comment.]

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 204 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS *

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 6 work-hours × \$85 per hour = Up to \$510	\$0	Up to \$510	Up to \$104,040.

* Table does not include estimated costs for reporting

The FAA estimates that it takes about 1 work-hour per product to comply with the reporting requirement in this AD.

The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the cost of reporting the

inspection results on U.S. operators to be \$17,340, or \$85 per product.

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 8 work-hours × \$85 per hour = Up to \$680	\$0	Up to \$680.

The FAA has received no definitive data on which to base the cost estimates for the other on-condition corrective actions for the operational check specified in this AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to

respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public

reporting for this collection of information is estimated to take approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of

information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-18-08 Airbus SAS: Amendment 39-21709; Docket No. FAA-2021-0719; Project Identifier MCAI-2021-00858-T.

(a) Effective Date

This airworthiness directive (AD) is effective September 14, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A319-171N; Model A320-271N, -272N, and -273N airplanes; and Model A321-271N, -272N, -271NX, and -272NX airplanes; certificated in any category; as identified in European Union Aviation Safety Agency (EASA) AD 2021-0177, dated July 23, 2021 (EASA AD 2021-0177).

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic Power.

(e) Unsafe Condition

This AD was prompted by a report indicating that during inspection of the engines, two original rods installed to maintain an interface plate between the pylon and nacelle were found damaged at both rod-eye ends. The FAA is issuing this AD to address damage that could lead to rupture of the rod-eye ends, which could result in fuel and hydraulic pipe chafing, consequent fuel or hydraulic leakage, and possible fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0177.

(h) Exceptions and Clarifications to EASA AD 2021-0177

(1) Where EASA AD 2021-0177 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (2) of EASA AD 2021-0177 specifies a compliance time for the initial detailed inspection for Group 2 airplanes, this AD requires initial compliance at the later of the times specified in paragraphs (h)(2)(i) and (ii) of this AD. Remaining provisions of paragraph (2) of EASA AD 2021-0177 that are not specifically referenced in this paragraph remain fully applicable and must be complied with.

(i) Before exceeding 750 total flight hours, but no earlier than 650 total flight hours, since either manufacture of the airplane or embodiment of Airbus Service Bulletin A320-29-1189, as applicable.

(ii) Within 750 flight hours after the effective date of this AD.

(3) The "Remarks" section of EASA AD 2021-0177 does not apply to this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2021-0177 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0177, dated July 23, 2021.

(ii) [Reserved]

(3) For information about EASA AD 2021-0177, contact EASA, Konrad-Adenauer-Ufer

3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on August 24, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-18706 Filed 8-26-21; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2020-1147; Airspace Docket No. 20-ASO-30]

RIN 2120-AA66

Amendment of Area Navigation (RNAV) Route Q-29; Northeastern United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects a final rule published by the FAA in the **Federal Register** on July 26, 2021, that amends area navigation (RNAV) route Q-29 in the northeastern United States.

This action is in support of the Northeast Corridor Atlantic Coast Route Project (NEC ACR) for improved efficiency of the National Airspace System (NAS) while reducing the dependency on ground based navigational systems. This action makes an administrative correction to the spelling of the final point on the legal description of RNAV route Q-29.

DATES: Effective date 0901 UTC, October 7, 2021. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC, 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email: fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT: Sean Hook, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

History

The FAA published a final rule for Docket No. FAA-2020-1147 in the

Federal Register (86 FR 39952; July 26, 2021), amending RNAV route Q-29 in the northeastern United States. The Q-route amendment supports the strategy to transition the NAS from a ground-based navigation aid and radar-based system to a satellite-based PBN system. The final point, DUNOM, was incorrectly spelled in the legal description and this action only corrects that error.

United States area navigation routes are published in paragraph 2006 of FAA Order 7400.11E, dated July 21, 2020, and effective September 15, 2020, which is incorporated by reference in 14 CFR 71.1. The RNAV routes listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020 and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the description of RNAV route Q-29 as published in the **Federal Register** on July 26, 2021 (86 FR 39952) is corrected as follows:

Paragraph 2006 United States Area Navigation Routes.

* * * * *

Q-29 HARES, LA TO DUNOM, ME

HARES, LA	WP	(Lat. 33°00'00.00" N, long. 091°44'00.00" W)
BAKRE, MS	WP	(Lat. 33°53'45.85" N, long. 090°58'04.75" W)
MEMFS, TN	WP	(Lat. 35°00'54.62" N, long. 089°58'58.87" W)
OMDUE, TN	WP	(Lat. 36°07'47.32" N, long. 088°58'11.49" W)
SIDAE, KY	WP	(Lat. 37°20'00.00" N, long. 087°50'00.00" W)
CREEP, OH	FIX	(Lat. 39°55'15.28" N, long. 084°18'31.41" W)
KLYNE, OH	WP	(Lat. 40°41'54.46" N, long. 083°18'44.19" W)
DUTSH, OH	WP	(Lat. 41°08'26.35" N, long. 082°33'12.68" W)
WWSHR, OH	WP	(Lat. 41°20'34.09" N, long. 082°03'05.76" W)
DORET, OH	FIX	(Lat. 41°48'05.90" N, long. 080°35' 04.64" W)
Jamestown, NY (JHW)	VOR/DME	(Lat. 42°11'18.99" N, long. 079°07'16.70" W)
HANKK, NY	FIX	(Lat. 42°53'41.82" N, long. 077°09'15.21" W)
GONZZ, NY	WP	(Lat. 43°05'22.00" N, long. 076°41'12.00" W)
KRAZZ, NY	WP	(Lat. 43°25'00.00" N, long. 074°18'00.00" W)
NIPPY, NY	FIX	(Lat. 43°41'23.08" N, long. 073°58'06.74" W)
CABCI, VT	WP	(Lat. 44°49'19.94" N, long. 071°42'55.14" W)
EBONY, ME	FIX	(Lat. 44°54'08.68" N, long. 067°09'23.65" W)
DUNOM, ME	WP	(Lat. 44°54'09.29" N, long. 066°58'13.68" W)