

with the actions required by paragraph (g)(1) of this AD.

(3) The actions required by paragraphs (g)(1) and (2) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with § 43.9(a)(1) through (4) and § 91.417(a)(2)(v). The record must be maintained as required by § 91.417, § 121.380, or § 135.439.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Mitch Soth, Flight Test Engineer, Southwest Section, Flight Test Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email mitch.soth@faa.gov.

(2) The subject of this AD is addressed in Transport Canada Emergency AD CF-2019-16, dated May 6, 2019. You may view the Transport Canada AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2021-0497.

(j) Material Incorporated by Reference

None.

Issued on August 26, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-19049 Filed 9-3-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0381; Project Identifier MCAI-2020-01656-E; Amendment 39-21694; AD 2021-17-11]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Type Certificate Previously Held by Rolls-Royce plc) Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Rolls-Royce Deutschland Ltd & Co KG (RRD) Trent XWB-75, Trent XWB-79, Trent XWB-79B, and Trent XWB-84 model turbofan engines. This AD was prompted by reports of cracks in the intermediate-pressure compressor (IPC) rotor 1 (R1) blades installed on certain Trent XWB model turbofan engines. This AD requires initial and repetitive borescope inspections (BSIs) of the affected IPC R1 blades and, depending on the results of the inspections, replacement of all 34 IPC R1 blades. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 12, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 12, 2021.

ADDRESSES: For service information identified in this final rule, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: +44 (0)1332 242424; fax: +44 (0)1332 249936; website: <https://www.rolls-royce.com/contact-us.aspx>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0381.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0381; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal

holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kevin Clark, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7088; fax: (781) 238-7199; email: kevin.m.clark@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain RRD Trent XWB-75, Trent XWB-79, Trent XWB-79B, and Trent XWB-84 model turbofan engines. The NPRM published in the **Federal Register** on May 28, 2021 (86 FR 28716). The NPRM was prompted by reports of cracks in the IPC R1 blades installed on certain Trent XWB model turbofan engines. The NPRM proposed to require initial and repetitive BSIs of the affected IPC R1 blades and, depending on the results of the inspections, replacement of all 34 IPC R1 blades with parts eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2020-0277, dated December 11, 2020 (referred to after this as “the MCAI”), to address the unsafe condition on these products. The MCAI states:

Occurrences have been reported of finding cracked IPC R1 blades on certain Trent XWB engines that were close to their first planned refurbishment shop visit.

This condition, if not corrected, could lead to blade failure and consequent engine in-flight shut-down (IFSD), possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition and avoid dual engine IFSD, Rolls-Royce issued the inspection NMSB to provide inspection instructions and the NMSB to provide information on threshold and intervals.

For the reasons described above, this [EASA] AD requires repetitive inspections of the affected parts and, depending on findings, accomplishment of applicable corrective action(s).

You may obtain further information by examining the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0381.

Discussion of Final Airworthiness Directive Comments

The FAA received comments from two commenters. The commenters were Delta Air Lines (Delta) and the Air Line Pilots Association, International (ALPA). The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Add a Definition for “Affected IPC Blades”

Delta requested that the FAA add a definition of “affected IPC blades” to paragraph (h) of this AD. Delta reasoned that the part number of the affected IPC R1 blades was established in paragraph (c), Applicability, but not in the proposed rule.

The FAA disagrees with the need to add a definition of an affected IPC blade to this AD, because paragraph (c), Applicability, is part of the proposed rule. The FAA clarified paragraph (c), Applicability, of this AD, by adding “(affected IPC R1 blade).”

Request To Add Clarifying Instructions for Repeat BSI

Delta requested that the FAA add language similar to paragraph (g)(1) of this AD to paragraph (g)(2) of this AD to clarify the instructions for the repeat BSI requirement.

The FAA disagrees. Paragraph (g)(2) of this AD instructs the operator to repeat the inspection required by

paragraph (g)(1) of this AD. It is unnecessary to add additional information to paragraph (g)(2) of this AD since the repetitive inspection required by paragraph (g)(2) of this AD is the same as required by paragraph (g)(1) of this AD.

Support for the AD

The ALPA supported the AD without further comment.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Rolls-Royce Non-Modification Service Bulletin (NMSB) Trent XWB 72-K633, Initial Issue, dated August 7, 2020. This service information specifies procedures for performing initial and repetitive BSIs of the Trent XWB-75, XWB-79, XWB-79B, and XWB-84 IPC R1 blades. This service information is reasonably

available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Other Related Service Information

The FAA reviewed Rolls-Royce Alert NMSB Trent XWB 72-AK612, Initial Issue, dated July 9, 2020; Rolls-Royce Alert NMSB Trent XWB 72-AK613, Initial Issue, dated July 17, 2020; and Rolls-Royce Alert NMSB Trent XWB 72-AK632, Initial Issue, dated August 7, 2020.

Rolls-Royce Alert NMSB Trent XWB 72-AK612 describes procedures for performing an in-shop BSI of the Trent XWB-75, XWB-79, XWB-79B, and XWB-84 IPC R1 blades. Rolls-Royce Alert NMSB Trent XWB 72-AK613 describes procedures for performing an on-wing BSI of the Trent XWB-75, XWB-79, XWB-79B, and XWB-84 IPC R1 blades. Rolls-Royce Alert NMSB Trent XWB 72-AK632 defines the initial inspection threshold and repeat inspection intervals for Trent XWB-75, XWB-79, XWB-79B, and XWB-84 IPC R1 blades.

Costs of Compliance

The FAA estimates that this AD affects 15 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
BSI affected IPC R1 blades	6 work-hours × \$85 per hour = \$510	\$0	\$510	\$7,650

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the mandated inspection. The FAA has no way of determining the

number of aircraft that might need this replacement.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement of IPC blades	100 work-hours × \$85 per hour = \$8,500	\$187,408	\$195,908

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–17–11 Rolls-Royce Deutschland Ltd & Co KG (Type Certificate previously held by Rolls-Royce plc): Amendment 39–21694; Docket No. FAA–2021–0381; Project Identifier MCAI–2020–01656–E.

(a) Effective Date

This airworthiness directive (AD) is effective October 12, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Rolls-Royce Deutschland Ltd & Co KG (Type Certificate previously held by Rolls-Royce plc) Trent XWB–75, Trent XWB–79, Trent XWB–79B, and Trent XWB–84 model turbofan engines with an installed intermediate-pressure compressor (IPC) rotor 1 (R1) blade, part number (P/N) KH21559 (affected IPC R1 blade).

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by reports of cracks in the IPC R1 blades installed on certain Trent XWB model turbofan engines. The FAA is issuing this AD to prevent failure of the IPC R1 blades. The unsafe condition, if not addressed, could result in failure of the engine, in-flight shutdown of the engine, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, perform an initial borescope inspection (BSI) of the affected IPC R1 blades using the Accomplishment Instructions, paragraphs 3.A.(3)(b) and (c) (on-wing) or 3.B.(2)(b) and (c) (in-shop), as applicable, of Rolls-Royce Non-Modification Service Bulletin Trent XWB 72–K633, Initial Issue, dated August 7, 2020.

Figure 1 to Paragraph (g)(1) – Inspection threshold

Flight cycles (FCs) since new	Compliance time
Less than 2,300 FCs since new	Before exceeding 2,300 FCs since new, or within 50 FCs after the effective date of this AD, whichever occurs later
2,300 or more FCs since new	Within 50 FCs after the effective date of this AD

(2) Thereafter, repeat the BSI of the affected IPC R1 blades required by paragraph (g)(1) of this AD before exceeding 200 engine FCs since the last BSI of the IPC R1 blades.

(3) If, during any inspection required by paragraph (g)(1) or (2) of this AD, any affected IPC R1 blade is found cracked, remove all 34 IPC R1 blades from service and replace with parts eligible for installation.

Note 1 to paragraph (g): The FCs specified in Figure 1 to paragraph (g)(1) of this AD are those accumulated by the IPC R1 blade having the highest flight cycles in the IPC R1 blade set since the first installation of the blade on an engine. When the FCs of the IPC R1 blade set cannot be established, use the FCs accumulated by the engine since new.

(h) Definition

For the purpose of this AD, a part eligible for installation is any IPC R1 blade having P/N KH21559 with zero engine FCs since new, any IPC R1 blade having P/N KH21559 that has been inspected in accordance with paragraph (g)(1) of this AD and a crack was

not found, or any IPC R1 blade having a P/N not listed in this AD.

(i) Credit for Previous Actions

You may take credit for the initial BSI required by paragraph (g)(1) of this AD if you performed the initial BSI before the effective date of this AD using Rolls-Royce Alert Non-Modification Service Bulletin (NMSB) Trent XWB 72–AK612, Initial Issue, dated July 9, 2020, or Rolls-Royce Alert NMSB Trent XWB 72–AK613, Initial Issue, dated July 17, 2020, as applicable.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information. You may

email your request to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Kevin Clark, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7088; fax: (781) 238–7199; email: *kevin.m.clark@faa.gov*.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2020–0277, dated December 11, 2020, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0381.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference

(IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce Non-Modification Service Bulletin Trent XWB 72–K633, Initial Issue, dated August 7, 2020.

(ii) [Reserved]

(3) For Rolls-Royce service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: +44 (0)1332 242424; fax: +44 (0)1332 249936; website: <https://www.rolls-royce.com/contact-us.aspx>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238–7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on August 12, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–19175 Filed 9–3–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0727; Project Identifier AD–2021–00835–R; Amendment 39–21726; AD 2021–19–08]

RIN 2120–AA64

Airworthiness Directives; Robinson Helicopter Company Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Robinson Helicopter Company Model R44 and R44 II helicopters. This AD was prompted by reports of cracked tail rotor blades (blades). This AD requires checking each blade for any crack and removing any cracked blade from service. This AD also requires removing all affected blades from service and prohibits installing any affected blade on any helicopter. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective September 22, 2021.

The FAA must receive comments on this AD by October 22, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Robinson Helicopter Company, Pete Riedl, 2901 Airport Drive, Torrance, CA 90505, United States; phone: (310) 539–0508; email: eng1@robinsonheli.com; website: <https://robinsonheli.com/>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0727; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for the Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: James Guo, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone (562) 627–5357; email james.guo@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA received reports of spanwise cracks found along the leading edge of part number (P/N) C029–3 blades, serial numbers (S/N) 9410 through 9909. These affected blades were factory-installed or shipped as spares between March and December 2019. The cracks were found at different inspection intervals ranging from preflight inspections to 100-hour inspections. In one instance, a cracked blade was

suspected when the pilot felt abnormal vibrations during flight; subsequent investigation determined that the blade was cracked. The cause of the cracks is a manufacturing defect in the properties of the blade skin that makes the blades prone to stress corrosion cracking. This condition, if not addressed, could result in reduced controllability and subsequent loss of control of the helicopter. The FAA is issuing this AD to address the unsafe condition on these products.

FAA’s Determination

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information

The FAA reviewed Robinson Helicopter Company R44 Service Bulletin

SB–108, dated June 30, 2021. This service bulletin specifies removing P/N C029–3 blades with S/N 9410 through 9909 from service. For continued operation until the affected blades are replaced, the service bulletin specifies a preflight inspection to be performed by the pilot.

AD Requirements

This AD requires, before further flight and thereafter before each flight, checking blade P/N C029–3 with S/N 9410 through 9909 inclusive, for any crack along the leading edge of the blade. An owner/operator (pilot) may perform this required check but must enter compliance with the applicable paragraph of this AD in the helicopter maintenance records in accordance with 14 CFR 43.9(a)(1) through (4) and 91.417(a)(2)(v). A pilot may perform this check because it involves visually checking each blade for a crack. This action can be performed equally well by a pilot or a mechanic. This check is an exception to the FAA’s standard maintenance regulations. This AD also requires, before further flight, removing from service any cracked blade and prohibits installing the affected blades on any helicopter. Additionally, this AD requires, within three months after the effective date of this AD, removing all affected blades from service.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those