

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Leonardo S.p.a.:** Docket No. FAA–2021–0720; Project Identifier 2019–SW–079–AD.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by October 25, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Leonardo S.p.a. Model AW109SP helicopters, certificated in any category, with an affected part as identified in European Union Aviation Safety Agency (EASA) AD 2019–0213, dated August 29, 2019 (EASA AD 2019–0213).

**(d) Subject**

Joint Aircraft Service Component (JASC) Codes: 2913, Hydraulic Pump (Elect/Eng), Main.

**(e) Unsafe Condition**

This AD was prompted by reports of the ineligible installation of hydraulic pump part number (P/N) 109–0760–42–103 on Model AW109SP helicopters resulting in the applicable instructions for continued airworthiness not being available. The FAA is issuing this AD to address this unsafe condition. The unsafe condition, if not addressed, could result in failure of the hydraulic pump and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0213.

**(h) Exceptions to EASA AD 2019–0213**

(1) Where EASA AD 2019–0213 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2019–0213 requires compliance from its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (2) of EASA AD 2019–0213 specifies to replace a part if any discrepancy is detected during the inspection, this AD requires removing that part from service.

(4) Where paragraph (3) of EASA AD 2019–0213 specifies to replace a part before exceeding 1,600 flight hours since first

installation on a helicopter, this AD requires removing that part from service before 1600 hours time in service since first installation on a helicopter.

(5) Where the service information required by EASA AD 2019–0213 specifies discarding the o-ring and gasket, this AD requires removing those parts from service.

(6) Where the service information required by EASA AD 2019–0213 specifies recording compliance with the service bulletin in the helicopter logbook, this AD does not include that requirement.

(7) This AD does not require the “Remarks” section of EASA AD 2019–0213.

**(i) No Reporting Requirement**

Although the service information referenced in EASA AD 2019–0213 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are prohibited.

**(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(l) Related Information**

(1) For EASA AD 2019–0213, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0720.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228–7323; email [Darren.Gassetto@faa.gov](mailto:Darren.Gassetto@faa.gov).

Issued on August 26, 2021.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021–19254 Filed 9–7–21; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2021–0725; Project Identifier MCAI–2020–01402–T]

**RIN 2120–AA64**

**Airworthiness Directives; Bombardier, Inc., Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2017–22–06, which applies to certain Bombardier, Inc., Model CL–600–2B16 (601–3A, 601–3R, and 604 Variants) airplanes. AD 2017–22–06 requires repetitive inspections for fuel leakage at the engine and auxiliary power unit (APU) fuel pumps, and related investigative and corrective actions if necessary. Since the FAA issued AD 2017–22–06, terminating actions have been developed and additional airplanes have been determined to be affected by the unsafe condition. This proposed AD would retain the requirements of AD 2017–22–06, and require an inspection of the APU, repair if necessary, and modification of the engine electrical fuel pump (EFP) installation. This proposed AD would also add airplanes to the applicability. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by October 25, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0725; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

#### FOR FURTHER INFORMATION CONTACT:

Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7367; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2021-0725; Project Identifier MCAI-2020-01402-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal

contact received about this proposed AD.

### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7367; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Background

The FAA issued AD 2017-22-06, Amendment 39-19086 (82 FR 49498, October 26, 2017) (AD 2017-22-06), for certain Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. AD 2017-22-06 requires repetitive inspections for fuel leakage at the engine and APU fuel pumps, and related investigative and corrective actions if necessary. AD 2017-22-06 resulted from reports of fuel leaks in the engine and APU EFP cartridge/canister electrical connectors and conduits. The FAA issued AD 2017-22-06 to address fuel leaks in certain fuel pumps to remove a potential fuel ignition hazard. FAA AD 2017-22-06 corresponds to AD CF-2016-32R1, dated October 12, 2016, issued by Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada.

### Actions Since AD 2017-22-06 Was Issued

The preamble to AD 2017-22-06 explains that the FAA considered the requirements “interim action” and was considering further rulemaking. The FAA has now determined that further rulemaking is indeed necessary, and

this proposed AD follows from that determination.

Since the FAA issued AD 2017-22-06, a general visual inspection of the APU and a modification of the engine EFP installation have been developed to address the root cause of the fuel leaks and provide terminating action for the repetitive general visual inspections and rectifications of fuel leaks from the engine and APU EFP electrical wiring conduit outlets. In addition, it was determined that additional airplanes are affected by the unsafe condition.

TCCA has issued TCCA AD CF-2016-32R4, dated October 13, 2020 (TCCA AD CF-2016-32R4); and TCCA AD CF-2020-38, dated October 13, 2020 (TCCA AD CF-2020-38); to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. This proposed AD refers to the TCCA ADs as the Mandatory Continuing Airworthiness Information, or the MCAI. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0725.

This proposed AD was prompted by reports of fuel leaks from the electrical connectors and conduits of the engine and APU EFP cartridge/canister, and additional actions have been developed to address the root cause of the fuel leaks. The FAA is proposing this AD to address the potential for a fire hazard as a result of fuel leak from the APU EFP electrical conduit in the hot landing light compartment. See the TCCA ADs for additional background information.

### Related Service Information Under 1 CFR Part 51

Bombardier has issued the following service information, which describes procedures for repetitive general visual inspections and rectifications for any fuel leak from the engine and APU EFP electrical wiring conduit outlets. These documents are distinct since they apply to different airplane serial numbers.

- Bombardier Service Bulletin 604-28-022, Revision 3, dated August 31, 2018.
- Bombardier Service Bulletin 605-28-010, Revision 3, dated August 31, 2018.
- Bombardier Service Bulletin 650-28-001, Revision 3, dated January 3, 2019.

Bombardier has also issued the following service information, which describes procedures for a detailed visual inspection of the APU for any damage or deformations (e.g., cut wires and a broken harness assembly of the fuel boost pump connector), modifying

the engine EFP installation, and repair if necessary. These documents are distinct since they apply to different airplane serial numbers.

- Bombardier Service Bulletin 604–28–024, dated June 16, 2020.
- Bombardier Service Bulletin 650–28–002, dated June 16, 2020.
- Bombardier Service Bulletin 605–28–012, dated June 16, 2020.

This proposed AD would also require Bombardier Service Bulletin 604–28–022, dated October 19, 2015, and Bombardier Service Bulletin 605–28–010, dated October 19, 2015, which the Director of the Federal Register approved for incorporation by reference as of November 30, 2017 (82 FR 49498, October 26, 2017).

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA’s Determination**

This product has been approved by the aviation authority of another

country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Proposed Requirements of This NPRM**

This proposed AD would retain all of the requirements of AD 2017–22–06 and require accomplishing the actions specified in the service information described previously, except as discussed under “Difference Between this Proposed AD and the MCAI.

**Difference Between This Proposed AD and the MCAI**

Paragraph E.1. of TCCA AD CF–2016–32R4, for airplane serial numbers 6125 through 6163, requires inspecting for

fuel leaks within 600 hours or 12 months, whichever occurs first after “the date of aeroplane entry in-service.” Paragraph (i) of this proposed AD, however, would require compliance for those airplanes within 600 flight hours or 12 months, whichever occurs first after “the effective date of this [FAA] AD.” Paragraph D.1. of TCCA AD CF–2016–32R4 requires compliance for this action for other serial numbers within 600 flight hours or 12 months after the effective date of the AD. The FAA has determined that the risk is not higher for serial numbers 6125 through 6163 compared with the other identified airplanes required to accomplish the same inspection. Therefore, for this AD, the compliance time is the same for all airplanes that are required to inspect for fuel leaks.

**Costs of Compliance**

The FAA estimates that this proposed AD affects 128 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2017-22-06 (for 121 airplanes).	1 work-hour × \$85 per hour = \$85.	\$0	\$85 per inspection cycle ...	\$10,285 per inspection cycle.
New proposed actions .....	20 work-hours × \$85 per hour = \$1,700.	1,768	\$3,468 .....	\$443,904.

The FAA estimates the following costs to do any necessary repair that

would be required based on the results of any required actions. The FAA has no

way of determining the number of aircraft that might need this repair:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
5 work-hours × \$85 per hour = \$425 .....	\$8,618	\$9,043

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA has determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the

States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive (AD) 2017–22–06, Amendment 39–19086 (82 FR 49498, October 26, 2017), and
  - b. Adding the following new AD:

**Bombardier, Inc.:** Docket No. FAA–2021–0725; Project Identifier MCAI–2020–01402–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by October 25, 2021.

**(b) Affected ADs**

This AD replaces AD 2017–22–06, Amendment 39–19086 (82 FR 49498, October 26, 2017) (AD 2017–22–06).

**(c) Applicability**

This AD applies to Bombardier, Inc., Model CL–600–2B16 (601–3A, 601–3R, and 604 Variants) airplanes, certificated in any category, serial numbers 5301 through 5665 inclusive, 5701 through 5990 inclusive, and 6050 through 6163 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 28, Fuel.

**(e) Reason**

This AD was prompted by reports of fuel leaks from the electrical connectors and conduits of the engine and auxiliary power unit (APU) electrical fuel pump (EFP)

cartridge/canister, and additional actions have been developed to address the root cause of the fuel leaks. The FAA is issuing this AD to address the potential for a fire hazard as a result of fuel leak from the APU EFP electrical conduit in the hot landing light compartment.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Actions for Certain Airplanes, With Revised Service Information and Method of Compliance Provisions**

This paragraph restates the requirements of paragraph (g) of AD 2017–22–06, with revised service information and method of compliance provisions. For Model CL–600–2B16 airplanes having serial numbers 5301 through 5665 inclusive: Within 600 flight hours or 12 months, whichever occurs first after November 30, 2017 (the effective date of AD 2017–22–06), do the inspections specified in paragraphs (g)(1) through (3) of this AD, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 604–28–022, dated October 19, 2015, or Bombardier Service Bulletin 604–28–022, Revision 3, dated August 31, 2018. Do all applicable corrective actions before further flight. Repeat the inspections at intervals not to exceed 600 flight hours or 12 months, whichever occurs first. As the effective date of this AD, use Bombardier Service Bulletin 604–28–022, Revision 3, dated August 31, 2018, only.

(1) Do a general visual inspection for traces of fuel coming from the right-hand engine boost pump at the location of the belly fairing screw (FS412, BL 0.0).

(2) Do a general visual inspection for traces of fuel coming from the left-hand engine boost pump at the location of the belly fairing screw (FS412, BL 0.0).

(3) Do a general visual inspection for traces of fuel coming from the EFP electrical wiring conduit outlet at the lower body fairing area for engine EFPs and at the right-hand landing light compartment for the APU EFP.

**(h) Retained Actions for Certain Other Airplanes, With Revised Service Information and Compliance Method Provisions**

This paragraph restates the requirements of paragraph (h) of AD 2017–22–06, with revised service information and compliance

method provisions. For Model CL–600–2B16 airplanes having serial numbers 5701 through 5955 inclusive, 5957, 5960 through 5966 inclusive, 5968 through 5971 inclusive, and 5981: Within 600 flight hours or 12 months, whichever occurs first after November 30, 2017 (the effective date of AD 2017–22–06), do the inspections specified in paragraphs (h)(1) through (3) of this AD, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions in Bombardier Service Bulletin 605–28–010, dated October 19, 2015, or Bombardier Service Bulletin 605–28–010, Revision 3, dated August 31, 2018. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections at intervals not to exceed 600 flight hours or 12 months, whichever occurs first. As of the effective date of this AD, use Bombardier Service Bulletin 605–28–010, Revision 3, dated August 31, 2018, only.

(1) Do a general visual inspection for traces of fuel coming from the right-hand engine boost pump at the location of the belly fairing screw (FS412, BL 0.0).

(2) Do a general visual inspection for traces of fuel coming from the left-hand engine boost pump at the location of the belly fairing screw (FS412, BL 0.0).

(3) Do a general visual inspection of the right-hand landing light compartment for traces of fuel coming from the APU EFP.

**(i) New Requirements of This AD: Inspections and Rectifications**

For the airplanes identified in figure 1 to paragraph (i) of this AD: At the applicable compliance time specified in figure 1 to paragraph (i) of this AD, do a general visual inspection for any fuel leak from the engine and APU EFP electrical wiring conduit outlets, in accordance with the Accomplishment Instructions of the applicable service information specified in figure 1 to paragraph (i) of this AD. If any fuel leak is found during the general visual inspection, before further flight, correct the fuel leak in accordance with the Accomplishment Instructions of the applicable service information specified in figure 1 to paragraph (i) of this AD. Thereafter, repeat the general visual inspection at intervals not to exceed 600 flight hours or 12 months, whichever occurs first.

FIGURE 1 TO PARAGRAPH (i)—COMPLIANCE TIMES AND SERVICE INFORMATION

Serial Nos.—	Compliance time—	Bombardier service bulletin—
5956, 5958, 5959, 5967, 5972 through 5980 inclusive, and 5982 through 5990 inclusive.	Within 600 flight hours or 12 months, whichever occurs first after the effective date of this AD.	Bombardier Service Bulletin 605–28–010, Revision 3, dated August 31, 2018.
6050 through 6163 inclusive .....	Within 600 flight hours or 12 months, whichever occurs first after the effective date of this AD.	Bombardier Service Bulletin 650–28–001, Revision 3, dated January 3, 2019.

**(j) New Requirements of This AD: Inspection and Modification**

Within 60 months after the effective date of this AD: Do a detailed visual inspection of

the APU for any damage or deformations, and modify the engine EFP installation, in accordance with the Accomplishment Instructions of the applicable service

information specified in figure 2 to paragraph (j) of this AD. If any damage or deformations are found during the detailed visual inspection, before further flight, do the repair

in accordance with the Accomplishment Instructions of the applicable service

information specified in figure 2 to paragraph (j) of this AD.

FIGURE 2 TO PARAGRAPH (j)—SERVICE INFORMATION

Serial Nos.—	Bombardier service bulletin—
5301 through 5665 inclusive .....	Bombardier Service Bulletin 604–28–024, dated June 16, 2020.
5701 through 5990 inclusive .....	Bombardier Service Bulletin 605–28–012, dated June 16, 2020.
6050 through 6163 inclusive .....	Bombardier Service Bulletin 650–28–002, dated June 16, 2020.

**(k) No Reporting Requirement**

Where service information identified in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(l) Terminating Actions**

Accomplishing the actions required by paragraph (j) of this AD terminates all requirements of this AD.

**(m) Credit for Previous Actions**

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 604–28–022, dated October 19, 2015, provided that within 4 months or 150 flight hours from the effective date of this AD or within 1 year from the last inspection, whichever occurs first, the actions accomplished in paragraph (g) are done using Bombardier Service Bulletin 604–28–022, Revision 3, dated August 31, 2018.

(2) This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 605–28–010, dated October 19, 2015, provided that within 4 months or 150 flight hours from the effective date of this AD or within 1 year from the last inspection, whichever occurs first, the actions accomplished in paragraph (h) of this AD are done using Bombardier Service Bulletin 605–28–010, Revision 3, dated August 31, 2018.

(3) This paragraph provides credit for actions required by paragraph (i) of this AD, if those actions were performed before the effective date of this AD using the service information in paragraphs (l)(3)(i) through (iii) of this AD, provided that within 1 year from the last inspection, the actions accomplished in paragraph (i) of this AD are done using Bombardier Service Bulletin 650–28–001, Revision 3, dated January 3, 2019. This service information is not incorporated by reference in this AD.

(i) Bombardier Service Bulletin 650–28–001, dated November 3, 2017.

(ii) Bombardier Service Bulletin 650–28–001, Revision 1, dated May 14, 2018.

(iii) Bombardier Service Bulletin 650–28–001, Revision 2, dated August 31, 2018.

**(n) Other FAA AD Provisions**

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as

appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(o) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF–2016–32R4, dated October 13, 2020; and TCCA AD CF–2020–38, dated October 13, 2020; for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0725.

(2) For more information about this AD, contact Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7367; fax 516–794–5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1–866–538–1247 or direct-dial telephone 1–514–855–2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued on September 1, 2021.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021–19237 Filed 9–7–21; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF THE TREASURY**

**Internal Revenue Service**

**26 CFR Parts 1, 53, 54 and 301**

[REG–102951–16]

RIN 1545–BN36

**Electronic-Filing Requirements for Specified Returns and Other Documents; Hearing**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Proposed rule; notice of hearing.

**SUMMARY:** This document provides a notice of public hearing on proposed regulations amending the rules for filing electronically and affects persons required to file partnership returns, corporate income tax returns, unrelated business income tax returns, withholding tax returns, and certain information returns, registration statements, disclosure statements, notifications, actuarial reports, and certain excise tax returns.

**DATES:** The public hearing is being held on Wednesday, September 22, 2021 at 10:00 a.m. EDT. The IRS must receive speakers’ outlines of the topics to be discussed at the public hearing by Tuesday, September 21, 2021.

**ADDRESSES:** The public hearing is being held by teleconference. Individuals who want to testify (by telephone) at the public hearing must send an email to [publichearings@irs.gov](mailto:publichearings@irs.gov) to receive the telephone number and access code for the hearing. The subject line of the email must contain the regulation number [REG–102951–16] and the word TESTIFY. For example, the subject line may say: Request to TESTIFY at Hearing for REG–102951–16. The email must include the name(s) of the speaker(s) and title(s). No outlines will be accepted by email. Send all outline submissions electronically via the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov) (IRS REG–102951–16). Both the email requesting to testify and the outline submissions must be received by September 21, 2021.

**FOR FURTHER INFORMATION CONTACT:** Concerning these proposed regulations,