

2018, for related information. You may examine the MCAI at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1076.

(2) Viking SB V3/0010, Revision NC and Viking PSM 1-3-5, Revision IR, contain additional information related to this AD.

(3) For more information about this AD, contact Deep Gaurav, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7300; email: [deep.gaurav@faa.gov](mailto:deep.gaurav@faa.gov).

(4) For service information related to this AD, contact Viking Air Limited Technical Support, 1959 De Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; telephone: (North America) (800) 663-8444; fax: (250) 656-0673; email: [technical.support@vikingair.com](mailto:technical.support@vikingair.com); website: <https://www.vikingair.com/support/service-bulletins>. You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

Issued on February 1, 2022.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-02547 Filed 2-7-22; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-0091; Project Identifier MCAI-2021-01123-T]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A318 series airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. This proposed AD was prompted by reports that during inspections accomplished in accordance with certain airworthiness limitation items (ALIs), cracks were detected in double joggle areas at frame (FR) 16 and FR20, right hand and left hand sides. This proposed AD would require repetitive special detailed inspections of certain areas and applicable on-condition

actions, as specified in a European Union Aviation Safety Agency (EASA) AD. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 25, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this material on the EASA website at <https://ad.easa.europa.eu>.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0091; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

#### FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email [sanjay.ralhan@faa.gov](mailto:sanjay.ralhan@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0091; Project Identifier MCAI-2021-01123-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include

supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email [sanjay.ralhan@faa.gov](mailto:sanjay.ralhan@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0227, dated October 11, 2021 (EASA AD 2021-0227) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus SAS Model A318 series airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

This proposed AD was prompted by reports that during inspections accomplished in accordance with ALI tasks 531153 and 531155, cracks were detected in the double joggle areas at FR16 and FR20, right hand and left hand sides. The FAA is proposing this

AD to address cracks in these areas, which, if not detected and corrected, could reduce the structural integrity of the fuselage. See the MCAI for additional background information.

#### Other Relevant Rulemaking

AD 2020-20-05, Amendment 39-21261 (85 FR 65197, October 15, 2020) (AD 2020-20-05) applies to Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, -133, -151N, and -153N airplanes; Model A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N, -253N, -271N, -272N, and -273N airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes. AD 2020-20-05 requires incorporating new or more restrictive airworthiness limitations. Accomplishment of the proposed actions would terminate ALI Tasks 531153-02-1, 531153-02-2, 531155-02-1 and 531155-02-2, as required by paragraph (i) of AD 2020-20-05 for Model A318 series airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes only.

#### Related Service Information Under 1 CFR Part 51

EASA AD 2021-0227 specifies procedures for repetitive special detailed inspections (rototest inspections) of double joggle areas at FR16 and FR20, right hand and left

hand sides for cracking, applicable on-condition actions (repair) and an optional modification of the double joggle area, which terminates the repetitive inspections. The modification includes a rotating probe inspection of certain fastener holes for cracks, a check of the fastener holes for a minimum diameter, and applicable on-condition actions (repair and oversizing holes). This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA's Determination

These products have been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

#### Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2021-0227 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

#### Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD

process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2021-0227 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021-0227 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-0227 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2021-0227. Service information required by EASA AD 2021-0227 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0091 after the FAA final rule is published.

#### Costs of Compliance

The FAA estimates that this proposed AD would affect 1,549 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

#### ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 55 work-hours × \$85 per hour = \$4,675 .....	\$0	Up to \$4,675 .....	Up to \$7,241,575.

#### ESTIMATED COSTS FOR OPTIONAL ACTIONS

Labor cost	Parts cost	Cost per product
60 work-hours × \$85 per hour = \$5,100 .....	\$1,624	\$6,724

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus SAS:** Docket No. FAA-2022-0091; Project Identifier MCAI-2021-01123-T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 25, 2022.

#### (b) Affected ADs

This AD affects AD 2020-20-05, Amendment 39-21261 (85 FR 65197, October 15, 2020) (AD 2020-20-05).

#### (c) Applicability

This AD applies to Airbus SAS Model airplanes specified in paragraphs (c)(1) through (4) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2021-0227, dated October 11, 2021 (EASA AD 2021-0227).

(1) Model A318-111, -112, -121, and -122 airplanes.

(2) Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.

(3) Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes.

(4) Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Unsafe Condition

This AD was prompted by reports that, during inspections accomplished as specified in certain airworthiness limitation items (ALIs), cracks were detected in the double joggle areas at frame (FR) 16 and FR20 in the nose forward fuselage. The FAA is issuing this AD to address cracks in these areas, which, if not detected and corrected, could reduce the structural integrity of the fuselage.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0227.

#### (h) Exceptions to EASA AD 2021-0227

(1) Where EASA AD 2021-0227 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021-0227 does not apply to this AD.

(3) Where paragraph (2) of EASA AD 2021-0227 specifies to “contact Airbus for approved repair instructions and, within the compliance time specified therein, accomplish those instructions accordingly” if any cracks are detected, for this AD if any cracking is detected, the cracking must be repaired before further flight using a method approved by Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(4) Where paragraphs (3) and (4) of EASA AD 2021-0227 specify “Airbus approved repair instructions,” or “post-repair inspection instructions approved by Airbus,” for this AD, to be acceptable for credit, the repair instructions must be approved by Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0227 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Terminating Action for Certain Requirements in AD 2020-20-05

Accomplishing the initial inspections required by this AD terminates ALI Tasks 531153-02-1, 531153-02-2, 531155-02-1 and 531155-02-2, as required by paragraph (i) of AD 2020-20-05 only for the airplanes identified in paragraph (c) of this AD.

#### (k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraphs (h)(3), (i), and (k)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s existing maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (l) Related Information

(1) For EASA AD 2021-0227, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0091.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email [sanjay.ralhan@faa.gov](mailto:sanjay.ralhan@faa.gov).

Issued on February 2, 2022.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives,  
Compliance & Airworthiness Division,  
Aircraft Certification Service.*

[FR Doc. 2022-02520 Filed 2-7-22; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2020-7071; Project Identifier 2019-CE-048-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Viking Air Limited (Type Certificate Previously Held by Bombardier Inc. and de Havilland, Inc.) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 64-09-03, which applies to all de Havilland (type certificate now held by Viking Air Limited) Model DHC-2 “Beaver” airplanes. AD 64-09-03 requires inspecting the aileron mass balance weight arms for cracks and corrosion and replacing any damaged part. Since the FAA issued AD 64-09-03, Transport Canada superseded its mandatory continuing airworthiness information (MCAI) to correct an unsafe condition on these products. This proposed AD would require establishing a corrosion prevention and control program to identify and correct corrosion. This proposed AD would also require completing all of the initial tasks identified in the program and reporting corrosion findings to Viking. The proposed corrosion prevention and control program would include the inspection of the aileron balance weight arms required by AD 64-09-03. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 25, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Viking Air Limited Technical Support, 1959 De Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; phone: (North America) (800) 663-8444; fax: (250) 656-0673; email: [technical.support@vikingair.com](mailto:technical.support@vikingair.com); website: <https://www.vikingair.com/support/service-bulletins>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-7071; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Aziz Ahmed, Aviation Safety Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; phone: (516) 287-7329; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2020-7071; Project Identifier 2019-CE-048-AD” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA issued AD 64-09-03, Amendment 718 (29 FR 5390; April 22, 1964) (AD 64-09-03) for all de Havilland (type certificate now held by Viking Air Limited) Model DHC-2 “Beaver” airplanes. AD 64-09-03 requires repetitively inspecting the aileron mass balance weight arms for cracks and corrosion and replacing any damaged part. AD 64-09-03 resulted from cracks and corrosion found on aileron mass balance weight arm part numbers (P/Ns) C2WA151, C2WA152, C2WA127, and C2WA128.

**Actions Since AD 64-09-03 Was Issued**

Since the FAA issued AD 64-09-03, the type certificate holder for Model DHC-2 airplanes changed from de Havilland to Viking Air Limited. Transport Canada, which is the aviation authority for Canada, superseded its prior ADs on this unsafe condition and issued AD CF-2019-25, dated July 5, 2019 (referred to after this as “the MCAI”), to correct an unsafe condition for all serial-numbered Viking Air Limited Model DHC-2 Mk. I, DHC-2 Mk. II, and DHC-2 Mk. III airplanes. The MCAI states:

Service experience indicates that aging aircraft are more likely to be affected by corrosion. Viking Air Limited (Viking), as Type Certificate holder for DHC-2, has developed a supplementary inspection and corrosion control program which identifies specific area that must be inspected to ensure the corrosion-related degradation does not