

This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3520; email: bill.ashforth@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet www.myboeingfleet.com. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on July 1, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-19298 Filed 9-8-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0978; Project Identifier AD-2022-00460-E]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) GENx-1B and GENx-2B model turbofan engines. This proposed AD was prompted by a manufacturer investigation that revealed that certain high-pressure turbine (HPT) stage 2 disks, forward seals, and stages 6-10 compressor rotor spools were manufactured from powder metal material suspected to contain iron inclusion. This proposed AD would require the replacement of the affected HPT stage 2 disks, forward seals, and stages 6-10 compressor rotor spools. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 24, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ge.com; website: <https://www.ge.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this

material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0978; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7178; email: Alexei.T.Marqueen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0978; Project Identifier AD-2022-00460-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be

placed in the public docket of this NPRM. Submissions containing CBI should be sent to Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA was notified by the manufacturer of the detection of iron inclusion in an HPT stage 2 disk manufactured from the same powder metal material used to manufacture certain HPT stage 2 disks, forward seals, and stages 6–10 compressor rotor spools for GENx–1B64, GENx–1B64/P1, GENx–1B64/P2, GENx–1B67, GENx–1B67/P1, GENx–1B67/P2, GENx–1B70, GENx–1B70/75/P1, GENx–1B70/75/P2, GENx–1B70/P1, GENx–1B70/P2, GENx–1B70C/P1, GENx–1B70C/P2, GENx–1B74/75/P1, GENx–1B74/75/P2, GENx–1B76/P2, GENx–1B76A/P2 (GENx–1B) and GENx–2B67, GENx–2B67B, and GENx–2B67/P (GENx–2B) model turbofan engines. Further investigation by the manufacturer determined that the iron inclusion is attributed to deficiencies in the manufacturing process. The investigation by the manufacturer also determined that certain GENx–1B and

GENx–2B HPT stage 2 disks, forward seals, and stages 6–10 compressor rotor spools made from billets manufactured using the same process may have reduced material properties and a lower fatigue life capability due to iron inclusion, which may cause premature fracture and uncontained failure. As a result of its investigation, the manufacturer published service information that specifies procedures for the removal and replacement of certain HPT stage 2 disks, forward seals, and stages 6–10 compressor rotor spools installed on GENx–1B and GENx–2B model turbofan engines. This condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the aircraft.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information

The FAA reviewed GE GENx–1B Service Bulletin 72–0505, Revision 02, dated April 5, 2022. The FAA also reviewed GE GENx–2B Service Bulletin 72–0444, Revision 02, dated April 5, 2022. This service information describes

procedures for removing the HPT stage 2 disk, forward seal, and stages 6–10 compressor rotor spool. These documents are distinct since they apply to different engine models.

Proposed AD Requirements in This NPRM

This proposed AD would require the removal of certain HPT stage 2 disks, forward seals, and stages 6–10 compressor rotor spools and replacement with parts eligible for installation.

Differences Between This Proposed AD and the Service Information

GE GENx–1B Service Bulletin 72–0505, Revision 02, dated April 5, 2022, uses the term “HPT rotor stage 2 disk,” while this proposed AD uses the term “HPT stage 2 disk.”

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 3 engines installed on airplanes of U.S. registry. The FAA estimates that 0 engines installed on airplanes of U.S. registry would require replacement of the forward seal or HPT stage 2 disk.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace stages 6–10 compressor rotor spool.	8 work-hours × \$85 per hour = \$680.	\$846,519 (average pro-rated part cost).	\$847,199	\$2,541,597
Replace forward seal	8 work-hours × \$85 per hour = \$680.	\$364,558 (average pro-rated part cost).	365,238	0
Replace HPT stage 2 disk	8 work-hours × \$85 per hour = \$680.	\$363,424 (average pro-rated part cost).	364,104	0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an

unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

General Electric Company: Docket No. FAA–2022–0978; Project Identifier AD–2022–00460–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by October 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company GENx–1B64, GENx–1B64/P1, GENx–1B64/P2, GENx–1B67, GENx–1B67/P1,

GENx–1B67/P2, GENx–1B70, GENx–1B70/75/P1, GENx–1B70/75/P2, GENx–1B70/P1, GENx–1B70/P2, GENx–1B70C/P1, GENx–1B70C/P2, GENx–1B74/75/P1, GENx–1B74/75/P2, GENx–1B76/P2, GENx–1B76A/P2, GENx–2B67, GENx–2B67B, and GENx–2B67/P model turbofan engines with an installed high-pressure turbine (HPT) stage 2 disk, forward seal, or stages 6–10 compressor rotor spool with a part number (P/N) and serial number (S/N) identified in Table 1 to paragraph (c) of this AD.

Table 1 to Paragraph (c) – Affected HPT Stage 2 Disks, Forward Seals, and Stages 6-10 Compressor Rotor Spools

Part Name	P/N	S/N
HPT stage 2 disk	2300M84P02	TMT4AF08
		TMT4AF10
		TMT4AF11
		TMT4AF12
Forward seal	2417M60P02	VOLF1931
		VOLF1933
		VOLF1942
		VOLF1977
		VOLF1993
		VOLF2014
Stages 6-10 compressor rotor spool	2340M36G01	GWN0R86N
Stages 6-10 compressor rotor spool	2439M35G01	GWN0RCKT
		GWN0R62G
		GWN0R86J
Stages 6-10 compressor rotor spool	2439M35G02	GWN0RA89
		GWN0R6K9
		GWN0R7G9
		GWN0R7K4
		GWN0R752
Stages 6-10 compressor rotor spool	2610M90G01	GWN0R98P
		GWN0R5EK
		GWN0R6EH
		GWN0R7K1
		GWN0R89A

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section; 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by a manufacturer investigation that revealed certain HPT stage 2 disks, forward seals, and stages 6–10

compressor rotor spools were manufactured from powder metal material suspected to contain iron inclusion. The FAA is issuing this AD to prevent fracture and potential

uncontained failure of certain HPT stage 2 disks, forward seals, and stages 6–10 compressor rotor spools. The unsafe condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the aircraft.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before exceeding 600 flight cycles after the effective date of this AD, remove the affected HPT stage 2 disk, forward seal, and stages 6–10 compressor rotor spool from service and replace with a part eligible for installation.

(2) For affected engines not in service, before further flight, remove the affected HPT stage 2 disk, forward seal, and stages 6–10 compressor rotor spool and replace with a part eligible for installation.

(h) Definitions

(1) For the purpose of this AD, a “part eligible for installation” is any HPT stage 2 disk, forward seal, or stages 6–10 compressor rotor spool with a P/N and S/N not identified in Table 1 to paragraph (c) of this AD.

(2) For the purpose of this AD, “engines not in service” are engines that are in long-term or short-term storage as of the effective date of this AD.

(i) Installation Prohibition

After the effective date of this AD, do not install an HPT stage 2 disk, forward seal, or stages 6–10 compressor rotor spool with a P/N and S/N identified in Table 1 to paragraph (c) of this AD onto any engine.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7178; email: Alexei.T.Marqueen@faa.gov.

Issued on July 21, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-19397 Filed 9-8-22; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R08-OAR-2021-0001; FRL-10014-01-R8]

Air Plan Approval; Montana; Revisions to Regional Haze State Implementation Plan and Partial Withdrawals to Regional Haze Federal Implementation Plan

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve a State Implementation Plan (SIP) revision submitted by the State of Montana on March 25, 2020, addressing regional haze. Specifically, EPA is proposing to approve a SIP revision for the first implementation period of the Clean Air Act’s (CAA) regional haze program that addresses the nitrogen oxides (NO_x) and sulfur dioxide (SO₂) Best Available Retrofit Technology (BART) requirements for two electric generating unit (EGU) facilities, as well as proposing to withdraw portions of the Federal Implementation Plan (FIP) promulgated by EPA in 2012 (2012 regional haze FIP) addressing the NO_x, SO₂ and particulate matter (PM) BART requirements for two cement kilns and the PM BART requirements for the same two EGU facilities. This action also addresses the United States Court of Appeals for the Ninth Circuit’s June 9, 2015 vacatur and remand of portions of the FIP. EPA is proposing this action pursuant to sections 110 and 169A of the CAA.

DATES: Written comments must be received on or before November 8, 2022.

Public hearing: If anyone contacts us requesting a public hearing on or before September 26, 2022, we will hold a hearing. Additional information about the hearing, if requested, will be published in a subsequent **Federal Register** document. Contact Jaslyn Dobrahner at dobrahner.jaslyn@epa.gov, to request a hearing or to determine if a hearing will be held.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-R08-OAR-2021-0001, to the Federal Rulemaking Portal: <https://www.regulations.gov>. Follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from www.regulations.gov. EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be

Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to make. EPA will generally not consider comments or comment contents located outside of the primary submission (*i.e.*, on the web, cloud, or other file sharing system). For additional submission methods, the full EPA public comment policy, information about CBI or multimedia submissions, and general guidance on making effective comments, please visit <https://www.epa.gov/dockets/commenting-epa-dockets>.

Docket: All documents in the docket are listed in the www.regulations.gov index. Although listed in the index, some information is not publicly available, *e.g.*, CBI or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, will be publicly available only in hard copy. Publicly available docket materials are available electronically in www.regulations.gov. To reduce the risk of COVID-19 transmission, for this action we do not plan to offer hard copy review of the docket. Please email or call the person listed in the **FOR FURTHER INFORMATION CONTACT** section if you need to make alternative arrangements for access to the docket.

FOR FURTHER INFORMATION CONTACT: Jaslyn Dobrahner, Air and Radiation Division, EPA, Region 8, Mailcode 8ARD-IO, 1595 Wynkoop Street, Denver, Colorado 80202-1129, telephone number: (303) 312-6252, email address: dobrahner.jaslyn@epa.gov.

SUPPLEMENTARY INFORMATION:

Throughout this document wherever “we,” “us,” or “our” is used, we mean EPA.

Table of Contents

- I. What action is EPA proposing?
- II. Background
 - A. Requirements of the Clean Air Act and EPA’s Regional Haze Rule
 - B. Best Available Retrofit Technology (BART)
 - C. Long-Term Strategy and Reasonable Progress Requirements
 - D. Monitoring, Recordkeeping, and Recording
 - E. Consultation With Federal Land Managers (FLMs)
 - F. Clean Air Act 110(l)
 - G. Regulatory and Legal History of the Montana Regional Haze FIP
- III. EPA’s Evaluation of Montana’s Regional Haze SIP Revisions