

this AD requires using April 26, 2022 (the effective date of AD 2022–06–02).

(3) Where paragraph (2) of EASA AD 2022–0120R1 specifies “any discrepancy,” for this AD “any discrepancy” includes broken fittings, missing bolts, an electronics rack FIN 80VU that is in contact with structure, any bush that has migrated, burred material, and cracks.

(4) Where the service information referenced in EASA AD 2022–0120R1 specifies to “replace the damaged parts with new parts,” this AD allows replacing damaged parts with new or serviceable parts.

(5) The “Remarks” section of EASA AD 2022–0120R1 does not apply to this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the inspections and corrective actions required by paragraph (g) of this AD if those actions were accomplished prior to the effective date of this AD using Airbus Service Bulletin A320–25–1BKJ, Revision 02, dated April 9, 2020, with corrections referenced in the Airbus Technical Adaptation 80827186/024/2020, Issue 1, dated September 18, 2020.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Additional Information

(1) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email dan.rodina@faa.gov.

(2) For Airbus service information identified in this AD that is not incorporated by reference, contact Airbus SAS, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; website airbus.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0120R1, dated June 30, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0120R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 9, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–25114 Filed 11–17–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1478; Project Identifier MCAI–2022–00668–E]

RIN 2120–AA64

Airworthiness Directives; Pratt & Whitney Canada Corp. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2004–04–09, which applies to certain Pratt & Whitney Canada Corp. (P&WC) JT15D–1, JT15D–1A, and JT15D–1B model turbofan engines. AD 2004–04–09 requires a one-time borescope inspection (BSI) of the rear face of certain impellers for evidence of a machined groove or step, and repair or replacement of the impeller if a groove or step is found. Since the FAA issued AD 2004–04–09, the FAA was notified of an uncontained failure of an impeller installed on a P&WC JT15D–1A engine during takeoff and subsequent investigation by the manufacturer that discovered machining marks on the impeller. This proposed AD would require borescope fluorescent penetrant inspection (FPI) of the rear face of certain impellers for evidence of machining witness lines and, depending on the results of the inspection, replacement of the impeller, as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by January 3, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2022–1478 or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For material that is proposed for IBR in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; phone: (888) 663–3639; email: *AD-CN@tc.gc.ca*. You may find this material on the Transport Canada website at *tc.canada.ca/en/aviation*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

FOR FURTHER INFORMATION CONTACT:

Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7146; email: *barbara.caufield@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2022–1478; Project Identifier MCAI–2022–00668–E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner.

Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2004–04–09, Amendment 39–13490 (69 FR 9520, March 1, 2004) (AD 2004–04–09), for certain P&WC JT15D–1, JT15D–1A, and JT15D–1B model turbofan engines. AD 2004–04–09 was prompted by three reports of uncontained failure of the impeller. AD 2004–04–09 requires a one-time borescope inspection of the rear face of certain impellers for evidence of a machined groove or step, and repair or replacement of the impeller if a groove or step is found. The FAA issued AD 2004–04–09 to prevent uncontained failure of the impeller and possible damage to the airplane.

Actions Since AD 2004–04–09 Was Issued

Since the FAA issued AD 2004–04–09, Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF–2022–27, dated June 2, 2022 (Transport Canada AD CF–2022–27), to address an unsafe condition for P&WC JT15D–1, JT15D–1A, and JT15D–1B model turbofan engines. The MCAI states that there has been one recent in-service event of a JT15D–1A engine uncontained failure during a takeoff roll of the airplane. An investigation by P&WC has determined that a crack originated from machining marks on the back face of the impeller and subsequently propagated until the impeller fractured. There is evidence that the event engine had been previously inspected in accordance with P&WC Service Bulletin (SB) No. JT15D–72–7590, dated May 23, 2003 (mandated by Transport Canada AD CF–2003–17,

dated June 23, 2003), but it appears that the machining marks were not detected. P&WC, therefore, published P&WC SB JT15D–72–7655, Original Issue, dated April 14, 2022, to inspect the rear face of the impeller using a new borescope FPI procedure. As a result, Transport Canada issued AD CF–2022–27 to require accomplishment of the borescope FPI at the next hot section inspection until the impeller, part number (P/N) 3020365, is replaced at the next scheduled engine overhaul.

This proposed AD was prompted by three prior reports of uncontained failure of the impeller, and one additional recent report of an in-service uncontained failure event. The FAA is proposing this AD to address uncontained failure of the impeller. This condition, if not addressed, could result in fracture of the impeller, subsequent uncontained failure of the engine, and damage to the airplane. See Transport Canada AD CF–2022–27 for additional background information.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2022–1478.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the Transport Canada AD. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Transport Canada AD CF–2022–27. Transport Canada AD CF–2022–27 specifies instructions for performing a one-time inspection of the rear face of the impeller and replacing the impeller if unacceptable machining witness lines or crack indications are found. Transport Canada AD CF–2022–27 also specifies instructions for replacing the impeller at the next scheduled engine overhaul.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would retain none of the requirements of AD 2004–04–09. This proposed AD would require

accomplishing the actions specified in Transport Canada AD CF–2022–27, described previously.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and CAAs to use this process. As a result, the FAA

proposes to incorporate by reference Transport Canada AD CF–2022–27 in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF–2022–27 in its entirety through that incorporation. Using common terms that are the same as the heading of a particular section in the Transport Canada AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "Compliance," compliance with this AD requirement is not limited to the section titled "Corrective Actions" in Transport

Canada AD CF–2022–27. Service information required by the Transport Canada AD for compliance will be available at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA–2022–1478 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 100 engines installed on airplanes of U.S. Registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect impeller	6 work-hours × \$85 per hour = \$510	\$0	\$510	\$51,000
Replace impeller	30 work-hours × \$85 per hour = \$2,550	75,000	77,550	7,755,000

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive 2004–04–09, Amendment 39–13490 (69 FR 9520, March 1, 2004); and
 - b. Adding the following new airworthiness directive:

Pratt & Whitney Canada Corp.: Docket No. FAA–2022–1478; Project Identifier MCAI–2022–00668–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) action by January 3, 2023.

(b) Affected ADs

This AD replaces AD 2004–04–09, Amendment 39–13490 (69 FR 9520, March 1, 2004) (AD 2004–04–09).

(c) Applicability

This AD applies to Pratt & Whitney Canada Corp. JT15D–1, JT15D–1A, and JT15D–1B model turbofan engines as identified in Transport Canada AD CF–2022–27, dated June 2, 2022 (Transport Canada AD CF–2022–27).

(d) Subject

Joint Aircraft Service Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by three prior reports of uncontained failure of the impeller, and one additional recent report of an in-service uncontained failure event. The FAA is issuing this AD to prevent uncontained failure of the impeller. The unsafe condition, if not addressed, could result in fracture of the impeller, subsequent uncontained failure of the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: Perform all required actions within the compliance times specified in, and in accordance with, Transport Canada AD CF–2022–27.

(h) No Reporting Requirement

Although the service information referenced in Transport Canada AD CF–2022–27 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD,

if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD and email it to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Transport Canada AD CF-2022-27, dated June 2, 2022.

(ii) [Reserved]

(3) For Transport Canada AD CF-2022-27, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; phone: (888) 663-3639; email: AD-CN@tc.gc.ca; website: tc.canada.ca/en/aviation.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 10, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-25016 Filed 11-17-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

International Trade Administration

19 CFR Part 351

[Docket No. 221115-0239]

RIN 0625-AB23

Determining the Existence of a Particular Market Situation That Distorts Costs of Production

AGENCY: Enforcement and Compliance, International Trade Administration, Department of Commerce.

ACTION: Advanced notice of proposed rulemaking.

SUMMARY: Enforcement and Compliance (E&C), of the Department of Commerce (Commerce), administers the antidumping duty (AD) and countervailing duty (CVD) AD/CVD trade remedy laws of the Tariff Act of 1930, as amended (the Act). Section 773(e) of the Act provides for Commerce to address, in its antidumping calculations, the existence of a particular market situation (PMS), such that the cost of materials and fabrication do not accurately reflect the cost of production in the ordinary course of trade. Commerce seeks public comments as it considers revisiting its PMS methodology and issuing a new regulation that would identify information that Commerce should take into consideration and should not take into consideration in determining whether a PMS exists that distorts the cost of production. Commerce also seeks comments as it considers adjustments to calculations when the amount of distortion in the cost of production caused by a PMS cannot be quantified based on the record before it.

DATES: Comments must be received no later than December 18, 2022.

ADDRESSES: Submit electronic comments only through the Federal eRulemaking Portal at <https://www.Regulations.gov>, Docket No. ITA-2022-0012. Comments may also be submitted by mail or hand delivery/courier, addressed to Lisa W. Wang, Assistant Secretary for Enforcement and Compliance, Room 18022, Department of Commerce, 1401 Constitution Ave. NW, Washington, DC 20230. An appointment must be made in advance with the APO/Dockets Unit at (202) 482-4920 to submit comments in person by hand delivery or courier. All comments submitted during the comment period permitted by this document will be a matter of public record and will generally be available on the Federal eRulemaking Portal at

<https://www.Regulations.gov>. Commerce will not accept comments accompanied by a request that part or all of the material be treated confidentially because of its business proprietary nature or for any other reason. Therefore, do not submit confidential business information or otherwise sensitive or protected information.

Any questions concerning the process for submitting comments should be submitted to Enforcement & Compliance Communications office at (202) 482-0063 or ECCcommunications@trade.gov.

FOR FURTHER INFORMATION CONTACT: Scott McBride at (202) 482-6292 and Hendricks Valenzuela at (202) 482-4750.

SUPPLEMENTARY INFORMATION:

Background on Particular Market Situation

In 2015, pursuant to the Trade Preferences Extension Act (TPEA), section 771(15) of the Act was amended to provide that Commerce consider sales to be outside the “ordinary course of trade” when there are situations in which Commerce “determines that the particular market situation prevents a proper comparison with the export price or constructed export price.” Further, section 773(e) of the Act was amended to provide that in determining the “costs of material and fabrication or other processing of any kind employed in producing the merchandise, during a period which would ordinarily permit the production of the merchandise in the ordinary course of trade,” for determining constructed value, “if a particular market situation exists such that the cost of materials and fabrication or other processing of any kind does not accurately reflect the cost of production in the ordinary course of trade,” Commerce “may use another calculation methodology under this subtitle or any other calculation methodology.” The Act does not (1) define a particular market situation (“PMS”), (2) identify the information which Commerce should consider in determining the existence of a PMS that “does not accurately reflect the costs of production in the ordinary course of trade,” or (3) provide Commerce with guidance as to the information which Commerce should consider in determining if a market situation is, or is not, “particular.”

The legislative history of the cost-based particular market situation reflects that Congress intended for Commerce to not only identify such situations, but to also effectively address them in its calculations. For example, in advocating for the TPEA language, one