

# Rules and Regulations

Federal Register

Vol. 87, No. 241

Friday, December 16, 2022

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF AGRICULTURE

### Federal Crop Insurance Corporation

#### 7 CFR Part 457

[Docket ID FCIC–22–0007]

RIN 0563–AC80

#### Walnut Crop Insurance Provisions; Correction

**AGENCY:** Federal Crop Insurance Corporation, U.S. Department of Agriculture (USDA).

**ACTION:** Correcting amendment.

**SUMMARY:** On October 25, 2022, the Federal Crop Insurance Corporation (FCIC) revised the Walnut Crop Insurance Provisions. That final rule contained an incorrect instruction in the Settlement of Claim section. This document makes the correction.

**DATES:** Effective December 16, 2022.

**FOR FURTHER INFORMATION CONTACT:** Francie Tolle; telephone (816) 926–7730; email [francie.tolle@usda.gov](mailto:francie.tolle@usda.gov). Persons with disabilities who require alternative means of communication should contact the USDA Target Center at (202) 720–2600 or (844) 433–2774.

#### SUPPLEMENTARY INFORMATION:

##### Background

The Common Crop Insurance Regulations in 7 CFR part 457 were revised by a final rule with request for comments published in the **Federal Register** on October 25, 2022 (87 FR 64365). Changes were made in that rule to the Walnut Crop Insurance Provisions. In reviewing the changes made, FCIC found an incorrect instruction in the Settlement of Claim section. This document makes the correction in the Walnut Crop Insurance Provisions.

##### List of Subjects in 7 CFR Part 457

Acreage allotments, Crop insurance, Reporting and recordkeeping requirements.

Accordingly, 7 CFR part 457 is corrected by making the following amendment:

#### PART 457—COMMON CROP INSURANCE REGULATIONS

■ 1. The authority citation for part 457 continues to read as follows:

**Authority:** 7 U.S.C. 1506(l) and 1506(o).

■ 2. In § 457.122, in the “Walnut Crop Provisions,” in section 11, revise paragraph (d).

The revision reads as follows:

#### § 457.122 Walnut crop insurance provisions.

\* \* \* \* \*

##### 11. Settlement of Claim

\* \* \* \* \*

(d) Mature walnut production damaged due to an insurable cause of loss which occurs within the insurance period may be adjusted for quality based on an inspection by the Dried Fruit Association or during our loss adjustment process. Walnut production that has mold damage greater than 8 percent, based on the net delivered weight, will be reduced by the quality adjustment factors contained in the Special Provisions. If walnut production exceeds 30 percent mold damage and will not be sold, the production to count will be zero.

\* \* \* \* \*

**Marcia Bunger,**  
Manager, Federal Crop Insurance Corporation.

[FR Doc. 2022–27228 Filed 12–15–22; 8:45 am]

**BILLING CODE 3410–08–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–1237; Project Identifier MCAI–2022–00434–T; Amendment 39–22264; AD 2022–25–08]

RIN 2120–AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A300 series airplanes; Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes); and Model A310 series airplanes. This AD was prompted by a report that a Model A319 airplane lost the right-hand front windshield in flight. Due to the design similarity, this condition can also exist or develop on Model A300, A300–600, and A310 series airplanes. This AD requires repetitive inspections and electrical test measurements (ETMs) of the affected parts, and applicable corrective actions, and prohibits the installation of affected parts under certain conditions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective January 20, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 20, 2023.

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1237; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website [easa.europa.eu](https://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](https://ad.easa.europa.eu).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this

material at the FAA, call 206–231–3195. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1237.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th Street, Des Moines, WA 98198; telephone 206–231–3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes; Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and B4–622R airplanes; Model A300 C4–605R Variant F airplanes; Model A300 F4–605R and F4–622R airplanes; and Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes. The NPRM published in the **Federal Register** on September 27, 2022 (87 FR 58463). The NPRM was prompted by AD 2022–0058, dated March 28, 2022, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2022–0058) (referred to after this as the MCAI). The MCAI states that a Model A319 airplane lost the right-hand front windshield in flight, with consequent rapid flight deck depressurization, causing damage to flight deck items and systems, and significant increase of flightcrew workload. The investigations

identified several contributing factors, including manufacturing variability, fretting between windshield components, water ingress, and electrical braids corrosion, which led to a thermal shock and overheat, damaging more than one windshield structural ply and impairing the structural integrity of the windshield. Due to the design similarity, this condition can also exist or develop on Model A300, A300–600, and A310 series airplanes. This condition, if not addressed, could lead to failure of the windshield, possibly result in injury to the flightcrew and in-flight depressurization of the airplane, and would significantly increase pilot workload.

In the NPRM, the FAA proposed to require repetitive inspections and ETMs of the affected parts, and applicable corrective actions, and prohibit the installation of affected parts under certain conditions, as specified in EASA AD 2022–0058. The FAA is issuing this AD to address possible windshield failure. This condition, if not addressed, could possibly result in injury to the flightcrew and in-flight depressurization of the airplane, and would significantly increase pilot workload.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1237.

**Discussion of Final Airworthiness Directive**

**Comments**

The FAA received comments from the Air Line Pilots Association, International (ALPA) and FedEx Express

who supported the NPRM without change.

**Conclusion**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. This AD is adopted as proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

EASA AD 2022–0058 specifies procedures for repetitive detailed inspections and ETMs of the affected parts, and applicable corrective actions. The corrective actions include replacing any affected window with a serviceable window. EASA AD 2022–0058 also prohibits installing certain part numbers.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

**Costs of Compliance**

The FAA estimates that this AD affects 120 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

| Labor cost                                 | Parts cost | Cost per product                 | Cost on U.S. operators        |
|--|------------|----------------------------------|-------------------------------|
| 4 work-hours × \$85 per hour = \$340 ..... | \$0        | \$340 per inspection cycle ..... | \$40,800 per inspection cycle |

The FAA estimates the following costs to do any necessary on-condition action that would be required based on

the results of the inspection. The agency has no way of determining the number

of aircraft that might need this on-condition action:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

| Labor cost                                    | Parts cost | Cost per product |
|---|------------|------------------|
| 20 work-hours × \$85 per hour = \$1,700 ..... | \$11,393   | \$13,093         |

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2022–25–08 Airbus SAS:** Amendment 39–22264; Docket No. FAA–2022–1237; Project Identifier MCAI–2022–00434–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 20, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1)

through (6) of this AD, certificated in any category.

(1) Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes.

(2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.

(3) Model A300 B4–605R and B4–622R airplanes.

(4) Model A300 C4–605R Variant F airplanes.

(5) Model A300 F4–605R and F4–622R airplanes.

(6) Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 56, Windows.

#### (e) Unsafe Condition

This AD was prompted by a report that a Model A319 airplane lost the right-hand front windshield in flight. Due to the design similarity, this condition can also exist or develop on Model A300, A300–600, and A310 series airplanes. The FAA is issuing this AD to address possible windshield failure. This condition, if not addressed, could possibly result in injury to the flightcrew and in-flight depressurization of the airplane, and would significantly increase pilot workload.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0058, dated March 28, 2022 (EASA AD 2022–0058).

#### (h) Exceptions to EASA AD 2022–0058

(1) Where EASA AD 2022–0058 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Note 2 to paragraph (3) of EASA AD 2022–0058 specifies that, “operators may refer to the SB” when a lack of data impairs the determination of the windshield age or utilization, for this AD replace those words with “operators must refer to the SB”.

(3) Where paragraph (6) of EASA AD 2022–0058 refers to a “defect, as identified in the SB,” for purposes of this AD, defects include manufacturing variability, fretting between windshield components, water ingress, and electrical braids corrosion.

(4) This AD does not adopt the “Remarks” section of EASA AD 2022–0058.

#### (i) No Reporting Requirement

Although paragraphs (11) and (12) of EASA AD 2022–0058 and the service information referenced therein specify to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (k) Additional Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0058, dated March 28, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0058, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on November 29, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-27304 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-0985; Project Identifier AD-2022-00096-T; Amendment 39-22260; AD 2022-25-04]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-400 and 747-8 series airplanes. This AD was prompted by reports of three opened door 5 right ceiling stowage boxes that fell freely and injured a flight attendant in each event. This AD requires replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on certain other airplanes. This AD also requires an operation check of the stowage boxes or snubber, as applicable, and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective January 20, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 20, 2023.

#### ADDRESSES:

*AD Docket:* You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2022-0985; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket

Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA-2022-0985.

**FOR FURTHER INFORMATION CONTACT:** Julie Linn, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3684; email: [Julie.Linn@faa.gov](mailto:Julie.Linn@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 747-400 and 747-8 series airplanes. The NPRM published in the **Federal Register** on September 20, 2022 (87 FR 57422).

The NPRM was prompted by reports of an opened door 5 right ceiling stowage box that fell freely approximately 12 inches on a Model 747-8 airplane, and two additional door 5 ceiling stowage box free fall events on Model 747-400 airplanes. In one reported occurrence, an opened door 5 ceiling stowage box fell freely approximately 10 inches; in another, the stowage box fell freely approximately 8 inches. In each occurrence, a flight attendant was injured. Boeing and the supplier have since investigated and analyzed affected snubbers, part number (P/N) SP5378, used on the door 5 ceiling stowage boxes on Model 747-400 and 747-8 airplanes. It was determined that over time, air can get into the cylinder of the affected snubber and delay its damping functionality, which means the affected snubber will not meet the requirement of the door 5 ceiling stowage boxes to open at a rate of not more than 15 degrees per second, when open more than 2.5 inches. The supplier has designed a replacement snubber, P/N SP26172, which meets those requirements.

In the NPRM, the FAA proposed to require replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on certain other airplanes. The NPRM also proposed to require an operation check of the stowage boxes or snubber, as applicable, and applicable on-condition actions.

The FAA is issuing this AD to address an unlatched door 5 ceiling stowage box, which can open and fall freely more than 2.5 inches, possibly resulting in injury to the flightcrew or maintenance personnel.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received comments from Air Line Pilots Association, International, who supported the NPRM without change.

##### Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

#### Related Service Information Under 14 CFR Part 51

The FAA reviewed Boeing Special Attention Requirements Bulletin 747-25-3726 RB, dated January 6, 2022. This service information specifies procedures for replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on other airplanes. The service information also specifies procedures for an operation check of the stowage boxes or snubbers, as applicable, to ensure that the free-fall distance is no greater than 2.5 inches, and applicable on-condition actions including a post-snobber-replacement check until eventual replacement of any affected snubber. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

#### Costs of Compliance

The FAA estimates that this AD affects 45 airplanes of U.S. registry. The