

Proposed Rules

Federal Register

Vol. 88, No. 68

Monday, April 10, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-0661; Project Identifier MCAI-2022-00737-Q]

RIN 2120-AA64

Airworthiness Directives; Ipeco Pilot and Co-Pilot Seats

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2019-21-06, which applies to certain Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats. AD 2019-21-06 requires modification and re-identification of the affected seats, initial and repetitive inspections of the affected track lock springs and, depending on the findings, replacement of the track lock springs with a part eligible for installation. Since the FAA issued AD 2019-21-06, the FAA determined the need for a mandatory terminating action to the track lock spring inspections. This proposed AD was prompted by reports of track lock spring failures occurring on affected seats. This proposed AD would retain the requirements of AD 2019-21-06. This proposed AD would also add a mandatory terminating action for the initial and repetitive inspections of the affected track lock springs. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by May 25, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-0661; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Ipeco service information identified in this NPRM, contact Ipeco Holdings Limited, Aviation Way, Southend on Sea, SS2 6UN, United Kingdom; phone: +44 1702 545118; fax: +44 1702 540782; email: Customersupport@ipeco.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT: Kevin Kung, Aviation Safety Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7244; email: 9-AVS-AIR-BACO-COS@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-0661; Project Identifier MCAI-2022-00737-Q" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other

information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kevin Kung, Aviation Safety Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2019-21-06, Amendment 39-19772 (84 FR 60325, November 8, 2019) (AD 2019-21-06), for certain Ipeco pilot and co-pilot seats. AD 2019-21-06 was prompted by an MCAI originated by the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union. EASA issued EASA AD 2018-0262, dated December 6, 2018 (EASA AD 2018-0262), to correct an unsafe condition identified as reports of track lock spring failures occurring on affected seats, including those seats already modified by EASA AD 2016-0256, dated December 16, 2016 (EASA AD 2016-0256).

AD 2019-21-06 requires modification and re-identification of the affected seats, initial and repetitive inspections of the affected track lock springs and, depending on the findings, replacement of the track lock springs with a part

eligible for installation. AD 2019–21–06 also adds additional seat part numbers to the applicability. The FAA issued AD 2019–21–06 to prevent unexpected movement of pilot and co-pilot seats on takeoff and landing.

Actions Since AD 2019–21–06 Was Issued

Since the FAA issued AD 2019–21–06, the Civil Aviation Authority (CAA), which is the aviation authority for the United Kingdom (UK) (UK CAA), superseded EASA AD 2018–0262 and issued UK CAA AD G–2022–0011, dated June 9, 2022 (UK CAA AD G–2022–0011) (also referred to after this as the MCAI). The MCAI states that occurrences of track lock spring failures continued to be reported, including seats already modified, as required by EASA AD 2016–0256. Consequently, the manufacturer published revised service information, which specifies instructions for inspection and replacement, if necessary, of affected track lock springs. The MCAI partially retains the requirements of EASA AD 2018–0262, which is superseded. The MCAI maintains the inspection of affected seats and springs and, depending on the results of the inspection, replacement of the affected springs from EASA AD 2018–0262. The MCAI also adds a mandatory terminating action, which requires that replacement of affected springs and lever, and the installation of a lever control placard, is accomplished. Track lock spring failures, if not addressed,

could lead to further cases of unexpected movement of pilot and co-pilot seats on takeoff and landing, which could result in reduced control of the airplane.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–0661.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Ipeco Service Bulletin (SB) Number 063–25–15, Issue 2; SB Number 063–25–16, Issue 2; SB Number 063–25–17, Issue 2; and SB Number 063–25–18, Issue 2; all dated March 8, 2022. These SBs provide instructions for removal and replacement of the levers and springs of affected track lock springs and the installation of a lever control placard.

This proposed AD would also require Ipeco SB Number 063–25–08, Revision 00; SB Number 063–25–09, Revision 00; and SB Number 063–25–10, Revision 00; all dated May 31, 2016, which the Director of the Federal Register approved for incorporation by reference as of December 12, 2017 (82 FR 51552, November 7, 2017).

This proposed AD would also require Ipeco SB Number 063–25–14, Revision 00, dated August 14, 2018, which the Director of the Federal Register approved for incorporation by reference as of December 13, 2019 (84 FR 60325, November 8, 2019).

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in **ADDRESSES**.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of these same type designs.

Proposed AD Requirements in This NPRM

This proposed AD would retain all of the requirements of AD 2019–21–06. This proposed AD would also add a mandatory terminating action for the initial and repetitive inspections of the affected track lock springs.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 120 pilot and co-pilot seats installed on, but not limited to, ATR 42 and ATR 72 airplanes of U.S. registry. The FAA estimates that seats installed on 34 ATR 42 airplanes and seats installed on 21 ATR 72 airplanes will require modification and inspection.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect ATR 42 or ATR 72 flight crew seats ..	0.25 work-hours × \$85 per hour = \$21.25	\$0	\$21.25	\$2,550
Modify ATR 42 or ATR 72 flight crew seats ...	2 work-hours × \$85 per hour = \$170	56	226	27,120
Report results of ATR 42 or ATR 72 inspection.	1 work-hour × \$85 per hour = \$85	0	85	10,200
Modify ATR 42 or ATR 72 flight crew seats per mandatory terminating action.	2.5 work-hours × \$85 per hour = \$212.50	56	268.50	32,220

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the inspection. The FAA has no way of determining the number of

aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Remove seat and replace ATR 42 track lock spring ...	1.5 work-hours × \$85 per hour = \$127.50	\$28	\$155.50
Remove seat and replace ATR 72 track lock spring ...	1.50 work-hours × \$85 per hour = \$127.50	28	155.50

The FAA has included all known costs in its cost estimate. According to

the manufacturer, however, some of the costs of this proposed AD may be

covered under warranty, thereby

reducing the cost impact on affected operators.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive 2019–21–06, Amendment 39–19772 (84 FR 60325, November 8, 2019); and
 - b. Adding the following new airworthiness directive:

Ipeco Holdings Limited: Docket No. FAA–2023–0661; Project Identifier MCAI–2022–00737–Q.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 25, 2023.

(b) Affected ADs

This AD replaces AD 2019–21–06, Amendment 39–19772 (84 FR 60325, November 8, 2019); (AD 2019–21–06).

(c) Applicability

- (1) This AD applies to:
 - (i) Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats with a part number (P/N) listed in Paragraph 1.A., Planning Information, Tables 1 and 2, of Ipeco Service Bulletin (SB) Number 063–25–14, Revision 00, dated August 14, 2018, and
 - (ii) Ipeco pilot seat P/N 3A063–0099–01–1 and Ipeco co-pilot seat P/N 3A063–0100–01–1.

(2) These seats are installed on, but not limited to, ATR–GIE Avions de Transport Régional ATR 42 and ATR 72 airplanes.

(d) Subject

Joint Aircraft System Component (JASC) Code 2510, Flight Compartment Equipment.

(e) Unsafe Condition

This AD was prompted by reports of track lock spring failures occurring on affected seats. The FAA is issuing this AD to prevent unexpected movement of pilot and co-pilot seats on takeoff and landing. The unsafe condition, if not addressed, could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Modification and Re-identification of Seats, Inspections and Replacement of Track Lock Spring, and Reporting

This paragraph retains the requirements of paragraph (g) of AD 2019–21–06, with a revised compliance date for affected seat inspections and reporting of inspection results.

(1) For seats that have not installed the track lock spring modification kit, within two years after December 12, 2017 (the effective date of AD 2017–22–02), modify and re-identify each affected pilot and co-pilot seat using the Accomplishment Instructions of Ipeco SB Number 063–25–08, Revision 00; Ipeco SB Number 063–25–09, Revision 00; or Ipeco SB Number 063–25–10, Revision 00; all dated May 31, 2016, as applicable to each affected seat.

(2) For all affected seats:

(i) Within 750 flight hours (FHs) after December 13, 2019 (the effective date of AD 2019–21–06), and, thereafter at intervals not to exceed 750 FHs, inspect the track lock spring of each seat in accordance with the Accomplishment Instructions, paragraph 3.2, of Ipeco SB Number 063–25–14, Revision 00, dated August 14, 2018.

(ii) If, during any inspection as required by paragraph (g)(2)(i) of this AD, any damage on, or incorrect installation of, any track lock spring is found on the pilot or co-pilot seat, before further flight, replace both track lock springs of the affected seat with a part eligible for installation using the Accomplishment Instructions, paragraph 3.3.3.1 or 3.3.3.2, as applicable, of Ipeco SB Number 063–25–14, Revision 00, dated August 14, 2018.

(3) Within 30 days after the initial and repetitive inspections, and thereafter for two years after December 13, 2019 (the effective date of AD 2019–21–06), send the inspection results, including no findings, to Ipeco at technicalsupport@ipeco.com.

(h) New Mandatory Terminating Action

As a mandatory terminating action to the inspections required by paragraph (g)(2)(i) of this AD, within 12 months after the effective date of this AD, or at the next Base Maintenance check, whichever occurs later, modify and re-identify each affected seat in accordance with the Accomplishment Instructions of Ipeco SB Number 063–25–15, Issue 2; SB Number 063–25–16, Issue 2; SB Number 063–25–17, Issue 2; or SB Number 063–25–18, Issue 2; all dated March 8, 2022, as applicable to each affected seat.

(i) Installation Prohibition

After the effective date of this AD, do not install any pilot or co-pilot seat identified in paragraph (c)(1)(i) of this AD unless the seat is modified and re-identified as specified in paragraph (g)(1) of this AD.

(j) Definitions

(1) For the purpose of this AD, “damage” includes cracks, breaks, corrosion, or deformation of the track lock spring.

(2) For the purpose of this AD, “incorrect installation” is installing the track lock spring at an angle or position different from the angle or position shown in Figures 6 and 7 of Ipeco SB Number 063–25–14, Revision 00, dated August 14, 2018.

(3) For the purpose of this AD, a “part eligible for installation” is:

(i) A modified seat provided, before installation, it has passed an inspection (no damage is found); and

(ii) A track lock spring provided that it passed an inspection (no damage is found).

(k) Credit for Previous Actions

You may take credit for the actions required by paragraph (g)(2)(ii) of this AD if the actions were performed before the effective date of this AD using ATR SB No. ATR42–25–0191, Original Issue, dated July 4, 2016; ATR SB No. ATR42–25–0191, Revision No. 01, dated July 20, 2016; or ATR SB No. ATR72–25–1157, Revision No. 02, dated March 9, 2017.

(l) Special Flight Permits

Special flight permits are prohibited.

(m) Alternative Methods of Compliance (AMOCs)

The Manager, Boston ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (n)(2) of this AD. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(n) Additional Information

(1) Refer to United Kingdom (UK) Civil Aviation Authority (CAA) AD G–2022–0011, dated June 9, 2022, for related information. This UK CAA AD may be found in the AD docket at regulations under Docket No. FAA–2023–0661.

(2) For more information about this AD, contact Kevin Kung, Aviation Safety Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7244; email: 9-AVS-AIR-BACO-COS@faa.gov.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on [DATE 35 DAYS AFTER PUBLICATION OF THE FINAL RULE].

(i) Ipeco Service Bulletin (SB) Number 063–25–15, Issue 2, dated March 8, 2022.

(ii) Ipeco SB Number 063–25–16, Issue 2, dated March 8, 2022.

(iii) Ipeco SB Number 063–25–17, Issue 2, dated March 8, 2022.

(iv) Ipeco SB Number 063–25–18, Issue 2, dated March 8, 2022.

(4) The following service information was approved for IBR on December 13, 2019 (84 FR 60325, November 8, 2019).

(i) Ipeco SB Number 063–25–14, Revision 00, dated August 14, 2018.

(ii) [Reserved]

(5) The following service information was approved for IBR on December 12, 2017 (82 FR 51552, November 7, 2017).

(i) Ipeco SB Number 063–25–08, Revision 00, dated May 31, 2016.

(ii) Ipeco SB Number 063–25–09, Revision 00, dated May 31, 2016.

(iii) Ipeco SB Number 063–25–10, Revision 00, dated May 31, 2016.

(6) For Ipeco service information identified in this AD, contact Ipeco Holdings Limited, Aviation Way, Southend on Sea, SS2 6UN, United Kingdom; phone: +44 1702 545118; fax: +44 1702 540782; email: Customersupport@ipeco.com.

(7) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on April 1, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–07177 Filed 4–7–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2023–0666; Project Identifier MCAI–2022–00555–Q]

RIN 2120–AA64

Airworthiness Directives; Survitec Group Limited (RFD Beaufort Ltd.) Life Jackets

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 life jackets. This proposed AD was prompted by a report that some life jackets were found packed in the wrong valise (container). This proposed AD would require an inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of life jackets and, if necessary, replacement of the life jacket. This proposed AD would also limit the installation of affected parts under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 25, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–0666; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Survitec Group Limited, t/a RFD Beaufort Ltd, Kingsway, Dunmurry, Belfast BT17 9AF, United Kingdom; telephone +44 2890 301531; fax +44 2890 621765; email steve.pickering@survitecgroup.com; website [survitecgroup.com](https://www.survitecgroup.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.