

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–08–05 The Boeing Company:

Amendment 39–22420; Docket No. FAA–2022–1312; Project Identifier AD–2022–00551–T.

(a) Effective Date

This airworthiness directive (AD) is effective June 30, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks found in the station (STA) 2370 pivot bulkhead forward outer chord. Analysis revealed higher bending stresses across the chord than originally assessed. The FAA is issuing this AD to address cracking in the STA 2370 pivot bulkhead forward outer chord. Such cracking, if not detected and corrected, could result in a severed pivot bulkhead outer chord, loss of horizontal stabilizer control, and loss of controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 777–53A0098, dated April 5, 2022, which is referred to in Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022, use the phrase “the original issue date of Requirements Bulletin 777–53A0098 RB,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Luis Cortez-Muniz, Aerospace Engineer, Airframe Sections, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3958; email: luis.a.cortez-muniz@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 777–53A0098 RB, dated April 5, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on April 18, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–11305 Filed 5–25–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF STATE**22 CFR Part 22**

[Public Notice: 12091]

RIN 1400–AF33

Schedule of Fees for Consular Services—Nonimmigrant and Special Visa Fees

AGENCY: Department of State.

ACTION: Final rule; delay of effective date.

SUMMARY: The Department of State (the Department) is delaying the effective date of a final rule that appeared in the *Federal Register* on March 28, 2023, to provide for a 60-day delay in the effective date after receipt of the final rule in the Congress.

DATES: The effective date of the rule amending 22 CFR part 22 published at 88 FR 18243, March 28, 2023, is delayed until June 17, 2023.

FOR FURTHER INFORMATION CONTACT: Johanna Cruz, Management Analyst, Office of the Comptroller, Bureau of Consular Affairs, Department of State; phone: 202–485–8915; email: fees@state.gov.

SUPPLEMENTARY INFORMATION: The Government Accountability Office (GAO) has informed the Department that the report prepared pursuant to the Congressional Review Act, 5 U.S.C. 801 *et seq.*, was not delivered to the U.S. Senate until April 17, 2023 (the reports to the House of Representatives and GAO were delivered on March 29, 2023). Accordingly, the Department is correcting the final rule to provide for an effective date of June 17, 2023. See 5 U.S.C. 801(a)(3).

Kevin E. Bryant,

Deputy Director, Office of Directives Management, U.S. Department of State.

[FR Doc. 2023–11420 Filed 5–25–23; 8:45 am]

BILLING CODE 4710–06–P