

decision to revoke, it may appeal the decision in writing to the Board, and ultimately to USDA. A DV auditor whose approval has been revoked must submit a new application to the Board and await approval;

* * * * *

■ 3. Revise § 981.450 to read as follows:

§ 981.450 Exempt dispositions.

As provided in § 981.50, any handler disposing of almonds for crushing into oil, or for animal feed, may have the kernel weight of these almonds excluded from their program obligations, so long as:

(a) The handler qualifies as, or delivers such almonds to, a Board-approved accepted user;

(b) Each delivery is made directly to the accepted user by June 30 of each crop year; and

(c) Each delivery is certified to the Board by the handler on ABC Form 8.

§§ 981.466 and 981.467 [Stayed]

■ 4. Sections 981.466 and 981.467 are stayed indefinitely.

■ 5. Revise § 981.481 to read as follows:

§ 981.481 Interest and late payment charges.

(a) Pursuant to § 981.81(e), the Board shall impose an interest charge on any handler whose assessment payment has not been received in the Board's office within 30 days of the invoice date shown on the handler's statement, unless an envelope containing the payment has been legibly postmarked by the U.S. Postal Service or some other verifiable delivery tracking system as having been remitted within 30 days of the invoice date. The interest charge shall be a rate of one and a half percent per month and shall be applied to the unpaid assessment balance for the number of days all or any part of the unpaid balance is delinquent beyond the 30-day payment period.

(b) In addition to the interest charge specified in paragraph (a) of this section, the Board shall impose a late payment charge on any handler whose payment has not been received in the Board's office within 60 days of the invoice date, unless an envelope containing the payment has been legibly postmarked by the U.S. Postal Service or some other verifiable delivery tracking system as having been remitted within 60 days of the invoice date. The late

payment charge shall be 10 percent of the unpaid balance.

Erin Morris,

Associate Administrator, Agricultural Marketing Service.

[FR Doc. 2023–21702 Filed 9–29–23; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1220; Project Identifier MCAI–2023–00478–T; Amendment 39–22553; AD 2023–19–03]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A330–200 series airplanes; Model A330–200 Freighter series airplanes; Model A330–300 series airplanes; Model A330–800 series airplanes; Model A330–900 series airplanes; Model A340–200 series airplanes; and Model A340–300 series airplanes. This AD was prompted by a report of cracks found in the fuel control unit housing assembly of a Honeywell GTCP331–350 auxiliary power unit (APU), which caused fuel leakage in the APU compartment. This AD requires replacing any affected APU fuel control unit or affected APU, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD also prohibits the installation of affected parts under certain conditions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 6, 2023.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 6, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–1220; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for

Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For EASA material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- For Honeywell International Inc. service information incorporated by reference in this AD, contact Honeywell International, Inc., 111 South 34th Street, Phoenix, AZ 85034; phone: (800) 601–3099; fax: (602) 365–5577; website: myaerospace.honeywell.com/wps/portal.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at *regulations.gov* under Docket No. FAA–2023–1220.

FOR FURTHER INFORMATION CONTACT:

Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3667; email Timothy.P.Dowling@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Model A330–200 series airplanes; Model A330–200 Freighter series airplanes; Model A330–300 series airplanes; Model A330–800 series airplanes; Model A330–900 series airplanes; Model A340–200 series airplanes; and Model A340–300 series airplanes. The NPRM published in the **Federal Register** on June 27, 2023 (88 FR 41516). The NPRM was prompted by AD 2023–0057, dated March 16, 2023, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2023–0057) (also referred to as the MCAI). The MCAI states cracks were found in the fuel control unit housing assembly of a Honeywell GTCP331–350 APU, which caused fuel leakage in the APU compartment. This condition, if not addressed, could lead to an uncommanded in-flight shutdown of the APU, or a fire in the APU compartment, possibly resulting in damage to the airplane.

In the NPRM, the FAA proposed to require replacing any affected APU fuel control unit or affected APU, as specified in EASA AD 2023-0057. The NPRM also proposed to prohibit the installation of affected parts under certain conditions. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-1220.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

This product has been approved by the aviation authority of another

country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 14 CFR Part 51

EASA AD 2023-0057 specifies procedures for replacing affected APU fuel control units or APUs. EASA AD 2023-0057 also prohibits the

installation of affected parts under certain conditions.

Honeywell Service Bulletin GTCP331-49-7954, dated December 19, 2007, specifies serial numbers for affected APU fuel control units.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 128 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 5 work-hours × \$85 per hour = \$425.	*\$	Up to \$425	Up to \$54,400.

* The FAA has received no definitive data on which to base the parts cost estimate.

The FAA has included all known costs in its cost estimate. According to the APU manufacturer, however, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023-19-03 Airbus SAS: Amendment 39-22553; Docket No. FAA-2023-1220; Project Identifier MCAI-2023-00478-T.

(a) Effective Date

This airworthiness directive (AD) is effective November 6, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS airplanes specified in paragraphs (c)(1) through (7) of this AD, certificated in any category.

- (1) Model A330-201, -202, -203, -223, and -243 airplanes.
- (2) Model A330-223F and -243F airplanes.
- (3) Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.
- (4) Model A330-841 airplanes.
- (5) Model A330-941 airplanes.
- (6) Model A340-211, -212, and -213 airplanes.
- (7) Model A340-311, -312, and -313 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 49, Airborne Auxiliary Power.

(e) Unsafe Condition

This AD was prompted by a report of cracks in the fuel control unit housing assembly of a Honeywell GTCP331-350

auxiliary power unit (APU), which caused fuel leakage in the APU compartment. The FAA is issuing this AD to address the cracked fuel control unit housing assemblies. The unsafe condition, if not addressed, could result in an uncommanded APU in-flight shutdown, or fire in the APU compartment, which could result in damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023-0057, dated March 16, 2023 (EASA AD 2023-0057).

(h) Exceptions to EASA AD 2023-0057

(1) Where EASA AD 2023-0057 refers to its effective date; this AD requires using the effective date of this AD.

(2) This AD does not adopt the "Remarks" section of EASA AD 2023-0057.

(3) Where EASA AD 2023-0057 defines "the SB," for this AD, operators must use Honeywell Service Bulletin GTCP331-49-7954, dated December 19, 2007.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or

changes to procedures or tests identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3667; email Timothy.P.Dowling@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023-0057, dated March 16, 2023.

(ii) Honeywell Service Bulletin GTCP331-49-7954, dated December 19, 2007.

(3) For EASA AD 2023-0057, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) For Honeywell service information identified in this AD, contact Honeywell International, Inc., 111 South 34th Street, Phoenix, AZ 85034; phone: (800) 601-3099; fax: (602) 365-5577; website: myaerospace.honeywell.com/wps/portal.

(5) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on September 15, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-21635 Filed 9-29-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0190; Project Identifier 2019-CE-048-AD; Amendment 39-22556; AD 2023-19-06]

RIN 2120-AA64

Airworthiness Directives; Viking Air Limited (Type Certificate Previously Held by Bombardier Inc. and de Havilland Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 64-09-03, which applied to all de Havilland (type certificate now held by Viking Air Limited (Viking)) Model DHC-2 "Beaver" airplanes. AD 64-09-03 required inspecting the aileron mass balance weight arms for cracks and corrosion and replacing any damaged part. Since the FAA issued AD 64-09-03, Transport Canada superseded its mandatory continuing airworthiness information (MCAI) to correct an unsafe condition on these products. This AD requires incorporating into the existing maintenance records for your airplane the actions and associated thresholds and intervals, including life limits, specified in a supplemental inspection and corrosion control manual for Model DHC-2 airplanes. This AD also requires completing all of the initial tasks identified in this manual and reporting certain corrosion findings to Viking. The actions in this supplemental inspection and corrosion control manual include the inspection of the aileron balance weight arms required by AD 64-09-03. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 6, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 6, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-0190; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room