

# Rules and Regulations

Federal Register

Vol. 88, No. 237

Tuesday, December 12, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF DEFENSE

### Office of the Secretary

#### 5 CFR Part 3601

[Docket ID: DoD-2021-OS-0032]

RIN 0790-AL21

#### Supplemental Standards of Ethical Conduct for Employees of the Department of Defense; Correction

**AGENCY:** Department of Defense (DoD).

**ACTION:** Final rule; correcting amendment.

**SUMMARY:** The Department of Defense is correcting a final rule that appeared in the **Federal Register** on February 28, 2023. The Department of Defense, with the concurrence of the U.S. Office of Government Ethics (OGE), finalized amendments to its Supplemental Standards of Ethical Conduct for Employees of the Department of Defense (DoD Supplemental Regulation). The amendments revised and updated the DoD Supplemental Regulation originally written in 1993, to supplement the OGE Standards of Ethical Conduct for Employees of the Executive Branch (OGE Standards). Amendments included changes in the following areas: designation of separate agency components for the purposes of gifts and teaching, speaking, and writing; additional exceptions for gifts from outside sources; additional limitations on gifts between DoD employees; and authority to waive any of the provisions of the DoD Supplemental Regulation.

**DATES:** This final rule correction is effective December 12, 2023 and is applicable beginning March 30, 2023.

**FOR FURTHER INFORMATION CONTACT:** Karen Dalheim, Standards of Conduct Office, Office of the Secretary of Defense, Office of the General Counsel; telephone: 703-695-3422.

**SUPPLEMENTARY INFORMATION:** Subsequent to the publication of the final rule on February 28, 2023 (88 FR

12541), it was discovered that during the final review and editing of the final rule, a comma was moved in the first sentence of § 3601.106(a) introductory text that changed the meaning of the sentence. The document corrects the CFR to reflect the intended version of this paragraph.

#### List of Subjects in 5 CFR Part 3601

Conflict of interests, Executive branch standards of conduct, Government employees.

Accordingly, the Department of Defense amends 5 CFR part 3601 by making the following correcting amendment:

#### PART 3601—SUPPLEMENTAL STANDARDS OF ETHICAL CONDUCT FOR EMPLOYEES OF THE DEPARTMENT OF DEFENSE

■ 1. The authority citation for part 3601 continues to read as follows:

**Authority:** 5 U.S.C. 301, 7301, 7351, 7353; 5 U.S.C. Chapter 131; E.O. 12674, 54 FR 15159, 3 CFR, 1989 Comp., p. 215, as modified by E.O. 12731, 55 FR 42547, 3 CFR, 1990 Comp., p. 306; 5 CFR 2635.105, 2635.203(a), 2635.204(k), 2635.803, 2635.807.

■ 2. In § 3601.106, revise the first sentence of paragraph (a) introductory text to read as follows:

#### § 3601.106 Prior approval for outside employment and business activities.

(a) A DoD employee, other than a special Government employee, who is required to file a financial disclosure report (OGE Forms 450 or 278e) shall obtain approval from the agency designee before engaging in a business activity or compensated outside employment with a prohibited source, unless general approval has been given in accordance with paragraph (b) of this section. \* \* \*

\* \* \* \* \*

Dated: December 6, 2023.

**Patricia L. Toppings,**  
*OSD Federal Register Liaison Officer,*  
*Department of Defense.*

[FR Doc. 2023-27172 Filed 12-11-23; 8:45 am]

**BILLING CODE 6001-FR-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1721; Project Identifier MCAI-2023-00676-T; Amendment 39-22608; AD 2023-23-06]

RIN 2120-AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2023-04-13, which applied to certain Dassault Aviation Model FALCON 2000EX airplanes. AD 2023-04-13 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD continues to require the actions in AD 2023-04-13 and requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations; as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective January 16, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 16, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of May 12, 2023 (88 FR 20741, April 7, 2023).

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at *regulations.gov* under Docket No. FAA-2023-1721; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1721.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3226; email [Tom.Rodriguez@faa.gov](mailto:Tom.Rodriguez@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2023-04-13, Amendment 39-22360 (88 FR 20741, April 7, 2023) (AD 2023-04-13). AD 2023-04-13 applied to certain Dassault Aviation Model FALCON 2000EX airplanes. AD 2023-04-13 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2023-04-13 to address reduced structural integrity of the airplane. AD 2023-04-13 specifies that accomplishing the revision required by paragraph (g) or (j) of that AD terminates the requirements of paragraph (g)(1) of AD 2010-26-05, Amendment 39-16544 (75 FR 79952, December 21, 2010), for Dassault Aviation Model FALCON 2000EX airplanes. This AD therefore continues to allow that terminating action.

The NPRM published in the **Federal Register** on August 29, 2023 (88 FR 59476). The NPRM was prompted by AD 2023-0100, dated May 11, 2023, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2023-0100) (also referred to as the MCAI). The MCAI states that new or more restrictive airworthiness limitations have been developed.

In the NPRM, the FAA proposed to continue to require the actions in AD

2023-04-13. The NPRM also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2023-0100. The FAA is issuing this AD to address reduced structural integrity of the airplane.

You may examine the MCAI in the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1721.

**Discussion of Final Airworthiness Directive**

**Comments**

The FAA received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

**Related Service Information Under 1 CFR Part 51**

EASA AD 2023-0100 specifies new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This AD also requires EASA AD 2022-0136, dated July 6, 2022, which the Director of the Federal Register approved for incorporation by reference as of May 12, 2023 (88 FR 20741, April 7, 2023).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

The FAA estimates that this AD affects 245 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA estimates the total cost per operator for the retained actions from AD 2023-04-13 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection

program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. In the past, the agency has estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new actions to be \$7,650 (90 work-hours × \$85 per work-hour).

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

- a. Removing Airworthiness Directive (AD) 2023–04–13, Amendment 39–22360 (88 FR 20741, April 7, 2023); and
- b. Adding the following new AD:

#### 2023–23–06 Dassault Aviation:

Amendment 39–22608; Docket No. FAA–2023–1721; Project Identifier MCAI–2023–00676–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 16, 2024.

#### (b) Affected ADs

(1) This AD replaces AD 2023–04–13, Amendment 39–22360 (88 FR 20741, April 7, 2023) (AD 2023–04–13).

(2) This AD affects AD 2010–26–05, Amendment 39–16544 (75 FR 79952, December 21, 2010) (AD 2010–26–05).

#### (c) Applicability

This AD applies to Dassault Aviation Model FALCON 2000EX airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before January 15, 2023.

#### (d) Subject

Air Transport Association (ATA) of America Code: 05, Time Limits/Maintenance Checks.

#### (e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Maintenance or Inspection Program Revision, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2023–04–13, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before January 15, 2022, except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0136, dated July 6, 2022

(EASA AD 2022–0136). Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

#### (h) Retained Exceptions to EASA AD 2022–0136, With No Changes

This paragraph restates the exceptions specified in paragraph (k) of AD 2023–04–13, with no changes.

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2022–0136 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022–0136 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable within 90 days after May 12, 2023 (the effective date of AD 2023–04–13).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0136 is at the applicable “limitation” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2022–0136, or within 90 days after the May 12, 2023 (the effective date of AD 2023–04–13), whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2022–0136 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2022–0136 does not apply to this AD.

#### (i) Retained Provisions for Alternative Actions or Intervals, With a New Exception

This paragraph restates the requirements of paragraph (l) of AD 2023–04–13, with a new exception. Except as required by paragraph (j) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2022–0136.

#### (j) New Maintenance or Inspection Program Revision

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2023–0100, dated May 11, 2023 (EASA AD 2023–0100). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

#### (k) Exceptions to EASA AD 2023–0100

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2023–0100.

(2) Paragraph (3) of EASA AD 2023–0100 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2023–0100 is at the applicable “limitations” and “associated thresholds” as

incorporated by the requirements of paragraph (3) of EASA AD 2023–0100, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) and (5) of EASA AD 2023–0100.

(5) This AD does not adopt the “Remarks” section of EASA AD 2023–0100.

#### (l) New Provisions for Alternative Actions and Intervals

After the maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections), and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2023–0100.

#### (m) Terminating Action for Certain Actions in AD 2010–26–05

Accomplishing the actions required by paragraph (g) or (j) of this AD terminates the requirements of paragraph (g)(1) of AD 2010–26–05, for Dassault Aviation Model FALCON 2000EX airplanes only.

#### (n) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (o) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (o) Additional Information

For more information about this AD, contact Tom Rodriguez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3226; email Tom.Rodriguez@faa.gov.

#### (p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on January 16, 2024.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0100, dated May 11, 2023.

(ii) [Reserved]

(4) The following service information was approved for IBR on May 12, 2023 (88 FR 20741, April 7, 2023).

(i) European Union Aviation Safety Agency (EASA) AD 2022–0136, dated July 6, 2022.

(ii) [Reserved]

(5) For EASA ADs 2022–0136 and 2023–0100, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website: [easa.europa.eu](http://easa.europa.eu). You may find these EASA ADs on the EASA website: [ad.easa.europa.eu](http://ad.easa.europa.eu).

(6) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on November 9, 2023.

#### Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–27117 Filed 12–11–23; 8:45 am]

BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–1815; Project Identifier MCAI–2023–00581–T; Amendment 39–22606; AD 2023–23–04]

RIN 2120–AA64

#### Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes. This AD was prompted by stress analysis results indicating that cracks may appear in the center wing box at frame 42 and slanted junction areas. This AD requires a one-time inspection of the center wing box at frame 42 and slanted junction areas, and applicable corrective actions, if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference.

The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective January 16, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 16, 2024.

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2023–1815; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2023–1815.

**FOR FURTHER INFORMATION CONTACT:** Tim Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3667; email: [timothy.p.dowling@faa.gov](mailto:timothy.p.dowling@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes. The NPRM published in the **Federal Register** on September 6, 2023 (88 FR 60908). The NPRM was prompted by AD 2023–0074, dated April 5, 2023, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2023–0074) (also referred to as the MCAI). The MCAI states that stress analysis results from A321 XLR certification and fatigue and damage tolerance harmonization have revealed

that cracks may appear in the center wing box at frame 42 and slanted junction areas of the affected airplanes. Cracks may appear due to the high fatigue stress in affected areas.

In the NPRM, the FAA proposed to require a one-time inspection of the center wing box at frame 42 and slanted junction areas, and applicable corrective actions, if necessary, as specified in EASA AD 2023–0074. The FAA is issuing this AD to detect potential cracks in the center wing box at frame 42 and slanted junction areas. The unsafe condition, if not addressed, could affect the structural integrity of the fuselage.

You may examine the MCAI in the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2023–1815.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

##### Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

#### Related Service Information Under 14 CFR Part 51

EASA AD 2023–0074 specifies procedures for one-time rototest and high frequency eddy current inspections for cracks of the center wing box rear lower spar junction area at frame 42; a rototest inspection for cracks of the frame 42 slanted beam connection; a detailed visual inspection of certain fasteners for damage; and applicable corrective actions. Corrective actions include obtaining and following instructions for crack repair and replacing damaged fasteners. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.