

evaluation the general supply and demand for milk. If the market administrator finds that uneconomic movements are occurring, and such movements are persistent and pervasive, or are not being made in a way that assures orderly marketing and efficient handling of milk in the marketing area, after good cause shown, the market administrator may disallow the payments of distributing plant delivery credit on such milk. Before making such a finding, the market administrator shall give the handler on such milk sufficient notice that an investigation is being considered and shall provide notice that the handler has the opportunity to explain why such movements were necessary, or the opportunity to correct such movements prior to the disallowance of any distributing plant delivery credits. Any disallowance of distributing plant delivery credit pursuant to this provision shall remain confidential between the market administrator and the handler.

**Erin Morris,**

*Associate Administrator, Agricultural Marketing Service.*

[FR Doc. 2024-01829 Filed 1-30-24; 8:45 am]

BILLING CODE 3410-02-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1895; Project Identifier MCAI-2023-00652-T; Amendment 39-22649; AD 2023-26-06]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes). This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is

issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 7, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 7, 2024.

**ADDRESSES:**

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA-2023-1895; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; website *easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at *regulations.gov* under Docket No. FAA-2023-1895.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3225; email *dan.rodina@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A300-600 series airplanes. The NPRM published in the **Federal Register** on October 2, 2023 (88 FR 67685). The NPRM was prompted by AD 2023-0091, dated May 5, 2023, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2023-0091) (also referred to as the MCAI). The MCAI states that new or more restrictive airworthiness limitations have been developed.

EASA AD 2023-0091 specifies that it requires certain tasks (limitations) already in Airbus A300-600

Airworthiness Limitations Section (ALS), Part 2 DT-ALI, Revision 03, that is required by EASA AD 2019-0090, dated April 26, 2019 (which corresponds to FAA AD 2019-21-01, Amendment 39-19767 (84 FR 56935, October 24, 2019) (AD 2019-21-01)), and that incorporation of EASA AD 2023-0091 invalidates (terminates) prior instructions for those tasks. This AD would therefore terminate the limitations required by paragraph (g) of AD 2019-21-01, for the tasks identified in the service information referred to in EASA AD 2023-0091 only.

In the NPRM, the FAA proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2023-0091. The FAA is issuing this AD to address fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-1895.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received comments from FedEx and DonZel Culver. Both commenters supported the NPRM without change.

##### Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

#### Related Service Information Under 14 CFR Part 51

EASA AD 2023-0091 specifies new or more restrictive airworthiness limitations for airplane structures and safe life limits. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

## Costs of Compliance

The FAA estimates that this AD affects 128 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2023–26–06 Airbus SAS:** Amendment 39–22649; Docket No. FAA–2023–1895; Project Identifier MCAI–2023–00652–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective March 7, 2024.

#### (b) Affected ADs

This AD affects AD 2019–21–01, Amendment 39–19767 (84 FR 56935, October 24, 2019) (AD 2019–21–01).

#### (c) Applicability

This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1) through (4) of this AD, certificated in any category.

- (1) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.
- (2) Model A300 B4–605R and B4–622R airplanes.
- (3) Model A300 F4–605R and F4–622R airplanes.
- (4) Model A300 C4–605R Variant F airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0091, dated May 5, 2023 (EASA AD 2023–0091).

#### (h) Exceptions to EASA AD 2023–0091

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2023–0091.

(2) Where paragraph (3) of EASA AD 2023–0091 specifies "Within 12 months after the effective date of this AD, revise the AMP," this AD requires replacing those words with "Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable."

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2023–0091 is at the applicable "associated thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2023–0091, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraph (4) of EASA AD 2023–0091.

(5) This AD does not adopt the "Remarks" section of EASA AD 2023–0091.

#### (i) Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2023–0091.

#### (j) Terminating Action for AD 2019–21–01

Accomplishing the actions required by this AD terminates the corresponding requirements of AD 2019–21–01 for the tasks identified in the service information referenced in EASA AD 2023–0091 only.

#### (k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (l) Additional Information

For more information about this AD, contact Dan Rodina, Aviation Safety

Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023-0091, dated May 5, 2023.

(ii) [Reserved]

(3) For EASA AD 2023-0091, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 2, 2024.

**Caitlin Locke,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024-01965 Filed 1-31-24; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1041; Project Identifier AD-2022-01223-T; Amendment 39-22657; AD 2024-01-06]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, 737-700, and 737-800 series airplanes. This AD was prompted by an evaluation by the design approval holder (DAH) indicating the fuselage skin repairs at the double row of fasteners centered on certain stringers have inadequate inspection requirements for continuing airworthiness following repair accomplishment. This AD is intended to complete certain programs to support

the airplane reaching its limit of validity (LOV). This AD requires repetitive inspections for cracks of skin repairs at Stringer S-17, and corrective actions if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 7, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 7, 2024.

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1041; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1041.

**FOR FURTHER INFORMATION CONTACT:** Bill Ashforth, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3520; email [Bill.Ashforth@faa.gov](mailto:Bill.Ashforth@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company (Boeing) Model 737-600, 737-700, and 737-800 series airplanes. The NPRM was published in the **Federal Register** on May 25, 2023 (88 FR 33849). The NPRM was prompted by an evaluation by the DAH indicating the fuselage skin repairs at the double row of fasteners centered on certain stringers have inadequate inspection requirements for continuing airworthiness following

repair accomplishment, which could result in fatigue cracking of the repair going undetected.

In the NPRM, the FAA proposed to require repetitive inspections for cracking of the skin repairs at S-17, and corrective actions if necessary. The FAA is issuing this AD to address this fatigue cracking, which, if not addressed, could grow to a critical length and result in rapid decompression and loss of the airplane's structural integrity.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received comments from the Air Line Pilots Association, International (ALPA) who supported the NPRM without change.

The FAA also received comments from Aviation Partners Boeing (APB), Boeing, Southwest Airlines (Southwest), and SunExpress Airline (SunExpress).

#### Compliance With AMOC Procedures

APB determined that the incorporation of supplemental type certificate (STC) ST00830SE for installation of split scimitar winglets affects compliance with the mandated actions in the proposed rule, but the extent of the impact to compliance is not fully known at this time. APB noted that paragraph (h) of the proposed AD would replace the provisions in Boeing Service Bulletin 737-53A1217 R1 that specify contacting Boeing for an alternative method of compliance (AMOC) for alternative inspections and corrective actions, and instead would require using a method approved in accordance with paragraph (i) of the proposed AD. APB stated that for affected airplanes with these winglets, approval of any alternative inspections and corrective actions for Zone 3 and Zone 4 repairs must be obtained from the Manager, AIR-520 Continued Operational Safety Branch, FAA, through the means described in paragraph (i)(1) of the proposed AD. APB asserted that Boeing does not have delegation to approve repairs in areas affected by the configuration of STC ST00830SE and cannot use ODA approval as specified in paragraph (i)(3) of the proposed AD.

The FAA acknowledges APB's comment. Paragraph (h)(1) of this AD states that AMOC approval be obtained using a method approved in accordance with the procedures specified in "paragraph (i)" of this AD, and does not limit approvals to the provisions of paragraph (i)(1) or (3) of this AD. Therefore, no change to this AD is necessary.