

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-02-02 De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.): Amendment 39-22666; Docket No. FAA-2023-0933; Project Identifier MCAI-2022-00554-T.

(a) Effective Date

This airworthiness directive (AD) is effective March 21, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Model DHC-8-401 and -402 airplanes, certificated in any category, having serial numbers 4001 and 4003 through 4633 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code: 55, Stabilizers.

(e) Unsafe Condition

This AD was prompted by reports that the saddle washer (radius filler) for the front and rear spar joints may have been incorrectly manufactured for several years. The FAA is issuing this AD to address gaps and bending of the saddle washer that could have the potential to reduce the life of the bolt, which in turn could affect the structural integrity of the horizontal stabilizer to vertical stabilizer joint.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 8,000 flight hours after the effective date of this AD, perform a detailed inspection for signs of gapping or bending of the saddle washers and adjacent washers in the front spar and rear spar horizontal/vertical stabilizer joint fitting in accordance with Section 3.B., Part A, of the Accomplishment Instructions of De Havilland Aircraft of

Canada Limited Service Bulletin 84-55-12, Revision B, dated April 20, 2023.

(h) Corrective Actions

If any gaps or bending of the washers are found during the inspection required by paragraph (g) of this AD, before further flight, replace the saddle washer, washers, PLI washer, bolt, and barrel nut, as applicable, in accordance with Section 3.B., Part B, of the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-55-12, Revision B, dated April 20, 2023.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using De Havilland Aircraft of Canada Limited Service Bulletin 84-55-12, dated September 7, 2021; or De Havilland Aircraft of Canada Limited Service Bulletin 84-55-12, Revision A, dated February 16, 2022.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-avs-nyacos@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or De Havilland Aircraft of Canada Limited's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Additional Information

(1) Refer to Transport Canada AD CF-2022-21, dated April 21, 2022, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-0933.

(2) For more information about this AD, contact Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyacos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) De Havilland Aircraft of Canada Limited Service Bulletin 84-55-12, Revision B, dated April 20, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Dash 8 Series Customer Response Centre, 5800 Explorer Drive, Mississauga, Ontario, L4W 5K9, Canada; telephone 855-310-1013 or 647-277-5820; email thd@dehavilland.com; website dehavilland.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 24, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-03081 Filed 2-14-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2023-1649; Project Identifier AD-2022-00905-T; Amendment 39-22667; AD 2024-02-03]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-8 and 747-8F series airplanes. This AD was prompted by a report that all six Integrated Display Units (IDUs) became blank when new flight plan data was entered in the Flight Management System (FMS), and by a determination that indication of decaying airspeed in certain scenarios is required. This AD requires installing updated software. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 21, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 21, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–1649; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services, 2600 Westminister Boulevard., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2023–1649.

FOR FURTHER INFORMATION CONTACT: Raja Vengadasalam, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone 206–231–3537; email *raja.vengadasalam@faa.gov*.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 747–8 and 747–8F series airplanes. The NPRM published in the **Federal Register** on August 25, 2023 (88

FR 58120). The NPRM was prompted by a report indicating all six IDUs became blank when new flight plan data was entered in the FMS. It was determined that the Jeppesen airport map database (AMDB) had an error in the data structure tied to the Sydney airport (YSSY). The Electronic Flight Instrumentation System/Engine Indicating and Crew Alerting System (EICAS) Interface Units (EIUs) were unable to process the data structure, resulting in the displays blanking. Jeppesen subsequently fixed the AMDB to address the issue with YSSY and additional airport codes with an incorrect data structure. The current EIU software is unable to process incorrect data structures, which results in an EIU fault that cannot be cleared by the automated reset function of an EIU. After five resets the EIU defaults to shut down, resulting in all six IDUs, which are controlled by the EIUs, becoming blank. The EIU shut down can also result in an autothrottle disconnect and a degraded autopilot mode. The problem can occur on the ground when an airport code with an incorrect data structure in the AMDB is entered as an origin or destination and the flight plan is then put into operation by the FMS. In flight, the problem can occur when an airport code with an incorrect data structure in the AMDB is entered as the selected diversion airport.

Additionally, the existing software does not provide an earlier indication of decaying airspeed during the landing phase for flap settings 25 and 30. The revised software provides an earlier threshold for triggering the low airspeed alerting EICAS Caution message.

In the NPRM, the FAA proposed to require installing updated software. The unsafe condition, if not addressed, could result in loss of all flight deck displays (Primary Flight Display/EICAS/Navigation Display, not including standby displays) combined with potential impact to the autopilot and auto-throttle functionality and lack of crew visibility of any subsequent system failures, which can prevent continued safe flight and landing; it could also

result in inadequate alerting of decaying airspeed, unacceptably low airspeed, and loss of control of the airplane.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from two commenters. Boeing stated it had no technical objection to the proposed AD. An anonymous individual commented generally on the manufacturer but provided no comments on the proposed actions or on the determination of the costs.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 747–31A2544 RB, dated March 31, 2020. This service information specifies procedures for installing Integrated Display System (IDS) 804 software in each of the six Liquid Crystal Display (LCD) IDUs and in each of the three EIUs, if not already installed; followed by installing IDS 805 software, which includes EIU software part number COL3F–0034–E805 and LCD software part number 3177–COL–DL8–05.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 19 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Software Installation	Up to 6 work-hours × \$85 per hour = \$510.	Up to \$650	Up to \$1,160	Up to \$22,040.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-02-03 The Boeing Company:
Amendment 39-22667; Docket No. FAA-2023-1649; Project Identifier AD-2022-00905-T.

(a) Effective Date

This airworthiness directive (AD) is effective March 21, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-8 and 747-8F series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020.

(d) Subject

Air Transport Association (ATA) of America Code: 31, Instruments.

(e) Unsafe Condition

This AD was prompted by a report that all six Integrated Display Units (IDUs) became blank when new flight plan data was entered in the Flight Management System, and by a determination that indication of decaying airspeed in certain scenarios is required. The FAA is issuing this AD to address problems with the Electronic Flight Instrumentation System/Engine Indicating and Crew Alerting System (EICAS) Interface Units (EIUs), which control the IDUs. The unsafe condition, if not addressed, could result in loss of all flight deck displays (Primary Flight Display/EICAS/Navigation Display, not including standby displays) combined with potential impact to the autopilot and auto-throttle functionality and lack of crew visibility of any subsequent system failures, which can prevent continued safe flight and landing; it could also result in inadequate alerting of decaying airspeed, unacceptably low airspeed, and loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 747-31A2544, dated March 31, 2020, which is referred to in Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time column of the table in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020, uses the phrase “the original issue date of Requirements Bulletin 747-31A2544 RB,” this AD requires using “the effective date of this AD.”

(2) For Group 2 airplanes identified in Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020: The concurrent requirements specified in Action 1 of Table 1 of the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020, do not apply.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization that has been authorized by the Manager, AIR-520 Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Raja Vengadasalam, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone 206-231-3537; email raja.vengadasalam@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 747-31A2544 RB, dated March 31, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services, 2600 Westminister Boulevard, MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 26, 2024.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-03082 Filed 2-14-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-0039; Project Identifier MCAI-2023-00966-R; Amendment 39-22665; AD 2024-02-01]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Helicopters Model EC225LP helicopters. This AD was prompted by a report of incorrect door opening instructions on the placards located on the right hand (RH) side of the VIP flap door. This AD requires installing a placard specifying jettisoning instructions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 1, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 1, 2024.

The FAA must receive comments on this AD by April 1, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2024-0039; or in person at

Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material incorporated by reference in this final rule, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*. You may find this material on the EASA website at *https://ad.easa.europa.eu*.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA material is also available at *regulations.gov* under Docket No. FAA-2024-0039.

Other Related Service Information:

For Airbus Helicopters service information identified in this final rule, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at *airbus.com/en/products-services/helicopters/hcare-services/airbusworld*. You may also view this service information at the FAA contact information under *Material Incorporated by Reference* above.

FOR FURTHER INFORMATION CONTACT:

William McCully, Aviation Safety Engineer, FAA, International Validation Branch, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone (404) 474-5548; email *william.mccully@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2024-0039; Project Identifier MCAI-2023-00966-R" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to

regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to William McCully, Aviation Safety Engineer, FAA, International Validation Branch, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone (404) 474-5548; email *william.mccully@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0072, dated April 26, 2022 (EASA AD 2022-0072), to correct an unsafe condition on Airbus Helicopters Model EC 225 LP helicopters, serial numbers 2650, 2651, 2653, 2684, 2712, and 2796.

This AD was prompted by a report that placards located on the RH side of the VIP flap door of the passenger cabin do not provide adequate door opening instructions necessary to operate the RH side VIP flap door in case of the helicopter ditching. The unsafe condition, if not addressed, could prevent jettisoning of the RH side VIP flap door during an emergency situation, possibly obstructing evacuation and resulting in injury to occupants.

You may examine the EASA AD in the AD docket at *regulations.gov* under Docket No. FAA-2024-0039.

Related Service Information Under 14 CFR Part 51

EASA AD 2022-0072 requires installing a placard over the current placard, which correctly specifies