

prescribed under the provisions of § 21.16.

Special conditions are initially applicable to the model for which they are issued. Should the applicant apply for a supplemental type certificate to modify any other model included on the same type certificate to incorporate the same novel or unusual design feature, these special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, the Robinson Model R66 helicopter must comply with the fuel-vent and exhaust-emission requirements of 14 CFR part 34, and the noise-certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with title 14, Code of Federal Regulations (14 CFR) § 11.38, and they become part of the type certification basis under § 21.101.

Novel or Unusual Design Features

The Robinson Model R66 helicopter will incorporate the following novel or unusual design feature:

A four-axis full authority digital FBW FCS that provides aircraft control through pilot control inputs or coupled autopilot modes in addition to degraded modes.

Discussion

The Skyrse Robinson Model R66 helicopter is configured with a FBW FCS, which needs to be evaluated for acceptable static stability characteristics.

For conventional rotorcraft having mechanical linkages from the primary cockpit flight controls to the rotor, static longitudinal stability means that a pull displacement or force on the cyclic will result in a reduction of speed relative to the trim speed, and that a push displacement or force will result in a higher speed relative to the trim speed. Acceptable longitudinal stability is necessary for the following reasons:

- Airspeed change cues are provided to the pilot through increased and decreased forces on the controller.
- Short periods of unattended control of the rotorcraft do not result in significant changes in attitude, airspeed, or load factor.
- A predictable pitch response is provided to the pilot.
- An acceptable level of pilot workload, to attain and maintain trim speed and attitude, is provided to the pilot.
- Longitudinal stability provides gust stability.

The pitch control movement of the cyclic for the FBW FCS is an attitude

command, which results in a rotor movement to attain the commanded pitch attitude. The flight path commanded by the initial cyclic input will remain stick-free until the pilot gives another command. This control function is applied during “normal” control laws within the approved flight envelope.

Sections 27.171, 27.173, and 27.175 establish the minimum requirements for static longitudinal stability for visual flight rules (VFR), and appendix B of part 27, sections IV and VII, “Airworthiness Criteria for Helicopter Instrument Flight”, provides the airworthiness criteria for helicopter instrument flight. However, these requirements are inadequate for the modified Skyrse Robinson R-66 helicopter because the longitudinal control laws may permit neutral or negative static stability, rather than requiring positive static stability throughout the approved flight envelope. As detailed in § 27.173(b) and considered in Advisory Circular (AC) 27.173(A), “Static Longitudinal Stability”, which is contained within AC 27-1B, “Certification of Normal Category Rotorcraft”, and the positive control force stability requirements in appendix B to part 27, sections IV and VII, the slope of the control position (cyclic) versus the airspeed curve must be positive (*i.e.*, provide positive static stability) throughout the full range of altitude for which certification is requested with the throttle and collective pitch held constant.

The design of the Skyrse FBW FCS is such that the static stability requirements identified under part 27 and appendix B, section IV, may not be met for all flight conditions.

The proposed special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

Applicability

As discussed above, these proposed special conditions are applicable to the model for which they are issued. Should the applicant apply for a supplemental type certificate to modify any other model included on the same type certificate to incorporate the same novel or unusual design feature, these special conditions would apply to the other model as well.

Conclusion

This action affects only a certain novel or unusual design feature on the Model R66 of helicopters. It is not a rule of general applicability and affects only

the applicant who applied to the FAA for approval of these features on the helicopter.

List of Subjects in 14 CFR Part 27

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 40113, 44701, 44702, and 44704.

The Proposed Special Conditions

Accordingly, the FAA proposes the following special conditions as part of the type certification basis for Robinson Model R66 helicopters, as modified by Skyrse.

In lieu of the requirements of §§ 27.173(b) and 27.175 for VFR operations, and the airworthiness criteria for helicopter instrument flight requirements in part 27, appendix B, sections IV and VII, the following special conditions apply:

The rotorcraft must be shown to have suitable longitudinal stability in any condition normally encountered in service, including the effects of atmospheric disturbance. The showing of suitable static longitudinal stability must be based primarily on a positive control movement (positive control sense of motion as referenced in AC 27.173A), in addition to rotorcraft handling qualities by assessing pilot workload, cues, and pilot compensation for specific test procedures during the flight test evaluation.

Issued in Kansas City, Missouri, on November 14, 2025.

Patrick R. Mullen,
Manager, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service.

[FIR Doc. 2025-20611 Filed 11-20-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-5028; Project Identifier MCAI-2025-00434-T]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A320–251N, –252N, –253N, –271N, –272N, and –273N airplanes. This proposed AD was prompted by a detected deviation to the manufacturing process of the angle fitting connection to side panel skin between certain frames (FR) at a certain stringer on both left hand (LH) and right hand (RH) sides. This proposed AD would require inspecting the fastener holes to ensure they are the nominal diameter, and applicable corrective actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 5, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2025–5028; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad–Adenauer–Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at regulations.gov under Docket No. FAA–2025–5028.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT:

Promita Dey, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 316–946–4106; email: promita.dey@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2025–5028; Project Identifier MCAI–2025–00434–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Promita Dey, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 316–946–4106; email: promita.dey@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2025–0065, dated March 27, 2025 (EASA AD 2025–0065) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus SAS Model A320–251N, –252N, –253N, –271N, –272N, and –273N

airplanes. The MCAI states a deviation to the manufacturing process was detected during a review of the cold working process in the assembly line. This deviation could adversely affect the fatigue life of the angle fitting connection to side panel skin between FR 35 and FR 36 at stringer 30 on both LH and RH sides. This could lead to crack initiation and propagation which could possibly result in reduced structural integrity of the airplane. The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA–2025–5028.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2025–0065 specifies procedures for special detailed inspections of the holes on the angle fitting connection to the side panel skin between FR 35 and FR 36 at stringer 30 on both the LH and RH side for discrepancies (fastener holes not in nominal condition), and applicable corrective actions. Corrective actions include a rototest inspection of the affected holes for cracking, repair, and contacting the manufacturer for additional instructions. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2025–0065 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA)

ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2025-0065 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2025-0065 in its entirety through that incorporation, except for any differences identified as exceptions in the

regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2025-0065 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2025-0065. Material required by EASA AD 2025-

0065 for compliance will be available at regulations.gov under Docket No. FAA-2025-5028 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 224 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
27 work-hours × \$85 per hour = \$2,295	\$0	\$2,295	\$514,080

ESTIMATED COSTS OF ON-CONDITION ACTIONS *

Labor cost	Parts cost	Cost per product
20 work-hours × \$85 per hour = \$1,700	\$0	\$1,700

* The FAA has received no definitive data on which to base the cost estimates for the on-condition obtaining and following instructions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS: Docket No. FAA-2025-5028; Project Identifier MCAI-2025-00434-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 5, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A320-251N, -252N, -253N, -271N, -272N, and -273N airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2025-0065, dated March 27, 2025 (EASA AD 2025-0065).

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a detected deviation to the manufacturing process of the angle fitting connection to side panel skin between frame (FR) 35 and FR 36 at stringer 30 on both left hand (LH) and right hand (RH) sides. The FAA is issuing this AD to address reduced fatigue life of the affected area, which if not addressed, could result in crack initiation and propagation which could possibly result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2025-0065.

(h) Exceptions to EASA AD 2025-0065

- (1) This AD does not adopt the “Remarks” section of EASA AD 2025-0065.

(2) Where paragraphs (2) and (3) of EASA AD 2025–0065 specify “discrepancy”, this AD requires replacing that text with “fastener hole not in nominal condition”.

(3) Where paragraph (4) of EASA AD 2025–0065 specifies “any discrepancy is detected, as defined in the SB, before next flight, contact Airbus for approved repair instructions and, within the compliance time specified therein, accomplish those instructions accordingly”, this AD requires replacing that text with “if any cracking is detected, the cracking must be repaired before further flight using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature”.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2025–0065 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: *AMOC@faa.gov*. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any material contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Additional Information

For more information about this AD, contact Promita Dey, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 316–946–4106; email: *promita.dey@faa.gov*.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2025–0065, dated March 27, 2025.

(ii) Reserved.

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; website *easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit *www.archives.gov/federal-register/cfr/ibr-locations* or email *fr.inspection@nara.gov*.

Issued on November 18, 2025.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–20572 Filed 11–20–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–3428; Project Identifier AD–2024–00428–T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 787–8, 787–9, and 787–10 airplanes. This proposed AD was prompted by reports of door assist handles pulled loose from their lower attach point in the doorway support bracket during pre-

flight checks. This proposed AD would require, for certain airplanes, installing a new retainer above the lower keyway of the support bracket assembly and installing a placard on certain support bracket assemblies or marking the part, and for certain airplanes would require an inspection of the forward and aft door assist handles and applicable on-condition actions. For certain other airplanes, this proposed AD would require installing a new retainer above the lower keyway of the support bracket assembly at certain locations and reidentifying the support bracket assembly. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 5, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2025–3428; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For the Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2025–3428.

FOR FURTHER INFORMATION CONTACT: Julie Linn, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3584; email: *julie.linn@faa.gov*.