TABLE 1 TO TARAGRAPH (g)—HEVISED MODEL 323D AIRWORTHINESS EIMHATION TASKS—CONTINUED							
Task No.	Task title	Existing task interval	Revised task interval	Inspection document	Zone		
55–40–00–252	Vertical Fin Left and Right Rear Spar Cap at	15,000 hours TIS,	23,600 hours TIS,	4-12-MQ	340		

then every 14,500

hours TIS thereafter.

TABLE 1 TO PARAGRAPH (a)—REVISED MODEL 525R AIRWORTHINESS LIMITATION TASKS-

Note 1 to paragraph (g): Additional guidance for accomplishing the actions required by this AD can be found in Textron Aviation Service Letter SL525B-05-04, Revision 1, dated January 7, 2025.

Detailed Inspection.

(h) Provisions for Alternative Actions and Intervals

After the action required by paragraph (g) of this AD has been done, no alternative actions and associated thresholds and intervals are allowed unless they are approved as specified in the provisions of paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Central Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Central Certification Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@ faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(j) Additional Information

- (1) For more information about this AD, contact Soban Saeed, Aviation Safety Engineer, FAA, 1801 South Airport Road, Wichita, KS 67209; phone: (316) 946-4123; email: CCB-COS@faa.gov.
- (2) For Textron Aviation material identified in this AD that is not incorporated by reference, contact Textron Aviation, Inc., P.O. Box 7706, Wichita, KS 67277; phone: (316) 517-6215; email: citationpubs@ txtav.com; website: ww2.txtav.com/ technical publications/.

(k) Material Incorporated by Reference

None.

Issued on November 24, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification

[FR Doc. 2025-21416 Filed 11-26-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Attachment Hole #1 (Eddy Current) Special

[Docket No. FAA-2025-5036: Project Identifier MCAI-2024-00748-R]

RIN 2120-AA64

Airworthiness Directives; Airbus **Helicopters**

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Model EC120B helicopters. This proposed AD was prompted by a report of cyclic flight control restrictions due to the incorrect positioning of the bonding braid on the socket of the pilot cyclic stick, which limited full movement of the pilot cyclic stick during flight. This proposed AD would require a one-time inspection of the position of the bonding braid on the socket of the pilot cyclic stick and, depending on the results, correcting the positioning of the bonding braid and installing a binding clamp. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by January 12, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
 - Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-5036; or in person at Docket Operations between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

then every 12,100

hours TIS thereafter.

Material Incorporated by Reference:

• For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

 You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA,

call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Steven Warwick, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222–5225; email: steven.r.warwick@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the ADDRESSES section. Include "Docket No. FAA-2025-5036; Project Identifier MCAI-2024-00748-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received

about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Steven Warwick, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0243, dated December 13, 2024 (EASA AD 2024-0243) (also referred to as the MCAI), to address an unsafe condition for all Airbus Helicopters Model EC 120 B helicopters. The MCAI advises of a report that a pilot experienced several occurrences of a cyclic flight control restriction when turning right during an instruction flight. Subsequent investigation determined that the bonding braid on the socket of the pilot cyclic stick had moved to an incorrect position, which limited full movement

of the pilot cyclic stick. This condition, if not addressed, could result in a cyclic flight control restriction during flight and consequent loss of control of the helicopter.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2025–5036.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024—0243, which specifies a one-time inspection of the position of the bonding braid on the socket of the pilot cyclic stick and, depending on the results, correcting the positioning of the bonding braid and installing a binding clamp. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

These products have been approved by the civil aviation authority (CAA) of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024–0243, described previously, as incorporated by reference, except for any differences

identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some CAA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024–0243 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024-0243 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024-0243 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2024-0243. Material referenced in EASA AD 2024-0243 for compliance will be available at regulations.gov under Docket No. FAA-2025-5036 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 72 helicopters of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect position of bonding braid and install binding clamp.	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$6,120

The FAA estimates the following costs to do any repairs that would be

required based on the results of the proposed inspection. The agency has no

way of determining the number of helicopters that might need this repair.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Correct position of bonding braid	1 work-hour × \$85 per hour = \$85	\$0	\$85

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters: Docket No. FAA–2025–5036; Project Identifier MCAI–2024–00748–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 12, 2026

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters EC120B helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 6700, Rotorcraft Flight Control.

(e) Unsafe Condition

This AD was prompted by a report of cyclic flight control restrictions due to the incorrect positioning of the bonding braid on the socket of the pilot cyclic stick, which limited full movement of the pilot cyclic stick during flight. The FAA is issuing this AD to detect and correct the incorrect positioning of the bonding braid on the socket of the pilot cyclic stick. The unsafe condition, if not addressed, could result in a cyclic flight control restriction during flight and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0243, dated December 13, 2024 (EASA AD 2024–0243).

(h) Exceptions to EASA AD 2024-0243

- (1) Where EASA AD 2024–0243 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where EASA AD 2024–0243 requires compliance in terms of flight hours, this AD requires using hours time-in-service.
- (3) This AD does not adopt the "Remarks" section of EASA AD 2024–0243.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person

identified in paragraph (j) of this AD and email to: *AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Steven Warwick, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222–5225; email: steven.r.warwick@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) European Union Aviation Safety Agency (EASA) AD 2024–0243, dated December 13, 2024.
 - (ii) [Reserved]
- (3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: *ADs@easa.europa.eu*; website: *easa.europa.eu*. You may find the EASA material on the EASA website at *ad.easa.europa.eu*.
- (4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on November 24, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–21495 Filed 11–26–25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 730

[Docket No. FDA-2023-N-4225]

RIN 0910-AI82

Testing Methods for Detecting and Identifying Asbestos in Talc-Containing Cosmetic Products; Withdrawal

AGENCY: Food and Drug Administration, Department of Health and Human Services.