

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2026-02-05 Leonardo S.p.A.: Amendment 39-23241; Docket No. FAA-2026-0014; Project Identifier MCAI-2024-00309-R.

(a) Effective Date

This airworthiness directive (AD) is effective February 6, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.A. Model AB412 and AB412 EP helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5300, Fuselage Structure (General).

(e) Unsafe Condition

This AD was prompted by a report of a cracked left upper cap angle (cap angle) part number 212-030-191-1. The FAA is issuing this AD to detect and correct cracking or damage of the cap angle which, if not addressed, could result in reduced structural integrity of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024-0104, dated May 24, 2024 (EASA AD 2024-0104).

(h) Exceptions to EASA AD 2024-0104

(1) Where EASA AD 2024-0104 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2024-0104 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(3) Where paragraph (1) of EASA AD 2024-0104 specifies "Within 25 FH [flight hours] since last inspection accomplished in accordance with the instructions of Agusta MBT 412-128 (as required by EASA AD 2009-0185), or within 5 FH after the effective date of this AD, whichever occurs later", this AD requires replacing that text with "Within 5 hours time-in-service after the effective date of this AD".

(4) Where the material referenced in paragraph (1) of EASA AD 2024-0104 specifies "if no cracks are revealed", this AD requires replacing that text with "If there are no cracks in the area inspected".

(5) This AD does not adopt paragraph (2) of EASA AD 2024-0104.

(6) Where paragraph (3) of EASA AD 2024-0104 specifies contacting Leonardo for approved instructions if there is a crack or

damage, and where the material referenced in EASA AD 2024-0104 specifies to contact Leonardo Helicopters for further instruction if there is a crack, this AD requires, before further flight, actions done in accordance with a method approved by the Manager, International Validation Branch, FAA; or EASA; or Leonardo S.p.A.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(7) Where paragraph (3) of EASA AD 2024-0104 specifies "any crack or damage", this AD requires replacing that text with "any crack or damage (smoking of the fitting attachment and crazing of sealant bead around the fitting as crack indications)".

(8) This AD does not adopt the "Remarks" section of EASA AD 2024-0104.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024-0104 specifies to submit certain information to the manufacturer, this AD does not require that action.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: *AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Deep Gaurav, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 228-3731; email: *deep.gaurav@faa.gov*.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024-0104, dated May 24, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: *ADS@easa.europa.eu*; website: *easa.europa.eu*. You may find the EASA material on the EASA website at *ad.easa.europa.eu*.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email *fr.inspection@nara.gov*.

Issued on January 13, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026-01183 Filed 1-21-26; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-0629; Project Identifier MCAI-2023-01183-R; Amendment 39-23237; AD 2026-02-01]

RIN 2120-AA64

Airworthiness Directives: Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC635T2+, and EC135T3 helicopters. This AD was prompted by reports of ruptured and deformed flexible couplings. This AD requires inspecting the axial displacement of the tail rotor drive shaft and, depending on the results, taking corrective actions including inspecting the flexible couplings. This AD also prohibits installing a tail rotor drive shaft unless certain procedures are followed. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 26, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 26, 2026.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-0629; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and

other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-0629.

FOR FURTHER INFORMATION CONTACT:

Aaron Nguyen, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222-5134; email: aaron.t.nguyen@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all AHD Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC635T2+, and EC135T3 helicopters. The NPRM was published in the **Federal Register** on April 25, 2025 (90 FR 17352). The NPRM was prompted by AD 2023-0197, dated November 10, 2023 (EASA AD 2023-0197) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI advises of reports of ruptured and deformed flexible couplings, and that investigations determined that a flexible coupling installed with high axial displacement causes increased stresses and friction between its sheets. The MCAI states that this unsafe condition, if not detected and corrected, could lead to cracks and extensive deformation of flexible couplings and consequent high vibration of the tail rotor drive shaft, possibly resulting in reduced control of the helicopter.

In the NPRM, the FAA proposed to require inspecting the axial displacement of the tail rotor drive shaft and, depending on the results, taking corrective actions including inspecting

the flexible couplings. The NPRM also proposed to prohibit installing a tail rotor drive shaft unless certain procedures are followed. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2025-0629.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Additional Changes Made to This AD

The FAA has revised paragraph (h) of this AD to clarify that where paragraphs (4) and (6) of EASA AD 2023-0197 specify replacing the flexible couplings in accordance with the instructions of section 4.1 of the service information referenced, this AD requires replacing the flexible couplings in accordance with the instructions of sections 4.1 and 4.2 of the service information referenced in EASA AD 2023-0197.

The FAA has also revised paragraph (h) of this AD to clarify that this AD prohibits installing a tail rotor drive shaft unless certain procedures are followed, as stated in the Preamble of the NPRM.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2023-0197, which specifies a one-time inspection of the flexible coupling for axial displacement and, depending on the results, corrective actions. Corrective actions include replacing both flexible couplings and correcting the axial displacement, or inspecting the flexible couplings, replacing each

flexible coupling having a discrepancy, and correcting the axial displacement. For certain flexible couplings not replaced based on the results of the flexible coupling inspection, EASA AD 2023-0197 requires replacing the flexible couplings within a longer compliance time. EASA AD 2023-0197 also prohibits installing a tail rotor drive shaft on any helicopter unless certain procedures are followed. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Differences Between This AD and the MCAI

The MCAI applies to Model EC635 P2+, EC635 P3, EC635 T1, and EC635 T3 helicopters, whereas this AD does not because these models do not have an FAA type certificate.

Costs of Compliance

The FAA estimates that this AD affects 69 helicopters of U.S. registry. Labor rates are estimated at \$85 per hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Inspecting both flexible couplings for axial displacement will take 8 work-hours for an estimated cost of \$680 per helicopter and \$46,920 for the U.S. fleet.

If required, replacing both flexible couplings will take 2 work-hours, and parts will cost \$4,100 for an estimated cost of \$4,270 per helicopter. Replacing one flexible coupling will take 1 work-hour and parts will cost \$2,050 for an estimated cost of \$2,135 per flexible coupling.

If required, correcting the axial displacement of the flexible couplings will take 5 work-hours for an estimated cost of \$425 per helicopter.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2026-02-01 Airbus Helicopters

Deutschland GmbH: Amendment 39-23237; Docket No. FAA-2025-0629; Project Identifier MCAI-2023-01183-R.

(a) Effective Date

This airworthiness directive (AD) is effective February 26, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC635T2+, and EC135T3 helicopters, certificated in any category.

Note 1 to paragraph (c): Helicopters with an EC135P3H designation are Model

EC135P3 helicopters and helicopters with an EC135T3H designation are Model EC135T3 helicopters.

(d) Subject

Joint Aircraft System Component (JASC) Code 6510, Tail Rotor Drive Shaft.

(e) Unsafe Condition

This AD was prompted by reports of ruptured and deformed flexible couplings. The FAA is issuing this AD to detect axial displacement of the tail rotor drive shaft that exceeds allowable limits. The unsafe condition, if not addressed, could result in cracks and extensive deformation of flexible couplings, high vibration of the tail rotor drive shaft, and consequent reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2023-0197, dated November 10, 2023 (EASA AD 2023-0197).

(h) Exceptions to EASA AD 2023-0197

(1) Where EASA AD 2023-0197 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2023-0197 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraphs (2) and (6) of EASA AD 2023-0197 state “new”, this AD requires replacing that text with “new (zero hours time-in-service)”.

(4) Where paragraph (4) of EASA AD 2023-0197 states “any discrepancy”, for the purpose of this AD, discrepancy may be indicated by cracks, mechanical damage, deformation, delamination, corrosion, loose rivets, or damaged surface protection, where these discrepancies exceed the allowable limits as defined in the material referenced in EASA AD 2023-0197.

(5) Where paragraph (4) of EASA AD 2023-0197 states “replace that flexible coupling”, this AD requires replacing that text with “replace that flexible coupling with a new (zero hours time-in-service) flexible coupling”.

(6) Where paragraphs (4) and (6) of EASA AD 2023-0197 state “in accordance with the instructions of section 4.1 of the Accomplishment Procedure of the ASB”, this AD requires replacing that text with “in accordance with the instructions of sections 4.1 and 4.2 of the Accomplishment Procedure of the material, referenced in EASA AD 2023-0197”.

(7) This AD does not adopt the “Remarks” section of EASA AD 2023-0197.

(i) No Reporting or Returning of Parts Requirement

Although the material referenced in EASA AD 2023-0197 specifies to submit certain

information and to send parts to the manufacturer, this AD does not require those actions.

(j) Special Flight Permits

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(l) Additional Information

For more information about this AD, contact Aaron Nguyen, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222-5134; email: aaron.t.nguyen@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023-0197, dated November 10, 2023.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 14, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026-01180 Filed 1-21-26; 8:45 am]

BILLING CODE 4910-13-P