

(5) This AD does not adopt the “Remarks” section of EASA AD 2025–0123.

#### (l) New Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless the actions and intervals are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2025–0123.

#### (m) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (n) of this AD and email to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (n) Additional Information

For more information about this AD, contact Kimi Kim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 781–238–7693; email: [9-AVS-AIR-BACO-COS@faa.gov](mailto:9-AVS-AIR-BACO-COS@faa.gov).

#### (o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following material was approved for IBR on [Date 35 Days After Publication of the Final Rule].

(i) European Union Aviation Safety Agency (EASA) AD 2025–0123, dated May 28, 2025.

(ii) [Reserved]

(4) The following material was approved for IBR on November 2, 2023 (88 FR 66681, September 28, 2023).

(i) EASA AD 2023–0058, dated March 16, 2023.

(ii) [Reserved]

(5) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu). You

may find this material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 29, 2026.

**Steven W. Thompson,**

*Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2026–02419 Filed 2–5–26; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2026–0741; Project Identifier AD–2025–00817–T]

RIN 2120–AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 777–200, –200LR, –300, and –300ER series airplanes. This proposed AD was prompted by a report of corrosion found on a satellite communications (SATCOM) high gain antenna adapter plate. This proposed AD would require repetitive inspections for corrosion of the SATCOM high gain antenna adapter plate and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 23, 2026.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to [regulations.gov](http://regulations.gov). Follow the instructions for submitting comments.

- *Fax*: 202–493–2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**AD Docket:** You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2026–0741; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

#### *Material Incorporated by Reference:*

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website [myboeingfleet.com](http://myboeingfleet.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA–2026–0741.

#### **FOR FURTHER INFORMATION CONTACT:**

Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov).

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2026–0741; Project Identifier AD–2025–00817–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](http://regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA has received a report indicating that during a heavy maintenance check on a Model 767 airplane, corrosion was found on a certain SATCOM high gain antenna adapter plate. The most severe corrosion was found at the nutplates around the edge of the adapter plate; the nutplates are used to fasten the antenna assembly

to the adapter plate. Corrosion was also found at the adapter plate mounting lugs and the area around the bonding strap that is connected between the adapter plate and the airplane skin. Contributing factors that lead to an increase in risk of a parts departing airplane (PDA) event include a lack of nutplate or nutplate recess corrosion protection, lack of instructions for re-application of primer and paint, lack of maintenance inspections and repair procedures, and moisture protection appears to be inadequate for the environment. Undetected corrosion of the adapter plate could lead to a PDA event. A PDA event of the SATCOM high gain antenna adapter system could damage the primary flight control surfaces, which could result in loss of continued safe flight and landing.

The SATCOM high gain antenna for Model 777 airplane has a similar adapter plate to the one installed on Model 767 airplanes. In related rulemaking, the FAA issued an NPRM, Docket No. FAA–2025–0741 (90 FR 17741), to address the unsafe condition on Model 767 airplanes.

**FAA’s Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Boeing Alert Requirements Bulletin 777–23A0454

RB, dated May 16, 2025. This material specifies procedures for repetitive detailed inspections for corrosion of the SATCOM high gain antenna adapter plate and applicable on-condition actions. On-condition actions include repairing the SATCOM high gain antenna adapter plate or replacing it with a new or serviceable SATCOM high gain antenna adapter plate if any corrosion found is less than or equal to 0.005 inch in depth; and replacing the SATCOM high gain antenna adapter plate with a new or serviceable SATCOM high gain antenna adapter plate if any corrosion found is greater than 0.005 inch in depth. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in the material already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this material at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2026–0741.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 238 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed inspection .....	11 work-hours × \$85 per hour = \$935 per inspection cycle.	None .....	\$935 per inspection cycle .....	\$222,530 per inspection cycle.

The FAA estimates the following costs to do any necessary repairs or replacements that would be required

based on the results of the proposed inspection. The agency has no way of determining the number of aircraft that

might need these repairs or replacements:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Repair of adapter plate .....	5 work-hours × \$85 per hour = \$425 .....	Negligible .....	\$425
Replacement of adapter plate .....	2 work-hour × \$85 per hour = \$170 .....	\$18,000 .....	18,170

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and

procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2026–0741; Project Identifier AD–2025–00817–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 23, 2026.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all The Boeing Company Model 777–200, –200LR, –300, and –300ER series airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 23, Communications.

#### (e) Unsafe Condition

This AD was prompted by a report of corrosion found on a satellite communications (SATCOM) high gain antenna adapter plate. The FAA is issuing this AD to address corrosion of the adapter plate, which could lead to a part departing airplane (PDA). A PDA event of the SATCOM high gain antenna adapter system could damage the primary flight control surfaces, which could result in loss of continued safe flight and landing.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 777–23A0454 RB, dated May 16, 2025, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 777–23A0454 RB, dated May 16, 2025.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 777–23A0454, dated May 16, 2025, which is referred to in Boeing Alert Requirements Bulletin 777–23A0454 RB, dated May 16, 2025.

#### (h) Exception to Requirements Bulletin Specifications

Where the Condition and Boeing Recommended Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 777–23A0454 RB, dated May 16, 2025, refer to the original issue date of Requirements Bulletin 777–23A0454 RB, this AD requires using the effective date of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational

Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Related Information

For more information about this AD, contact Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 777–23A0454 RB, dated May 16, 2025.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 29, 2026.

**Peter A. White,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2026–02420 Filed 2–5–26; 8:45 am]

**BILLING CODE 4910–13–P**

### COMMODITY FUTURES TRADING COMMISSION

#### 17 CFR Part 40

**RIN 3038–AF14**

#### Event Contracts; Withdrawal of Proposed Regulatory Action

**AGENCY:** Commodity Futures Trading Commission.

**ACTION:** Notice of withdrawal of proposed rules.

**SUMMARY:** The Commodity Futures Trading Commission (“Commission” or “CFTC”) is formally withdrawing a notice of proposed rulemaking published on June 10, 2024, titled “Event Contracts.” The Commission does not intend to issue final rules with