

provisions of title II of the Unfunded Mandates Reform Act of 1995 (2 U.S.C. chapter 25) (UMRA) for State, local and Tribal governments, or the private sector of \$100 million or more in any one year. Thus, the proposed rule is not subject to the requirements of sections 202 and 205 of the UMRA.

List of Subjects in 7 CFR Part 205

Administrative practice and procedure, Agriculture, Agricultural commodities, Animals, Archives and records, Crops, Disinfectants, Fees, Imports, Labeling, Livestock, National List, National Organic Standards Board (NOSB), Organically produced products, Plants, Reporting and recordkeeping requirements, Sanitizers, Seals and insignia, Soil conservation, Sunset.

For the reasons stated in the preamble, AMS proposes to amend 7 CFR part 205 as follows:

PART 205—NATIONAL ORGANIC PROGRAM

■ 1. The authority citation for 7 CFR part 205 continues to read as follows:

Authority: 7 U.S.C. 6501–6524.

■ 2. Amend § 205.601 by:

■ a. Redesignating paragraphs (a)(2) through (8) as paragraphs (a)(3) through (9);

■ b. Adding new paragraph (a)(2);

■ c. Redesignating paragraphs (j)(2) through (11) as paragraphs (j)(3) through (12); and

■ d. Adding new paragraph (j)(2).

The additions read as follows:

§ 205.601 Synthetic substances allowed for use in organic crop production.

* * * * *

(a) * * *

(2) Carbon dioxide.

* * * * *

(j) * * *

(2) Carbon dioxide—must be sourced as a byproduct.

* * * * *

■ 3. Amend § 205.602 by revising paragraph (h) to read as follows:

§ 205.602 Nonsynthetic substances prohibited for use in organic crop production.

* * * * *

(h) Sodium nitrate—unless use is restricted to no more than 20% of the crop's total nitrogen requirement.

* * * * *

■ 4. Amend § 205.603 by:

■ a. Redesignating paragraphs (a)(20) through (30) as paragraphs (a)(21) through (31);

■ b. Adding new paragraph (a)(20); and

■ c. Revising paragraph (d)(1).

The addition and revision read as follows:

§ 205.603 Synthetic substances allowed for use in organic livestock production.

* * * * *

(a) * * *

(20) Meloxicam (CAS #71125–38–7)—Federal law restricts this drug to use by or on the lawful written or oral order of a licensed veterinarian, in full compliance with the AMDUCA and 21 CFR part 530 of the Food and Drug Administration regulations. Also, for use under 7 CFR part 205, the NOP requires:

(i) Use by or on the lawful written order of a licensed veterinarian; and

(ii) A withdrawal period of at least two times that required by the FDA.

* * * * *

(d) * * *

(1) DL-methionine, DL-methionine-hydroxy analog, and DL-methionine-hydroxy analog calcium (CAS #'s 59–51–8, 583–91–5, 4857–44–7, and 922–50–9)—for use only in organic poultry production.

* * * * *

Erin Morris,

Administrator, Agricultural Marketing Service.

[FR Doc. 2026–05598 Filed 3–20–26; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2026–2716; Project Identifier AD–2025–00990–T]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–8, 737–9, and 737–8200 airplanes. This proposed AD was prompted by a leak through the form-in-place (FiP) gasket found during a leak check. This proposed AD would require a detailed inspection of the FiP gasket at the engine fuel shutoff valve access panel for correct sealant installation, or a detailed inspection at the engine fuel shutoff valve access panel for any damage on the preformed seal,

depending on configuration; a fluid leak test of the engine fuel shutoff valve access panel for any leak; and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 7, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

• *Fax:* 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2026–2716; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

• For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2026–2716.

FOR FURTHER INFORMATION CONTACT: Erica Bayles, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 907–271–5844; email: *erica.e.bayles@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2026–2716; Project Identifier AD–2025–00990–T” at the beginning of your comments. The most

helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Erica Bayles, Aviation Safety Engineer, FAA, 2200 South 216th

St., Des Moines, WA 98198; phone: 907-271-5844; email: *erica.e.bayles@faa.gov*. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has received a report indicating a leak through the FiP gasket was found during a leak check, completed as part of a non-conformance disposition for the Boeing Company Model 737-8, 737-9, and 737-8200 airplanes. An investigation found that the fairing requirements of the engine fuel shutoff valve access panel caused thin regions of the FiP gasket. This caused the manufacturer to apply non-permitted sealant after the initial FiP gasket had cured, which resulted in an uneven sealing surface on the engine fuel shutoff valve access panel and a fuel leak. Non-conforming FiP gasket installations may compromise the designated drainage provision in the wing leading edge area. This condition, if not addressed, could result in fuel leaking onto the engine nozzle and a consequent fire on the ground.

FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 737-57A1358

RB, dated November 17, 2025. This material specifies procedures for a detailed inspection of the FiP gasket at the engine fuel shutoff valve access panel of the left and right wing for correct sealant installation, or a detailed inspection at the engine fuel shutoff valve access panel of the left and right wings for any damage on the preformed seal, depending on configuration; a fluid leak test of the engine fuel shutoff valve access panel for any leak; and applicable on-condition actions. On-condition actions include replacing the FiP gasket, repairing damage to the preformed gasket, and repeating the leak test until no leak is found.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the material already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this material at *regulations.gov* under Docket No. FAA-2026-2716.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 433 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

| Action | Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
|--|---|------------|------------------|------------------------|
| Inspection for sealant application | 1 work-hours × \$85 per hour = \$85 | \$0 | \$85 | Up to \$36,805. |
| Inspection for damage | 1 work-hour × \$85 per hour = \$85 | 0 | 85 | Up to \$36,805. |
| Leak test | 1 work-hour × \$85 per hour = \$85 | 0 | 85 | 36,805. |

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The agency has no way of determining the

number of aircraft that might need these replacements:

ON-CONDITION COSTS

| Action | Labor cost | Parts cost | Cost per product |
|-------------------|--|---------------------|------------------|
| Replacement | Up to 3 work-hours × \$85 per hour = \$255 | Up to \$1,000 | Up to \$1,255. |

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs to the preformed gasket specified in this proposed AD.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby

reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA–2026–2716; Project Identifier AD–2025–00990–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 7, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737–8, 737–9, and 737–8200 airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a leak through the form-in-place (FiP) gasket found during a leak check. An investigation found that the fairing requirements of the engine fuel shutoff valve access panel caused thin regions of the FiP gasket, which caused non-permitted sealant to be applied after the initial FiP gasket had cured, resulting in an uneven sealing surface on the engine fuel shutoff valve access panel and a fuel leak. The FAA is issuing this AD to address incorrect sealant installation and damage to preformed seals. The unsafe condition, if not addressed, could result in fuel leaking onto the engine nozzle and a consequent fire on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–57A1358, dated November 17, 2025, which is referred to in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025.

(h) Exceptions to Requirements Bulletin Specifications

(1) Where the Compliance Time columns of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, refer to the original issue date of Requirements Bulletin 737–57A1358 RB, this AD requires using the effective date of this AD.

(2) Where Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(3) Where Table 1 and Table 2 in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, specifies "Do a fluid leak test of the engine fuel shutoff valve access panel for any leak. If any leak is found, do all applicable on-condition corrective action(s) and repeat the leak test until no leak is found", this AD requires replacing that text with "Do a fluid leak test of the engine fuel shutoff valve access panel for any leak. If any leak is found, replace the FiP gasket and repeat the leak test until no leak is found".

(4) Where Table 3 and Table 4 in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, specifies "Do a fluid leak test of the engine fuel shutoff valve access panel for any leak. If any leak is found, do all applicable on-condition corrective action(s) and repeat the leak test until no leak is found", this AD requires replacing that text with "Do a fluid leak test of the engine fuel shutoff valve access panel for any leak. If any leak is found, replace the existing sealant installation with a removable fay seal and repeat the leak test until no leak is found".

(5) Where step 4. b. of Appendix A in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, specifies "If any water leaks from the engine fuel shutoff valve access panel in less than two minutes, the fluid leak test has failed", this AD requires replacing that text with "If any water leaks from the engine fuel shutoff valve access panel in less than two minutes, the fluid leak test has failed. Replace the FiP gasket in accordance with Figure 3 (Group 1) and removable fay seal in accordance with Figure 7 (Group 2), and repeat the leak test until no leak is found".

(6) Where step 4. b. of Appendix B in Boeing Alert Requirements Bulletin 737–57A1358 RB, dated November 17, 2025, specifies "If any water leaks from the engine fuel shutoff valve access panel in less than two minutes, the fluid leak test has failed", this AD requires replacing that text with "If any water leaks from the engine fuel shutoff valve access panel in less than two minutes, the fluid leak test has failed. Replace the FiP gasket in accordance with Figure 4 (Group 1) and removable fay seal in accordance with Figure 8 (Group 2), and repeat the leak test until no leak is found".

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD.

Information may be emailed to: *AMOC@faa.gov*. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Additional Information

For more information about this AD, contact Erica Bayles, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 907-271-5844; email: *erica.e.bayles@faa.gov*.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-57A1358 RB, dated November 17, 2025.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website *myboeingfleet.com*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit *www.archives.gov/federal-register/cfr/ibr-locations* or email *fr.inspection@nara.gov*.

Lona C. Saccomando,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2026-05597 Filed 3-20-26; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2026-2720; Project Identifier MCAI-2023-00668-R]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2019-09-03 and AD 2021-05-15, which apply to certain Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters. AD 2019-09-03 requires a one-time inspection of the jettisoning mechanism of the cabin doors. AD 2021-05-15 requires repetitive inspections, modifying the release system of each cabin lateral sliding plug door or modifying the design of the jettison system of each cabin lateral sliding plug door. Since the FAA issued AD 2021-05-15, the manufacturer developed a prerequisite modification for certain helicopters, determined improved modification instructions were necessary for installation of the release system of the cabin lateral sliding plug door, and determined the compliance time could be extended. This proposed AD would require modifying the release system of each cabin lateral sliding plug door or modifying the design of the jettison system of each cabin lateral sliding plug door as a terminating action for the repetitive inspections. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by May 7, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket

No. FAA-2026-2720; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI) any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: *ADS@easa.europa.eu*; website: *easa.europa.eu*. You may find the EASA material on the EASA website at *ad.easa.europa.eu*.

- You may view this material at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Aryanna Sanchez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222-5257; email: *aryanna.t.sanchez@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under **ADDRESSES**. Include "Docket No. FAA-2026-2720; Project Identifier MCAI-2023-00668-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt