

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive 2022–02–12, Amendment 39–21909 (87 FR 7687, February 10, 2022); and
 - b. Adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA–2026–8817; Project Identifier MCAI–2026–00010–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by November 6, 2026.

(b) Affected ADs

This AD replaces AD 2022–02–12, Amendment 39–21909 (87 FR 7687, February 10, 2022).

(c) Applicability

This AD applies to all Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by the determination that certain parts have new and more restrictive airworthiness

limitations, including life limits and maintenance tasks. The FAA is issuing this AD to address the failure of certain parts, which could result in the loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Action

(1) Within 30 days after the effective date of this AD, revise the airworthiness limitations section of the existing maintenance manual or instructions for continued airworthiness and the existing approved maintenance inspection program, as applicable, by incorporating into maintenance records required by 14 CFR 91.417(a)(2) or 135.439(a)(2), as applicable, the requirements (airworthiness limitations) specified in Air vehicle maintenance planning information, AW139 39–B–AMPI–00–P, Chapter 04, Airworthiness Limitations, Issue 015, dated January 07, 2025.

(h) Provisions or Alternative Requirements (Airworthiness Limitations)

After the action required by paragraph (g) of this AD has been accomplished, no alternative actions and associated thresholds and intervals, including any life limits, are allowed unless they are approved by Manager, International Validation Branch, FAA; or EASA; or Leonardo S.p.a. EASA Design Organization Approval (DOA) for repair instructions and accomplishing those instructions. If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Anthony Kenward, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222–5157; email: anthony.b.kenward@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Air vehicle maintenance planning information, AW139 39–B–AMPI–00–P, Chapter 04, Airworthiness Limitations, Issue 015, dated January 07, 2025.

(ii) [Reserved]

(3) For Leonardo S.p.a. material identified in this AD, contact Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; phone: (+39) 0331–225074; fax: (+39) 0331–229046; or at: customerportal.leonardocompany.com/en-US/.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 16, 2026.

Hollister B. Thorson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026–19343 Filed 9–21–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2026–8809; Project Identifier MCAI–2025–01312–T]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A300 series airplanes; Model A300 B4–601, A300 B4–603, and A300 B4–622 airplanes; Model A300 B4–600R series airplanes; Model A300 C4–605R Variant F airplanes; and Model A300 F4–600R series airplanes. This proposed AD was prompted by reports of cracking of the main landing gear (MLG) two-piece cages due to incorrect machining. This proposed AD would require replacing an affected MLG with a serviceable MLG and would limit the installation of an affected MLG under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 6, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2026–8809; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2026–8809.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT:

Taylor Stanley, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 407–852–7677; email: Taylor.Stanley@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2026–8809; Project Identifier MCAI–2025–01312–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change,

and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Taylor Stanley, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 407–852–7677; email: Taylor.Stanley@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2025–0170, dated August 4, 2025 (EASA AD 2025–0170) (also referred to as the MCAI), to correct an unsafe condition for all Airbus SAS Model A300 B4–2C, A300 B4–103, A300 B4–120, A300 B4–203, A300 B4–220, A300 C4–203, A300 F4–203, A300 B4–601, A300 B4–603, A300 B4–622, A300 C4–620, A300 B4–605R, A300 B4–622R, A300 F4–605R, A300 F4–622R, A300 C4–605R Variant F, and A300F4–608ST airplanes. Model A300 B4–120, A300 B4–220, A300 C4–203, A300 F4–203, A300 C4–620, and A300 F4–608ST airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability. The

MCAI states that occurrences were reported of cracks found in the MLG two-piece cages. Subsequent investigation determined that the root cause of the cracking was incorrect machining before installation of the MLG two-piece cage into the MLG eye fitting. This condition, if not corrected, could lead to structural failure of the MLG during takeoff or landing, possibly resulting in damage to the airplane and injury to occupants.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2026–8809.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2025–0170 specifies procedures for replacement of an affected MLG with a serviceable MLG and limits the installation of an affected MLG or overhauled MLG under certain conditions. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2025–0170 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2025–0170 by

reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2025–0170 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2025–0170 does not mean that operators need to comply only with that section. For example, where the AD requirement refers to “all required

actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2025–0170. Material required by EASA AD 2025–0170 for compliance will be available at *regulations.gov* under Docket No. FAA–2026–8809 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 99

airplanes of U.S. registry. The FAA has no definitive data on the number of affected MLGs that may need to be replaced and no way of knowing whether the affected MLGs are installed on all or some of the affected airplanes. Therefore, based on the assumption that one MLG would need to be replaced on all affected airplanes, the FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
28 work-hours × \$85 per hour = \$2,380	* \$0	\$2,380	\$235,620

* The FAA has received no definitive data on which to base the cost estimates for the parts specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority. The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.
- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:
Airbus SAS: Docket No. FAA–2026–8809; Project Identifier MCAI–2025–01312–T.

- (a) Comments Due Date**
- The FAA must receive comments on this airworthiness directive (AD) by November 6, 2026.
- (b) Affected ADs**
- None.
- (c) Applicability**
- This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1) through (5) of this AD, certified in any category.
- (1) Model A300 B4–2C, B4–103, and B4–203 airplanes.
 - (2) Model A300 B4–601, B4–603, and B4–622 airplanes.
 - (3) Model A300 B4–605R and B4–622R airplanes.
 - (4) Model A300 C4–605R Variant F airplanes.

- (5) Model A300 F4–605R and F4–622R airplanes.
- (d) Subject**
- Air Transport Association (ATA) of America Code 32, Landing gear.
- (e) Unsafe Condition**
- This AD was prompted by reports of cracking of the main landing gear (MLG) two-piece cages due to incorrect machining. The FAA is issuing this AD to address such cracking, which could lead to structural failure of the MLG during takeoff or landing. This unsafe condition, if not address, could result in damage to the airplane and injury to occupants.
- (f) Compliance**
- Comply with this AD within the compliance times specified, unless already done.
- (g) Requirements**
- Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2025–0170, dated August 4, 2025 (EASA AD 2025–0170).

- (h) Exceptions to EASA AD 2025–0170**
- (1) Where EASA AD 2025–0170 refers to its effective date, this AD requires using the effective date of this AD.
 - (2) Where EASA AD 2025–0170 defines a serviceable MLG part as an “MLG (LH or RH side), eligible for installation in accordance with Airbus instructions, which”, this AD requires replacing that text with “MLG (LH or RH side), eligible for installation, which”.
 - (3) This AD does not adopt the “Remarks” section of EASA AD 2025–0170.
- (i) No Reporting Requirement**
- Although the material referenced in EASA AD 2025–0170 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR-520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Additional Information

For more information about this AD, contact Taylor Stanley, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 407-852-7677; email: Taylor.Stanley@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2025-0170, dated August 4, 2025.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 18, 2026.

Lona C. Saccomando,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2026-19355 Filed 9-21-26; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2026-8807; Project Identifier MCAI-2025-01385-T]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A350-941 airplanes. This proposed AD was prompted by reports of engine health monitoring (EHM) messages requiring premature removal of hydro-mechanical units (HMUs). This proposed AD would require replacing certain HMUs before reaching a reduced life limit and would limit the installation of affected parts under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 6, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2026-8807; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221

8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at regulations.gov under Docket No. FAA-2026-8807.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT:

Anthony Decaro, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 562-627-5374; email: anthony.d.decaro@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include "Docket No. FAA-2026-8807; Project Identifier MCAI-2025-01385-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI