

with the home country supervisor for the foreign bank as appropriate.

(c) *Timing.* The Board will notify a foreign bank or company of its determination under this section within 30 days of the filing of the election unless the Board determines that it does not have sufficient information on which to base a finding.

§ 225.93 What are the consequences of a foreign bank failing to continue to meet applicable capital and management requirements?

(a) *Notice by the Board.* If a foreign bank or company has made an effective election to be treated as a financial holding company under this subpart and the Board finds that the foreign bank ceases to be well capitalized or well managed, the Board will notify the foreign bank or company in writing that it is not in compliance with the applicable requirement(s) for a financial holding company and identify the areas of noncompliance.

(b) *Notification by a financial holding company required.* Promptly upon becoming aware that it has ceased to be well capitalized or well managed, the foreign bank, or any company that controls such foreign bank, must notify the Board and identify the area of noncompliance.

(c) *Execution of agreement acceptable to the Board—* (1) *Agreement required; time period.* Within 45 days after receiving a notice under paragraph (a) of this section, the foreign bank or company must execute an agreement acceptable to the Board to comply with all applicable capital and management requirements.

(2) *Extension of time for executing agreement.* Upon request by a company, the Board may extend the 45-day period under paragraph (c)(1) of this section if the Board determines that granting additional time is appropriate under the circumstances. A request by a company for additional time must include an explanation of why an extension is necessary.

(3) *Agreement requirements.* An agreement required by paragraph (c)(1) of this section to correct a capital or management deficiency must:

- (i) Explain the specific actions that the foreign bank or company will take to correct all areas of noncompliance;
- (ii) Provide a schedule within which each action will be taken;
- (iii) Provide any other information that the Board may require; and
- (iv) Be acceptable to the Board.

(d) *Limitations during period of noncompliance.* Until the Board determines that a company has corrected the conditions described in a

notice under paragraph (a) of this section:

- (1) The Board may impose any limitations or conditions on the conduct or the U.S. activities of the foreign bank or company or any of its affiliates as the Board finds to be appropriate and consistent with the purposes of the Bank Holding Company Act; and
- (2) The company and its affiliates may not engage in any new activity in the United States or acquire control or shares of any company under section 4(k) of the Bank Holding Company Act without prior approval from the Board.

(e) *Consequences of failure to correct conditions within 180 days—*(1) *Termination of offices and divestiture.* If a foreign bank or company does not correct the conditions described in a notice under paragraph (a) of this section within 180 days of receipt of the notice or such additional time as the Board may permit, the Board may order the foreign bank or company to terminate the foreign bank's U.S. branches and agencies and divest any commercial lending companies owned or controlled by the foreign bank or company. Such divestiture must be done in accordance with the terms and conditions established by the Board.

(2) *Alternative method of complying with a divestiture order.* A foreign bank or company may comply with an order issued under paragraph (e)(1) of this section by ceasing to engage (both directly and through any subsidiary) in all activities that are not permissible for a foreign bank to conduct under sections 2(h) and 4(c) of the Bank Holding Company Act. The termination of activities must be done within the time period referred to in paragraph (e)(1) of this section and subject to terms and conditions acceptable to the Board.

(f) *Consultation with other agencies.* In taking any action under this section, the Board will consult with the relevant Federal and state regulatory authorities.

§ 225.94 What are the consequences of an insured branch failing to maintain a satisfactory or better rating under the Community Reinvestment Act?

(a) *Insured branch as an "insured depository institution."* A U.S. branch of a foreign bank that is insured by the Federal Deposit Insurance Corporation shall be treated as an "insured depository institution" for purposes of § 225.84.

(b) *Applicability.* The provisions of § 225.84, with the modifications contained in this section, shall apply to a foreign bank that operates an insured branch referred to in paragraph (a) of this section, and any company that owns or controls such a foreign bank,

that has made an effective election under § 225.92 in the same manner and to the same extent as they apply to a financial holding company.

By order of the Board of Governors of the Federal Reserve System, January 18, 2000.

Jennifer J. Johnson,

Secretary of the Board.

[FR Doc. 00-1646 Filed 1-24-00; 8:45 am]

BILLING CODE 6210-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-309-AD; Amendment 39-11518; AD 2000-02-01]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-8 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-8 series airplanes, that requires detailed visual and eddy current inspections of the lower wing skin at the 3 outboard fasteners of the stringer 64 end fitting to detect cracks; and corrective actions, if necessary. This amendment is prompted by reports of fatigue cracks found in the lower wing skin initiating from the outboard fasteners of the stringer 64 end fitting. The actions specified by this AD are intended to prevent such fatigue cracking, which could reduce structural integrity and loss of fail-safe capability of the airplane.

DATES: Effective February 29, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 29, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office,

3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Greg DiLibero, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5231; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-8 series airplanes was published in the **Federal Register** on October 27, 1999 (64 FR 57806). That action proposed to require detailed visual and eddy current inspections of the lower wing skin at the 3 outboard fasteners of the stringer 64 end fitting to detect cracks; and corrective actions, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 294 airplanes of the affected design in the worldwide fleet. The FAA estimates that 251 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the inspection required by this AD on U.S. operators is estimated to be \$60,240, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between

the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-02-01 McDonnell Douglas:
Amendment 39-11518. Docket 98-NM-309-AD.

Applicability: Model DC-8 series airplanes, as listed in McDonnell Douglas Service Bulletin DC8-57-100, Revision 01, dated August 26, 1998; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by

this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking of the lower wing skin, which could reduce structural integrity and loss of fail-safe capability of the airplane, accomplish the following:

Note 2: This AD will affect Principal Structural Elements (PSE) 57.08.037, 57.08.038, 57.08.021, and 57.08.022 of the DC-8 Supplemental Inspection Document (SID).

Inspection, Repair, and Modification

(a) Within 24 months after the effective date of this AD, perform detailed visual and eddy current inspections to detect cracks in the lower wing skin fastener holes in the area surrounding 3 outboard fasteners of the stringer 64 end fitting, in accordance with McDonnell Douglas Service Bulletin DC8-57-100, Revision 01, dated August 26, 1998.

Note 3: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If any crack is detected in the skin fastener holes and it is less than 3.1 inches long, prior to further flight, repair in accordance with the service bulletin. Within 14,100 landings after accomplishment of the repair, inspect the lower wing skin to detect cracks, in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate.

(2) If any crack is detected in the skin fastener holes and it is greater than or equal to 3.1 inches long, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(3) If no crack is found, within 24 months after the effective date of this AD, accomplish the preventative modification (including stress or split sleeve coining the three fastener holes in the skin, and installing new pins), in accordance with the service bulletin. Accomplishment of this action constitutes terminating action for the requirements of this AD.

Note 4: This AD does not terminate the inspection requirements for PSE's 57.08.037, 57.08.038, 57.08.021, and 57.08.022 of the DC-8 SID in accordance with AD 93-01-15, amendment 39-6330.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) Except as provided by paragraphs (a)(1) and (a)(2) of this AD, the actions shall be done in accordance with McDonnell Douglas Service Bulletin DC8-57-100, Revision 01, dated August 26, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on February 29, 2000.

Issued in Renton, Washington, on January 13, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-1368 Filed 1-24-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-SW-74-AD; Amendment 39-11517; AD 2000-01-19]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GmbH Model EC 135 P1 and EC 135 T1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) applicable to Eurocopter Deutschland GmbH (ECD) Model EC 135 P1 and EC 135 T1 helicopters. This action requires inspecting main rotor expansion bolt safety wires, bolt heads, and bolt nuts;

replacing any unairworthy expansion bolt with a hexagon bolt; and, as necessary, replacing any bolt nut before further flight. This AD also requires replacing each expansion bolt, regardless of condition, no later than January 31, 2000. This amendment is prompted by reports of main rotor blade expansion bolt nuts becoming loose. This condition, if not corrected, could result in severe vibration during flight and subsequent loss of control of the helicopter.

DATES: Effective February 4, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 4, 2000.

Comments for inclusion in the Rules Docket must be received on or before March 27, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-74-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

The service information referenced in this AD may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, Room 663, Fort Worth, Texas.

FOR FURTHER INFORMATION CONTACT:

Richard A. Monschke, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5116, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: Luftfahrt-Bundesamt (LBA), the airworthiness authority for the Federal Republic of Germany, notified the FAA that an unsafe condition may exist on Model EC 135 P1 and EC 135 T1 helicopters. The LBA advises that severe vibrations occurred during a helicopter flight due to an expansion bolt nut becoming loose.

ECD has issued Alert Service Bulletin EC135-62A-005, Revision 1, dated November 16, 1999 (ASB). The ASB specifies inspecting the safety wire, bolt head, and bolt nut for the extent of thread protrusion of the expansion bolt through the end of the nut; replacing the expansion bolt by a hexagon bolt as necessary; and replacing the nut as necessary. In addition, all hexagon bolts must replace all expansion bolts no later than January 31, 2000. The LBA classified this ASB as mandatory and issued AD 1999-264, dated July 2, 1999,

to ensure the continued airworthiness of these helicopters in the Federal Republic of Germany.

These helicopter models are manufactured in the Federal Republic of Germany and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other ECD Model EC 135 P1 and EC 135 T1 helicopters of the same type designs registered in the United States, this AD is being issued to prevent a main rotor blade expansion bolt from becoming loose, severe vibration during flight, and subsequent loss of control of the helicopter. This AD requires, before further flight and at intervals not to exceed 15 hours time-in-service (TIS), inspecting the main rotor blade expansion bolt safety wire, bolt head, and bolt nut for the extent of thread protrusion of the expansion bolt through the end of the nut; replacing any unairworthy expansion bolt with a hexagon bolt; and replacing the nut as necessary. The AD also requires replacing all expansion bolts, part number (P/N) L621M1010 223, with hexagon bolts, P/N L621M1010 222, before further flight after January 31, 2000. The actions are required to be accomplished in accordance with the ASB described previously. The short compliance time involved is required because the previously described critical unsafe condition can adversely affect the structural integrity of the helicopter. Therefore, inspecting the main rotor blade expansion bolt safety wire, bolt head, and bolt nut; replacing any unairworthy expansion bolt with a hexagon bolt; and replacing the nut as necessary is required before further flight and this AD must be issued immediately.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

The FAA estimates that 14 helicopters will be affected by this AD, that it will take approximately 10 work hours to