

structural inspection intervals may be approved for this aft pressure bulkhead and pylon pressure pan in the vicinity of the hydraulic fittings and the hydraulic tube adapters.

(g) When the information in TR MRM2-129, dated June 1, 2004, is included in the general revisions of the Maintenance Requirement Manual, this TR may be removed.

Corrective Action

(h) If any crack is found during any inspection done in accordance with Bombardier CRJ 700/900 Series TR MRM2-129, dated June 1, 2004, or the same inspection specified in the general revisions of the Maintenance Requirement Manual, do the actions specified in paragraphs (h)(1) and (h)(2) of this AD.

(1) Before further flight, repair the crack in accordance with a method approved by either the Manager, New York Aircraft Certification Office (ACO), FAA; or Transport Canada Civil Aviation (TCCA) (or its delegated agent).

(2) Within 30 days after repairing any crack in accordance with paragraph (h)(1) of this AD, revise the Airworthiness Limitations section of the Instructions of Continued Airworthiness by inserting a copy of the inspection requirements for the repair required by paragraph (h)(1) of this AD into Section 1.4, Part 2 (Airworthiness Limitations) of Bombardier Regional Jet Model CL-600-2C10 and CL-600-2D24 Maintenance Requirements Manual, CSP B-053. Thereafter, except as provided in paragraph (i) of this AD, no alternative structural inspection intervals may be approved for this aft pressure bulkhead and pylon pressure pan in the vicinity of the hydraulic fittings, and the hydraulic tube adapters.

Alternative Methods of Compliance (AMOCs)

(i) The Manager, New York ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(j) Canadian airworthiness directive CF-2004-14, dated July 20, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on November 17, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-26493 Filed 11-30-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19755; Directorate Identifier 2004-NM-23-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 747 airplanes. This proposed AD would require repetitive tests to detect hot air leaking from the trim air diffuser ducts or sidewall riser duct assemblies (collectively referred to in this proposed AD as "TADDs"), related investigative actions, and corrective actions if necessary. This proposed AD also would provide an optional terminating action for the repetitive tests. This proposed AD is prompted by reports of deteriorating sealants both inside and outside the center wing fuel tank due to heat damage from leaking TADDs. We are proposing this AD to prevent leakage of fuel or fuel vapors into areas where ignition sources may be present, which could result in a fire or explosion.

DATES: We must receive comments on this proposed AD by January 18, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket

Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Technical information: Dan Kinney, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6499; fax (425) 917-6590.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-19755; Directorate Identifier 2004-NM-23-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

We have received a report indicating that inspections have revealed deteriorating sealants both inside and outside the center wing fuel tank on certain Boeing Model 747 airplanes. The deterioration is attributed to damage caused by hot air leaking from the trim air diffuser ducts or sidewall riser duct assemblies (collectively referred to in this proposed AD as "TADDs"), which are part of the cabin air distribution system that is located between the top of the center wing fuel tank and the floor of the passenger cabin. These hot air leaks occur when the fiberglass diffuser ducts are damaged by the hot bleed air that they carry, leading the fiberglass diffuser ducts to leak or disconnect from the titanium trim air manifold. The release of hot air can damage the upper skin of the center wing section, the longitudinal floor beams, and the fuselage frame intercostals, as well as the sealants of the center wing fuel tank. Damage to the sealants inside or outside the center wing fuel tank could allow fuel or fuel vapors to leak into an area where ignition sources may be present. This condition, if not corrected, could result in a fire or explosion.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 747-21A2418, Revision 2, dated March 4, 2004; including Information Notice (IN) 747-21A2418 IN 01, dated March 11, 2004. The service bulletin describes procedures for repetitive tests to detect hot air leaking from the TADDs, related investigative actions, and corrective actions if

necessary. The related investigative actions are repetitive general visual inspections for discrepancies or damage of the TADDs; and, if necessary, for damage of adjacent structure, the primary and secondary fuel barriers of the center wing fuel tank, control cables, and cable pulleys, and for raised cable seals. The corrective actions, if any damage is found, consist of replacing any damaged TADD with a new TADD having the same part number, or a new, improved TADD that has a higher temperature tolerance; and repairing any damage to adjacent structure, the primary and secondary fuel barriers of the center wing fuel tank, control cables, cable pulleys, or raised cable seals. After a TADD is replaced with a new TADD having the same part number, there is no need to test or inspect the replaced TADD until 21,200 flight hours after the replacement. After a TADD is replaced with a new, improved TADD, the repetitive inspections are no longer needed for that TADD. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

IN 747-21A2418 IN 01 identifies some headings that were inadvertently omitted from the Accomplishment Instructions of Boeing Alert Service Bulletin 747-21A2418, Revision 2. These headings clarify what procedures apply to which airplane configuration.

The service bulletin refers to Chapter 21-61-20 of the 747 Airplane Maintenance Manual as an additional source for service information for the test and inspection of the TADDs. Chapter 21-61-20 contains, among other things, detailed procedures for the general visual inspection of the TADDs for damage or discrepancies, including detachment of the trim air duct from the diffuser duct, delamination, missing or softened surface material, or blackened material. For any discrepant TADD, Chapter 21-61-20 also describes procedures for a general visual inspection for damage of the primary and secondary fuel barriers of the center wing tank; structure adjacent to the discrepant TADD; and cables, cable pulleys, and raised cable seals in the over-wing area.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require doing the actions specified in the service information described previously, except as discussed under

"Differences Between the Proposed AD and Service Information."

This proposed AD also provides an optional terminating action for the repetitive inspections, which is replacing the existing TADDs with new, improved TADDs. We have determined that it is acceptable to allow you to continue doing repetitive tests and inspections in lieu of requiring that you do the terminating action. In making this determination, we considered that long-term continued operational safety in this case will be adequately ensured by repetitive inspections to detect hot air leaking from the TADDs or discrepancies of the TADDs before these conditions are a hazard to the airplane.

Clarification of Proposed Requirements

This proposed AD would require that any replacement TADD must be new. Used TADDs are not acceptable replacement parts. Because the material of the TADDs deteriorates at a known rate, an operator would have to know how many total flight hours had been accumulated on a serviceable TADD, and would have to test and inspect that TADD at appropriate intervals. We find that it is unlikely that operators will have all of the data that would be needed for a serviceable TADD to be an acceptable replacement. Therefore, this proposed AD would allow replacement only with new parts.

Differences Between the Proposed AD and Service Information

For the hot air leak test, the service bulletin provides a compliance time of the earlier of 180 days or 2,000 flight hours after the release date of Revision 2 of the service bulletin, once the airplane has accumulated 20,000 total flight hours. For this test, this proposed AD would require the initial test to be done prior to the accumulation of 21,200 flight hours, or within 1,200 flight hours after the effective date of this AD, whichever is later. This compliance time is the equivalent of the inspection threshold of 20,000 total flight hours, plus a grace period of 1,200 flight hours (which is equivalent to one repetitive interval, as specified in the service bulletin). In developing an appropriate compliance time for this AD, we considered the manufacturer's recommendation, and the degree of urgency associated with the subject unsafe condition. In light of these factors, we find that a 1,200-flight-hour grace period represents an appropriate interval of time for affected airplanes (with close to or more than 20,000 total flight hours as of the effective date of the AD) to continue to operate without compromising safety.

Costs of Compliance

This proposed AD would affect about 1,305 airplanes worldwide. The

following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Hot air leak test	3	\$65	None	\$195 per test cycle	246	\$47,970 per test cycle.
General visual inspection	5	65	None	\$325 per inspection cycle ..	246	\$79,950 per inspection cycle.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the ADDRESSES section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2004-19755; Directorate Identifier 2004-NM-23-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by January 18, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes; certificated in any category; line numbers 1 through 1316 inclusive.

Unsafe Condition

(d) This AD was prompted by reports of deteriorating sealants both inside and outside the center wing fuel tank due to heat damage from leaking trim air diffuser ducts or sidewall riser duct assemblies (collectively referred to in this AD as "TADDs"). We are issuing this AD to prevent leakage of fuel or fuel vapors into areas where ignition sources may be present, which could result in a fire or explosion.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Repetitive Tests and Inspections

(f) Do the actions in Table 1 of this AD at the times specified in Table 1 of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-21A2418, Revision 2, dated March 4, 2004; including Information Notice 747-21A2418 IN 01, dated March 11, 2004.

TABLE 1.—COMPLIANCE TIMES

Do this action—	Initially at the later of—	Then repeat within this interval until paragraph (j) is done—
(1) Repetitive test to detect hot air leaking from TADDs.	Prior to the accumulation of 21,200 total flight hours, or within 1,200 flight hours after the effective date of this AD.	1,200 flight hours.
(2) General visual inspection for damage or discrepancies of the TADDs.	Prior to the accumulation of 27,000 total flight hours, or within 7,000 flight hours after the effective date of this AD, except as provided by paragraph (g) of this AD.	7,000 flight hours.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level

of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Note 2: Boeing Alert Service Bulletin 747-21A2418, Revision 2, refers to Chapter 21-

61-20 of the 747 Airplane Maintenance Manual as an additional source for service information for the test and inspections of the TADDs.

(g) If any hot air leak is found during any test required by paragraph (f) of this AD: Before further flight, do the general visual inspection for damage or discrepancies of the TADDs, in accordance with the

Accomplishment Instructions of Boeing Alert Service Bulletin 747-21A2418, Revision 2, dated March 4, 2004; including Information Notice 747-21A2418 IN 01, dated March 11, 2004.

Corrective Actions

(h) If any damage or discrepancy is found during any general visual inspection for damage required by paragraph (f) or (g) of this AD: Before further flight, perform a general visual inspection for damage of the primary and secondary fuel barriers of the center wing tank; structure adjacent to the discrepant TADD; and cables, cable pulleys, and raised cable seals in the over-wing area; do applicable repairs; and replace the damaged TADD with a new TADD having the same part number or a new, improved TADD having a part number listed in the "New TADD Part Number" or "New Sidewall Riser Duct Assy Part Number" column, as applicable, of the tables in Section 2.C.2. of the service bulletin. Do all of these actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-21A2418, Revision 2, dated March 4, 2004; including Information Notice 747-21A2418 IN 01, dated March 11, 2004. Then, repeat the test and inspection required by paragraph (f) of this AD at the times specified in Table 1 of this AD, except as provided by paragraphs (i) and (j) of this AD.

Note 3: Only new TADDs, not used ones, are acceptable as replacement parts, as specified in paragraph (h) of this AD.

(i) For any TADD, whether damaged or not, that is replaced with a new TADD having the same part number as the TADD being replaced: Within 21,200 flight hours after the TADD is replaced, do the test to detect hot air leaking from the replaced TADD, and within 27,000 flight hours after the TADD is replaced, do the general visual inspection for damage, as specified in paragraph (f) of this AD. Thereafter, repeat the test and inspection at the repetitive intervals specified in Table 1 of this AD.

Optional Terminating Action

(j) For any TADD that is replaced with a new, improved TADD having a part number listed in the "New TADD Part Number" or "New Sidewall Riser Duct Assy Part Number" column, as applicable, of the tables in Section 2.C.2. of Boeing Alert Service Bulletin 747-21A2418, Revision 2, dated March 4, 2004; including Information Notice 747-21A2418 IN 01, dated March 11, 2004: The repetitive tests and inspections required by this AD are terminated for the TADD that is replaced with a new, improved TADD.

Previously Accomplished Actions

(k) Actions accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 747-21A2418, dated November 14, 2002; or Revision 1, dated October 16, 2003; are acceptable for compliance with the corresponding actions required by this AD.

Alternative Methods of Compliance (AMOCs)

(l) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the

authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on November 17, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-26492 Filed 11-30-04; 8:45 am]

BILLING CODE 4910-13-P

NATIONAL INDIAN GAMING COMMISSION

25 CFR Part 542

RIN 3141-AA27

Minimum Internal Control Standards

AGENCY: National Indian Gaming Commission.

ACTION: Proposed rule revisions.

SUMMARY: In response to the inherent risks of gaming enterprises and the resulting need for effective internal controls in Tribal gaming operations, the National Indian Gaming Commission (Commission or NIGC) first developed Minimum Internal Control Standards (MICS) for Indian gaming in 1999, and then later revised them in 2002. The Commission recognized from the outset that periodic technical adjustments and revisions would be necessary in order to keep the MICS effective in protecting Tribal gaming assets and the interests of Tribal stakeholders and the gaming public. To that end, the following proposed rule revisions contain certain proposed corrections and revisions to the Commission's existing MICS, which are necessary to correct erroneous citations or references in the MICS and to clarify, improve, and update other existing MICS provisions. The purpose of these proposed MICS revisions is to address apparent shortcomings in the MICS and various changes in Tribal gaming technology and methods. Public comment to these proposed MICS revisions will be received by the Commission for a period of forty-five (45) days after the date of their publication in the **Federal Register**. After consideration of all received comments, the Commission will make whatever changes to the proposed revisions that it deems appropriate and then promulgate and publish the final revisions to the Commission's MICS Rule, 25 CFR part 542.

DATES: Submit comments on or before January 18, 2005.

ADDRESSES: Mail comments to "Comments to First Proposed MICS

Rule Revisions, National Indian Gaming Commission, 1441 L Street, NW., Washington, DC 20005, Attn: Vice-Chairman Nelson Westrin." Comments may be transmitted by facsimile to Vice-Chairman Westrin at (202) 632-0045, but the original also must be submitted to the above address.

FOR FURTHER INFORMATION CONTACT: Vice-Chairman Nelson Westrin, (202) 632-7003 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

On January 5, 1999, the Commission first published its Minimum Internal Control Standards (MICS) as a Final Rule. As gaming Tribes and the Commission gained practical experience applying the MICS, it became apparent that some of the standards required clarification or modification to operate as the Commission had intended and to accommodate changes and advances that had occurred over the years in Tribal gaming technology and methods. Consequently, the Commission, working with an Advisory Committee composed of Commission and Tribal representatives, published the new final revised MICS rule on June 27, 2002.

As the result of the practical experience of the Commission and Tribes working with the newly revised MICS, it has once again become apparent that additional corrections, clarifications, and modifications are needed to ensure that the MICS continue to operate as the Commission intended. To identify which of the current MICS need correction, clarification or modification, the Commission initially solicited input and guidance from NIGC employees, who have extensive gaming regulatory expertise and experience and work closely with Tribal gaming regulators in monitoring the implementation, operation, and effect of the MICS in Tribal gaming operations. The resulting input from NIGC staff convinced the Commission that the MICS require continuing review and prompt revision on an ongoing basis to keep them effective and up-to-date. To address this need, the Commission decided to establish a Standing MICS Advisory Committee to assist it in both identifying and developing necessary MICS revisions and revisions on an ongoing basis.

In recognition of its government-to-government relationship with Tribes and related commitment to meaningful Tribal consultation, the Commission requested gaming Tribes, in January 2004, for nominations of Tribal representatives to serve on its Standing