

specified time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 737-53A1197, dated August 25, 2006, specifies a compliance time "After the Date of this Service Bulletin," this AD requires compliance for paragraph (h) of this AD within the specified time after September 23, 2008 (the effective date of AD 2008-17-03, Amendment 39-15641 (73 FR 48288, August 19, 2008)). For the initial inspection, the grace period for airplanes that have exceeded the specified threshold is extended to 4,500 flight cycles after September 23, 2008 (the effective date of AD 2008-17-03).

(3) Where Boeing Alert Service Bulletin 737-53A1188, Revision 2, dated May 9, 2007; Boeing Alert Service Bulletin 737-53A1188, Revision 3, dated September 6, 2013; and Boeing Alert Service Bulletin 737-53A1197, dated August 25, 2006; specify to contact Boeing for appropriate action, including repair of damage outside the scope of the service information, repair using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2008-17-03, Amendment 39-15641 (73 FR 48288, August 19, 2008), are approved as AMOCs for the corresponding provisions of this AD.

(l) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6450; fax: 425-917-6590; email: alan.pohl@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680;

Internet <https://www.myboeingfleet.com>. You may view the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on April 4, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-08301 Filed 4-11-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0226; Directorate Identifier 2014-CE-009-AD]

RIN 2120-AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Diamond Aircraft Industries GmbH Models DA40 and DA40F airplanes that would supersede AD 2013-24-14, which resulted from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the fatigue strength found in the aft main spar not ensuring unlimited lifetime structural integrity. We are issuing this proposed AD to require actions to address the unsafe condition on these products and to change the compliance time to coincide with other regulatory requirements.

DATES: We must receive comments on this proposed AD by May 29, 2014.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Str.5, A-2700 Wiener Neustadt, Austria; telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: <http://www.diamondaircraft.com/contact/technical.php>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0226; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0226; Directorate Identifier 2014-CE-009-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On November 22, 2013, we issued AD 2013–24–14, Amendment 39–17689 (78 FR 72568; December 3, 2013). That AD required actions intended to address an unsafe condition on Diamond Aircraft Industries GmbH Models DA40 and DA40F airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

The inspections required by AD 2013–24–13 are tied to calendar time and the Major Structural Inspection (MSI) identified in Chapter 5 of the airplane maintenance manual (AMM). This compliance time mirrors the mandatory continuing airworthiness information (MCAI) issued by the State of Design for these products.

However, U.S. operators are not required to comply with the requirement to inspect before the next MSI since the Limitations in Chapter 4 of the AMM are mandatory and the MSI in Chapter 5 of the AMM is not mandatory.

Relevant Service Information

Diamond Aircraft Industries GmbH has issued Mandatory Service Bulletin MSB 40–074, MSB D4–094, and MSB F4–028 (co-published as a single document), dated May 10, 2013; Diamond Aircraft Industries GmbH Work Instructions WI–MSB 40–074, WI–MSB D4–094, and WI–MSB F4–028, (co-published as a single document), dated May 10, 2013; and DA 40 Series AMM, Chapter Section 05–28–50, Section 2 (Cockpit), page 11, Item 31, sub-item “The rear main bulkhead,” Rev. 7, dated April 1, 2013. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 747 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to

comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$100 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$455,670, or \$610 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39–17689 (78 FR 72568; December 3, 2013), and adding the following new AD:

Diamond Aircraft Industries GmbH: Docket No. FAA–2014–0226; Directorate Identifier 2014–CE–009–AD.

(a) Comments Due Date

We must receive comments by May 29, 2014.

(b) Affected ADs

This AD supersedes AD 2013–24–14, Amendment 39–17689 (78 FR 72568; December 3, 2013).

(c) Applicability

This AD applies to Diamond Aircraft Industries Model DA 40 airplanes, serial numbers 40.006 through 40.009, 40.011 through 40.1071, and 40.1073 through 40.1077; and Model DA 40 F airplanes, serial numbers 40.FC001 through 40.FC029; certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 57: Wings.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. We are issuing this proposed AD to correct an incorrect compliance time and to modify the aft main spar in the cabin area to ensure the structural integrity of the airplane.

(f) Actions and Compliance

Comply with this AD within the compliance times specified in paragraphs (f)(1) through (f)(4) of this AD, unless already done.

(1) *For airplanes with less than 1,500 hours TIS:* At or before 2,000 hours time-in-service (TIS) after the effective date of this AD or within the next 114 months after the effective date of this AD, whichever occurs first, modify the aft main spar in the cabin area following the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instructions WI–MSB 40–074, WI–MSB D4–094, and WI–MSB F4–028 (co-published as a single document), dated May 10, 2013, as specified in Diamond Aircraft Industries GmbH Mandatory Service Bulletins (MSB) 40–074, D4–094, and F4–028 (co-published as a single document), dated May 10, 2013.

(2) *For airplanes with 1,500 hours or more than 1,500 hours TIS but less than 2,000 hours TIS:* At or before 500 hours TIS after

the effective date of this AD or within the next 114 months after the effective date of this AD, whichever occurs first, modify the aft main spar in the cabin area following the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instructions WI-MSB 40-074, WI-MSB D4-094, and WI-MSB F4-028 (co-published as a single document), dated May 10, 2013, as specified in Diamond Aircraft Industries GmbH Mandatory Service Bulletins (MSB) 40-074, D4-094, and F4-028 (co-published as a single document), dated May 10, 2013.

(3) *For airplanes with 2,000 hours or more than 2,000 hours TIS but less than 2,500 hours TIS:* At or before 500 hours TIS after the effective date of this AD or within the next 48 months after the effective date of this AD, whichever occurs first, modify the aft main spar in the cabin area following the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instructions WI-MSB 40-074, WI-MSB D4-094, and WI-MSB F4-028 (co-published as a single document), dated May 10, 2013, as specified in Diamond Aircraft Industries GmbH Mandatory Service Bulletins (MSB) 40-074, D4-094, and F4-028 (co-published as a single document), dated May 10, 2013.

(4) *For airplanes with 2,500 hours or more than 2,500 hours TIS:* Within the next 100 hours TIS after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first, inspect the aft spar center section following DIAMOND AIRCRAFT INDUSTRIES DA 40 SERIES AIRPLANE MAINTENANCE MANUAL (AMM), Chapter Section 05-28-50, Section 2 (Cockpit), Item 31, sub-item "The rear main bulkhead," page 11, Rev. 7, dated April 1, 2013, and perform any applicable corrective actions.

(i) After doing the inspection required by paragraph (f)(4) of this AD including any applicable corrective actions, at or before 500 hours TIS after the effective date of this AD or within the next 48 months after the effective date of this AD, whichever occurs first, modify the aft main spar in the cabin area following the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instructions WI-MSB 40-074, WI-MSB D4-094, and WI-MSB F4-028 (co-published as a single document), dated May 10, 2013, as specified in Diamond Aircraft Industries GmbH Mandatory Service Bulletins (MSB) 40-074, D4-094, and F4-028 (co-published as a single document), dated May 10, 2013.

(ii) The modification required in paragraph (f)(4)(i) of this AD may be done instead of the inspection required by paragraph (f)(4) of this AD provided it is done within the next 100 hours TIS after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer,

FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2013-0145, dated July 15, 2013, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0226. For service information related to this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Str.5, A-2700 Wiener Neustadt, Austria; telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: <http://www.diamondaircraft.com/contact/technical.php>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on April 8, 2014.

Timothy Smyth,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-08312 Filed 4-11-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0196; Directorate Identifier 2014-NM-015-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, Model CL-600-2D24 (Regional Jet Series 900) airplanes, and Model CL-

600-2E25 (Regional Jet Series 1000) airplanes. This proposed AD was prompted by two in-service reports of fracture of the rudder pedal tubes installed on the pilot-side rudder bar assembly. This proposed AD would require repetitive inspections for cracking and damage of the pilot-side rudder pedal tubes, and corrective action if necessary. This proposed AD would also provide optional terminating action for the repetitive inspections. We are proposing this AD to detect and correct cracked and damaged pilot-side rudder pedal tubes, which could result in loss of function of the pilot's rudder pedal during flight, takeoff, or landing, and could result in reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by May 29, 2014.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0196; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will