

Issued in Renton, Washington, on February 16, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 2016-03996 Filed 2-24-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0254; Directorate Identifier 2010-NM-180-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Proposed rule; withdrawal.

SUMMARY: The FAA withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), which would have applied to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. For certain airplanes, the NPRM would have required a one-time inspection for damage of the hydraulic actuator rod ends and actuator attach fittings on the thrust reversers, and repair or replacement if necessary. For all airplanes, the NPRM would have required repetitive inspections for damage of the hydraulic actuator rod ends, attach bolts, and nuts; repetitive inspections for damage of fitting assemblies, wear spacers, and actuator attach fittings on the thrust reverser; repetitive measurements of the wear spacer; and corrective actions if necessary. Since the NPRM was issued, the manufacturer notified us that an assumption regarding a failure mode of the rod ends or attachment fittings for the thrust reverser actuator used in the original safety assessment was incorrect. A new safety analysis was conducted and we determined that this issue is no longer a safety concern. Accordingly, the NPRM is withdrawn.

DATES: As of February 25, 2016, the proposed rule, which was published in the **Federal Register** on March 22, 2011 (76 FR 15864), is withdrawn.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2011-0254; or in person at the Docket Management Facility between 9 a.m.

and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD action, the NPRM (76 FR 15864, March 22, 2011), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tak Kobayashi, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6499; fax: 425-917-6590; email: Takahisa.Kobayashi@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with a notice of proposed rulemaking (NPRM) for a new AD for certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. The NPRM published in the **Federal Register** on March 22, 2011 (76 FR 15864) ("the NPRM"). For certain airplanes, the NPRM would have required a one-time inspection for damage of the hydraulic actuator rod ends and actuator attach fittings on the thrust reversers, and repair or replacement if necessary. For all airplanes, the NPRM would have required repetitive inspections for damage of the hydraulic actuator rod ends, attach bolts, and nuts; repetitive inspections for damage of fitting assemblies, wear spacers, and actuator attach fittings on the thrust reverser; repetitive measurements of the wear spacer; and corrective actions if necessary.

The NPRM was prompted by reports of in-service damage of the attachment fittings for the thrust reverser actuator. The proposed actions were intended to detect and correct such damage, which could result in actuator attach fitting failure, loss of the thrust reverser auto restow function, and consequent loss of control of the airplane.

Actions Since NPRM Was Issued

Since we issued the NPRM, the manufacturer has notified us that an assumption regarding a failure mode of the attachment fittings for the thrust reverser actuator used in the original safety assessment was incorrect. It was originally assumed that all hydraulic actuators attached to the thrust reverser

have the failure mode (failure of the hydraulic actuator rod end or attach fitting due to severe wear-out) addressed in the NPRM. Based on field reports and design review, the manufacturer found that certain hydraulic actuators do not have this failure mode. Based on this new manufacturer finding, a new safety analysis was conducted and we determined that this issue is no longer a safety concern.

FAA's Conclusions

Upon further consideration, we have determined that the safety concern identified in the NPRM does not affect The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes identified in the NPRM. Accordingly, the NPRM is withdrawn.

Withdrawal of the NPRM does not preclude the FAA from issuing another related action or commit the FAA to any course of action in the future.

Regulatory Impact

Since this action only withdraws an NPRM, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Withdrawal

Accordingly, we withdraw the NPRM, Docket No. FAA-2011-0254, Directorate Identifier 2010-NM-180-AD, which was published in the **Federal Register** on March 22, 2011 (76 FR 15864).

Issued in Renton, Washington, on February 15, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 2016-03693 Filed 2-24-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-3703; Directorate Identifier 2015-NM-115-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 767–200, –300, and –400ER series airplanes. This proposed AD was prompted by an evaluation by the design approval holder (DAH) indicating that the skin lap splice is subject to widespread fatigue damage (WFD). This proposed AD would require repetitive external detailed and surface high frequency eddy current (HFEC) inspections of the outer skin for cracking around fastener heads common to the inboard fastener row of the skin lap splice. We are proposing this AD to detect and correct fatigue cracking of the skin lap splice, which, if not detected, could grow and result in possible rapid decompression and reduced structural integrity of the airplane.

DATES: We must receive comments on this proposed AD by April 11, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone: 206–544–5000, extension 1; fax: 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–3703.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–3703; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6447; fax: 425–917–6590; email: wayne.lockett@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2016–3703; Directorate Identifier 2015–NM–115–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Structural fatigue damage is progressive. It begins as minute cracks, and those cracks grow under the action of repeated stresses. This can happen because of normal operational conditions and design attributes, or because of isolated situations or incidents such as material defects, poor fabrication quality, or corrosion pits, dings, or scratches. Fatigue damage can occur locally, in small areas or structural design details, or globally. Global fatigue damage is general degradation of large areas of structure with similar structural details and stress levels. Multiple-site damage is global damage that occurs in a large structural element such as a single rivet line of a lap splice joining two large skin panels. Global damage can also occur in multiple elements such as adjacent frames or stringers. Multiple-site

damage and multiple-element-damage cracks are typically too small initially to be reliably detected with normal inspection methods. Without intervention, these cracks will grow, and eventually compromise the structural integrity of the airplane, in a condition known as WFD. As an airplane ages, WFD will likely occur, and will certainly occur if the airplane is operated long enough without any intervention.

The FAA's WFD final rule (75 FR 69746, November 15, 2010) became effective on January 14, 2011. The WFD rule requires certain actions to prevent structural failure due to WFD throughout the operational life of certain existing transport category airplanes and all of these airplanes that will be certificated in the future. For existing and future airplanes subject to the WFD rule, the rule requires that DAHs establish a limit of validity (LOV) of the engineering data that support the structural maintenance program. Operators affected by the WFD rule may not fly an airplane beyond its LOV, unless an extended LOV is approved.

The WFD rule (75 FR 69746, November 15, 2010) does not require identifying and developing maintenance actions if the DAHs can show that such actions are not necessary to prevent WFD before the airplane reaches the LOV. Many LOVs, however, do depend on accomplishment of future maintenance actions. As stated in the WFD rule, any maintenance actions necessary to reach the LOV will be mandated by ADs through separate rulemaking actions.

In the context of WFD, this action is necessary to enable DAHs to propose LOVs that allow operators the longest operational lives for their airplanes, and still ensure that WFD will not occur. This approach allows for an implementation strategy that provides flexibility to DAHs in determining the timing of service information development (with FAA approval), while providing operators with certainty regarding the LOV applicable to their airplanes.

We have received an evaluation by the DAH indicating that the skin lap splice is subject to WFD. As a result of WFD analysis, the stringer S–2R skin lap splice from station (STA) 368 to STA 434 requires additional supplemental inspection beyond the inspections specified in the Boeing Model 767 airplane maintenance planning document. This condition, if not corrected, could result in cracking of the skin lap splice, which could grow and result in possible rapid

decompression and reduced structural integrity of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014. The service information describes procedures for a detailed inspection and a surface HFEC inspection at section 41, stringer S-2R skin lap splice from STA 368 to STA 434, for any cracking, and repair. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the Service Information.” For information on the procedures and compliance times, see this service

information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3703.”

The phrase “corrective actions” is used in this proposed AD. “Corrective actions” are actions that correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Costs of Compliance

We estimate that this proposed AD affects 356 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections	3 work-hours × \$85 per hour = \$255 per inspection cycle.	\$0	\$255 per inspection cycle	\$90,780 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2016-3703; Directorate Identifier 2015-NM-115-AD.

(a) Comments Due Date

We must receive comments by April 11, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Boeing Company Model 767-200, -300, and -400ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that the skin lap splice is subject to widespread fatigue damage. We are issuing this AD to detect and correct fatigue cracking of this skin lap splice, which, if not detected, could grow and result in possible rapid decompression and reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Actions

At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014, except as required by paragraph (h) of this AD: Do a detailed inspection and a surface high frequency eddy current (HFEC) inspection at section 41, stringer S-2R skin lap splice from body station (STA) 368 to STA 434, for any cracking, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert

Service Bulletin 767-53A0260, dated August 26, 2014. Do all applicable corrective actions before further flight. Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014. If any existing external repair is found in the inspection area, then the inspections in Part 1 of the

Accomplishment Instructions of Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014, are not required in the area hidden by the repair, provided that the repair was previously approved by the Manager, Seattle Aircraft Certification Office (ACO), or by the Authorized Representative of the Boeing Commercial Airplanes Organization Designation Authorization (ODA), or installed as specified in Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014. Inspections in Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014, remain applicable in areas not hidden by the repair.

(h) Exception to the Service Information

Where Boeing Alert Service Bulletin 767-53A0260, dated August 26, 2014, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes ODA that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

(1) For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6447; fax: 425-917-6590; email: wayne.lockett@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone: 206-544-5000, extension 1; fax: 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on February 15, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-03698 Filed 2-24-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-3702; Directorate Identifier 2015-NM-103-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2013-24-12, which applies to all The Boeing Company Model 747-8 and 747-8F airplanes. AD 2013-24-12 currently requires repetitive ultrasonic or dye penetrant inspections for cracking of the barrel nuts and bolts on each forward engine mount, and related investigative and corrective actions if necessary. Since we issued AD 2013-24-12, we have determined that it is necessary to mandate the installation of new barrel nuts or new inspections to adequately address the unsafe condition. This proposed AD would retain the requirements of AD 2013-24-12 and

add requirements to install new barrel nuts at the forward engine mounts; or identify the part number of the barrel nuts, inspect affected barrel nuts for gaps of the strut bulkhead and forward engine mount, and do related investigative and corrective actions if necessary. This proposed AD would also remove airplanes from the applicability. We are proposing this AD to detect and correct cracked barrel nuts on a forward engine mount, which could result in reduced load capacity of the forward engine mount, separation of an engine under power from the airplane, and consequent loss of control of the airplane.

DATES: We must receive comments on this proposed AD by April 11, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone: 206-544-5000, extension 1; fax: 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3702.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3702; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office