

# Proposed Rules

Federal Register

Vol. 84, No. 135

Monday, July 15, 2019

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## NUCLEAR REGULATORY COMMISSION

### 10 CFR Parts 50 and 52

[Docket No. PRM-50-118; NRC-2019-0071]

#### Measurement Standards Used at U.S. Nuclear Power Plants; Correction

**AGENCY:** Nuclear Regulatory Commission.

**ACTION:** Petition for rulemaking; correction.

**SUMMARY:** The U.S. Nuclear Regulatory Commission (NRC) is correcting a notice that was published in the **Federal Register** (FR) on May 15, 2019, regarding the receipt of a petition for rulemaking from Michael Taylor, dated December 3, 2018, as amended on January 24, 2019. This action is necessary to correct a Docket ID and telephone number.

**DATES:** The correction is effective July 15, 2019.

**ADDRESSES:** Please refer to Docket ID NRC-2019-0071 when contacting the NRC about the availability of information regarding this document. You may obtain publicly-available information related to this document using any of the following methods:

- *Federal Rulemaking Website:* Go to <https://www.regulations.gov> and search for Docket ID NRC-2019-0071. Address questions about NRC dockets to Carol Gallagher; telephone: 301-415-3463; email: [Carol.Gallagher@nrc.gov](mailto:Carol.Gallagher@nrc.gov). For technical questions, contact the individual listed in the **FOR FURTHER INFORMATION CONTACT** section of this document.

- *NRC's Agencywide Documents Access and Management System (ADAMS):* You may obtain publicly-available documents online in the ADAMS Public Documents collection at <https://www.nrc.gov/reading-rm/adams.html>. To begin the search, select "Begin Web-based ADAMS Search." For problems with ADAMS, please contact the NRC's Public Document Room (PDR) reference staff at 1-800-397-4209, 301-

415-4737, or by email to [pdr.resource@nrc.gov](mailto:pdr.resource@nrc.gov).

**FOR FURTHER INFORMATION CONTACT:** Solomon Sahle, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001; telephone: 301-415-3781; email: [Solomon.Sahle@nrc.gov](mailto:Solomon.Sahle@nrc.gov).

**SUPPLEMENTARY INFORMATION:** In the FR on May 15, 2019 (84 FR 21727), correct the Docket ID "Docket ID NRC-2019-0084" to "Docket ID NRC-2019-0071" and the telephone number from "301-415-3407" to "301-415-3781."

Dated at Rockville, Maryland, this 9th day of July 2019.

For the Nuclear Regulatory Commission.  
**Cindy K. Bladey,**  
*Federal Register Liaison Officer, Division of Rulemaking, Office of Nuclear Material Safety and Safeguards.*

[FR Doc. 2019-14896 Filed 7-12-19; 8:45 am]

**BILLING CODE** 7590-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0518; Product Identifier 2019-NM-062-AD]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 and 787-9 airplanes. This proposed AD was prompted by a report that a passenger entry door assist handle became detached during use. This proposed AD would require a detailed inspection of all passenger and service entry door assist handles for correct installation and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 29, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0518.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0518; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: [brandon.lucero@faa.gov](mailto:brandon.lucero@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send

your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2019–0518; Product Identifier 2019–NM–062–AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this proposed AD.

**Discussion**

The FAA received a report indicating that a passenger entry door assist handle became detached during use. An investigation found that incorrect installation of the door assist handle is possible due to the handle insert giving a false indication of correct installation. This condition, if not addressed, could result in an incorrectly installed door assist handle becoming detached and unavailable to use during door operation or airplane egress, which could cause injury to passengers, flightcrew, or maintenance personnel.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Boeing Requirements Bulletin B787–81205–SB250176–00 RB, Issue 001, dated March 6, 2019. The service information describes procedures for a detailed inspection of all passenger and service entry door assist handles for correct installation and applicable on-condition actions. On-condition actions include re-installation of the door assist handles, a detailed inspection for correct installation, and replacement of the doorway support assembly if necessary.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require accomplishment of the actions identified in Boeing Requirements Bulletin B787–81205–SB250176–00 RB, Issue 001, dated March 6, 2019, described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0518.

**Explanation of Requirements Bulletin**

The FAA worked in conjunction with industry, under the Airworthiness Directive Implementation Aviation Rulemaking Committee (AD ARC), to enhance the AD system. One enhancement is a process for annotating which steps in the service information are “required for compliance” (RC) with an AD. Boeing has implemented this RC concept into Boeing service bulletins.

In an effort to further improve the quality of ADs and AD-related Boeing service information, a joint process improvement initiative was worked between the FAA and Boeing. The initiative resulted in the development of a new process in which the service information more clearly identifies the actions needed to address the unsafe condition in the “Accomplishment Instructions.” The new process results in a Boeing Requirements Bulletin, which contains only the actions needed to address the unsafe condition (*i.e.*, only the RC actions).

**Costs of Compliance**

The FAA estimates that this proposed AD affects 579 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection (16 handles per airplane) .....	18 work-hours × \$85 per hour = \$1,530 .....	\$0	\$1,530	\$885,870

The FAA estimates the following costs to do any necessary on-condition

actions that would be required. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
Up to 44 work-hours × \$85 per hour = up to \$3,740 .....	Up to \$14,916 ..	Up to \$18,656.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance

and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**The Boeing Company:** Docket No. FAA-2019-0518; Product Identifier 2019-NM-062-AD.

#### (a) Comments Due Date

The FAA must receive comments by August 29, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to The Boeing Company Model 787-8 and 787-9 airplanes, certificated in any category, as identified in Boeing Requirements Bulletin B787-81205-SB250176-00 RB, Issue 001, dated March 6, 2019.

#### (d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

#### (e) Unsafe Condition

This AD was prompted by a report that a passenger entry door assist handle became detached during use. The FAA is issuing this AD to address the incorrect installation of the door assist handle due to the handle insert giving a false indication of correct installation. This condition, if not addressed, could result in an incorrectly installed door assist handle becoming detached and unavailable to use during door operation or airplane egress, which could cause injury to passengers, flightcrew, or maintenance personnel.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Requirements Bulletin B787-81205-SB250176-00 RB, Issue 001, dated March 6, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Requirements Bulletin B787-81205-SB250176-00 RB, Issue 001, dated March 6, 2019.

*Note 1 to paragraph (g):* Guidance for accomplishing the actions required by this AD can be found in Boeing Service Bulletin B787-81205-SB250176-00, Issue 001, March 6, 2019, which is referred to in Boeing Requirements Bulletin B787-81205-SB250176-00 RB, Issue 001, dated March 6, 2019.

#### (h) Exceptions to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Requirements Bulletin B787-81205-SB250176-00 RB, Issue 001, dated March 6, 2019, uses the phrase "the Issue 001 date of Requirements Bulletin B787-81205-SB250176-00 RB," this AD requires using "the effective date of this AD."

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair,

modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Related Information

(1) For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: brandon.lucero@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on June 26, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-14901 Filed 7-12-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF COMMERCE

### National Oceanic and Atmospheric Administration

#### 15 CFR Part 922

### Findings on the Active Candidate Status of the Proposed Designation of Wisconsin-Lake Michigan National Marine Sanctuary

**AGENCY:** Office of National Marine Sanctuaries (ONMS), National Ocean Service (NOS), National Oceanic and Atmospheric Administration (NOAA), Department of Commerce (DOC).

**ACTION:** Findings on Active Candidate Status.

**SUMMARY:** The National Oceanic and Atmospheric Administration (NOAA) is publishing findings concerning the status of its proposal to designate the Wisconsin-Lake Michigan National Marine Sanctuary (WLMNMS) in order to fulfill the procedural requirements of the National Marine Sanctuaries Act (NMSA).

**DATES:** The designation deadline was July 9, 2019.