

Rules and Regulations

Federal Register

Vol. 61, No. 62

Friday, March 29, 1996

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 925

[Docket No. FV95-925-1C]

Grapes Grown in a Designated Area of Southeastern California; Interim Final Rule To Revise Container Requirements

AGENCY: Agricultural Marketing Service, USDA.

ACTION: Correction to interim final rule.

SUMMARY: This document contains a correction to the interim final rule published on March 19, 1996 [61 FR 11127] concerning grapes grown in Southeastern California.

EFFECTIVE DATE: March 19, 1996.

FOR FURTHER INFORMATION CONTACT: Charles L. Rush, Marketing Order Administration Branch, Fruit and Vegetable Division, AMS, USDA, P.O. Box 96456, room 2526-S, Washington, DC 20090-6456, telephone (202) 690-3670; or Rose M. Aguayo, California Marketing Field Office, Marketing Order Administration Branch, Fruit and Vegetable Division, AMS, USDA, 2202 Monterey Street, Suite 102B, Fresno, California 93721; telephone (209) 487-5901.

SUPPLEMENTARY INFORMATION:

Background

This rule adds two new containers to the list of containers authorized for use by table grape handlers regulated under the marketing order. This rule also reduces the minimum net weight of containers of California table grapes from 22 pounds to 20 pounds and for grapes packed in poly bags from 20 pounds to 18 pounds.

Need for Correction

The interim final rule as published contains an error in the amendatory language affecting 7 CFR part 925.

Correction of Publication

Accordingly, in FR Doc. 96-6348, published March 19, 1996, page 11129, amendatory language number 2, is corrected to read as follows:

§ 925.304 [Corrected]

2. In § 925.304, paragraph (b)(2) is revised and paragraphs (b)(1)(vi) and (b)(1)(vii) are redesignated as paragraphs (b)(1)(viii) and (b)(1)(ix) and new paragraphs (b)(1)(vi) and (b)(1)(vii) are added to read as follows:

Dated: March 25, 1996.

Robert C. Keeney,

Director, Fruit and Vegetable Division.

[FR Doc. 96-7653 Filed 3-28-96; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 95-NM-70-AD; Amendment 39-9553; AD 96-07-04]

Airworthiness Directives; Fokker Model F27 Mark 050 and Model F28 Mark 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Fokker Model F27 Mark 050 and Model F28 Mark 0100 series airplanes, that requires an inspection to verify that adequate clearance exists between the insulation screen and the two adjacent terminal bolts, and replacement of the circuit breaker terminal bolts with new bolts, if necessary. This amendment is prompted by a report that circuit breaker terminal bolts that were too long were discovered installed in the circuit breaker panels. The actions specified by this AD are intended to prevent damage to the insulation screen between adjacent rows of circuit breakers, as the result of a circuit breaker terminal bolt being too long; this condition could lead to electrical arcing and loss of the associated electrical system, which could result in the potential for an electrical fire.

DATES: Effective April 29, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 29, 1996.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Aircraft USA, Inc., 1199 North Fairfax Street, Alexandria, Virginia 22314. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (206) 227-2141; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Fokker Model F27 Mark 050 and Model F28 Mark 0100 series airplanes was published in the Federal Register on November 28, 1995 (60 FR 58584). That action proposed to require a one-time inspection to verify that adequate clearance exists between the insulation screen and the two adjacent terminal bolts, and replacement of the circuit breaker terminal bolts with new bolts, if necessary.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 44 Model F28 Mark 0100 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators of Model F28 Mark 0100