

appropriate compliance time for this action, the FAA considered not only the degree of urgency associated with addressing the subject unsafe condition, but also the manufacturer's and foreign airworthiness authority's recommendations regarding an appropriate compliance time, and an appropriate interval of time that parallels the normally scheduled maintenance for the majority of affected operators.

In consideration of all of these factors, and in consideration of the amount of time that has already elapsed since issuance of the original NPRM, the FAA has determined that further delay of this modification is not appropriate.

However, under the provisions of paragraph (b) of the final rule, the FAA may approve requests for adjustments to the compliance time if data are submitted that substantiate that such an adjustment would provide an acceptable level of safety.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 129 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required action, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$30,960, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-04-50 Fokker: Amendment 39-10361. Docket 97-NM-274-AD.

Applicability: Model F.28 Mark 0070 and Model F.28 Mark 0100 series airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a possible ignition hazard due to accumulation of water and fuel between the front spar and auxiliary spar, which could result in increased risk of an in-flight fire, accomplish the following:

(a) Within 12 months after the effective date of this AD, modify the wing leading edge torsion box, in accordance with Fokker Service Bulletin SBF100-57-034, dated December 20, 1996.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with Fokker Service Bulletin SBF100-57-034, dated December 20, 1996. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., Technical Support Department, P.O. Box 75047, 1117 ZN Schiphol Airport, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Dutch airworthiness directive BLA No. 1996-153(A), dated December 31, 1996.

(e) This amendment becomes effective on April 3, 1998.

Issued in Renton, Washington, on February 13, 1998.

Stewart R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-4412 Filed 2-26-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-SW-09-AD; Amendment 39-10363; AD 98-05-01]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model SA-366G1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Eurocopter France Model SA-366G1 helicopters, with certain main rotor head frequency adapters

(frequency adapters) installed. This proposal requires inspecting the frequency adapter to determine if a certain frequency adapter is installed, and if so, removing and discarding the frequency adapter and replacing it with an airworthy frequency adapter before further flight. This amendment is prompted by a report of disbonding of the metal center section of a frequency adapter from the elastomer, caused by a lack of adherence during the production process. The actions specified by this AD are intended to prevent vibrations caused by disbonding of the center section of a frequency adapter from the elastomer, that could result in loss of control of the helicopter.

EFFECTIVE DATE: April 3, 1998.

FOR FURTHER INFORMATION CONTACT: Mr. Mike Mathias, Aerospace Engineer, Rotorcraft Standards Staff, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5123, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to Eurocopter France Model SA-366G1 helicopters was published in the **Federal Register** on August 26, 1997 (62 FR 45183). That action proposed to require inspecting the frequency adapter to determine if a certain frequency adapter is installed, and if so, removing and discarding the frequency adapter and replacing it with an airworthy frequency adapter before further flight.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed except that Note 4 is added to this rule to provide a reference to the French AD. The FAA has determined that this change will neither increase the economic burden on an operator nor increase the scope of the AD.

The FAA estimates that 91 helicopters of U.S. registry will be affected by this AD, that it will take approximately 6 work hours per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$5,200 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$505,960.

The regulations adopted herein will not have substantial direct effects on the

States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 98-05-01 Eurocopter France:

Amendment 39-10363. Docket No. 97-SW-09-AD.

Applicability: Model SA-366G1 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe

condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required within the next 100 hours time-in-service or 6 months after the effective date of this AD, whichever occurs first, unless accomplished previously.

To prevent vibrations caused by disbonding of the center section of a frequency adapter from the elastomer, that could result in loss of control of the helicopter, accomplish the following:

(a) Determine the part number, serial number, and date of manufacture of the main rotor head frequency adapter (frequency adapter).

(b) After making the determination in paragraph (a) and before further flight, if frequency adapter, part number (P/N) 704A33-640-031 (E1T2624-01A), or delivered in pairs under the P/N 365A31-1858-01, manufactured before April 1, 1991, with serial number (S/N) equal to or less than 8188; or P/N 704A33-640-046 (E1T3023-01), or delivered in pairs under the P/N 365A31-1858-02, manufactured before April 1, 1991, with S/N equal to or less than 3122 is installed, remove the frequency adapter and replace it with an airworthy frequency adapter.

Note 2: Eurocopter France SA-366 Service Bulletin No. 01.23, dated May 9, 1996, pertains to this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, FAA Rotorcraft Directorate, Rotorcraft Standards Staff. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Standards Staff.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Standards Staff.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 96-116-019(B), dated June 19, 1996.

Issued in Fort Worth, Texas, on February 19, 1998.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 98-4979 Filed 2-26-98; 8:45 am]

BILLING CODE 4910-13-U