

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

CFE Company: Docket No. 98-ANE-69-AD.

Applicability: CFE Company Model CFE738-1-1B turbofan engines, installed on but not limited to the Dassault Aviation Falcon 2000 series airplanes.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of certain high pressure compressor (HPC) rotor components, which could result in an uncontained engine failure and damage to the airplane, accomplish the following:

(a) Remove from service certain stage 4 and 5 blisks and impeller aft shafts prior to exceeding the new reduced cyclic life limits as follows, and replace with serviceable parts:

Nomenclature	Part No. (P/N)	Cyclic Life Limit (cycles since new)
Stage 4 and 5 Blisk.	6079T74P07	2,370
	6079T74P08	3,450
Impeller Aft Shaft	6079T74P09	3,790
	6079T80P04	5,100
	6079T80P05	2,160
	6079T80P06	7,100
	6079T80P07	7,100

(b) Except for the provisions of paragraph (c) of this AD, no parts, identified by P/N in paragraph (a) of this AD, may be installed that exceed the new life limits.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Issued in Burlington, Massachusetts, on September 16, 1999.

Donald E. Plouffe,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 99-24787 Filed 9-22-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-197-AD]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB 2000 series airplanes. This proposal would require modification of the airplane by coldworking fastener holes at the front and rear wing spars and by installing modified support angles for the lower

trailing edge panel of the wing. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent fatigue cracking in the lower spar cap of the wing rear spar and in the lower skin at the wing front spar, just outside the nacelle, on the left-hand and right-hand side of the airplane, which could result in fuel leakage and consequent fire in or around the wing.

DATES: Comments must be received by October 25, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-197-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact

concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-197-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-197-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfartsverket (LFV), which is the airworthiness authority for Sweden, recently notified the FAA that an unsafe condition may exist on certain Saab Model SAAB 2000 series airplanes. The LFV advises that, during full-scale fatigue testing of the airplane, cracks were detected at some fastener holes in the lower spar cap of the wing rear spar and in the lower skin at the wing front spar, just outside the nacelle, on the left-hand and right-hand sides of the airplane. This condition, if not corrected, could result in fuel leakage and consequent fire in or around the wing.

Explanation of Relevant Service Information

Saab has issued Service Bulletin 2000-57-029, dated June 4, 1999, which describes procedures for modification of the airplane by coldworking fastener holes at the front and rear wing spars and by installing modified support angles for the lower trailing edge panel of the wing. The modification also involves nondestructive test (NDT) and detailed visual inspections of holes for discrepancies, and repairs, if necessary. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The LFV classified this service bulletin as mandatory and issued Swedish airworthiness directive SAD 1-142, dated June 4, 1999, in order to assure the continued airworthiness of these airplanes in Sweden.

FAA's Conclusions

This airplane model is manufactured in Sweden and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR

21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LFV has kept the FAA informed of the situation described above. The FAA has examined the findings of the LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Differences Between Proposed Rule and Service Bulletin

Operators should note that, although the service bulletin specifies that the manufacturer may be contacted for repair instructions for certain damage conditions, this proposal would require the repair of those conditions to be accomplished in accordance with a method approved by either the FAA, or the LFV (or its delegated agent). In light of the type of repair that would be required to address the identified unsafe condition, and in consonance with existing bilateral airworthiness agreements, the FAA has determined that, for this proposed AD, a repair approved by either the FAA or the LFV would be acceptable for compliance with this proposed AD.

Cost Impact

The FAA estimates that 3 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 180 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. The manufacturer states that necessary parts would be provided at no cost to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$32,400, or \$10,800 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects

on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Saab Aircraft AB: Docket 99-NM-197-AD.

Applicability: Model SAAB 2000 series airplanes, as listed in Saab Service Bulletin 2000-57-029, dated June 4, 1999; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or

repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking in the lower spar cap of the wing rear spar and in the lower skin at the wing front spar, just outside the nacelle, on the left-hand and right-hand side of the airplane, which could result in fuel leakage and consequent fire in or around the wing, accomplish the following:

(a) Prior to the accumulation of 13,000 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs later, modify the airplane by coldworking the fastener holes at the front and rear wing spar (including all applicable nondestructive test and detailed visual inspections and repairs of holes) and installing modified support angles for the lower trailing edge panel of the wing, in accordance with the instructions of Saab Service Bulletin SAAB 2000-57-029, dated June 4, 1999.

(b) Where Saab Service Bulletin 2000-57-029, dated June 4, 1999, specifies that Saab be contacted for repair instructions for certain damage conditions, this AD requires that such damage conditions must be repaired in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Luftfartsverket (LFV) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Swedish airworthiness directive SAD 1-142, dated June 4, 1999.

Issued in Renton, Washington, on September 17, 1999.

D.L. Rigglin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-24848 Filed 9-22-99; 8:45 am]

BILLING CODE 4910-13-P

PRESIDIO TRUST

36 CFR Part 1010

RIN 3212-AA02

Management of the Presidio: Environmental Quality

AGENCY: The Presidio Trust.

ACTION: Extension of public comment period.

SUMMARY: This action extends until October 5, 1999 the period for public comment on the proposed rule published in the **Federal Register** (64 FR 39951-39963) on July 23, 1999 (proposed 36 CFR Part 1010). This proposed rule would implement the National Environmental Policy Act (NEPA) and replace the Presidio Trust's interim procedures and guidelines implementing NEPA, the availability of which was noticed in the **Federal Register** on September 14, 1998 (63 FR 49142).

DATES: Comments on the proposed rule must be received by October 5, 1999.

ADDRESSES: Written comments on the proposed rule must be sent to Karen A. Cook, General Counsel, Presidio Trust, 34 Graham Street, P.O. Box 29052, San Francisco, CA 94129-0052.

FOR FURTHER INFORMATION CONTACT: Karen A. Cook, General Counsel, Presidio Trust, 34 Graham Street, P.O. Box 29052, San Francisco, CA 94129-0052. Telephone: 415-561-5300.

Dated: September 17, 1999.

Karen A. Cook,

General Counsel.
[FR Doc. 99-24785 Filed 9-22-99; 8:45 am]

BILLING CODE 4310-4R-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[MD069-3031b and MD070-3031b; FRL-6440-7]

Approval and Promulgation of Air Quality Implementation Plans; Maryland; Control of Volatile Organic Compounds From Vinegar Generators and Leather Coating Operations

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA proposes to approve the State Implementation Plan (SIP) revision submitted by the State of Maryland for the purpose of establishing volatile organic compound control requirements on vinegar generators and leather coating operations. In the Final Rules section of this **Federal Register**, EPA is approving the State's SIP submittal as a direct final rule without prior proposal because the Agency views this as a noncontroversial submittal and anticipates no adverse comments. A more detailed description of the state submittal and EPA's evaluation are included in a Technical Support Document (TSD) prepared in support of this rulemaking action. A copy of the TSD is available, upon request, from the EPA Regional Office listed in the **ADDRESSES** section of this document. If no adverse comments are received in response to this action, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period on this action. Any parties interested in commenting on this action should do so at this time.

DATES: Comments must be received in writing by October 25, 1999.

ADDRESSES: Written comments should be addressed to Kathleen Henry, Chief, Permits and Technical Assessment Branch, Mailcode 3AP11, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103. Copies of the documents relevant to this action are available for public inspection during normal business hours at the Air Protection Division, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103; the Maryland Department of the Environment, 2500 Broening Highway, Baltimore, Maryland, 21224.