

Corrections

Federal Register
Vol. 65, No. 135
Thursday, July 13, 2000

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

DEPARTMENT OF COMMERCE
Bureau of Export Administration

15 CFR Part 774
[Docket No. 990625176-0029-02]
RIN 0694-AB86

Revisions and Clarifications to the
Export Administration Regulations;
Commerce Control List

Correction
In rule document 00-13252 beginning on page 34073 in the issue of Friday, May 26, 2000, make the following correction:

- PART 774 [CORRECTED]
1. On page 34075, in Supplement No. 1 to Part 774, in the third column, in “note 1.”, in the second line, “desired” should read “designed”.
 2. On page 34076, in the same supplement, in the second column, in paragraph b.2.f.3., “+0.3” should read “±0.3”.
 3. On the same page, in the same supplement, in the same column, in paragraph b.3.a.3., “+10” should read “±10”.

[FR Doc. C0-13252 Filed 7-12-00; 8:45 am]
BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 39
[Docket No. 2000-NM-208-AD; Amendment 39-11801; AD 2000-13-02]
RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and EMB-145 Series Airplanes

Correction
In rule document 00-16110 beginning on page 39541 in the issue of Tuesday, June 27, 2000, make the following correction:

§39.13 [Corrected]
On page 39543, in the first column, in paragraph (b), the lines between “Assisted Start:” and “APU bleed start:” are corrected to read as follows:

Crossbleed Start:
N2 (operating engine). ABOVE 80%
Crossbleed AUTO OR OPEN
Engine Bleed (operating engine). OPEN
Start/Stop Selector START, THEN RUN
Engine Indication MONITOR
Check ITT and N2 rising. Observe limits.
Check ignition and fuel flow indication at 10% N2.
APU bleed start:
* * * * *

[FR Doc. C0-16110 Filed 7-12-00; 8:45 am]
BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 71
[Airspace Docket No. 00-ACE-7]
Amendment to Class E Airspace; Hampton, IA

Correction
In rule document 00-12821, in the issue of Friday, June 16, 2000, on page 37833, in the third column, the phrase “ACE AI E5 Hampton, IA [Revised]” should read “ACE IA E5 Hampton, IA [Revised]”.
[FR Doc. C0-12821 Filed 7-12-00; 8:45 am]
BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 71
[Airspace Docket No. 00-ASO-24]

Proposed Establishment of Class D Airspace; Oak Grove, NC

Correction
In proposed rule document 00-15944 beginning on page 39111 in the issue of Friday, June 23, 2000 make the following correction:
On page 39111, in the first column, under the heading DATES: , “June 24, 2000” should read “July 24, 2000 ”.

[FR Doc. C0-15944 Filed 7-12-00; 8:45 am]
BILLING CODE 1505-01-D