

Order 13132, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket No. 2000-SW-38-AD, published in the **Federal Register** on February 14, 2001 (66 FR 10241), is withdrawn.

Issued in Fort Worth, Texas, on September 19, 2002.

Eric D. Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02-24990 Filed 10-1-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-61-AD]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model AS 365 N3 and EC 155B Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for the specified Eurocopter France (Eurocopter) helicopters. This proposal would revise the Airworthiness Limitations section of the maintenance manuals by establishing a new service life limit for the Fenestron pitch change control rod (control rod). This proposal is prompted by a failure of a control rod on a prototype helicopter that led to a precautionary landing. The actions specified by this proposed AD are intended to prevent failure of the control rod, loss of control of the tail rotor, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before December 2, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2001-SW-61-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to

the Rules Docket at the following address: *9-asw-adcomments@faa.gov*. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Jim Grigg, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5490, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposals contained in this document may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this proposal must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2001-SW-61-AD." The postcard will be date stamped and returned to the commenter.

Discussion

The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on Eurocopter Model AS 365 N and Model EC 155B helicopters. The DGAC advises that a control rod failure occurred on a prototype aircraft and mandates removing control rod, part number (P/N) 365A33616121, at certain times depending on the number of helicopter flight hours.

Eurocopter has issued Alert Telex No. 04A003, for Model EC 155B helicopters, and Alert Telex No. 01.00.54, for Model AS 365 N3 helicopters, both dated

September 5, 2001. The alert telexes specify a new service life of 300 flight hours for control rod, P/N 365A33616121. The DGAC classified these alert telexes as mandatory and issued AD No. 2001-443-054(A), for Model AS 365 N3 helicopters, and AD No. 2001-444-003(A), for Model EC 155B helicopters. Both AD's are dated October 17, 2001 and were issued to ensure the continued airworthiness of these helicopters in France.

These helicopter models are manufactured in France and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs registered in the United States. Therefore, the proposed AD would reduce the current service life limit of 1,500 hours time in service (TIS) to 300 hours TIS for the control rod, part number 365A33616121, and would require removing the control rod:

- Before further flight for helicopters with control rods having 700 or more hours TIS;
- Within 20 hours TIS for helicopters with control rods having 500 or more hours TIS, but less than 700 hours TIS; and
- Within 30 hours TIS for helicopters with control rods having more than 270 hours TIS and less than 500 hours TIS.

The proposed AD would require revising the Airworthiness Limitations section of the maintenance manuals to reflect the new retirement life of 300 hours TIS for the control rod. The actions would be required to be accomplished in accordance with the alert telexes described previously.

The FAA estimates that 2 helicopters of U.S. registry would be affected by this proposed AD, that it would take approximately 0.5 work hour per helicopter to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$60, assuming no control rods will reach the 300 hours TIS retirement life within the next year.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship

between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Eurocopter France: Docket No. 2001–SW–61–AD.

Applicability: Model AS 365 N3 with MOD 0764B39 (Quiet Fenestron) and Model EC 155B helicopters with tail rotor pitch change control rod, part number (P/N) 365A33616121, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability

provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the Fenestron pitch change control rod (control rod), loss of control of the tail rotor, and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove the control rod from service in accordance with Eurocopter Alert Telex No. 04A003, for Model EC 155B helicopters, and Alert Telex No. 01.00.54, for Model AS 365 N3 helicopters, both dated September 5, 2001, using the following table for the initial compliance time, and thereafter at intervals not to exceed 300 hours time-in-service (TIS):

Remove the control rod	For control rods with
Before further flight	700 or more hours TIS.
Within 20 hours TIS	500 or more hours TIS but less than 700 hours TIS.
Within 30 hours TIS	More than 270 hours TIS and less than 500 hours TIS.

(b) This AD revises the helicopter Airworthiness Limitations section of the maintenance manuals by establishing a new retirement life for control rod, P/N 365A33616121, of 300 hours TIS.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(d) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD No. 2001–443–054(A), for Model AS 365 N3 helicopters, and AD No. 2001–444–003(A), for Model EC 155B helicopters. Both AD's are dated October 17, 2001.

Issued in Fort Worth, Texas, on September 18, 2002.

Eric Bries,
*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*
[FR Doc. 02–24989 Filed 10–1–02; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 300

[FRL–7384–1]

National Oil and Hazardous Substance Pollution Contingency Plan; National Priorities List

AGENCY: Environmental Protection Agency.

ACTION: Notice of intent to delete a portion of the Department of Energy (DOE) Mound Superfund Site from the National Priorities List.

SUMMARY: The Environmental Protection Agency, (EPA) Region V is issuing a notice of intent to delete Parcel 4 from the Department of Energy (DOE) Mound Superfund Site (Mound Site) located in Miamisburg, Ohio, from the National

Priorities List (NPL) and requests public comments on this notice of intent to delete. Parcel 4 is located on the southern border of the operational area of the Mound Superfund Site. The NPL, promulgated pursuant to section 105 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, as amended, is found at Appendix B of 40 CFR part 300, which is the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). The EPA and the State of Ohio, through the Ohio Environmental Protection Agency, have determined that the DOE has implemented all appropriate response actions required with respect to Parcel 4. However, this deletion does not preclude future actions under Superfund or relieve DOE of their Long-Stewardship or Operation and Maintenance responsibilities. In the "Rules and Regulations" Section of today's **Federal Register**, we are publishing a direct final notice of deletion of Parcel 4 of the Mound Superfund Site without prior notice of intent to delete because we view this as a non-controversial revision and anticipate no adverse comment. We have explained our reasons for this