

(b) The adjustments displayed in paragraph (a) of this section apply to acts occurring beginning on November 1, 2004.

[FR Doc. 04-22537 Filed 10-6-04; 8:45 am]

BILLING CODE 7535-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-CE-40-AD; Amendment 39-13795; AD 2004-19-01]

RIN 2120-AA64

**Airworthiness Directives; Cessna Aircraft Company 120, 140, 140A, 150, F150, 170, 172, F172, FR172, P172D, 175, 177, 180, 182, 185, A185E, 190, 195, 206, P206, U206, TP206, TU206, 207, T207, 210, T210, 336, 337, and T337 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes a correction to Airworthiness Directive (AD) 2004-19-04, which was published in the **Federal Register** on September 17, 2004 (69 FR 55943), and applies to certain Cessna Aircraft Company (Cessna) 120, 140, 140A, 150, F150, 170, 172, F172, FR172, P172D, 175, 177, 180, 182, 185, A185E, 190, 195, 205, 205A, 206, P206, P206E, TP206A, TU206, TU206E, U206, U206E, 207, T207, 210, T210, 336, 337, and T337 series airplanes. We incorrectly referenced the AD number as AD 2004-19-04. The correct AD number is 2004-19-01. This action corrects the regulatory text.

**DATES:** The effective date of this AD remains November 1, 2004.

**FOR FURTHER INFORMATION CONTACT:** Gary D. Park, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4123; facsimile: (316) 946-4107.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

On September 8, 2004, FAA issued AD 2004-19-04, Amendment 39-13795 (69 FR 55943, September 17, 2004), which applies to certain Cessna 120, 140, 140A, 150, F150, 170, 172, F172, FR172, P172D, 175, 177, 180, 182, 185, A185E, 190, 195, 205, 205A, 206, P206, P206E, TP206A, TU206, TU206E, U206, U206E, 207, T207, 210, T210, 336, 337, and T337 series airplanes. This AD supersedes AD 86-26-04 with a new

AD that requires you to inspect and, if necessary, modify the pilot/co-pilot upper shoulder harness adjusters that have certain Cessna accessory kits incorporated.

#### Need for the Correction

The FAA incorrectly referenced the AD number as 2004-19-04. The correct AD number is AD 2004-19-01. This correction is needed to ensure that the correct AD number is entered in the logbook and to eliminate misunderstanding in the field.

#### Correction of Publication

■ Accordingly, the publication of September 17, 2004 (69 FR 55943), of Amendment 39-13795; AD 2004-19-04, which was the subject of FR Doc. 04-20774, is corrected as follows:

##### § 39.13 [Corrected]

■ On page 55945, in section 39.13 [Amended], replace 2004-19-04 with 2004-19-01.

Action is taken herein to correct this reference in AD 2004-19-04 and to add this AD correction to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The effective date remains November 1, 2004.

Issued in Kansas City, Missouri, on September 23, 2004.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-21814 Filed 10-6-04; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-NM-235-AD; Amendment 39-12861; AD 2002-16-22]

RIN 2120-AA64

**Airworthiness Directives; Boeing Model 727 Series Airplanes Modified in Accordance With Supplemental Type Certificate SA1444SO, SA1509SO, SA1543SO, or SA1896SO**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document corrects an error that appeared in airworthiness directive (AD) 2002-16-22 (final rule, correction) that was published in the **Federal Register** on August 16, 2004 (69 FR 50299). The error resulted in an incorrect reference to certain

supplemental type certificates. This AD is applicable to certain Boeing Model 727 series airplanes that have been converted from a passenger- to a cargo-carrying ("freighter") configuration. This AD requires, among other actions, installation of a fail-safe hinge, redesigned main deck cargo door warning and power control systems, and 9g crash barrier.

**DATES:** Effective September 19, 2002.

**FOR FURTHER INFORMATION CONTACT:** M. Hassan Amani, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6080; fax (770) 703-6097.

#### SUPPLEMENTARY INFORMATION:

Airworthiness Directive (AD) 2002-16-22, amendment 39-12861, applicable to certain Boeing Model 727 series airplanes that have been converted from a passenger- to a cargo-carrying ("freighter") configuration, was published in the **Federal Register** on August 15, 2002 (67 FR 53434). That AD requires, among other actions, installation of a fail-safe hinge, redesigned main deck cargo door warning and power control systems, and 9g crash barrier.

On August 16, 2004, we issued a final rule, correction (69 FR 50299, August 16, 2004), to AD 2002-16-22. The final rule, correction corrects an error that resulted in an incorrect reference to a supplemental type certificate. As published, the title of final rule, correction states "Boeing Model 727 Series Airplanes Modified with Supplemental Type Certificate SA1767SO or SA1768SO." However, the correct applicable supplemental type certificates (STC) are SA1444SO, SA1509SO, SA1543SO, or SA1896SO, as specified in AD 2002-16-22.

Since no other part of the regulatory information has been changed, the final rule is not being republished in the **Federal Register**.

The effective date of this AD remains September 19, 2002.

##### § 39.13 [Corrected]

■ On page 50299, in the second column, the title of AD 2002-16-22 is corrected to read as follows:

\* \* \* \* \*

Airworthiness Directives; Boeing Model 727 Series Airplanes Modified in Accordance With Supplemental Type Certificate SA1444SO, SA1509SO, SA1543SO, or SA1896SO.

\* \* \* \* \*