

chapter for an electronic item as if it were a check subject to that section.

\* \* \* \* \*

4. In § 210.9, revise paragraph (b)(5) to read as follows:

**§ 210.9 Settlement and payment.**

\* \* \* \* \*

(b) \* \* \*

(5) *Manner of settlement.* Settlement with a Reserve Bank under paragraphs (b)(1) through (4) of this section shall be made by debit to an account on the Reserve Bank's books, cash, or other form of settlement to which the Reserve Bank agrees, except that the Reserve Bank may, in its discretion, obtain settlement by charging the paying bank's account. A paying bank may not set off against the amount of a settlement under this section the amount of a claim with respect to another cash item, cash letter, or other claim under section 229.34(c) and (d) of this chapter (Regulation CC) or other law.

\* \* \* \* \*

**PART 229—AVAILABILITY OF FUNDS AND COLLECTION OF CHECKS (REGULATION CC)**

5. The authority citation for part 229 continues to read as follows:

**Authority:** 12 U.S.C. 4001 *et seq.*, 12 U.S.C. 5001–5018.

6. In § 229.2, add a new paragraph (fff) to read as follows:

**§ 229.2 Definitions.**

\* \* \* \* \*

(fff) *Remotely created check* means a check that is drawn on a customer account at a bank, is created by the payee, and does not bear a signature in the format agreed to by the paying bank and the customer.

7. In § 229.34, redesignate paragraphs (d), (e), and (f) as paragraphs (e), (f), and (g), and add a new paragraph (d) to read as follows:

**§ 229.34 Warranties.**

\* \* \* \* \*

(d) *Transfer and presentment warranties with respect to a remotely created check.*

A bank that transfers or presents a remotely created check and receives a settlement or other consideration warrants to the transferee bank, any subsequent collecting bank, and the paying bank that the person on whose account the remotely created check is drawn authorized the issuance of the check according to the terms stated on the check.

\* \* \* \* \*

8. In § 229.43, revise paragraph (b)(3) to read as follows:

**§ 229.43 Checks Payable in Guam, American Samoa, and the Northern Mariana Islands.**

\* \* \* \* \*

(b) *Rules applicable to Pacific islands checks.* \* \* \*

\* \* \* \* \*

(3) § 229.34(c)(2), (c)(3), (d), (e), and (f);

\* \* \* \* \*

9. In Appendix E to part 229:

a. Under paragraph II., § 229.2, paragraph (OO) is revised and a new paragraph (FFF) is added.

b. Under paragraph XX., § 229.34, redesignate paragraphs D., E., and F. as paragraphs E., F., and G., and add a new paragraph D.

**APPENDIX E TO PART 229—COMMENTARY**

\* \* \* \* \*

*II. Section 229.2 Definitions*

\* \* \* \* \*

*OO. 229.2(o) Interest Compensation*

1. This calculation of *interest compensation* derives from U.C.C. 4A–506(b). (See §§ 229.34(e) and 229.36(f).)

\* \* \* \* \*

*FFF. 229.2(fff) Remotely Created Check*

1. A remotely created check may be drawn on a consumer account or an account held by a corporation, unincorporated company, partnership, government unit or instrumentality, trust, or any other entity or organization. In accordance with principles of the law of agency, an agent of a payee is deemed to be the payee for purposes of the definition of remotely created checks.

2. A check authorized by a consumer over the telephone, which is created by the payee, and which bears a legend on the signature line such as “Authorized by Drawer” is an example of a remotely created check. A check that bears the signature of the customer or a signature purporting to be the signature of the customer in the format agreed to by the paying bank and the customer is not a remotely created check. For example, the agreed-upon format is often a handwritten signature, or in the case of corporate checks, a machine-applied signature. In these cases, a check that bears a handwritten or machine-applied signature (regardless of whether the signature was authentic) would not be a remotely created check. A typical forged check, such as a stolen personal check fraudulently signed by a person other than the drawer, is not covered by the definition of a remotely created check.

3. The definition of a remotely created check includes a remotely created check that has been reconvered to a substitute check.

\* \* \* \* \*

*XX. Section 229.34 Warranties*

\* \* \* \* \*

*D. 229.34(d) Transfer and Presentment Warranties*

1. The transfer and presentment warranties for remotely created checks supplement the Federal Trade Commission's Telemarketing Sales Rule, which requires telemarketers that submit checks for payment to obtain the customer's “express verifiable authorization” (the authorization may be either in writing or tape recorded and must be made available upon request to the customer's bank). 16 CFR 310.3(a)(3).

2. Any transferring bank, collecting bank, or presenting bank warrants that the remotely created check that it is transferring or presenting is authorized according to all of its terms by the person on whose account the check is drawn. The warranties are given only by banks and only to subsequent banks in the collection chain. The warranties ultimately shift liability for the loss created by an unauthorized remotely created check to the depository bank. The depository bank cannot assert the transfer and presentment warranties against a depositor; however, it would likely have a claim under other laws against that person or could choose to transfer the liability by contract. The transfer and presentment warranties differ from the U.C.C. warranty provisions, which are given by any person that transfers a remotely created check including a nonbank, apply only to remotely created consumer checks, and cover authorization of the issuance of the check in the amount for which the check is drawn.

3. The transfer and presentment warranties for a remotely created check apply to a remotely created check that has been reconvered to a substitute check.

\* \* \* \* \*

By order of the Board of Governors of the Federal Reserve System, February 28, 2005.

**Jennifer J. Johnson,**  
*Secretary of the Board.*

[FR Doc. 05–4128 Filed 3–3–05; 8:45 am]

**BILLING CODE 6210–01–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2004–19837; Directorate Identifier 2004–CE–43–AD]

**RIN 2120–AA64**

**Airworthiness Directives; Air Tractor, Inc. Models AT–300, AT–301, AT–302, AT–400, AT–400A, AT–401, AT–402, AT–602, AT–802, and AT–802A Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for

certain Air Tractor, Inc. (Air Tractor) Models AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-402, AT-602, AT-802, and AT-802A airplanes. This proposed AD would require you to repetitively tighten the four eyebolts that attach the front and rear spar of the horizontal stabilizer to the respective stabilizer strut to the specified torque, and repetitively replace at specified intervals any eyebolts that attach the front and rear spar of the horizontal stabilizer to the respective stabilizer strut. An option for replacing the steel brace assembly inside the stabilizer with a new steel brace assembly with larger bushings and stronger eyebolts that increases the interval for replacement of eyebolts for AT-602, AT-802, and AT-802A airplanes is also included in this proposed AD. This proposed AD results from reports of failures of the subject eyebolt. We are issuing this proposed AD to detect, correct, and prevent future fatigue failure in any eyebolt that attaches the front and rear spar of the horizontal stabilizer to the respective stabilizer strut. Failure of the eyebolt could lead to an abrupt change or complete loss of pitch control and/or the airplane departing from controlled flight.

**DATES:** We must receive any comments on this proposed AD by May 6, 2005.

**ADDRESSES:** Use one of the following to submit comments on this proposed AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- *Fax:* 1-202-493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

To get the service information identified in this proposed AD, contact Air Tractor, Incorporated, P.O. Box 485, Olney, Texas 76374.

To view the comments to this proposed AD, go to <http://dms.dot.gov>. The docket number is FAA-2004-19837.

**FOR FURTHER INFORMATION CONTACT:**

Andrew D. McAnaul, Aerospace Engineer, FAA, Fort Worth Airplane Certification Office (ACO), ASW-150, 2601 Meacham Boulevard, Fort Worth,

Texas 76193-0150. Current duty station: San Antonio Manufacturing Inspection District Office (MIDO-43), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; telephone: (210) 308-3365; facsimile: (210) 308-3370.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

*How do I comment on this proposed AD?* We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include the docket number, "FAA-2004-19837; Directorate Identifier 2004-CE-43-AD" at the beginning of your comments. We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed rulemaking. Using the search function of our docket Web site, anyone can find and read the comments received into any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). This is docket number FAA-2004-19837. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://dms.dot.gov>.

*Are there any specific portions of this proposed AD I should pay attention to?* We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. If you contact us through a nonwritten communication and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend this proposed AD in light of those comments and contacts.

**Docket Information**

*Where can I go to view the docket information?* You may view the AD docket that contains the proposal, any comments received, and any final disposition in person at the DMS Docket Offices between 9 a.m. and 5 p.m. (eastern standard time), Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5227) is located on the plaza level of the Department of Transportation NASSIF Building at the street address stated in **ADDRESSES**. You may also view the AD docket on the Internet at [http://](http://dms.dot.gov)

[dms.dot.gov](http://dms.dot.gov). The comments will be available in the AD docket shortly after the DMS receives them.

**Discussion**

*What events have caused this proposed AD?* In December 1985, Snow Engineering Co. issued Service Letter # 62 to recommend the inspection of eyebolts. This was in response to several reports of eyebolt failures on Models AT-301 and AT-400 airplanes.

In response to another failure of an eyebolt on an AT-400 airplane, Snow Engineering Co. issued Service Letter #129 in September 1995. This service letter recommended eyebolt replacement every 2,000 hours time-in-service (TIS) for Models AT-301 and AT-400 airplanes. After a report of an eyebolt failure on a Model AT-602 airplane, Snow Engineering Co. revised Service Letter #129 in November 2003 to recommend replacing eyebolts for Models AT-602, AT-802, and AT-802A airplanes every 1,350 hours TIS.

The FAA also received two service difficulty reports (SDRs) in November 2003. Both SDRs referenced Model AT-802 airplane eyebolt cracks. In December 2003, FAA issued Special Airworthiness Information Bulletin (SAIB) CE-04-23. This SAIB recommended periodic eyebolt replacement following Snow Engineering Co. Service Letter #129.

In April 2004, we received a report of both eyebolts that attach the left hand stabilizer failing in flight on a Model AT-602 airplane. These eyebolts had accumulated 1,675 hours TIS.

Engineering analysis concludes that the eyebolts failed as a result of high-cycle, low-nominal stress. This is most likely due to the loss of torque during service.

Air Tractor has since redesigned the horizontal stabilizer structure for Models AT-802 and AT-602 airplanes to accommodate a new, stronger eyebolt.

Snow Engineering Co. also revised Service Letter #129 with new eyebolt replacement intervals and issued Service Letter #129A to include procedures for optional replacement of the steel brace assembly inside the stabilizer with a new steel brace assembly with larger bushings to accommodate new stronger eyebolts on existing Models AT-602, AT-802, and AT-802A airplanes. This modification provides for increased safety and extends eyebolt replacement intervals.

*What is the potential impact if FAA took no action?* Failure of an eyebolt could lead to an abrupt change or complete loss of pitch control and/or aircraft departure from controlled flight.

Is there service information that applies to this subject? As discussed earlier, Snow Engineering Co. has issued the following Service Letters:

- Service Letter #129, revised: October 21, 2004; and
- Service Letter #129A, dated August 7, 2004.

What are the provisions of this service information? These service letters include procedures for:

- Service Letter #129 recommends tightening the eyebolt nut to a specified torque, replacing the eyebolt, and includes the inspection procedures when replacing any eyebolt; and
- Service Letter #129A, for certain eyebolts, recommends replacing eyebolts with larger eyebolts, tightening the eyebolt nut to a

specified torque, and procedures for replacing the steel brace assembly inside the stabilizer with a new steel brace assembly with larger bushings.

**FAA’s Determination and Requirements of This Proposed AD**

What has FAA decided? We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing AD action.

What would this proposed AD require? This proposed AD would require you to incorporate the actions in the previously-referenced service information.

How does the revision to 14 CFR part 39 affect this proposed AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22,

2002), which governs FAA’s AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

**Costs of Compliance**

How many airplanes would this proposed AD impact? We estimate that this proposed AD affects 1,011 airplanes in the U.S. registry.

What would be the cost impact of this proposed AD on owners/operators of the affected airplanes? We estimate the following costs to do the proposed tightening of the four eyebolt nuts to the specified torque:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
1 workhour × \$65 per hour = \$65 .....	No parts required .....	\$65	\$65 × 1,011 = \$65,715

We estimate the following costs to do any necessary replacement of the four eyebolts for the Models AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-402 AT-602, AT-802, and AT-802A airplanes:

Average labor cost	Average parts cost	Average total cost per airplane	Average total cost on U.S. operators
1 workhour × \$65 per hour = \$65 .....	\$186.30	\$251.30	1,011 × \$251.30 = \$254,064.30

We estimate the following costs to do any necessary replacement of the steel brace assembly inside the stabilizer with a new steel brace assembly with larger bushings on existing Models AT-602, AT-802, and AT-802A airplanes:

Average labor cost	Average parts cost	Average total cost per airplane	Average total cost on U.S. operators
22 workhours × \$65 per hour = \$1,430 .....	\$901.65	\$2,331.65	312 × \$2,331.65 = \$727,474.80

**Authority for this Rulemaking**

What authority does FAA have for issuing this rulemaking action? Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures

the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

**Regulatory Findings**

Would this proposed AD impact various entities? We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

Would this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD and placed it in the AD Docket. You may get

a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket FAA-2004-19837; Directorate Identifier 2004-CE-43-AD" in your request.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Air Tractor, Inc.:** Docket No. FAA-2004-19837; Directorate Identifier 2004-CE-43-AD.

**When Is the Last Date I Can Submit Comments on This Proposed AD?**

(a) We must receive comments on this proposed airworthiness directive (AD) by May 6, 2005.

**What Other ADs Are Affected by This Action?**

(b) None.

**What Airplanes Are Affected by This AD?**

(c) This AD affects the following airplane models and serial numbers that are certificated in any category:

Models	Serial numbers
AT-300, AT-301, AT-302, AT-400, and AT-400A .....	All serial numbers.
AT-401/AT-402 .....	All through 401-0700.
AT-602 .....	All through 602-0695 that have any 7/16-inch eyebolt (P/N AN47-22A) installed; all beginning with 602-0703; and all that have any 9/16-inch eyebolt (P/N 30774-1) installed.
AT-802 and AT-802A .....	All through 802A-0188 that have any 7/16-inch eyebolt (P/N AN74-30A) installed; all beginning with 802A-0189; and all that have any 9/16-inch eyebolt (P/N 30775-1) installed.

**What Is the Unsafe Condition Presented in This AD?**

(d) This AD is the result of reports of failures of the subject eyebolt. The actions specified in this AD are intended to detect,

correct, and prevent future fatigue failure in any eyebolt that attaches the front and rear spar of the horizontal stabilizer to the respective stabilizer strut. Failure of the eyebolt could lead to an abrupt change or

complete loss of pitch control and/or the airplane departing from controlled flight.

**What Must I Do To Address This Problem?**

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Tighten the four eyebolts that attach the front and rear spar of the horizontal stabilizer to the respective stabilizer strut using the torque values referenced in Snow Engineering Co. Service Letter #129, revised October 21, 2004.	Within the next 12 calendar months after the effective date of this AD, unless already done. Repetitively tighten thereafter at every 12 calendar months after the date of the initial tightening to the specified torque.	Follow Snow Engineering Co. Service Letter #129, revised October 21, 2004.
(2) Repetitively replace any eyebolts that attach the front and rear spar of the horizontal stabilizer to the respective stabilizer strut.	Initially replace upon accumulating the applicable number of hours time-in-service (TIS) referenced in Snow Engineering Co. Service Letter #129, revised October 21, 2004, or within 50 hours TIS after the effective date of this AD, whichever occurs later. Replace repetitively thereafter at the intervals referenced in Snow Engineering Co. Service Letter #129, revised October 21, 2004.	Follow Snow Engineering Co. Service Letter #129, revised October 21, 2004.
(3) <i>For Model AT-602 airplanes through serial number 602-0695 and AT-802, and 802A airplanes through serial number 802A-0188:</i> As an alternative in order to use the increased replacement compliance times in paragraph (e)(2) of this AD, you may replace the steel brace assembly inside the stabilizer with a new steel brace assembly with larger bushings, and. (i) <i>For the Model AT-602 airplane:</i> replace any 7/16-inch eyebolt with the 9/16-inch eyebolt (P/N 30774-1). (ii) <i>For the Model AT-802 and AT-802A airplanes:</i> replace any 7/16-inch eyebolt with the 9/16-inch eyebolt (P/N 30775-1).	At any time after the effective date of this AD. Use the applicable time in Snow Engineering Co. Service Letter #129A, dated August 7, 2004. The repetitive replacement of paragraph (e)(2) of this AD is still required.	Follow Snow Engineering Co. Service Letter #129A, dated August 7, 2004.

Actions	Compliance	Procedures
(4) Do not install any 5/16-inch eyebolt (P/N AN44-17A or AN44-21A), 7/16-inch eyebolt (AN47-22A or AN47-30A), or 9/16-inch eyebolt (P/N 30774-1 or 30775-1) that exceeds the corresponding cumulative hours TIS specified in paragraphs (e)(2) or (e)(3) of this AD..	As of the effective date of this AD. ....	Not Applicable.

### May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Fort Worth Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Andrew D. McAnaul, Aerospace Engineer, FAA, Fort Worth Airplane Certification Office (ACO), ASW-150, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150. Current duty station: San Antonio Manufacturing Inspection District Office (MIDO-43), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; telephone: (210) 308-3365; facsimile: (210) 308-3370.

### May I Get Copies of the Documents Referenced in This AD?

(g) To get copies of the documents referenced in this AD, contact Air Tractor, Incorporated, P.O. Box 485, Olney, Texas 76374. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, S.W., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-19837.

Issued in Kansas City, Missouri, on February 28, 2005.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-4238 Filed 3-3-05; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2004-19354; Directorate Identifier 2004-CE-30-AD]

RIN 2120-AA64

#### Airworthiness Directives; Precise Flight, Inc. Models SVS I and SVS IA Standby Vacuum Systems

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all airplanes equipped with Precise Flight, Inc. (Precise Flight) Models SVS I and SVS IA standby vacuum systems (SVS) installed under certain supplemental type certificates or through field approval. This proposed AD would require you to replace the airplane flight manual supplement (AFMS) in the airplane flight manual with the appropriate revision and install placards as defined in the AFMS, upgrade the Model SVS I or SVS IA SVS to the Model VI SVS, and add the instructions for continued airworthiness (ICA) to the maintenance schedule for the aircraft. This proposed AD results from several reports of failed shuttle control valves of the standby vacuum system (SVS) and one report of an airplane crash with a fatality in which improper use of the SVS was a factor. We are issuing this proposed AD to correct problems with the SVS before failure or malfunction during instrument flight rules (IFR) flight that can lead to pilot disorientation and loss of control of the aircraft.

**DATES:** We must receive any comments on this proposed AD by April 29, 2005.

**ADDRESSES:** Use one of the following to submit comments on this proposed AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov>

and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- *Fax:* 1-202-493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

To get the service information identified in this proposed AD, contact Precise Flight, Inc., 63120 Powell Butte Road, Bend Oregon 97701, telephone: (800) 547-2558; facsimile: (541) 388-1105; electronic mail:

[preciseflight@preciseflight.com](mailto:preciseflight@preciseflight.com);  
Internet: <http://www.preciseflight.com/>.

To view the comments to this proposed AD, go to <http://dms.dot.gov>. The docket number is FAA-2004-19354.

**FOR FURTHER INFORMATION CONTACT:** Ms. Marcia Smith, Aerospace Engineer, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4065; telephone: (425) 917-6484; facsimile: (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

*How do I comment on this proposed AD?* We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include the docket number, "FAA-2004-19354; Directorate Identifier 2004-CE-30-AD" at the beginning of your comments. We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed rulemaking. Using the search function of our docket Web site, anyone can find and read the comments received into any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association,